

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 01/26/2023

FORM APPROVED

OMB NO. 0938-039

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155796	X2) MULTIPLE CONSTRUCTION A. BUILDING -- _____ B. WING _____	X3) DATE SURVEY COMPLETED 12/07/2022
--	---	--	---

NAME OF PROVIDER OR SUPPLIER CEDARS THE	STREET ADDRESS, CITY, STATE, ZIP COD 14409 SUNRISE CT LEO, IN 46765
--	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
E 0000 Bldg. --	<p>An Emergency Preparedness Survey was conducted by the Indiana Department of Health in accordance with 42 CFR 483.73.</p> <p>Survey Date: 12/07/22</p> <p>Facility Number: 001215 Provider Number: 155796 AIM Number: 100450890</p> <p>At this Emergency Preparedness survey, The Cedars was found in compliance with Emergency Preparedness Requirements for Medicare and Medicaid Participating Providers and Suppliers, 42 CFR 483.73. The facility has a capacity of 65 and had a census of 38 at the time of this survey.</p> <p>Quality Review completed on 12/08/22</p>	E 0000		
K 0000 Bldg. 01	<p>A Life Safety Code Recertification and State Licensure Survey was conducted by the Indiana Department of Health in accordance with 42 CFR 483.90(a).</p> <p>Survey Date: 12/07/22</p> <p>Facility Number: 001215 Provider Number: 155796 AIM Number: 100450890</p> <p>At this Life Safety Code survey, The Cedars was found not in compliance with Requirements for Participation in Medicare/Medicaid, 42 CFR Subpart 483.90(a), Life Safety from Fire, and the</p>	K 0000		

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Chad Forth

Administrator

01/20/2023

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined other safeguards provide sufficient protection to the patients. (see instructions.) Except for nursing homes, the findings stated above are disclosable following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosed days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155796	X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____	X3) DATE SURVEY COMPLETED 12/07/2022
--	---	--	---

NAME OF PROVIDER OR SUPPLIER CEDARS THE	STREET ADDRESS, CITY, STATE, ZIP COD 14409 SUNRISE CT LEO, IN 46765
--	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
K 0223 SS=F Bldg. 01	<p>2012 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), Chapter 19, Existing Health Care Occupancies and 410 IAC 16.2.</p> <p>This one story facility with a basement was determined to be of Type V (111) construction and was fully sprinklered. The facility has a fire alarm system with smoke detection in the corridors, areas open to the corridors and hard wired smoke detectors in the resident rooms. The facility is fully protected by a Type II EES 300 kW diesel generator. The facility has a capacity of 65 and had a census of 38 at the time of this survey.</p> <p>All areas where the residents have customary access are sprinklered. All areas which provided facility services were sprinklered. The facility does have a barn providing facility services that was not sprinklered.</p> <p>Quality Review completed on 12/08/22</p> <p>NFPA 101 Doors with Self-Closing Devices Doors with Self-Closing Devices Doors in an exit passageway, stairway enclosure, or horizontal exit, smoke barrier, or hazardous area enclosure are self-closing and kept in the closed position, unless held open by a release device complying with 7.2.1.8.2 that automatically closes all such doors throughout the smoke compartment or entire facility upon activation of: * Required manual fire alarm system; and * Local smoke detectors designed to detect smoke passing through the opening or a required smoke detection system; and * Automatic sprinkler system, if installed; and * Loss of power.</p>			

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155796	X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____	X3) DATE SURVEY COMPLETED 12/07/2022
--	---	--	---

NAME OF PROVIDER OR SUPPLIER CEDARS THE	STREET ADDRESS, CITY, STATE, ZIP COD 14409 SUNRISE CT LEO, IN 46765
--	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
--------------------	--	---------------	---	----------------------

	<p>18.2.2.2.7, 18.2.2.2.8, 19.2.2.2.7, 19.2.2.2.8</p> <p>Based on observation and interview the facility failed to ensure 2 of 2 rolling fire doors/windows located in smoke barriers were kept in a closed position unless held open by a release device complying with 7.2.1.8.2.</p> <p>(1) Upon release of the hold-open mechanism, the leaf becomes self-closing.</p> <p>(2) The release device is designed so that the leaf instantly releases manually and, upon release, becomes self-closing, or the leaf can be readily closed.</p> <p>(3) The automatic releasing mechanism or medium is activated by the operation of approved smoke detectors installed in accordance with the requirements for smoke detectors for door leaf release service in NFPA 72, National Fire Alarm and Signaling Code.</p> <p>(4) Upon loss of power to the hold-open device, the hold open mechanism is released, and the door leaf becomes self-closing. This deficient practice could affect all residents.</p> <p>Findings include:</p> <p>Based on observations with the Maintenance Director on 12/07/22 at 12:30 p.m., there was a rolling fire door in the 300-smoke wall located in the salon, and a rolling fire door/window in the smoke wall between the kitchen and dining room. Both doors were held open with a cable containing a fusible link that did not release the door/window with the fire alarm. Based on interview at the time of observation, the Maintenance Director agreed both doors were held open with a device that did not release with the fire alarm and stated the rolling door/window did not close when the fire alarm system was activated.</p>	K 0223	<p>In regard to the roll up fire doors located in the kitchen, it is not a penetration through a smoke barrier and is in compliance with current regulations; therefore no changes will be needed. In regard to the salon roll up door, quotes have been obtained. The board will make the final decision as to replacement with a fire system tied roll up door to meet the regulations, or permanently securing the door so it is no longer in use. The board may also opt to permanently close the doorway to create a smoke and fire barrier with 2 layers of 5/8 drywall on both sides of steel studs. The facility was checked to ensure no other roll up doors in the nursing facility were out of compliance with this regulation and none were found. The corrective action will be completed as soon as possible but not later than March 7, 2022.</p>	03/07/2023
--	---	--------	--	------------

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155796	X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		X3) DATE SURVEY COMPLETED 12/07/2022
NAME OF PROVIDER OR SUPPLIER CEDARS THE			STREET ADDRESS, CITY, STATE, ZIP COD 14409 SUNRISE CT LEO, IN 46765		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCY (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
	<p>Hazard - see K322) Based on observation and interview, the facility failed to ensure the corridor doors to 1 of 3 soiled utility rooms was provided with a self-closing device which would cause the door to automatically close and latch into the door frame. This deficient practice could affect staff in the service hall.</p> <p>Findings include:</p> <p>Based on observations during a tour of the facility with the Maintenance Director on 12/07/22 at 12:05 p.m., the 300-hall soiled utility room exceeding 64 gallons of dirty linen and trash was equipped with self-closing device but did not latch into the frame due to paper shoved into the strike opening in the door frame. Based on interview at the time of observation, the Maintenance Director agreed paper was shoved in the latch catch preventing the door from latching and did remove the paper.</p> <p>3.1-19(b)</p>	K 0321	In regard to the blocked open door leading to a hazardous area, a search of other doors leading to other hazardous areas was conducted and all were found secured. An in-service with all staff will be conducted to educate on the importance of not interfering with locking devices for safety. Agency staff will also be oriented to ensure that they understand the importance of not interfering with locking devices. An audit of 20 doors per month will be conducted for 6 months to ensure compliance. This will be monitored in a QAPI PIP for 6 months with a 100% success rate prior to removal. This corrective action will be completed by January 26, 2022.	01/26/2023	