

PRELIMINARY HISTORIC BRIDGE ALTERNATIVE ANALYSIS REPORT

BUSINESS 37 NORTH OVER BEANBLOSSOM CREEK

Location: 0.1 Miles South of I-69, Monroe County, Indiana BRIDGE FILE #: MONROE NO. 913; NBI #: 5300130



PREPARED FOR:

PREPARED BY: BEAM, LONGEST & NEFF

MONROE COUNTY BOARD OF COMMISSIONERS

DATE: NOVEMBER 2023

TABLE OF CONTENTS

I.	EXISTING STRUCTURE DATA	1
II.	EXISTING CONDITIONS	2
III.	PURPOSE AND NEED	
IV.	ALTERNATIVES	4
V.	MINIMIZATION AND MITIGATION	11
VI.	PRELIMINARY PREFERRED ALTERNATIVE	12
VII.	APPENDIX	13
	MAPS	A
	PHOTOGRAPHS	В
	DESIGN CRITERIA AND SUPPORTING INFORMATION	C
	COST ESTIMATES	
	LOAD RATING SUMMARY AND SI&A INSPECTION REPORT	
	FRACTURE CRITICAL INSPECTION REPORT	
	ORIGINAL AND REHABILITATION PLANS	
	TRAFFIC AND ACCIDENT DATA	
	ALTERNATIVE PLAN VIEW EXHIBITS	
	ALILMATIVE LEAN VILW EMHOTIS	

PRELIMINARY HISTORIC BRIDGE ALTERNATIVE ANALYSIS REPORT

EXISTING BRIDGE NO. 53-00913 (NBI No. 5300130) BUSINESS 37 NORTH OVER BEANBLOSSOM CREEK BLOOMINGTON TOWNSHIP, MONROE COUNTY, INDIANA

I. EXISTING STRUCTURE DATA

A. Identification/History

Existing Bridge No.: Monroe No. 913 (53-00913, NBI 5300130) Project Location: 0.1 mile south of I-69, T-9-N, R-1-W

Latitude: 39° 13′ 54.12″ N (39.2317° N) **Longitude:** 86° 32′ 26.84″ W (-86.54079° W)

Des. No.: Not Available **Year Built**: 1946

Year Rehabilitated: 1969, 1985, and 1995; Year Repaired: 2018 and 2023

Most Recent Field Inspection Date: 04/28/2022 (BLN)

Average Daily Traffic (ADT)/Year of ADT: 10,190 VPD / 2029 & 13,752 VPD / 2049

Percentage of Commercial Vehicles: 5% (See current SI&A Report)

Low Volume Road: No

Functional Classification: Minor Arterial

Rural/Urban: Rural

National Highway System: No National Truck Network: No Detour Length: 1.5 miles

Load Rating: 21 Ton and 37 Ton H and HS Inventory, respectively (see current SI&A Report)

Sufficiency Rating: 52.7 out of 100 Functionally Obsolete **National Register of Historic Places (NRHP) Status**: Eligible

Historic Bridge Prioritization Status: Select

Historic Character-Defining Features: This bridge is eligible under Criterion C as it represents an early or distinctive phase in bridge construction, design, or engineering and it retains the historic integrity necessary to convey its engineering significance. This bridge is distinctive because it exemplifies an uncommon highway bridge type in Indiana. This bridge is eligible under Criterion C because it represents a variation, evolution, or transition that is conveyed through important features or innovations related to bridge construction, design, or engineering, and it retains historic integrity necessary to convey its engineering significance. This bridge displays exceptional overall or main span length for its type representing an innovative design and/or construction method.

B. Structure/Dimensions

MAIN SPANS

Surface Type: 1.75" modified portland cement concrete overlay on 6" precast prestressed concrete deck panels.

Out to Out of Copings: 32'-0"

Out to Out of Bridge Floor: 126'- 6 34''

Clear Roadway Width: 28'-0"

Number of Lanes on Structure: Two 12'-0" lanes

Skew: 00 degrees

Type of Superstructure: Steel Parker Pony Truss Bridge

Spans: 1 span @ 125'- 0 3/8"

Type of Substructure/Foundation: Concrete abutments on timber piling

Seismic Design Category: Seismic Design Category A (Preliminary investigation)

APPROACH SPANS Surface Type: N/A

Out to Out of Copings: N/A Out to Out of Bridge Floor: N/A Clear Roadway Width: N/A

Number of Lanes on Structure: N/A

Spans: N/A **Type of Substructure/Foundation:** N/A

Seismic Zone (only if Zone 2): N/A

C. Appurtenances

Bridge Railing: Miscellaneous aluminum two tube bridge railing connected to the Truss members.

Curbs: The concrete transition rails with curbs.

Sidewalks: N/A

Utilities: Overhead electric and communication lines and buried water line along the west ditch. The buried water line appears to cross the roadway 200 feet south of the bridge. In addition, overhead electric lines are in the southeast quadrant that appear to supply power to a utility building 125 feet from the southeast bridge corner.

Railroad: N/A

D. Approaches

ROADWAY

South Approach Roadway Width: Two, 12'-0" wide lanes with 4'-0" paved shoulders and 4'-0" earth shoulders (8'-0" total usable shoulder outside guardrail limits).

North Approach Roadway Width: North Bound (NB) lane is 16'-0" wide with 4'-0" (left) and 11'-0" (right) paved shoulders and 6'-0" (left) usable shoulder and 13'-0" (right) guardrail offset.

South Bound (SB) lane is 15'-0" wide with 9'-0" (left) and 5'-0" (right) paved shoulders and 12'-0" (left) and 5'-0" (right) usable shoulders.

Surface Type: Bituminous

Guardrail: Aluminum Rail with Steel W-Beam

Guardrail Transition: Aluminum Rail

Guardrail End Treatment: Steel W-Beam Type 1

II. EXISTING CONDITIONS

Photos detailing the existing conditions are included in Appendix B

A. Bridge Deck

General: The overall condition rating of the deck is fair (5 out of 9).

Repair/Maintenance Work: In 1969, the deck rehabilitation involved replacing the existing deck with a 6 1/4" precast pretensioned deck that was post tensioned together. In 1985, the deck was milled and overlaid with a modified portland cement concrete. In 1995, the bridge joints were replaced and ends of deck reconstructed. The joints were reconstructed in 2022. In 2023, a hole was found in the deck and an emergency repair was completed. The repair consisted of removing one full width panel section in Bay 5.

Surface Condition: Delamination and spalls throughout wearing surface. Leaking between panels. Transverse cracks in middle of deck and at edges of precast deck panels.

Overlay: 1.75-inch concrete overlay. East coping spalled at floor beams. Areas delaminated with some minor spalls and some patched with concrete.

Underside Condition: Underside of some panels have spalls with exposed steel. Some panels are missing beam connection clips. East deck coping spalled with exposed strands.

Joints: The joints are rated in satisfactory condition.

Drainage: N/A

Bridge Railing: There is impact damage to southeast bridge rail transition and damage to northeast bridge railing.

B. Superstructure

MAIN SPANS

General: The overall condition rating of the superstructure is fair (5 out of 9).

Repair/Maintenance Work: The 1985 work included cleaning and painting the steel truss and floor system. In 2018, the east exterior steel stringers were replaced.

Deficiencies: Heavy debris had accumulated on the lower chord and at low chord connections. There are areas of heavy pitting and minor section loss on inside of flanges, top of web, and rivet heads of lower chords. Low chord gusset plates have areas of moderate section loss near the center. Some vertical members have moderate to heavy section loss on the inside flange connection to the low chord. Lateral bracing connections with moderate to heavy section loss. Areas of surface rust and minor expansion rust on stringers and floor beams. Expansion bearings are severely rotated to the south and may have seized.

Fracture Critical Members: All of the connections are in fair to good condition. All the members are in satisfactory to good condition, except for lower chord member southwest L0L1, southeast L1L2, and vertical member northeast L1U1 that are in fair condition. No cracks were found in any of the members or connections. An in-depth fracture critical member inspection is required every two years.

Bearings/Pedestals: Northeast bridge seat has spalling that has caused some loss of bearing area. Debris has also collected on the bridge seats.

Damage: N/A

APPROACH SPANS - N/A

C. Substructure and Foundations

General: The existing substructure was rated in fair condition (5 out of 9). The existing substructure consists of concrete abutments on timber piles driven to rock.

Repair/Maintenance Work: N/A

Deficiencies: There is leaking on abutments. Spalling with exposed steel in mud walls at each bridge corner with 3 to 6 inches of section loss. Large spall with loss of bearing at South Abutment.

Drainage: N/A

Scour: According to the current bridge inspection report (see Appendix E), this bridge is considered as Low Risk for Vulnerability for Scour and was recorded as stable for scour conditions. No major scour was visible.

D. Approaches

General: The bridge was built on a short chord since it is within a large horizontal curve that ends approximately 125 north of the bridge. The roadway is fairly level at the bridge. The north approach roadway lanes are separated due to I-69 exit 123 ramps and converge together approximately 125 feet north of the bridge. The I-69 entrance ramp (NB lane) is fairly level and straight. The I-69 exit ramp (SB lane) goes over I-69 within a reverse curve, has superelevation, and comes down to tie into the bridge. The SB lane is

Approach Pavement: There are concrete approach slabs at each bridge end with a bituminous overlay. The existing bituminous approach pavement appears to be in good condition.

Guardrail: A guardrail transition type TGB and w-beam guardrail are at all four corners of the bridge.

Drives and Public Roads: There is a field entrance approximately 125 feet north of the bridge in the northwest quad. **Traffic-control Devices**: N/A

E. Slope walls

General: The channel is rated in good condition (7 out of 9) and is well defined. There is no slope wall or channel protection at the abutments and piers. The channel has a weir approximately 300 feet upstream.

Deficiencies: N/A

III. PURPOSE AND NEED

A. Background

This bridge carries Business 37 north over Beanblossom Creek. The project is located approximately 0.1 mile south of I-69 exit 123 in Monroe County. Please see Appendix A for location maps. Specifically, the project is in the northeast quarter of Section 8, Township 9 North, and Range 1 West as shown on the 7.5-minute Bloomington, Indiana USGS quadrangle map. The Beanblossom Creek flows east to west and has an upstream drainage area of approximately 112 square miles. Beanblossom Creek is not a navigable waterway at the intersection with Monroe County bridge 913.

Bridge 913 is a single span pony truss structure constructed in 1946. The existing structure span is 125.6'. The existing clear roadway over the bridge is 28'-0" and consists of two 12'-0" lanes with 2'-0" shoulders. The bridge was rehabilitated in 1969, 1985 and 1995 and repaired in 2018 and 2023. The latest bridge inspection report (4/28/2022, see Appendix E) assigned a bridge sufficiency rating of 52.7 out of a possible 100 and is considered functionally obsolete. The deck and superstructure are currently assessed as being in fair condition. During the past few years the deck and superstructure have continued to deteriorate causing load rating issues, critical findings, and minor repairs; therefore, we anticipate that the deck and superstructure condition ratings will be lowered to poor condition soon. The substructure is currently rated in satisfactory condition. Please see Appendix B for photographs of the existing road and bridge. In addition, additional information on this bridge may be found in the current load rating, and routine and fracture critical inspection reports that are provided in Appendices E and F.

According to the Indiana Historic Bridge Inventory, Bridge No. 913 is listed as a "Select" bridge, eligible for inclusion in the National Register of Historic Places (NRHP) under Criterion C. This bridge is eligible under Criterion C as it represents an early or distinctive phase in bridge construction, design, or engineering and it retains the historic integrity necessary to convey its engineering significance. This bridge is eligible under Criterion C because it represents a variation, evolution, or transition that is conveyed through important features or innovations related to bridge construction, design, or engineering, and it retains historic integrity necessary to convey its engineering significance.

B. Need

Monroe County has identified two needs that will be addressed by this project: the structural deficiencies caused by the deck and superstructure conditions and the substandard bridge geometry.

The bridge's needs are a result of the deterioration and distress exhibited by some of the truss verticals, diagonals, low chords, stringers, floor beams, and deck. In 2018 the poor condition of the east exterior stringers caused the bridge to be posted for load until the beams were replaced during an emergency repair. During the summer of 2023 a critical finding was issued for a 1 foot diameter hole that was discovered in the bridge deck. The hole was temporarily covered until the portion of deck was able to be repaired and replaced. The deterioration noted has resulted in a deck and superstructure condition rating of fair (5); however, with continued deterioration these condition ratings are expected to be lowered within the next couple inspection cycles. In addition the bridge shoulder width and bridge clear roadway width need improvement to meet current standards.

C. Purpose

The purpose of this project is to improve the overall condition of the bridge's deck and superstructure to good (7) or better. Improvement of the overall condition will also increase the structural capacity of the deck, truss members, and floor system. In addition the project will improve to bridge geometrics to satisfy current design standards.

D. Other Goals/Objective

In accordance with the Programmatic Agreement among the Federal Highway Administration, INDOT, the Indiana Historic Preservation Officer, and the Advisory Council on Historic Preservation regarding the Management and Preservation of Historic Bridges (HBPA) signed August 11, 2006, Monroe County is planning work on this bridge to follow the Secretary of the Interior's Standards for Rehabilitation, as specified in the HBPA's "Standard Treatment Approach for Historic Bridges."

An objective of this project is to improve the bridge railing test level to provide bridge railing that satisfies the minimum bridge railing test level. The current bridge railing safety performance criteria test level is unknown and assumed to be less than the required TL-5. The substandard bridge railing test level requires a Level Two Design Exception if not improved.

Another goal of this project is to ensure that the roadway has adequate roadway serviceability and that any proposed bridge structures satisfy all INDOT hydraulic requirements.

IV. ALTERNATIVES

The alternatives described in this document are based on the guidance for writing historic bridge Section 4(f) alternatives analysis produced by INDOT, Cultural Resource Office and finalized on December 14, 2012. Per the guidance, alternatives A through F must be analyzed in consecutive order until a feasible and prudent alternative has been determined. Once a feasible and prudent alternative has been determined, the remaining alternatives do not need to be discussed. A feasible alternative is one that is possible to engineer, design, and build. A prudent alternative is one that does not present significantly unique or unusual factors (e.g., cost; social, economic, or environmental impacts; community disruption).

This structure is listed on the INDOT historic bridge inventory list as a "Select" bridge. Per the terms of the "Programmatic Agreement Regarding Management and Preservation of Indiana's Historic Bridges" (Historic Bridge PA), the Federal Highway Administration–Indiana Division (FHWA) will satisfy its Section 106 responsibilities involving "Select" and "Non-Select" bridges through the Project Development Process (PDP) of the Historic Bridges PA (Stipulation III).

A. The No Build/Do Nothing Alternative

The No-Build/Do-Nothing Alternative was considered as a possible solution for the proposed project. This alternative proposed utilization of the existing facilities with no expenditure of capital funds or improvement of the roadway. The No-Build/Do-Nothing Alternative would not address the overall purpose and need of the project, which is to improve the physical condition of the bridge and prevent further deterioration. If the No-Build/Do-Nothing Alternative would be selected, deterioration of the bridge would continue. If the deterioration is not abated, weight restrictions will eventually be implemented until it becomes impassable to all vehicles. Although this alternative is feasible, it is not prudent to allow the bridge to deteriorate until it is impassable causing a significant community disruption.

B1. Rehabilitation of the Existing Bridge for Continued Vehicular Use (Two-Way Option) Meeting Secretary of Interior's Standards for Rehabilitation

The Secretary of the Interior (SOI) defines rehabilitation as "the act or process of making possible a compatible use for a property through repair, alterations, and additions while preserving those portions or features which convey its historical, cultural, or architectural values" (http://www.cr.nps.gov/local-law/arch_stnds_10.htm). The Standards for Rehabilitation follow the Department of Interior regulations 36 CFR 67, which defines rehabilitation as "the process of returning a building (structure) to a state of utility, through repair or alteration, which makes possible an efficient use while preserving those portions and features of the structure and its site and environment which are significant to its historic, architectural, and cultural values as determined by the Secretary". The 10 standards outlined shall be followed for each rehabilitation project.

Two-Way Option (Bridge Rehabilitation Including Roadway Reconstruction)

This alternative includes the rehabilitation of the existing bridge and the south and north approach roadway to improve the bridge condition but a few of the minimum design standards listed on the Level One controlling criteria checklist will not be met (see Table 1).

The bridge rehabilitation includes the replacement of the concrete bridge deck and aluminum bridge railing. Due to the close proximity to the exit and entrance ramps to I-69 at exit 123, type FT bridge railing will be constructed on a new concrete deck. The new bridge railing will satisfy the required bridge railing test level criteria and will provide additional protection from salt spray and water intrusion onto the steel truss. Rehabilitation of the truss would include replacement in-kind of some low chord members, some gusset plates, splice plates, some verticals, some external sway bracing, some lower lateral bracing, and some lattices. The east exterior stringers and any other stringers in poor condition will also be replaced. Repairs to some vertical and diagonal members and some floor beams will be completed to restore the members back to their original condition. The replacement or resetting of the truss bearings and reconstructing the bridge seats at the bearings will be completed. All connections affected by the rehabilitation will include the replacement of the rivets with high strength bolts. The bolts will have rounded heads to match the appearance of the original riveted construction. The truss would be cleaned and painted. The existing concrete bridge rail transitions and curbs are original, and they will be reconstructed to be like the existing but will satisfy current design standards. Current standard approach guardrail with end treatments would be installed. The roadway's horizontal alignment will satisfy the minimum radius, superelevation rate, and horizontal curve stopping sight distances. At the next design phase, the superelevation transition lengths will be evaluated once a survey of the project area is complete. According to the Indiana Design Manual (IDM) Fig. 412-2A and Fig. 55-3A (see Appendix C), requires an AASHTO design loading of HS-20. Currently the bridge satisfies HS-20 design loading, commercial and emergency vehicle legal loading requirements.

A bridge rehabilitation project requires that a scour analysis be performed for stream crossings to determine if the abutments are scour critical. The scour analysis model will be completed at the next design stage and review and approval by INDOT hydraulic bridge design is anticipated. If the substructure units are deemed scour critical, scour countermeasures shall be installed around the existing substructure units to alleviate any scour concerns. The existing bridge hydraulics were evaluated for the design storm events according to IDM Fig. 203-2C; however, no hydraulic model was created. The existing roadway serviceability at the bridge appears to satisfy the 1 foot of freeboard required above the Base Flood Elevation (BFE). In addition it appears that no over the road flow has been recorded at this location according to existing plans and Monroe County. Hydraulic modeling will be completed at the next design phase to confirm that the existing structure satisfies all hydraulic requirements. Please see Appendix C for additional hydraulic information.

The bridge will be closed approximately 10 months during construction for this alternative. The detour will route traffic onto SR 46 to I-69 exit 120A (1.5-mile detour). The project is considered a mobility significant project since it

would cause a temporary closure of I-69 exit 123. According to IDM Chapter 81-1.02, a transportation management plan (TMP) is anticipated for this project. In addition, an Interstate Highway Congestion Policy Exception Request is anticipated and coordination with INDOT Seymour District traffic will be required throughout the project design and construction. Coordination will be required with all affected utilities in the area. The overhead power lines that are east and west of the bridge are not expected to be affected. There is a water line that crosses the roadway 200 feet south of the bridge and follows the west ditch towards the south. The remainder of the utilities (sewer and fiber optic) have unknown locations. Further discussion and coordination are required for all utilities within the project limits.

The existing right of way is assumed to be located at the edges of pavement. This alternative will require reacquisition of the original right of way (50 feet on either side of the centerline of roadway) to complete this project.

Table 1:

B1. ALTERNATIVE CRITERIA CHECKLIST SUMMARY						
Design Element	Minimum Design Criteria	Existing Proposed Condition Condition				
Design Speed	Design Speed 45 mph		45 mph	No		
Lane Width	12 ft	12 ft	12 ft	No		
Usable Shoulder Width	8 ft	8 ft	8 ft	No		
Paved Shoulder Width	4 ft	4 ft Approach 2 ft Bridge	4 ft Approach 2.5 ft Bridge	Yes Bridge (Level 1)		
Bridge Clear Roadway Width	30 ft	28 ft	29 ft	Yes (Level 2)		
Structural Capacity	HS-20	HS-20	HS-20	No		
Horizontal Curve, Minimum Radius	960 ft	6139.17 ft	6139.17 ft	No		
Superelevation Transition Lengths	*	*	*	No		
Stopping Sight Distance Horizontal Curves	360 ft	> 360 ft	> 360 ft	No		
Stopping Sight Distance Vertical Curves	360 ft	> 360 ft	> 360 ft	No		
Maximum Grade	5%	0%	0%	No		
Travel Lane Cross Slope	2.0%	2.0%	2.0%	No		
Superelevation Rate	2.0%	2.0%	2.0%	No		
Vertical Clearance	N/A	N/A	N/A	N/A		
Bridge Railing Test Level	TL-5	Unknown	TL-5	No		

^{*}Superelevation transition lengths not evaluated for this option and will be evaluated at the next design stage if this is the chosen alternative.

This structure crosses Beanblossom Creek in a rural area and the ground is mainly tree covered along the banks with some areas of farm fields in the floodplain. A 401/404 permit will be required if scour countermeasures or channel clearing for debris are required. An Indiana Department of Natural Resources (IDNR) construction in a floodway permit will be required because the drainage area is greater than 50 square miles. There are possible wetlands near the project. An IDEM Construction Stormwater General Permit is not anticipated because the land disturbance is expected

to be less than 1 acre. A level 4 CE is required due to the anticipated structure rehabilitation impacts and historical significance of the bridge. No bat or bird habitat was found within the superstructure.

The existing bridge's geometry will not meet INDOT requirements since widening the truss is not prudent if we are to maintain the historic integrity of the existing bridge. The available bridge clear roadway width will not allow 4 foot shoulders over the bridge and would require a Level One Design Exception for shoulder width and a Level Two Design Exception for bridge clear roadway width. Please see Table 1 and Appendix C for the controlling design criteria checklist summary and additional information for required design criteria. This alternative would increase the remaining life of the bridge by 20 years. A plan view of this alternate is provided in Appendix I.

The rehabilitation option would include additional inspection costs versus the replacement alternatives. The bridge warrants replacement if its rehabilitation cost is greater than 80% of the replacement cost per IDM 412-5.04(01) (see Appendix C). The construction costs of the bridge rehabilitation, bridge maintenance, and roadway reconstruction for this alternative is approximately \$3,131,000 (see Appendix D or Section VI) and is approximately 81.8% of the estimated total bridge replacement cost of \$3,810,000 (see Appendix D or Section VI). This alternate is feasible since it may be designed and constructed following the Secretary Standards; however, the bridge would remain geometrically deficient due to the Level One and Two Design Exceptions required. Minimum design controlling standards necessary to rehabilitate the existing bridge cannot be met, and Monroe County does not wish to request design exceptions. The scope of this option does not address all the deficiencies; therefore, preliminarily this alterative is not prudent.

B2. Rehabilitation of the Existing Bridge for Continued Vehicular Use (Two-Way, One Lane Operation) NOT Meeting Secretary of Interior's Standards for Rehabilitation

The issues related to the use of the existing bridge in this alternative would be the same as those noted in the discussion of alternative B1. Consequently, preliminary review of this alternative in greater detail was not completed and this option is also preliminarily expected to be feasible and not be prudent.

C1. Rehabilitation of the Existing Bridge for Continued Vehicular Use (One-Way Pair) Meeting Secretary of Interior's Standards for Rehabilitation with Construction of New One-Way Structure

The issues related to the use of the existing bridge in this alternative would be the same as those noted in the discussion of alternative B1. Consequently, preliminary review of this alternative in greater detail was not completed and this option is also preliminarily expected to be feasible and not be prudent.

C2. Rehabilitation of the Existing Bridge for Continued Vehicular Use (One-Way Pair) NOT Meeting Secretary of Interior's Standards for Rehabilitation with Construction of New One-Way Structure

The issues related to the use of the existing bridge in this alternative would be the same as those noted in the discussion of alternative B1. Consequently, preliminary review of this alternative in greater detail was not completed and this option is also preliminarily expected to be feasible and not be prudent.

D. Bypass (non-vehicular)/ Build New Structure to North without Affecting the Historic Integrity

This alternative would consist of rehabilitating the existing bridge to meet pedestrian standards and construction of new approach roadway on a bypass alignment with a new bridge crossing Beanblossom Creek. All the minimum design standards listed on the Level One controlling criteria checklist would be met (see Table 2) for the new bypass bridge and roadway. The approach roadway would be realigned to meet the 45 mph design speed for the south approach and both the inbound and exit ramps at the north approach.

The new bridge is anticipated to be constructed over Beanblossom Creek approximately 50 feet east of the existing truss. Approximately 650 feet of the south approach, 450 feet of the inbound ramp, and about 1000 feet of the exit ramp would be reconstructed as part of the bypass to the existing structure. This alternative would require more tree clearing and the roadside ditches on the east side of Business 37 will be recut along the new roadway alignments; therefore, more environmental impacts are anticipated with this alternative. In addition, creating a bypass alignment increases the risk of impacting wetlands that are near the project site. See Appendix C for a wetland map of the project site. The bridge length is estimated to be approximately 215 feet, which would provide an opening large enough to meet the required Q100 opening from the hydraulic design calculations. The new bypass structure would consist of

two 12 feet lanes bordered by 8 feet shoulders to provide a clear roadway width of 40 feet. A parking area would be created at the ends of the existing truss bridge. A plan view of this alternate is provided in Appendix I.

Additional right-of-way would be required for this option and the project would be constructed under a full closure utilizing a detour route. A Construction Stormwater General Permit, IDNR construction in a floodplain, and Indiana Department of Environmental Management (IDEM) 401/404 permits are anticipated for this alternative. This alternative would impact the overhead power lines in the southeast quadrant and require demolition of a small utility building. It is unknown at this time if any other utilities would need to be relocated as part of this alternative.

The rehabilitation the existing structure will follow the Interior Secretary's Standards for Rehabilitation. Rehabilitation of the truss would include replacement in-kind of some low chord members, some gusset plates, splice plates, some verticals, some external sway bracing, some lower lateral bracing, and some lattices. The east exterior stringers and any other stringers in poor condition will also be replaced. Repairs to some vertical and diagonal members and some floor beams will be completed to restore the members back to their original condition. The replacement or resetting of the truss bearings and reconstructing the bridge seats at the bearings will be completed. All connections affected by the rehabilitation will include the replacement of the rivets with high strength bolts. The bolts will have rounded heads to match the appearance of the original riveted construction. The truss would be cleaned and painted. A new concrete deck with pedestrian railing will be constructed.

Table 2:

Design Element	Minimum Design Criteria	Existing Condition		
Design Speed	45 mph	45 mph	45 mph	No
Lane Width	12 ft	12 ft	12 ft	No
Usable Shoulder Width	8 ft	8 ft	8 ft	No
Paved Shoulder Width	4 ft	4 ft Approach 2 ft Bridge	4 ft Approach 8 ft Bridge	No
Bridge Clear Roadway Width	40 ft	28 ft	40 ft	No
Structural Capacity	HL-93	HS-20	HL-93	No
Horizontal Curve, Minimum Radius	960 ft	6139.17 ft	960 ft	No
Superelevation Transition Lengths	**	**	**	No
Stopping Sight Distance Horizontal Curves	360 ft	> 360 ft	> 360 ft	No
Stopping Sight Distance Vertical Curves	360 ft	> 360 ft	> 360 ft	No
Maximum Grade	5%	0%	0%	No
Travel Lane Cross Slope	2.0%	2.0%	2.0%	No
Superelevation Rate	**	**	**	No
Vertical Clearance	N/A	N/A	N/A	N/A
Bridge Railing Test Level	TL-5	Unknown	TL-5	No

^{**}Superelevation transition lengths and rate will be evaluated at the next design stage if this is the chosen alternative.

Alternate D is feasible because it can be designed and constructed. This option would meet the purpose and need developed by Monroe County and would also meet the INDOT design standards (See Table 2 below). The existing truss remaining in place would allow for visiting tourist and residents to stop and view the historic truss. The estimated construction cost for the new bypass bridge and roadway is \$5,746,000 and the estimated cost to rehabilitate and maintain the truss for pedestrian use is \$1,565,000. The estimated total cost would be \$7,311,000 (see Appendix D). This option is not prudent as this alternate has more environmental and utility impacts and it is more expensive than Alternate E (Relocate existing bridge and construct new bridge).

E. Relocation of Historic Bridge and New Bridge Construction

This alternative includes the construction of a new bridge and the relocation of the existing bridge. Due to the geometry of the alignment with the existing ramps to the north, minimization of environmental and utility impacts, construction of a new bridge would be on the same horizontal alignment that would reduce construction costs. The roadway alignment would be designed for a 45 mph speed. All the minimum design standards listed on the Level One controlling criteria checklist would be met (see Table 3) for the new bridge and roadway.

The existing bridge will be relocated to an off-site location and placed on new substructure units. This alternative would also consist of rehabilitating the existing structure as close as possible to the Interior Secretary's Rehabilitation Standards to accommodate a pedestrian loading. The existing truss would be dissembled, and match marked, transported, and reassembled at the new location for pedestrian use. Rehabilitation of the truss would include replacement in-kind of some low chord members, some gusset plates, splice plates, some verticals, some external sway bracing, some lower lateral bracing, and some lattices. The east exterior stringers and any other stringers in poor condition will also be replaced. Repairs to some vertical and diagonal members and some floor beams will be completed to restore the members back to their original condition. Portions of the existing truss bearings may be replaced. All connections affected by the rehabilitation will include the replacement of the rivets with high strength bolts. The bolts will have rounded heads to match the appearance of the original riveted construction. The truss would be cleaned and painted. A new concrete deck with pedestrian railing will be constructed.

The new vehicular structure over Beanblossom Creek would consist of two 12 foot lanes and 8 foot shoulders to provide a bridge clear roadway width of 40 feet. The bridge length is estimated to be approximately 215 feet, which would provide an opening large enough to meet the required Q100 opening from the hydraulic design calculations. Approximately 350 feet of the south approach roadway and 200 feet of approach roadway work on the north ramps would be required as part of the new bridge construction. A plan view of this alternate is provided in Appendix I.

Additional right-of-way would be required for this option and the project would be constructed under a full closure utilizing a detour route. A Construction Stormwater General Permit, IDNR construction in a floodplain, and Indiana Department of Environmental Management (IDEM) 401/404 permits are anticipated for this alternate. Coordination will be required with all affected utilities in the area. The overhead power lines that are east and west of the bridge are not expected to be affected. There is a water line that crosses the roadway 200 feet south of the bridge and follows the west ditch towards the south. The remainder of the utilities (sewer and fiber optic) have unknown locations. Further discussion and coordination are required for all utilities within the project limits.

This alternative is feasible because it can be designed and constructed. This option would meet the purpose and need developed by Monroe County and would also meet the INDOT design standards. The estimated construction cost for the new bridge and roadway is \$3,810,000. The estimated cost to relocate and rehabilitate the truss for pedestrian use in a new location is \$1,773,000. The estimated total cost would be \$5,583,000 (see Appendix D). This option is prudent since this is a Select structure.

Table 3:

Design Element	Minimum Design Criteria	Existing Condition	Alt. E Proposed Condition	sed Exception	
Design Speed	45 mph	45 mph	45 mph	No	
Lane Width	12 ft 12 ft 12 ft		No		
Usable Shoulder Width	8 ft	8 ft	8 ft	No	
Paved Shoulder Width			4 ft Approach 8 ft Bridge	No	
Bridge Clear Roadway Width	40 ft	28 ft	40 ft	No	
Structural Capacity	HL-93	HS-20	HL-93	No	
Horizontal Curve, Minimum Radius	960 ft	6139.17 ft	6139.17 ft	No	
Superelevation Transition Lengths	**	**	**	No	
Stopping Sight Distance Horizontal Curves	360 ft	> 360 ft	> 360 ft	No	
Stopping Sight Distance Vertical Curves	360 ft	> 360 ft	> 360 ft	No	
Maximum Grade	5%	0%	0%	No	
Travel Lane Cross Slope	2.0%	2.0%	2.0%	No	
Superelevation Rate	2.0%	2.0%	2.0%	No	
Vertical Clearance	N/A	N/A	N/A	N/A	
Bridge Railing Test Level	TL-5	Unknown	TL-5	No	

^{**}Superelevation transition lengths not evaluated for this option and will be evaluated at the next design stage.

F. Replacement – Demolition of Historic Bridge and New Bridge Construction

This option would not be prudent since this bridge is classified as a "Select" structure; therefore, this alternative was not considered.

V. MINIMIZATION AND MITIGATION

A. Minimization

Only the severely deteriorated and substandard portions of the bridge will be replaced. The members and connections that are replaced will be replaced in kind. All in kind replacements refer to replacing a bridge element with the same material and same size or dimensions. Any existing rivets required to be removed would be replaced with round headed bolts. The remaining portions of the bridge would be cleaned and painted to help preserve the bridge. The entire bridge will be rehabilitated to help preserve the bridge.

Per Attachment B (Standard Treatment Approach for Historic Bridges) of the Historic Bridges PA, Monroe County will provide rehabilitation plans to the Indiana SHPO when the design is approximately 30% complete, 60% complete, and when final design plans are complete. Portions of the original and previous rehabilitation plans are provided in Appendix G. The plan view of alternatives B, D, and E are shown in Appendix I.

B. Bridge Marketing

The existing bridge would be advertised to the public for use in a new location for vehicular or non-vehicular use. It is anticipated that public notices would be posted in the local newspapers and on INDOT's website and signage placed at the bridge. Monroe County will maintain a list of serious inquires.

C. Mitigation

Monroe County will coordinate with the SHPO to determine if photo-documentation of the existing bridge is necessary per the Historic Bridge PA. Any requirements for documentation will be included in the INDOT Project commitments database.

VI. PRELIMINARY PREFERRED ALTERNATIVE

The preliminary preferred alternative for this project is Alternate E, relocate the existing bridge and reconstruct a new bridge. The estimated construction costs for all alternatives evaluated are provided in Appendix D and the summary is shown below in Table 4. The maintenance costs Summarized below are costs associated with the maintenance of the existing truss bridge after rehabilitation for a 20 year time period. The maintenance costs include costs for fracture critical inspections, special inspections, and regular cleaning of the truss and bearings. Alternate E is both feasible and prudent and is the preliminary preferred alternative.

Table 4:

ALTERNATE COST SUMMARY							
Alternative	Meets Project Purpose and Need?	Right of Way Amount & Cost	Construction Cost (2029)	Maintenance Cost (2029)	Total Cost (2029)	Other Factors	Feasible & Prudent
A. No Build	No	N/A	\$0	\$0	\$0	Continued deterioration leads to closure	Feasible Not Prudent
B1. Rehabilitation for Continued Vehicular Use (mtg. S.O.I. stds.)	No	\$52,000	\$3,065,000	\$66,000	\$3,183,000	Does not meet all level 1 criteria and roadway serviceability	Feasible Not Prudent
B.2 Rehabilitation for Continued Vehicular Use (not mtg. S.O.I. stds.)	No	N/A	N/A	N/A	N/A	Does not meet all level 1 criteria and roadway serviceability	Feasible Not Prudent
C.1 Rehabilitation for Continued Vehicular Use One-Way Pair (mtg. S.O.I. stds.)	No	N/A	N/A	N/A	N/A	Does not meet all level 1 criteria and roadway serviceability	Feasible Not Prudent
C.2 Rehabilitation for Continued Vehicular Use One-Way Pair (not mtg. S.O.I. stds.)	No	N/A	N/A	N/A	N/A	Does not meet all level 1 criteria and roadway serviceability	Feasible Not Prudent
D. Bypass & Rehabilitation for Non-Vehicular Use	Yes	\$100,000	\$7,311,000*	\$15,000	\$7,426,000	Allows truss to be rehabbed & remain in place.	Feasible Not Prudent
E. Relocate & Replace	Yes	\$52,000	\$5,583,000**	\$15,000	\$5,650,000	Allows truss to be rehabbed & moved to new location.	Feasible and Prudent


Note: Alternative F may Not be considered prudent since this bridge is a select bridge. The cost break down for each alternative and additional cost information are provided in Appendix D.

^{*}Bypass bridge cost is \$5,746,000 and rehabilitated bridge cost is \$1,565,000.

^{**}New bridge cost is \$3,810,000 and relocated & rehabilitated bridge cost is \$1,773,000.

APPENDIX A Maps

Project Location





APPENDIX B Photographs



PHOTO 1: APPROACH LOOKING NORTH








PHOTO 3: APPROACH LOOKING WEST



PHOTO 4: TYPICAL FLOOR SYSTEM








PHOTO 6: EAST TRUSS LOOKING FROM DECK



PHOTO 7: LOOKING AT NORTH APPROACH FROM BRIDGE








PHOTO 9: LOOKING AT NORTH APPROACH FROM END OF BRIDGE



PHOTO 10: LOOKING AT SOUTH APPROACH FROM END OF BRIDGE








PHOTO 12: NORTHWEST QUADRANT



PHOTO 13: NORTHEAST QUADRANT








PHOTO 15: NORTH ABUTMENT



PHOTO 16: SOUTH ABUTMENT








PHOTO 18: LOOKING UPSTREAM FROM BRIDGE



PHOTO 19: SOUTH ABUTMENT



PHOTO 20: NORTH BRIDGE JOINT



PHOTO 21: SOUTH BRIDGE JOINT



PHOTO 22: OVERLAY SPALL NORTH END








PHOTO 24: SOUTH BRIDGE JOINT



PHOTO 25: TACK WELD SOUTHWEST L3








PHOTO 27: L4U3 NORTHWEST PAINT PEELING



PHOTO 28: L2U3 NORTHWEST PAINT PEELING








PHOTO 30: MODERATE SECTION LOSS IN WEB AT NELO



PHOTO 31: NORTHWEST ABUTMENT 2 SPALL IN MUDWALL

PHOTO 32: SPALL WITH EXPOSED REINFORCEMENT IN DECK





PHOTO 33: EXPANSION RUST AND SECTION LOSS AT NELO



PHOTO 34: SEL1 INTERIOR ANGLE SECTION LOSS







PHOTO 36: SEL2L1 INTERIOR GUSSET PLATE SECTION LOSS AT DIAGONAL END



PHOTO 37: SEL2L1 EXTERIOR GUSSET PLATE SECTION LOSS AT DIAGONAL END








PHOTO 39: TYPICAL LOW CHORD SPLICE



PHOTO 40: NEL1 60% SECTION LOSS ON INTERNAL FLANGE OF VERTICAL








PHOTO 42: TYPICAL FLOOR BEAM DETERIORATION AT TOP FLANGE



PHOTO 43: TYPICAL FLOOR BEAM DETERIORATION AT BOTTOM FLANGE







PHOTO 45: 45MPH SPEED LIMIT

APPENDIX C Design Criteria and Supporting Information

Section 1. Listing of Historic Bridges

Monroe Bridge No. 00182

NBI No.5300091 Eligible

Feature Carried: OLD SR 46

Feature Crossed: BR OF JACKS DEFEAT CREEK

101A Reinforced concrete slab

Latitude (degrees/minutes) 39

Longitude (degrees/minutes) 086 / 36.2

This bridge does not appear to possess significance under the National Register evaluation system for Criterion A. No evidence was found during data collection activities to indicate that this bridge possesses a significant association with important historical events or trends. As such, it is recommended not eligible under Criterion A.

This bridge is eligible under Criterion C because it represents a variation, evolution, or transition that is conveyed through important features or innovations related to bridge construction, design, or engineering, and it retains historic integrity necessary to convey its engineering significance.

Rationale: This bridge uses a distinctive construction method to address the engineering challenge of its substantial skew.



Bridge No. 00913

NBI No.5300130 Eligible

Feature Carried: BUSINESS 37N
Latitude (degrees/minutes) 39 / 13.9

Feature Crossed: BEANBLOSSOM CREEK Longitude (degrees/minutes) 086 / 32.4

310A Steel pony truss

This bridge does not appear to possess significance under the National Register evaluation system for Criterion A. No evidence was found during data collection activities to indicate that this bridge possesses a significant association with important historical events or trends. As such, it is recommended not eligible under Criterion A.

This bridge is eligible under Criterion C as it represents an early or distinctive phase in bridge construction, design, or engineering and it retains the historic integrity necessary to convey its engineering significance.

Rationale: This bridge is distinctive because it exemplifies an uncommon highway bridge type in Indiana.

This bridge is eligible under Criterion C because it represents a variation, evolution, or transition that is conveyed through important features or innovations related to bridge construction, design, or engineering, and it retains historic integrity necessary to convey its engineering significance.

Rationale: This bridge displays exceptional overall or main span length for its type representing an innovative design and/or construction method.

Monroe

Bridge No. 00919

NBI No.5300135 Eligible


Feature Carried: HARRODSBURG ROAD Latitude (degrees/minutes) 39 / 00.9 Feature Crossed: BRANCH OF CLEAR CREEK Longitude (degrees/minutes) 086 / 32.6


101A Reinforced concrete slab

This bridge is eligible under Criterion A as it has a direct and important association with a significant transportation route or is located at an important crossing. Further, it retains the historic integrity necessary to convey its historical significance.

Rationale: Crossing on Dixie Highway demonstrates development of the cross country transportation system.

This bridge does not appear to possess significance under the National Register evaluation system for Criterion C. No evidence was found during data collection activities to indicate that this bridge is an important example of bridge design, engineering, or construction. As such, it is recommended not eligible under Criterion C.





412-5.01(01) Select Bridge

A Select bridge has been identified as a historic bridge that is an excellent example of its structure type to be a suitable candidate for preservation. The intent of the PA is to preserve Select bridges in place for continued vehicular use. If rehabilitation alternatives are not in accordance with Section 412-5.02, and the owner is not granted a design exception or does not request one, the Select bridge must be bypassed or relocated for another use. See the PA for further guidance on bypassing or relocating the bridge.

412-5.01(02) Non-Select Bridge [Rev. Sep. 2021]

A Non-Select bridge has been identified as a historic bridge that is not an excellent example of its structure type or is not a suitable candidate for preservation. If the rehabilitation alternatives are not in accordance with Section 412-5.02, and the owner is not granted a design exception or does not request one, the Non-Select bridge must be marketed for re-use. In accordance with the *Programmatic Agreement Among the Federal Highway Administration, the Indiana Department of Transportation, the Indiana State Historic Preservation Officer, and the Advisory Council on Historic Preservation Regarding the Management and Preservation of Indiana's Historic Bridges (Historic Bridges PA)*, if no party steps forward to assume ownership of the bridge before the end of the public hearing comment period, the bridge may be demolished. See the *Historic Bridges PA* for further guidance on marketing or demolishing the bridge.

412-5.02 Historic Bridge Alternatives Analysis [Rev. Feb. 2018, Sep. 2021]

Where a project involves a historic bridge, the bridge owner must complete a Historic Bridge Alternatives Analysis. The Historic Bridge Alternative Analysis will serve as the Bridge Rehabilitation Report or Bridge Preventive Maintenance Meeting Minutes in the Stage 1 submittal. The required contents of the analysis, including explanations and tips for discussion of alternatives, is available from the Department's Historic Bridge Inventory Summary & Results webpage, under Historic Bridge Project Development Process Documents. The HBAA requires concurrence from Cultural Resources Office staff in the Division of Environmental Service and the Bridges Division Office of Bridge Design prior to proceeding to the Stage 2 (Preliminary Plans) submittal.

The evaluation of alternatives must address the following alternatives for both Select and Non-Select Bridges. The list is a hierarchy, meaning that the analysis must prove an alternative is either not feasible or prudent prior to proceeding to the next alternative. Note that Select bridges must be preserved as part of the project.

- 1. No Build/Do Nothing
- 2. Rehabilitation for continued vehicular use (two-lane or one-lane option), meeting the Secretary of Interiors Standards for Rehabilitation.
- 3. Rehabilitation for continued vehicular use (two-lane or one-lane option), not meeting the Secretary of Interiors Standards for Rehabilitation
- 4. Rehabilitation for continued vehicular use (one-way pair option), meeting the Secretary of Interiors Standards for Rehabilitation.
- 5. Rehabilitation for continued vehicular use (one-way pair option), not meeting the Secretary of Interiors Standards for Rehabilitation.
- 6. Bypass (non-vehicular use)/Build New Structure
- 7. Relocation of Historic Bridge and New Bridge Construction
- 8. Replacement Demolition of Historic Bridge and New Bridge Construction

In accordance with the *Programmatic Agreement Among the Federal Highway Administration, the Indiana Department of Transportation, the Indiana State Historic Preservation Officer, and the Advisory Council on Historic Preservation Regarding the Management and Preservation of Indiana's Historic Bridges (Historic Bridges PA)*, when any of the rehabilitation options are selected as the preferred alternative, the bridge owner is required to provide rehabilitation plans to the Indiana State Historic Preservation Officer (SHPO) when the design is approximately 30% complete (Stage 2 formerly Preliminary Plans), approximately 60% complete (Hearing Plans), and when plans are 100% complete (Stage 3 formerly Final Plans). If the project involves a bypass of the historic bridge, then the plan reviews will include a site plan and design of the new bridge and the historic bridge.

The Historic Bridge Alternatives Analysis document should clearly indicate that three plan reviews will be forthcoming.

Additionally, each of these submittals are reviewed by Cultural Resources Office staff in the Division of Environmental Service before the plans are submitted to the SHPO staff and consulting parties.

The SHPO staff is allotted a 30-day comment period on each plan review. Additionally, each of these submittals are reviewed by Cultural Resources Office staff in the Division of Environmental Service before the plans are submitted to the SHPO staff and consulting parties. See the INDOT Cultural Resources Manual, Part IV, Chapter 2 for more information.

All three plan review submittals are required for all projects for which the preferred alternative is rehabilitation of the historic bridge. Any outstanding plan submittals must be listed as commitments in the environmental document and the Project Commitments Database. These submittals should be completed prior to the submittal of the Environmental Consultation Form (ECF). The ECF cannot be approved until all three plan submittals have been completed.

412-5.03 Design Criteria [Rev. Feb. 2018]

The following design criteria should be used to evaluate if a historic bridge can be rehabilitated for continued vehicular use. The criteria should not be viewed as an absolute, that is, a design exception may be appropriate and should be considered where appropriate.

A historic bridge on low-volume road should be evaluated using the design criteria described herein. A low-volume road is defined as having a design-year ADT of less than or equal to 400 vpd. A historic bridge on roadway with a design-year ADT greater than 400 vpd should be evaluated using the 3R design criteria for the applicable functional classification. See Chapter 55 for 3R criteria. The criteria for Existing Structure to Remain in Place should be used for bridge clear roadway width and structural capacity. These criteria should be used to determine if a historic bridge can be rehabilitated for continued vehicular use.

Design Speed

The existing posted speed should be used as the design speed. If the road is not posted, an engineering speed study should be performed and the road should be posted between logical termini.

Approach Roadways Horizontal and Vertical Alignment

These should be analyzed within 300 ft of either side of the bridge in accordance with AASHTO's *Guidelines for Geometric Design of Very Low-Volume Local Roads (ADT* < 400) or the 3R design criteria, as applicable.

Structural Capacity

The structural capacity should be in accordance with Figure 412-2A, Historic Bridge Structural Capacity. The required capacity designations are those described in AASHTO *Standard Specifications for Highway Bridges*.

Bridge Width

The minimum bridge width should be in accordance with Figure 412-2B, Historic Bridge Minimum Clear Roadway Width.

Bridge Railing

Bridge railing may be left in place if there is no documented crash history or other evidence of crash history within the past 5 years such as damaged railing or concerns by local police agencies. If only slightly damaged, railing should be replaced in kind. If there is evidence of crash history within the past 5 years, the possible causes should be corrected, or new bridge railing provided as described in Section 404-4.0.

Approach Guardrail

Approach guardrail, if in place, should remain. If not in place, it may be omitted if there is no documented crash history or other evidence of crash history within the last 5 years, such as vehicles hitting the ends of the bridge railing or vehicles leaving the roadway. Crash history, such as that regarding damaged ends of bridge railings, may be an indicator of the need for approach guardrail.

In addition to those guardrails which the Department has standardized, there are others which have passed NCHRP 350 or MASH crash tests for specified test levels. If one of these devices is desired to be used for a specific project, the documentation to be provided is as follows:

- 1. an FHWA eligibility letter; and
- 2. complete details for the device as successfully crash tested.

Hydraulic Capacity

Improvements may consist of removal of sand bars or debris, channel clearing, or adding a supplemental structure. If a bridge is to remain in place and its approaches are realigned, the removal of existing roadway fill is an option toward improving the hydraulic capacity.

		ur Length : 5 mi		≤ Detour h < 10 mi	Detour Length ≥ 10 mi		Detour of Any Length
Design Year ADT	< 100	100 ≤ ADT ≤ 400	< 100	100 ≤ ADT ≤ 400	< 100	100 ≤ ADT ≤ 400	ADT > 400
AASHTO Live Loading	H-15	HS-15	HS-15	HS-15	HS-15	HS-20	3R Criteria for Structural
Required Capacity	15 tons	27 tons	27 tons	27 tons 27 tons 36		36 tons	Capacity, Existing Bridge to Remain in Place

Notes:

- 1. Detour length is defined as the total additional travel a through-bound vehicle would experience from closing the bridge. This is determined by the shortest route on which a vehicle with a loading of HS-20 (36 tons) is legally capable of traveling.
- 2. Vehicles that may use a bridge with AASHTO loading of H-15 (15 tons) or HS-15 (27 tons) include typical farm vehicle (15 tons), school bus carrying up to 84 passengers (15 tons), loaded garbage truck (27 tons), and single-unit fire engine (27 tons).
- 3. Vehicles that may use a bridge with AASHTO live loading of HS-20 (36 tons) include all of the H-15 and HS-15 vehicles, plus payloaded ready-mix-concrete truck (30 tons), and tractor-apparatus fire engine (36 tons).
- 4. A bridge on a dead-end road will be considered as having a detour length greater than 10 miles.
- 5. The annual traffic growth factor used in determining Design Year ADT must be justified.

HISTORIC BRIDGE STRUCTURAL CAPACITY

Figure 412-2A

		Minimum Clear Roa	adway Width ^{2,3}				
Lancs on Pridge	Design Year ADT	100 ≤ Design Year	Design Year				
Lanes on Bridge	< 100	ADT ≤ 400	ADT > 400				
One ¹	15 ft	16 ft	Not Applicable				
			3R Criteria for Clear Roadway				
Two	18 ft	20 ft	Width, Existing Bridge to Remain				
			in Place.				

Notes:

- ¹ The given values are applicable for rehabilitation of a Select bridge in a one-way pair or two-way configuration. The given values are applicable for rehabilitation of a Non-Select bridge in a one-way pair configuration. The owner must obtain a design exception for rehabilitation of a Non-Select bridge in a two-way configuration, or where the ADT is greater than 400 vpd.
- ² The minimum bridge width is defined as the most restrictive minimum distance between curbs, railings, or other obstructions on the bridge roadway.
- ³ The annual traffic growth factor used in determining Design Year ADT must be justified.

HISTORIC BRIDGE MINIMUM CLEAR ROADWAY WIDTH

Figure 412-2B

412-5.04 Economic and Other Criteria [Rev. Feb. 2018]

412-5.04(01) Select Bridge [Rev. Feb. 2018]

The appropriateness of rehabilitating a Select historic bridge should be determined based on the cultural significance of the bridge. The appropriateness of rehabilitating a Select bridge on a low volume road, as defined above, should further be assessed based on the cost effectiveness as follows:

- 1. if the initial rehabilitation cost is less than 80% of the replacement cost, rehabilitation is warranted; or
- 2. if the initial rehabilitation cost is equal to or greater than 80% of the replacement cost, the owner may request further consultation with FHWA to determine rehabilitation eligibility.

The above thresholds should not be viewed as absolute, i.e., if the initial rehabilitation cost is above 80% of the replacement cost, rehabilitation may still be considered a viable alternative. A rehabilitation project should result in a 20-year design life for the rehabilitated bridge.

A Select bridge may be rehabilitated and left in place, and a new bridge and new approaches may be built adjacent to it. This effectively creates one bridge and approaches for each direction of travel. For this situation, the new bridge must meet all design standards for a new bridge or obtain a design exception. Where appropriate, the new one-way bridge must be able to accommodate future widening to provide for two-way travel.

412-5.04(02) Non-Select Bridge [Rev. Feb. 2018]

The appropriateness of rehabilitating a Non-Select historic bridge should be determined based on the cultural significance of the bridge. A Non-Select bridge on a low-volume road, as defined above, should further be assessed based on the cost-effectiveness of the project and other criteria as follows.

If the initial rehabilitation cost is greater than or equal to 40% of the replacement cost, or the bridge meets two or more of the following criteria that cannot be economically corrected as part of a rehabilitation project, then replacement is warranted.

- 1. The bridge waterway opening is inadequate (i.e., National Bridge Inventory Item 71 is rated 2 or 3).
- 2. The bridge has a documented history of catching debris due to inadequate freeboard or due to piers in the stream.

- 3. The bridge requires special inspection procedures (i.e., the first character of National Bridge Inventory Item 92A or 92C is Y).
- 4. The bridge is classified as scour-critical (i.e., National Bridge Inventory Item 113 is rated 0, 1, 2, or 3.
- 5. The bridge has fatigue-prone welded components that are expected to reach the end of their service lives within the next 20 years. See Section 412-4.03(04) for information on conducting a fatigue analysis.
- 6. The bridge has a Sufficiency Rating of lower than 35.

The above cost thresholds should not be viewed as absolute. If the initial rehabilitation cost is above 40% of the replacement cost, rehabilitation may still be considered a viable alternative. A rehabilitation project should result in a 20-year design life for the rehabilitated bridge.

LEVEL ONE CONTROLLING CRITERIA CHECKLIST

Date: 11/20/2023 Route: Business 37 N over Beanblossom Creek

Submittal: Prelim. HBAA Report Design Year: 2049 AADT: 13,752

Des. No.: Not Applicable Functional Classification: Minor Arterial; Rural

Is route on the National Truck Network? ☐ Yes ☒ No Terrain: Level

Project Scope of Work: 3R Non Freeway Rehabilitation- Bridge Deck Replacement and Truss Rehabilitation	Design Criteria	Existing	Does the proposed design satisfy the criteria? (Enter the value provided in the appropriate column.)				
Enter the minimum criteria below.	Reference	Condition	Yes	No (1) (2)	N/A		
1. Design Speed: 45 mph	Fig 55-3A	45	45				
2. Lane Width, Mainline: 12 ft Auxiliary Lanes: N/A ft	Fig 55-3A	12 ft	12 ft				
3. Usable Shoulder Width (uncurbed sections) adjacent to: Mainline: 8 ft Auxiliary Lanes: N/A ft	Fig 55-3A	8 ft	8 ft				
Paved Shoulder Width (uncurbed sections) adjacent to: Mainline: 4 ft Auxiliary Lanes: N/A ft	Fig 55-3A	4 ft Approach 2 ft Bridge	4 ft Approach	2.5 ft (1) Bridge			
4. Bridge Clear Roadway Width 30 ft (3)	Fig 55-3A	28 ft		29 ft (3)			
5. Design Loading Structural Capacity HS 20	Fig 55-3A	HS 20	HS 20				
6. Horizontal Curve, Minimum Radius = 960 ft	Fig 43-2A	6139.17 ft	6139.17 ft				
7. Superelevation Transition Length 95 ft ⁽³⁾ Distribution 75/25 % (on tangent/on curve)	IDM 43- 3.03	Unknown	Unknown				
8a. Stopping Sight Distance, Horizontal Curve 360 ft	IDM 43- 4.02	>360 ft	>360 ft		N/A		
8b. Stopping Sight Distance, Vertical Curve (Crest Only) 360 ft	Fig 55-3A	>360 ft	>360 ft				
9. Maximum Grades 5 %	Fig 55-3A	0.5 %	0.5%				
10. Travel Lane Cross Slope: 2 %	Fig 55-3A	2 %	2 %				
11. Superelevation Rate $e_{max} = 2 \%$	IDM Fig. 43-3A (3)	2 %	2%				
12. Minimum Vertical Clearance N/A ft	Fig 55-3A	N/A			N/A		
13. Americans with Disabilities Act (ADA)	Fig 55-3A	N/A			N/A		
14. Bridge Railing Test Level (3) (circle one of the following) TL-2 TL-3 TL-5	IDM 404- 4.02	< TL-5	TL-5				

⁽¹⁾ For high speed facilities **and Freeways**, items 1-3, 5-6 & 8-12 require a Level One design exception when minimum criteria are not satisfied.

Are there plan revisions from the previous submittal that affect Level One criteria? \square Yes \square No Date

Submitted By Ahmed Elshoura Date 11/20/2023 INDOT location or Consultant: BLN

Checked By Alfred Wessling Date 11/20/2023

INDOT reviewer Click or tap here to enter text. Date Click or tap to enter a date.

⁽²⁾ For low speed facilities, items 1, 2(NTN only), 5 & 12 require a Level One design exception when minimum criteria are not satisfied.

⁽³⁾ A Level Two design exception is required for items not referenced in note 1 or 2 when minimum criteria are not satisfied. Include a brief explanation with the design computations.

According to level 1 Design Criteria Suppl. Cinfo. Shldn. width on

	Design Ele	ement		Manual Section		2-L	ane.	V	Multi	-Lane		
	Design-Year AADT			40-2.01	< 400	400 ≤ AADT < 3000	3000 ≤ AADT < 5000	≥ 5000	Undivided	Divided		
2 8	Design Forecast Period		3	55-4.01		20 Ye	ars (1)		20 Y€	ears (1)		
Controls	*Design Speed, mph (2)			55-4.01		Posted S	peed Limit		Posted S	peed Limit		
0	Access Control			40-5.0		Partial Co	ntrol / None			ntrol / None		
	Level of Service			40-2.0		Desirable: B	; Minimum: D			; Minimum: D		
		*Width		55-4.05	12 ft	12 ft	12 ft	12 ft		2 ft.		
	Travel Lane	Typic	al Surface Type (3)	Ch. 304		Asphalt /	Concrete			/ Concrete		
		*Width	Usable	55-4.05	D: 6 ft M: 2 ft	D: 8 ft M: 3 ft	D: 8 ft M: 6 ft	D: 11 ft M: B ft	Desirable: 11 ft Minimum: 8 ft	Rt: D: 11 ft; M: 9 ft Lt: D: 4 ft; M: 4 ft		
	Shoulder (4)	*Width	Paved	55-4.05	D: 4 ft M: 0 ft	D: 6 ft M: 2 ft	D: 6 ft M: 2 ft	D: 10 ft M: 2 ft <	Desirable: 10 ft Minimum: 8 ft	Rt: D: 10 ft; M: 8 ft Lt: D: 4 ft; M: 3 ft		
ints	Typical Surface Type (3)		Ch. 304	As	phalt / Concrete	/ Sealed Aggrega	ate		/ Sealed Aggregate			
Cross Slopes Cross Slopes Auxiliary Lane Median Width Obstruction Free Zone	*Trave	l Lane (5)	55-4.05			2%			2%			
	Cross Slopes	es Shoulder (6)					ved Width > 4 ft 4 Sealed Aggregate	% Asphalt /		ived Width > 4 ft 4% Aspha Sealed Aggregate		
		Lane	Width	55.405		Desirable: 12 ft	; Minimum: 11 ft		Desirable: 12 ft	t; Minimum: 11 ft		
	Auxiliary Lane	Shou	der Width	55-4.05	Des: Same as Next to Travel Lane; Min: 2 ft				Des: Same as Next to Travel Lane; Min: 2 ft			
				55-4.05	N/A			0.0 ft.				
5	Obstruction-Free-Zone	Width		55-5.02	See Section 55-5.02			See Section 55-5.02				
		Foreslope Cut Ditch Width			2:1 or Flatter (7)			2:1 or Fiatter (7)				
				55-4.05	(7)			(7)				
	Side Slopes	opes Backslope			2:1 or Flatter (7)			2:1 or Flatter (7)				
)	Fill				2:1 or F	latter (7)		2:1 or Flatter (7)			
	Median Slopes			55-4.05		N	I/A		Desirable: 8:1; Maximum: 4:1			
	New or Reconstructed	*Struc	tural Capacity	Ch. 403				HL-93				
	Bridge	*Clean	-Roadway Width (9)	55-6.03			F	uli Paved App				
	Existing Bridge	*Struc	tural Capacity	Ch. 72				HS-				
	to Remain in Place	*Clear	-Roadway Width	55-6.02			Trav	elway Plus 2	ft on Each Side			
Bridges	*Vertical		r Replaced assing Bridge			/		16.5	n)			
ā	Clearance, Arterial Under		assing Bridge (11)	55-6.0		/		14.0	ft			
	(10)		russ / atrian Bridges	402-6.01	1	/	Ne		xisting: 17.0 ft			
	Vertical Clearance, Arte	orial Ov	Vertical Clearance, Arterial Over Railroad (12)		/			23.0	ft /			

Fig. 412-2A use

GEOMETRIC DESIGN CRITERIA FOR RURAL ARTERIAL, 3R PROJECT 3 R Criteria for Figure 55-3A (Page 1 of 4) exist. Br. to REMAIN

According to Fig. 412-28 place

3R Criteria for Exist. Br. to Remain

in place is required for Historic Bridge

Br. clr. Rdwg. Width = Max Stravelway Plus 2 ft each side = 2(12)+2(2)

OR = 28 ft

30 ft for Arterials or collectors

Level One controlling criterion, see page 2 of 4.

	Design El	ement	Manual Section							
	Design Speed			50 mph	55 mph	60 mph				
	*Stopping Sight Distance	, Desirable	55-4.02	425 ft	495 ft	570 ft				
	Decision Sight	Speed / Path / Direction Change	42-2.0	750 ft	865 ft	990 ft				
क	Distance	Stop Maneuver		465 ft	535 ft	610 ft				
ent	Passing Sight Distance		42-3,0	Existing	Existing	Existing				
Elements	Intersection Sight Distant	ce, -3% to +3% (14)	55-4.06	P: 630 ft; SUT: 780 ft	P: 730 ft; SUT: 890 ft	P: 840 ft; SU: 1020 ft				
回	*Minimum Radius		55-4.03	See Section 55-4.03						
Alignment	*Superelevation Rate		55-4.03	See Section 55-4.03						
Ē	*Horizontal Sight Distance	e	55-4.03	See Section 55-4.03						
₹	*Vertical Curvature,	Crest	404	See Section 55-4.04						
	K-value	Sag	55-4.04		See Section 55-4.04					
	*Maximum	Level	FF 4.04	5%	4.5%	4%				
	Grade (13)	Rolling	55-4.04	6%	5.5%	5%				
	Minimum Grade		44-1.03		Desirable: 0.5%; Minimum 0.0%					

^{*} Level One controlling criterion. Except as noted in this chapter, the values shown in AASHTO's A Policy on Geometric Design of Highways and Streets (the Green Book) may be used as minimum values if they are lower than similar values shown herein. A controlling criterion that does not meet the minimum value is a design exception and is subject to approval. A streamlined design exception may be used for 3R projects. See Section 40-8.0.

GEOMETRIC DESIGN CRITERIA FOR RURAL ARTERIAL, 3R PROJECT Figure 55-3A (Page 2 of 4)

- (1) Design Forecast Period. For a partial 3R project, the pavement should be designed for at least a 10 year design life.
- (2) <u>Design Speed</u>. The minimum design speed should equal the anticipated posted speed limit after construction or the legal speed limit, 60 mph, on a non-posted multilane divided highway, or 55 mph on a non-posted two-lane highway.
- (3) <u>Surface Type.</u> The pavement-type selection will be determined by the Pavement Engineering Division or by the local jurisdiction.
- (4) Shoulder. The following will apply:
 - a. On an INDOT facility, the shoulder should be paved to the front face of guardrail. The desirable guardrail offset is 2 ft from the usable shoulder width. In a restrictive situation, the guardrail offset may be 0 ft from the usable shoulder width. See Section 49-4.0 for more information.
 - b. If guardrail is present, the minimum offset from E.T.L. to the front face of guardrail should desirably be equal to the shy-line distance, but should not be less than 4 ft. See Section 49-4.0 for shy-line offsets.
 - c. Usable shoulder width is defined as the distance from the edge of the travel lane to the shoulder break point.
- (5) Cross Slope, Travel Lane. Cross slopes of 1.5% are acceptable on an existing bridge to remain in place.
- (6) <u>Cross Slope, Shoulder.</u> Value is for a tangent section. See Figure 45-1A(1) or Figure 45-1A(2) for more-specific information. See Figure 43-3M or Figure 43-3N for shoulder cross slope on a horizontal curve.
- (7) Side Slopes. Section 55-4.05 provides additional information for side-slope criteria.
- (8) Structural Capacity, New or Reconstructed Bridge. The following will apply:
 - Each State-highway bridge within 15 mi of a Toll-Road gate must be designed for Toll-Road loading.
 - b. Each bridge on an Extra-Heavy-Duty Highway must be designed for the Michigan Train truck loading configuration.

GEOMETRIC DESIGN CRITERIA FOR RURAL ARTERIAL, 3R PROJECT Figure 55-3A (Page 3 of 4)

AVW 11/2023 A N/29/23

- (9) Width, New or Reconstructed Bridge. See Section 402-6.02(01) for more information. On a State highway, the minimum clear-roadway width should be 30 ft. Otherwise, the bridge clear-roadway width is the algebraic sum of the following:
 - a. the approach traveled-way width;
 - b. the approach usable shoulder width without guardrail; and
 - c. a bridge-railing offset (see Figure 402-6H).
- (10) <u>Vertical Clearance, Arterial Under.</u> Value includes an additional 6 in. allowance for a future pavement overlay. Vertical clearance applies from usable edge to usable edge of shoulders.
- (11) Vertical Clearance, Existing Bridge. See Section 55-6.02 for additional information on minimum allowable vertical clearance.
- (12) <u>Vertical Clearance, Arterial Over Railroad</u>. See Section 402-6.01(03) for additional information on railroad clearance under a highway.
- (13) Maximum Grade. A downgrade that is 1% steeper may be used for a one-way roadway.
- (14) <u>Intersection Sight Distance</u>. For left turn onto a 2-lane road. P = Passenger car; SUT = single unit truck. See Figure 46-10G for value for a combination truck.

GEOMETRIC DESIGN CRITERIA FOR RURAL ARTERIAL, 3R PROJECT Figure 55-3A (Page 4 of 4)

Level One Controlling Criteria Checklist Instructions

The Level One Design Criteria checklist should be completed regardless of the high-speed/low-speed or Level One/Level Two designation and included with each submittal. A separate checklist should be completed for the mainline and each Sline, ramp, and phase of maintenance of traffic. **All 10 high-speed controlling criteria apply to freeways and interstates, including exit and entrance ramps, regardless of design speed.** See Design Memo 20-13

See Indiana Design Manual Section 40-8.0 for information on design exception documentation.

<u>Submittal.</u> Typically the submittal is either Stage 1, Stage 2, Stage 3, or Final Tracings. Preliminary or Final Plans should be used for Bridge Rehabilitation, Partial 3R, and Traffic projects as appropriate. See IDM 14-2.0.

Des. No. Enter the 7-digit designation number.

Route. Enter the road name. For bridge projects enter the road name and the feature crossed, e.g. US231 over White River.

<u>National Truck Network.</u> Indiana's NTN is comprised of all federal aid primary routes as of 1991. The NTN is available as a separate layer on INDOT's <u>Road Inventory and Functional Class Viewer</u> (to best view the NTN, other layers should be turned off).

<u>Functional Classification.</u> IDM 40-1.01 describes the various functional classifications – arterial, collector, local road. Enter the functional classification as shown in IDM Figure 14-3C. Include the rural or urban designation. For urban designations, include the sub-designation of suburban, intermediate, or built up. Where the checklist is being used for a ramp, trail, or other unique feature, enter the description.

<u>Design Year and AADT.</u> Typically the design year is 10 to 20 years from the letting date. Enter the year and the corresponding AADT. See IDM 40-2.02

Terrain. Enter either rolling or level as appropriate. Indiana does not have mountainous terrain.

<u>Project Work Type.</u> IDM 40-6.0 describes the project scope of work categories. The scope of work determines which criteria apply to the geometric design of the project. See IDM Figure 14-3C, Project Design Criteria for acceptable entries.

<u>Design Criteria Reference.</u> Enter the *Indiana Design Manual* figure or AASHTO reference used to establish the minimum design criteria. When using an AASHTO reference, include both the title of the reference and the section, e.g. GB Table 5-3. Use the following abbreviations

IDM – Indiana Design Manual

GB – AASHTO's A Policy on Geometric Design of Highways and Streets (the Green Book)

LV – AASHTO's Geometric Guidelines for Design of Very Low Volume Roads $ADT \le 400$

IS – AASHTO's A Policy on Design Standards, Interstate System

<u>Existing Condition.</u> Enter the value of the existing condition. This field is mandatory for 3R projects or where an existing substandard condition is being retained.

<u>Proposed Design.</u> Enter the value provided (not an X) in the appropriate column. Where more than one value is needed, e.g. multiple horizontal curves, "see calculations" is acceptable.


Design Criteria Supplemental Information

<u>Calculations</u>. The documentation for each item should be included in the design computations with the checklist. Calculations must be initialed and dated. Where an existing condition on a 3R project is retained or replaced in kind, the evaluation of crash history and no expansion planned must be included.


Shoulder Width on a Bridge. The minimum shoulder width on a bridge is the minimum paved shoulder width from the geometric tables or the existing approach roadway paved shoulder width **without guardrail**, whichever is greater. The guardrail offset on the approach roadway should be carried over the bridge. The approximate 4-in loss due to connection of the concrete bridge railing transition/guardrail transition may reduce the offset but may not reduce the minimum paved shoulder width. See Bridge Clear Roadway Width for additional information.

Examples

1. (Desirable) A 2-ft guardrail offset is provided on the approach roadway. The approximate 4-in. reduction at the transition connection will result in a 1'-8" offset on the bridge. The minimum paved shoulder width is not reduced, and a design exception is not required (for shoulder width). Check bridge clear roadway width against minimum required.



2. Zero guardrail offset is provided on the approach roadway. The approximate 4-in. reduction at the transition connection will result in a 4-in reduction to the paved shoulder width on the bridge, and a design exception is required (for shoulder width). Check bridge clear roadway width against minimum required.



Design Criteria Supplemental Information (con'd)

<u>Bridge Clear Roadway Width.</u> Bridge clear roadway width is a Level Two criteria. Where the sum of the lane and shoulder widths is less than 30 ft (arterials and collectors) or 28 ft (local roads), the greater width is the minimum criteria.

Aug. 2022 [Note: "Local roads" is referring to the roadway functional classification, not local ownership of a roadway. The bridge clear roadway width provided should be that which is appropriate based on the site conditions, speed, traffic, needs of the bridge as part of the transportation network, as well as the needs of the community. Where the appropriate width is less than the minimums listed above, a brief explanation should be documented with the design computations.]

<u>Superelevation Transition Length and Distribution.</u> Superelevation transition length and distribution are Level Two criteria. Both the transition length and distribution are important aspects of providing appropriate superelevation.

<u>ADA Criteria</u>. Exceptions to ADA criteria are approved through the ADA Technical Advisory Committee. Exceptions are either a technical inquiry or determination of technical infeasibility.

<u>Bridge Railing Test Level.</u> Bridge railing test level is a Level Two criteria. The project-specific test level needs and site constraints should be included with the design computations. See Design Memo 19-08. Non-standard railing and modifications must be coordinated with the Bridge Design Division prior to use.

404-4.01 Bridge Railing Criteria [Rev. Sep. 2019]

AUW 11/2023 E 11/29/23

MASH Implementation. Per the AASHTO-FHWA Joint Implementation Agreement, all new and replacement installations of bridge railing on the National Highway System (NHS), with contract letting date after December 31, 2019, must be evaluated using the AASHTO *Manual for Assessing Safety Hardware* 2016 (MASH) criteria.

FHWA Policy. All new or replacement bridge railing on the NHS must meet MASH crash-test criteria.

New and Replacement Bridge Railing, INDOT. All new and replacement bridge railing on an INDOT bridge should meet MASH crash test criteria, both on and off the NHS. Exceptions should be rare. Exceptions will be considered on a project-by-project basis at the discretion of the Bridge Design Division off the NHS and in cooperation with FHWA on the NHS.

New and Replacement Bridge Railing, LPA. All new and replacement bridge railing on a local agency bridge should meet MASH crash test criteria, both on and off the NHS. On a locally-owned bridge that is not on the NHS, MASH-compliant railing is encouraged, but not required. NCHRP 350-compliant railing may be used at the bridge owner's discretion. The decision to use an NCHRP 350-compliant railing and supporting documentation should be included in the project file.

<u>Existing Bridge Railing</u>. Upgrading existing bridge railing should be considered on bridge preventative maintenance projects where such work is cost-effective. See Chapter 412. In general, existing NCHRP 350-compliant bridge railing in good condition may remain in place.

404-4.02 Test Level Selection [Rev. Sep. 2019]

This section provides guidance on selecting bridge railing test level. The guidance in this section is intended for use on INDOT and LPA bridges. Exceptions are discussed in Section 404-4.02(06).

MASH uses the same six Test Levels established under the previous crash testing criteria, National Cooperative Highway Research Program Report 350 (NCHRP 350) Recommended Procedures for the Safety Performance Evaluation of Highway Features.

<u>FHWA Policy</u>. All new or replacement railing on the NHS must meet Test Level 3 (TL-3) crash-test criteria at a minimum.

AVW 11/20123

If	And	The minimum (MASH) test level is	Applicable INDOT Bridge Standards	Notes
Bridge carries interstate mainline or system interchange ramp traffic	Pueto clos proximity To Exit o	112-5	Type FT Type TF-2	Determine the minimum test level. Use the evaluation criteria to below to
The design speed is ≥ 50 mph	Entrance Ramps of Exit 123	T-69 TL-3	Type FC Type PF-1 Type PS-1	assess if a higher test level is appropriate.
The design speed is ≤ 45 mph	The route is on the NHS	TL-3	Type FC Type PF-1 Type PS-1	A higher test level railing may be used to satisfy lower test level requirements.
The design speed is ≤ 45 mph	The route is not on the NHS	TL-2	Type TX (LPA only)	

Consider the following evaluation criteria when selecting the bridge railing test level.

- Highway design speed. Use the greater of posted speed or the design speed to establish
 the minimum test level. A lower test level may be acceptable for low volume roadways.
- Average annual daily traffic and percent trucks. Higher traffic volumes have inherently higher likelihood of crashes. High truck volumes (truck DDHV is 250 vph) are a consideration for selecting a higher test level.
- Highway geometry (grades and horizontal curvature). Steep grades (sustained longitudinal grades greater than 5%) and sharp curves (horizontal curve radius less than 1,500 ft) are considerations for using a higher test level.
- Type of land use below deck. Roadways under are higher risk than waterways under due to the risk of multiple injuries.
- In-service performance. Unsatisfactory in service performance is a consideration for selecting a higher test level.

LEVEL ONE DESIGN CRITERIA CHECKLIST

Date: 11/20/2023 Route: Business 37 N over Beanblossom Creek

Submittal: Prelim. HBAA Report Design Year: 2049 AADT: 13,752

Des. No. Not Applicable Functional Classification: Minor Arterial; Rural

Is route on the National Truck Network? ☐ Yes ☒ No Terrain: Level

Project Scope of Work: 3R Non Freeway Bridge Replacement	Design Criteria	Existing	Does the proposed design satisfy the criteria? (Enter the value provided in the appropriate column.)			
Enter the minimum criteria below.	Reference	Condition	Yes	No (1)	N/A	
1. Design Speed: 45 mph	IDM Fig. 55-3A	45	45			
2. Lane Width, Mainline: 12 ft Auxiliary Lanes: N/A ft	IDM Fig. 55-3A	12 ft	12 ft			
3. Usable Shoulder Width (uncurbed sections) adjacent to: Mainline: 8 ft Auxiliary Lanes: N/A ft	IDM Fig. 55-3A	8 ft	8 ft			
Paved Shoulder Width (uncurbed sections) adjacent to: Mainline: 4 ft Auxiliary Lanes: N/A ft	IDM Fig. 55-3A	2 ft Bridge 4 ft Approach	8 ft Bridge 4 ft Approach			
4. Bridge Clear Roadway Width 40 ft (3)	IDM Fig. 55-3A	28 ft	40 ft			
5. Design Loading Structural Capacity HL-93	IDM Fig. 55-3A	HS-20	HL-93			
6. Horizontal Curve, Minimum Radius = 960 ft	IDM Fig. 43-2A	6,139.17'	6,139.17			
7. Superelevation Transition Length 90 ft ⁽³⁾ Distribution 75/25 % (on tangent/on curve)	IDM 43-3.03 IDM 43-3.03	Unknown Unknown	X X			
8a. Stopping Sight Distance, Horizontal Curve 360 ft	IDM Fig. 55-3A	>360 ft	>360 ft			
8b. Stopping Sight Distance, Vertical Curve (Crest Only) 360 ft	IDM Fig. 44-3A	>360 ft	>360 ft			
9. Maximum Grades 5 %	IDM Fig. 55-3A	0.3%	0.5%			
10. Travel Lane Cross Slope: 2 %	IDM Fig. 55-3A	2%	2%			
11. Superelevation Rate $e_{max} = 2 \%$	IDM Fig.43-3A(3)	2%	2%			
12. Minimum Vertical Clearance N/A ft		N/A			X	
13. Americans with Disabilities Act (ADA)		N/A			X	
14. Bridge Railing Test Level (3) (circle one of the following) TL-2 TL-3 TL-5 (b) For high speed facilities and Freeways, items 1-3, 5-6 &	IDM 404-4.02	< TL-5	TL-5			

⁽¹⁾ For high speed facilities **and Freeways**, items 1-3, 5-6 & 8-12 require a Level One design exception when minimum criteria are not satisfied.

Are there plan revisions from the previous submittal that affect Level One criteria? \square Yes \square No Date Click or tap to enter a date.

Submitted By Alfred Wessling Date 11/20/2023 INDOT location or Consultant: BLN

Checked By Ahmed Elshoura Date 11/20/2023

INDOT reviewer Click or tap here to enter text. Date Click or tap to enter a date.

⁽²⁾ For low speed facilities, items 1, 2(NTN only), 5 & 12 require a Level One design exception when minimum criteria are not satisfied.

⁽³⁾ A Level Two design exception is required for items not referenced in note 1 or 2 when minimum criteria are not satisfied. Include a brief explanation with the design computations.

Functional Classification	Allowable Backwater, Annual EP	Roadway Serviceability, Annual EP	Service- ability Freeboard *	Bridge, Allowable Velocity, Annual EP	Culvert, Allowable Velocity, Annual EP
Freeway	1%	1%	2 ft	1%	2%
Ramp	1%	1%	tt 0	1%	2%
Non-Freeway, 4 or More Lanes	1%	1%	2 ft	1%	2%
Two-Lane Facility, AADT > 3000	1%	1%	1 ft	1%	2%
Two-Lane Facility, 1000 < AADT ≤ 3000	1%	4%	IJ O	1%	4%
Two-Lane Facility, AADT ≤ 1000	1%	10%	IJ O	1%	10%
Drive	1%	10%	0 ft	1%	10%


Required serviceability freeboard is based on the difference between the edge-of-pavement and the structure-headwater elevations throughout the floodplain or watershed. Roadway serviceability should consider backwater effects from a larger downstream waterway.

DESIGN-STORM FREQUENCY FOR BRIDGE OR CULVERT

Figure 203-2C (Page 1 of 2)

National Flood Hazard Layer FIRMette





Legend

SEE FIS REPORT FOR DETAILED LEGEND AND INDEX MAP FOR FIRM PANEL LAYOUT

SPECIAL FLOOD HAZARD AREAS

With BFE or Depth Zone AE, AO, AH, VE, AR Without Base Flood Elevation (BFE)

0.2% Annual Chance Flood Hazard, Areas depth less than one foot or with drainage areas of less than one square mile Zone X of 1% annual chance flood with average Regulatory Floodway

Future Conditions 1% Annual Chance Flood Hazard Zone X

Area with Reduced Flood Risk due to Levee. See Notes. Zone X

Area with Flood Risk due to Levee Zone D

NO SCREEN Area of Minimal Flood Hazard Zone X **Effective LOMRs**

Area of Undetermined Flood Hazard Zone D

Channel, Culvert, or Storm Sewer GENERAL | ---- Channel, Culvert, or Storr STRUCTURES | 1111111 Levee, Dike, or Floodwall

(B) 20.2

Cross Sections with 1% Annual Chance Water Surface Elevation Coastal Transect

Base Flood Elevation Line (BFE) Limit of Study mm 513 mm

Jurisdiction Boundary

Coastal Transect Baseline

Hydrographic Feature

Digital Data Available

No Digital Data Available Unmapped


point selected by the user and does not represent an authoritative property location. The pin displayed on the map is an approximate

This map complies with FEMA's standards for the use of The basemap shown complies with FEMA's basemap digital flood maps if it is not void as described below accuracy standards

authoritative NFHL web services provided by FEMA. This map reflect changes or amendments subsequent to this date and time. The NFHL and effective information may change or The flood hazard information is derived directly from the was exported on 11/7/2023 at 2:57 PM and does not become superseded by new data over time. This map image is void if the one or more of the following map legend, scale bar, map creation date, community identifiers, FIRM panel number, and FIRM effective date. Map images for unmapped and unmodernized areas cannot be used for elements do not appear: basemap imagery, flood zone labels, regulatory purposes.



Floodplain Analysis & Regulatory Assessment (FARA)



Point of Interest



Base Flood Elevation Point

VERSION

1.0

FLD_ZONE, SOURCE_DNR, **ZONE_SUBTY**



FEMA Zone AE Floodway; FEMA Administrative Floodway

Not Mapped

_ong: **-86.54074195060406** Lat: 39.231764279781665

Approximate Ground Elevation: 570.0 feet (NAVD88)

Base Flood Elevation: 586.3 Feet (NAVD88)

Drainage Area: Not Available

The information provided below is based on the point of interest shown in the map above.

County: Monroe

Stream Name:

Beanblossom Creek

Best Available Flood Hazard Zone: **FEMA Zone AE Floodway**

National Flood Hazard Zone: FEMA Zone AE Floodway

Is a Flood Control Act permit from the DNR needed for this location? yes

Is a local floodplain permit needed for this location? yes-

Floodplain Administrator: Tammy Behrman, Senior Planner

Community Jurisdiction: Monroe County, County proper

Phone: (812) 349-2560

Email: tbehrman@co.monroe.in.us

US Army Corps of Engineers District: Louisville

BFE at upstream coping of

Existing Bridge

Date Generated: 11/7/2023





About

Contact

Meetings & Minutes

AOPA Committee

Rules

Fee Approvals

Nonrule Policy Documents (NPD)

Division of Hearings

About

Administrative Review

Shared Neutrals

Related Agencies

Department of Natural Resources

Office of Environmental Adjudication

Roster by Waterway

- I. Navigability
- II. Establishing a Roster
- III. Roster by Waterway
- IV. Roster by County

E | E | G | H | I | J | K | L | M | N | O | P | R | S | I | V | W | Y ABCI

River (including Middle Fork): Navigable in Spencer County from its junction with the Ohio River for 28.4 river miles to the Perry-Spencer County Line. The Middle Fork is navigable from its junction with the Anderson River for 3.3 river miles. Anderson

Armuth Ditch: See Black Creek.

Arnold Creek: Navigable in Ohio County from its junction with the Ohio River for 4.4 river miles.

m

Baker Creek: Navigable in Spencer County from its junction with Little Pigeon Creek 1.8 river miles.

Project located

mouth of Griffy Creek; therefore stream is Not

Navigable at our project location.

upstream of

Creek: Navigable in Perry County from its junction with Oil Creek for 0.5 river miles. **Bald Knob**

Creek: See Baugo Creek. Banbango Creek: See Baugo Creek. Bangango Baugo Creek: Navigable from its junction with the St. Joseph River in South Bend for 15.2 river miles to the main forks (near Wakarusa).

Bayou Creek: Navigable in Vanderburgh County from its junction with the Ohio River for 1.5 river miles.

Beanblossom Creek: Navigable in Monroe County from its junction with the West Fork of the White River for 17.7 river miles to Griffy Creek



Wetlands - Monroe 913



November 28, 2023

Wetlands

Estuarine and Marine Deepwater

Estuarine and Marine Wetland

Freshwater Emergent Wetland

Freshwater Forested/Shrub Wetland

Freshwater Pond

Lake

Other

Riverine

National Wetlands Inventory (NWI) This page was produced by the NWI mapper

APPENDIX D Cost Estimates

Alternative B Rehabilitation cost

20-Year Maintenance Costs for Monroe 913

Convert to present worth, assuming a 4% yearly inflation rate

Fracture Critical Inspections (24 month frequency)

Assume \$2340 per inspection = \$2340/year

Inflation = 0.04 * 2340 = \$94/year

PW = A(P/A,4%,20) + G(P/G,4%,20)

= \$2340 * 13.590 + \$94 * 111.564

= \$42,288 ~ \$43,000

Special Detail Inspection (24 month frequency starting 4th year)

Assume \$800 per inspection = \$400/year

Inflation = $0.04 \times 400 = $16/year$

PW = A(P/A,4%,20) + G(P/G,4%,20)

= \$400 * 13.590 **+** \$16 * 111.564

= \$7,221~ \$8,000

Clean Truss for Maintenance (12 month frequency)

Assume \$250 per cleaning = \$810/year

Inflation = $0.04 \times 810 = $33/year$

PW = A(P/A,4%,20) + G(P/G,4%,20)

= \$810 * 13.590 **+** \$33 * 111.564

= \$14,690 ~ \$15,000

SUMMARY

PW Maintenance Costs = \$43,000+\$8,000+\$15,000

= \$66,000

	Single Pa	vment		Uniform Pa	yment Series		Arithmetic	Gradient	
	Compound Amount Factor Find F	Present Worth Factor Find P	Sinking Fund Factor Find A	Capital Recovery Factor Find A	Compound Amount Factor Find F	Present Worth Factor Find P	Gradient Uniform Series Find A	Gradient Present Worth Find P	
n	Given P F/P	Given F P/F	Given F A/F	Given P A/P	Given A F/A	Given A P/A	Given <i>G</i> A/G	Given G P/G	n
1	1.040	.9615	1.0000	1.0400	1.000	0.962	0	0	
2	1.082	.9246	.4902	.5302	2.040	1.886	0.490	0.925	
3	1.125	.8890	.3203	.3603	3.122	2.775	0.974	2.702	
4 5	1.170 1.217	.8548 .8219	.2355 .1846	.2755 .2246	4.246 5.416	3.630 4.452	1.451 1.922	5.267 8.555	
6	1.265	.7903	.1508	.1908	6.633	5.242	2.386	12.506	
7 8	1.316 1.369	.7599 .7307	.1266 .1085	.1666 .1485	7.898 9.214	6.002 6.733	2.843 3.294	17.066 22.180	
9	1.423	.7026	.0945	.1345	10.583	7.435	3.739	27.801	
10	1.480	.6756	.0833	.1233	12.006	8.111	4.177	33.881	
11	1.539	.6496	.0741	.1141	13.486	8.760	4.609	40.377	
12	1.601	.6246	.0666	.1066	15.026	9.385	5.034	47.248	
13	1.665	.6006	.0601	.1001	16.627	9.986	5.453	54.454	
14	1.732	.5775	.0547	.0947	18.292	10.563	5.866	61.962	
15	1.801	.5553	.0499	.0899	20.024	11.118	6.272	69.735	
16	1.873	.5339	.0458	.0858	21.825	11.652	6.672	77.744	
7	1.948	.5134	.0422	.0822	23.697	12.166	7.066	85.958	
8	2.026	.4936	.0390	.0790	25.645	12.659	7.453	94.350	
9	2.107	.4746	.0361	.0761	27.671	13.134	7.834	102.893	
20	2.191	.4564	.0336	.0736	29.778	13.590	8.209	111.564	
21	2.279	.4388	.0313	.0713	31.969	14.029	8.578	120.341	- 2
22	2.370	.4220	.0292	.0692	34.248	14.451	8.941	129.202	
23	2.465	.4057	.0273	.0673	36.618	14.857	9.297	138.128	
24	2.563	.3901	.0256	.0656	39.083	15.247	9.648	147.101	
25	2.666	.3751	.0240	.0640	41.646	15.622	9.993	156.104	
26	2.772	.3607	.0226	.0626	44.312	15.983	10.331	165.121	
27	2.883	.3468	.0212	.0612	47.084	16.330	10.664	174.138	
28	2.999	.3335	.0200	.0600	49.968	16.663	10.991	183.142	
29	3.119	.3207	.0189	.0589	52.966	16.984	11.312	192.120	
30	3.243	.3083	.0178	.0578	56.085	17.292	11.627	201.062	
31	3.373	.2965	.0169	.0569	59.328	17.588	11.937	209.955	
32	3.508	.2851	.0159	.0559	62.701	17.874	12.241	218.792	
33 34	3.648 3.794	.2741 .2636	.0151 .0143	.0551 .0543	66.209 69.858	18.148 18.411	12.540 12.832	227.563 236.260	
35	3.946	.2534	.0136	.0536	73.652	18.665	13.120	244.876	
10									
10 15	4.801 5.841	.2083 .1712	.0105 .00826	.0505 .0483	95.025 121.029	19.793 20.720	14.476 15.705	286.530 325.402	
50	7.107	.1407	.00626	.0466	152.667	21.482	16.812	361.163	
55	8.646	.1157	.00523	.0452	191.159	22.109	17.807	393.689	
50	10.520	.0951	.00420	.0442	237.990	22.623	18.697	422.996	
55	12.799	.0781	.00339	.0434	294.968	23.047	19.491	449.201	
70	15.572	.0642	.00275	.0427	364.290	23.395	20.196	472.479	
5	18.945	.0528	.00223	.0422	448.630	23.680	20.821	493.041	
80	23.050	.0434	.00181	.0418	551.244	23.915	21.372	511.116	
35	28.044	.0357	.00148	.0415	676.089	24.109	21.857	526.938	
0	34.119	.0293	.00121	.0412	827.981	24.267	22.283	540.737	
05	41.511	.0241	.00099	.0410	1 012.8	24.398	22.655	552.730	9
00	50.505	.0198	.00081	.0408	1 237.6	24.505	22.980	563.125	1

Page_____of _____

 Job:
 Monroe County Bridge No. 913
 DES:
 AE
 DATE:
 11/19/2023

 Item:
 Cost Estimate- Rehabilitation
 CK:
 AVW
 DATE:
 11/27/2023

ALTERNATIVE B- BRIDGE REHABILITATION

Item Num.	Pay Item	UNIT	QUANTITY	L	JNIT PRICE		AMOUNT
105-06845	CONSTRUCTION ENGINEERING	LSUM	1	\$	70,000.00	\$	70,000.00
	MOBILIZATION AND DEMOBILIZATION	LSUM	1	\$	117,000.00	\$	117,000.00
	CLEARING RIGHT OF WAY	LSUM	1	\$	47,000.00	\$	47,000.00
	PAVEMENT REMOVAL	SYS	556	\$	52.00	\$	28,912.00
	PRESENT STRUCTURE, REMOVE			,			-,-
202-51328	PORTIONS	LSUM	1	\$	150,000.00	\$	150,000.00
203-02000	EXCAVATION, COMMON	CYS	450	\$	90.00	\$	40,500.00
203-02070	BORROW	CYS	300	\$	68.00	\$	20,400.00
205-12108	STORM WATER MANAGEMENT BUDGET	DOL	20000	\$	1.00	\$	20,000.00
205 12616	STORMWATER MANAGEMENT	LCLIM	4	¢.	10 000 00	φ.	10 000 00
	IMPLEMENTATION SWQCP PREPARATION	LSUM LSUM	1	\$	10,000.00 15,000.00	\$	10,000.00
				•			15,000.00
	SUBGRADE TREATMENT, TYPE IC	SYS	1180	\$	50.00	\$	59,000.00
	GEOTEXTILE FOR RIPRAP TYPE 2B	CYS	141	\$	12.00	\$	1,692.00
	SUBBASE FOR PCCP	CYS	36	\$	181.00	\$	6,516.00
	WIDENING WITH HMA, TYPE 2B	TON	88	\$	251.00	\$	22,088.00
	MILLING, TRANSITION	SYS	934	\$	10.00	\$	9,340.00
401-07322	QC/QA-HMA, 3, 64, SURFACE, 9.5 MM QC/QA-HMA, 3, 64, INTERMEDIATE, 19.0	TON	175	\$	253.00	\$	44,275.00
401-07392		TON	130	\$	224.00	\$	29,120.00
401-07424	QC/QA-HMA, 3, 64, BASE, 19.0 MM	TON	415	\$	216.00	\$	89,640.00
401-10258	JOINT ADHESIVE, SURFACE	LFT	1200	\$	2.00	\$	2,400.00
401-10259	JOINT ADHESIVE, INTERMEDIATE	LFT	600	\$	2.50	\$	1,500.00
401-11785	LIQUID ASPHALT SEALANT	LFT	1200	\$	1.25	\$	1,500.00
406-05521	ASPHALT FOR TACK COAT	SYS	1800	\$	1.00	\$	1,800.00
601-01700	GUARDRAIL, TERMINAL SYSTEM, W- BEAM, CURVED, 1	EACH	1	\$	4,080.00	\$	4,080.00
601-02241	GUARDRAIL, REMOVE	LFT	500	\$	9.00	\$	4,500.00
601-02281	GUARDRAIL, MGS W-BEAM, 6 FT 3 IN SPA.	LFT	365	\$	31.50	\$	11,497.50
601-12289	GUARDRAIL, MGS, HEIGHT TRANSITION	EACH	2	\$	1,428.00	\$	2,856.00
601-12292	GUARDRAIL, MGS TRANSITION WITHOUT CURB	EACH	4	\$	4,392.00	\$	17,568.00
601-94689	GUARDRAIL, END TREATMENT, OS	EACH	2	\$	4,080.00	\$	8,160.00
	REINFORCED CONCRETE BRIDGE						
	APPROACH, 12 IN.	SYS	146	\$	285.00	\$	41,610.00
	RIPRAP, CLASS 1	TON	200	\$	130.00	\$	26,000.00
616-12248	GEOTEXTILE FOR RIPRAP TYPE 2A	SYS	200	\$	15.00	\$	3,000.00
619-11050	CLEAN STEEL BRIDGE, PARTIAL, QP-2, BRIDGE NO.	LSUM	1	\$	216,000.00	\$	216,000.00

Page_____of ____

 Job:
 Monroe County Bridge No. 913
 DES:
 AE
 DATE:
 11/19/2023

 Item:
 Cost Estimate- Rehabilitation
 CK:
 AVW
 DATE:
 11/27/2023

ALTERNATIVE B- BRIDGE REHABILITATION

Item Num.	Pay Item	UNIT	QUANTITY	U	INIT PRICE	AMOUNT
	DISPOSAL OF CLEANING WASTE					
	HAZARDOUS BRIDGE NO.	LSUM	1	\$	20,000.00	\$ 20,000.00
619-51859	PAINT STEEL BRIDGE, BRIDGE NO.	LSUM	1	\$	110,000.00	\$ 110,000.00
621-06553	SEED MIXTURE, R	LBS	35	\$	7.50	\$ 262.50
621-06574	SODDING	SYS	40	\$	90.00	\$ 3,600.00
628-09403	FIELD OFFICE, C	MONTH	12	\$	3,138.00	\$ 37,656.00
703-06029	REINFORCING BARS, EPOXY COATED	LBS	58230	\$	2.30	\$ 133,929.00
704-51002	CONCRETE, C, SUPERSTRUCTURE	CYS	116	\$	2,046.00	\$ 237,336.00
706-06351	CONCRETE BRIDGE RAILING TRANSITION, TPF-1	EACH	4	\$	7,800.00	\$ 31,200.00
706-09962	RAILING, CONCRETE PF-1	LFT	254	\$	186.00	\$ 47,244.00
706-11404	RAILING, STEEL PF-1	LFT	271	\$	111.00	\$ 30,081.00
709-51821	SURFACE SEAL	LSUM	1	\$	4,800.00	\$ 4,800.00
710-09158	PATCHING CONCRETE STRUCTURES	SFT	50	\$	210.00	\$ 10,500.00
711-05728	REPAIR, GUSSET PLATE	EACH	5	\$	1,200.00	\$ 6,000.00
711-05728	REPAIR, LOW CHORD	EACH	5	\$	18,000.00	\$ 90,000.00
711-05728	REPAIR, BEARING	EACH	2	\$	1,700.00	\$ 3,400.00
711-05728	REPAIR, LOW CHORD SPLICE	EACH	6	\$	600.00	\$ 3,600.00
711-05728	REPAIR, VERTICAL	EACH	4	\$	250.00	\$ 1,000.00
711-05728	REPAIR, DIAGONAL	EACH	1	\$	600.00	\$ 600.00
711-05728	REPAIR, STRUTS	EACH	6	\$	240.00	\$ 1,440.00
711-51035	STRUCTURAL STEEL	LBS	32543	\$	16.00	\$ 520,688.00
711-51864	DRILLED HOLE	EACH	600	\$	54.00	\$ 32,400.00
711-51866	RIVET, REMOVE	EACH	1200	\$	30.00	\$ 36,000.00
711-96800	STUD SHEAR CONNECTORS	EACH	1728	\$	7.50	\$ 12,960.00
724-12773	BRIDGE EXPANSION JOINT, PCF	LFT	64	\$	144.00	\$ 9,216.00
801-04308	ROAD CLOSURE SIGN ASSEMBLY	EACH	4	\$	374.50	\$ 1,498.00
801-06625	DETOUR ROUTE MARKER ASSEMBLY	EACH	30	\$	172.00	\$ 5,160.00
801-06640	CONSTRUCTION SIGN, A	EACH	30	\$	288.00	\$ 8,640.00
801-06775	MAINTAINING TRAFFIC	LSUM	1	\$	20,000.00	\$ 20,000.00
801-07119	BARRICADE, III-B	LFT	72	\$	21.00	\$ 1,512.00
	LINE, PREFORMED PLASTIC, SOLID, WHITE, 6 IN.	LFT	1230	\$	8.50	\$ 10,455.00
	LINE, PREFORMED PLASTIC, SOLID, YELLOW, 6 IN.	LFT	1230	\$	7.50	\$ 9,225.00
808-75996	SNOWPLOWABLE RAISED PAVEMENT MARKER, REMOVE	EACH	7	\$	61.00	\$ 427.00
808-75998	SNOWPLOWABLE RAISED PAVEMENT MARKER	EACH	16	\$	213.50	\$ 3,416.00

Subtotal = \$ 2,567,200.00

2023 Cost Estimate \$ 2,567,000.00

2029 Cost Estimate \$ 3,065,000.00

Alternative D Bypass and Rehabilitation for Non-Vehicular Use cost

Page_____of ____

Job:Monroe County Bridge No. 913DES:AVWDATE:11/28/2023

Item: Cost Estimate- Rehab Truss for Pedestrian Use for Bypass Alter. CK: AE DATE: 11/28/2023

REHABILITATE TRUSS FOR PEDESTRIAN USE FOR BYPASS ALTERNATIVE

Item Num.	Pay Item	UNIT	QUANTITY	U	INIT PRICE	AMOUNT
105-06845	CONSTRUCTION ENGINEERING	LSUM	1	\$	36,500.00	\$ 36,500.00
110-01001	MOBILIZATION AND DEMOBILIZATION	LSUM	1	\$	50,000.00	\$ 50,000.00
201-52370	CLEARING RIGHT OF WAY	LSUM	1	\$	20,000.00	\$ 20,000.00
203-02000	EXCAVATION, COMMON	CYS	50	\$	130.00	\$ 6,500.00
203-02070	BORROW	CYS	100	\$	77.00	\$ 7,700.00
205-12108	STORM WATER MANAGEMENT BUDGET	DOL	5000	\$	1.00	\$ 5,000.00
205-12616	STORMWATER MANAGEMENT IMPLEMENTATION	LSUM	1	\$	5,000.00	\$ 5,000.00
205-12618	SWQCP PREPARATION	LSUM	1	\$	5,000.00	\$ 5,000.00
207-09935	SUBGRADE TREATMENT, TYPE IC	SYS	50	\$	113.00	\$ 5,650.00
303-01180	COMPACTED AGGREGATE NO.53	TON	50	\$	104.00	\$ 5,200.00
306-08043	MILLING, TRANSITION	SYS	100	\$	26.50	\$ 2,650.00
401-07322	QC/QA-HMA, 3, 64, SURFACE, 9.5 MM	TON	20	\$	408.00	\$ 8,160.00
406-05521	ASPHALT FOR TACK COAT	SYS	100	\$	2.00	\$ 200.00
616-05688	RIPRAP, CLASS 1	TON	200	\$	140.00	\$ 28,000.00
616-12248	GEOTEXTILE FOR RIPRAP TYPE 2A	SYS	200	\$	12.50	\$ 2,500.00
619-11050	CLEAN STEEL BRIDGE, PARTIAL, QP-2, BRIDGE NO.	LSUM	1	\$	207,000.00	\$ 207,000.00
619-12459	DISPOSAL OF CLEANING WASTE HAZARDOUS BRIDGE NO.	LSUM	1	\$	20,000.00	\$ 20,000.00
619-51859	PAINT STEEL BRIDGE, BRIDGE NO.	LSUM	1	\$	104,000.00	\$ 104,000.00
621-06553	SEED MIXTURE, R	LBS	35	\$	8.00	\$ 280.00
621-06574	SODDING	SYS	40	\$	78.00	\$ 3,120.00
628-09403	FIELD OFFICE, C	MONTH	6	\$	3,300.00	\$ 19,800.00
703-06029	REINFORCING BARS, EPOXY COATED	LBS	41860	\$	2.35	\$ 98,371.00
704-51002	CONCRETE, C, SUPERSTRUCTURE	CYS	125	\$	1,840.00	\$ 230,000.00
706-09961	RAILING, CONCRETE PS-1	LFT	254	\$	173.00	\$ 43,942.00
706-11418	RAILING, STEEL PS-1	LFT	271	\$	115.00	\$ 31,165.00
709-51821	SURFACE SEAL	LSUM	1	\$	1,200.00	\$ 1,200.00
711-51035	STRUCTURAL STEEL	LBS	20000	\$	11.50	\$ 230,000.00
711-51864	DRILLED HOLE	EACH	600	\$	60.00	\$ 36,000.00
711-51866	RIVET, REMOVE	EACH	2200	\$	29.00	\$ 63,800.00
711-96800	STUD SHEAR CONNECTORS	EACH	1728	\$	6.90	\$ 11,923.20
724-12773	BRIDGE EXPANSION JOINT, PCF	LFT	64	\$	132.00	\$ 8,448.00
801-06775	MAINTAINING TRAFFIC	LSUM	1	\$	14,000.00	\$ 14,000.00

Total = \$ 1,311,109.20

2023 Cost Estimate \$ 1,311,000.00

2029 Cost Estimate \$ 1,565,000.00

Page_____of ____

Monroe County Bridge No. 913 Job: **DES**: AE **DATE**: 11/29/2023 **CK:** AVW **DATE:** 11/29/2023

Cost Estimate- New Bypass Bridge Item:

NEW BYPASS BRIDGE

Item Num.	Pay Item	UNIT	QUANTITY	L	INIT PRICE	AMOUNT
105-06845	CONSTRUCTION ENGINEERING	LSUM	1	\$	144,000.00	\$ 144,000.00
110-01001	MOBILIZATION AND DEMOBILIZATION	LSUM	1	\$	239,000.00	\$ 239,000.00
201-52370	CLEARING RIGHT OF WAY	LSUM	1	\$	144,000.00	\$ 144,000.00
202-02240	PAVEMENT REMOVAL	SYS	1902	\$	48.00	\$ 91,296.00
202-51328	PRESENT STRUCTURE, REMOVE			•		
000 00000	PORTIONS	LSUM	1	\$	57,500.00	\$ 57,500.00
	EXCAVATION, COMMON	CYS	3825	\$	70.50	\$ 269,662.50
203-02070		CYS	11970	\$	34.00	\$ 406,980.00
205-12108	STORMWATER MANAGEMENT BUDGET	DOL	20000	\$	1.00	\$ 20,000.00
205-12616	STORMWATER MANAGEMENT IMPLEMENTATION	LSUM	1	\$	10,000.00	\$ 10,000.00
205-12618	SWQCP PREPARATION	LSUM	1	\$	20,000.00	\$ 20,000.00
207-09935	SUBGRADE TREATMENT, TYPE IC	SYS	8535	\$	44.00	\$ 375,540.00
214-12239	GEOTEXTILE FOR PAVEMENT TYPE 2B	SYS	188	\$	10.00	\$ 1,880.00
302-06464	SUBBASE FOR PCCP	CYS	47	\$	173.00	\$ 8,131.00
306-08043	MILLING, TRANSITION	SYS	423	\$	11.00	\$ 4,653.00
401-07322	QC/QA-HMA, 3, 64, SURFACE, 9.5 mm	TON	725	\$	179.00	\$ 129,775.00
401-07392	QC/QA-HMA, 3, 64, INTERMEDIATE, 19.0 m	TON	1140	\$	121.00	\$ 137,940.00
401-07424	QC/QA-HMA, 3, 64, BASE, 19.0 mm	TON	3650	\$	126.50	\$ 461,725.00
401-10258	JOINT ADHESIVE, SURFACE	LFT	6450	\$	1.00	\$ 6,450.00
401-10259	JOINT ADHESIVE, INTERMEDIATE	LFT	6150	\$	1.20	\$ 7,380.00
401-11785	LIQUID ASPHALT SEALANT	LFT	6450	\$	0.70	\$ 4,515.00
406-05521	ASPHALT FOR TACK COAT	SYS	12500	\$	0.50	\$ 6,250.00
601-01700	GUARDRAIL, TERMINAL SYSTEM, W- BEAM CURVED, 1	EACH	1	\$	3,910.00	\$ 3,910.00
601-02241	GUARDRAIL, REMOVE	LFT	1400	\$	7.20	\$ 10,080.00
601-12281	GUARDRAIL MGS W-BEAM, 6 FT 3 IN. SPACING	LFT	1350	\$	29.00	\$ 39,150.00
601-12289	GUARDRAIL, MGS, HEIGHT TRANSITION	EACH	1	\$	1,495.00	\$ 1,495.00
601-12292	GUARDRAIL, MGS, TRANSITION WITHOUT CURB	EACH	4	\$	4,255.00	\$ 17,020.00
601-94689	GUARDRAIL, END TREATMENT, OS	EACH	3	\$	3,853.00	\$ 11,559.00
	REINFORCED CONCRETE BRIDGE					
609-06259	APPROACH, 12 IN.	SYS	195	\$	253.00	\$ 49,335.00
616-05688	RIPRAP, CLASS 1	TON	285	\$	129.00	\$ 36,765.00
616-12248	GEOTEXTILE FOR RIPRAP TYPE 2A	SYS	285	\$	9.00	\$ 2,565.00
621-06553	SEED MIXTURE, R	LBS	35	\$	7.00	\$ 245.00
621-06574	SODDING	SYS	40	\$	87.00	\$ 3,480.00
628-09403	FIELD OFFICE, C	MONTH	18	\$	2,933.00	\$ 52,794.00

Page_____of ____

Job:Monroe County Bridge No. 913DES:AEDATE:11/29/2023

 Item:
 Cost Estimate- New Bypass Bridge

 CK:
 AVW

 DATE:
 11/29/2023

NEW BYPASS BRIDGE

Item Num.	Pay Item	UNIT	QUANTITY	U	NIT PRICE	AMOUNT
701-09557	TEST PILE, DYNAMIC, PRODUCTION	LFT	90	\$	80.00	\$ 7,200.00
701-09559	TEST PILE, DYNAMIC, RESTRIKE	EACH	2	\$	4,485.00	\$ 8,970.00
701-09683	PILE SHOE, HP 12 X 74	EACH	30	\$	196.00	\$ 5,880.00
701-95780	PILE, STEEL H, HP 12 X 74	LFT	390	\$	155.00	\$ 60,450.00
702-51005	CONCRETE, A, SUBSTRUCTURE	CYS	142	\$	1,495.00	\$ 212,290.00
702-51015	CONCRETE, B, FOOTINGS	CYS	70	\$	633.00	\$ 44,310.00
702-92857	CONCRETE, C, SUBSTRUCTURE	CYS	40	\$	1,725.00	\$ 69,000.00
703-06028	REINFORCING BARS	LBS	27526	\$	2.00	\$ 55,052.00
703-06029	REINFORCING BARS, EPOXY COATED	LBS	124670	\$	2.00	\$ 249,340.00
704-51002	CONCRETE, C, SUPERSTRUCTURE	CYS	300	\$	1,610.00	\$ 483,000.00
706-09959	RAILING, CONCRETE FT	LFT	420	\$	170.00	\$ 71,400.00
706-11621	TRANSITION, TFT	EACH	4	\$	7,475.00	\$ 29,900.00
707-09865	STRUCTURAL MEMBER, CONCRETE, BULB-T BEAM, 36 IN. X 49 IN	LFT	852	\$	768.20	\$ 654,506.40
	SURFACE SEAL	LSUM	1	\$	2,500.00	\$ 2,500.00
	ROAD CLOSURE SIGN ASSEMBLY	EACH	4	\$	359.00	\$ 1,436.00
801-06625	DETOUR ROUTE MARKER ASSEMBLY	EACH	30	\$	165.00	\$ 4,950.00
801-06640	CONSTRUCTION SIGN, A	EACH	30	\$	276.00	\$ 8,280.00
801-06775	MAINTAINING TRAFFIC	LSUM	1	\$	15,000.00	\$ 15,000.00
801-07119	BARRICADE, III-B	LFT	72	\$	20.00	\$ 1,440.00
808-75052	LINE, PREFORMED PLASTIC, SOLID, WHITE, 6 IN.	LFT	3260	\$	8.00	\$ 26,080.00
808-75057	LINE, PREFORMED PLASTIC, SOLID, YELLOW, 6 IN.	LFT	3260	\$	6.00	\$ 19,560.00
808-75996	SNOWPLOWABLE RAISED PAVEMENT MARKER, REMOVE	EACH	24	\$	59.00	\$ 1,416.00
808-75998	SNOWPLOWABLE RAISED PAVEMENT MARKER	EACH	24	\$	196.00	\$ 4,704.00

Total = \$ 4,811,739.90

2023 Cost Estimate \$ 4,812,000.00

2029 Cost Estimate \$ 5,746,000.00

Alternative E Relocation and Replacement cost

Page_____of _____

Job:Monroe County Bridge No. 913DES:AVWDATE:11/27/2023

Item: Cost Estimate- Relocate & Rehab Truss for Pedestrian Use CK: AE DATE: 11/27/2023

RELOCATE AND REHABILITATE TRUSS FOR PEDESTRIAN USE

Item Num.	Pay Item	UNIT	QUANTITY	U	UNIT PRICE		AMOUNT
105-06845	CONSTRUCTION ENGINEERING	LSUM	1	\$	45,500.00	\$	45,500.00
110-01001	MOBILIZATION AND DEMOBILIZATION	LSUM	1	\$	65,000.00	\$	65,000.00
201-52370	CLEARING RIGHT OF WAY	LSUM	1	\$	30,000.00	\$	30,000.00
203-02000	EXCAVATION, COMMON	CYS	150	\$	113.00	\$	16,950.00
203-02070	BORROW	CYS	200	\$	67.00	\$	13,400.00
205-12108	STORM WATER MANAGEMENT BUDGET	DOL	5000	\$	1.00	\$	5,000.00
205 12616	STORMWATER MANAGEMENT IMPLEMENTATION	LSUM	1	\$	5,000.00	\$	5,000.00
	SWQCP PREPARATION	LSUM	1	\$	5,000.00	\$	5,000.00
	EXCAVATION, X	CYS	56	\$	345.00	\$	19,320.00
	SUBGRADE TREATMENT, TYPE IC	SYS	300	\$	62.00	\$	18,600.00
	MILLING, TRANSITION	SYS	100	\$	26.50	\$	2,650.00
	QC/QA-HMA, 3, 64, SURFACE, 9.5 MM	TON	25	\$	337.00	\$	8,425.00
101 07022	QC/QA-HMA, 3, 64, INTERMEDIATE, 19.0	1011	20	Ψ	007.00	Ψ	0,120.00
401-07392	MM	TON	45	\$	248.00	\$	11,160.00
401-07424	QC/QA-HMA, 3, 64, BASE, 19.0 MM	TON	50	\$	218.00	\$	10,900.00
	ASPHALT FOR TACK COAT	SYS	500	\$	1.84	\$	920.00
616-05688	RIPRAP, CLASS 1	TON	200	\$	121.00	\$	24,200.00
616-12248	GEOTEXTILE FOR RIPRAP TYPE 2A	SYS	200	\$	11.50	\$	2,300.00
619-11050	CLEAN STEEL BRIDGE, PARTIAL, QP-2, BRIDGE NO.	LSUM	1	\$	150,000.00	\$	150,000.00
619-12459	DISPOSAL OF CLEANING WASTE HAZARDOUS BRIDGE NO.	LSUM	1	\$	20,000.00	\$	20,000.00
619-51859	PAINT STEEL BRIDGE, BRIDGE NO.	LSUM	1	\$	75,000.00	\$	75,000.00
621-06553	SEED MIXTURE, R	LBS	35	\$	7.00	\$	245.00
621-06574	SODDING	SYS	40	\$	92.00	\$	3,680.00
628-09403	FIELD OFFICE, C	MONTH	12	\$	2,875.00	\$	34,500.00
702-51005	CONCRETE, A, SUBSTRUCTURE	CYS	50	\$	1,550.00	\$	77,500.00
702-51015	CONCRETE, B, FOOTINGS	CYS	45	\$	690.00	\$	31,050.00
703-06028	REINFORCING BARS	LBS	11875	\$	1.94	\$	23,037.50
703-06029	REINFORCING BARS, EPOXY COATED	LBS	41860	\$	2.04	\$	85,394.40
704-51002	CONCRETE, C, SUPERSTRUCTURE	CYS	125	\$	1,770.00	\$	221,250.00
706-09961	RAILING, CONCRETE PS-1	LFT	254	\$	177.00	\$	44,958.00
706-11418	RAILING, STEEL PS-1	LFT	271	\$	109.00	\$	29,539.00
709-51821	SURFACE SEAL	LSUM	1	\$	1,200.00	\$	1,200.00
711-12147	SUPERSTRUCTURE INSTALLATION REASSEMBLE	LSUM	1	\$	75,000.00	\$	75,000.00
	STRUCTURAL STEEL	LBS	20000	\$	10.00	\$	200,000.00
	DRILLED HOLE	EACH	600	\$	52.00	\$	31,200.00

Page_____of ____

Job:Monroe County Bridge No. 913DES:AVWDATE:11/27/2023

Item: Cost Estimate- Relocate & Rehab Truss for Pedestrian Use CK: AE DATE: 11/27/2023

RELOCATE AND REHABILITATE TRUSS FOR PEDESTRIAN USE

Item Num.	Pay Item	UNIT	QUANTITY	U	NIT PRICE	AMOUNT
711-51866	RIVET, REMOVE	EACH	2200	\$	29.00	\$ 63,800.00
711-96800	STUD SHEAR CONNECTORS	EACH	1728	\$	6.90	\$ 11,923.20
724-12773	BRIDGE EXPANSION JOINT, PCF	LFT	64	\$	132.00	\$ 8,448.00
801-04308	ROAD CLOSURE SIGN ASSEMBLY	EACH	2	\$	356.00	\$ 712.00
801-06775	MAINTAINING TRAFFIC	LSUM	1	\$	12,000.00	\$ 12,000.00
801-07119	BARRICADE, III-B	LFT	30	\$	20.00	\$ 600.00

Subtotal = \$ 1,485,362.10

Total = \$ 1,485,362.10

2023 Cost Estimate \$ 1,485,000.00

2029 Cost Estimate \$ 1,773,000.00

Page____of ____

 Job:
 Monroe County Bridge No. 913
 DES:
 AE
 DATE:
 11/19/2023

 Item:
 Cost Estimate- Replacement
 CK:
 AVW
 DATE:
 11/27/2023

3 SPAN CONTINUOUS PRESTRESSED CONCRETE BULB-T BEAM BRIDGE

Item Num.	Pay Item	UNIT	QUANTITY	L	JNIT PRICE		AMOUNT
105-06845	CONSTRUCTION ENGINEERING	LSUM	1	\$	87,000.00	\$	87,000.00
110-01001	MOBILIZATION AND DEMOBILIZATION	LSUM	1	\$	145,000.00	\$	145,000.00
201-52370	CLEARING RIGHT OF WAY	LSUM	1	\$	58,000.00	\$	58,000.00
202-02240	PAVEMENT REMOVAL	SYS	923	\$	50.00	\$	46,150.00
202-51330	PRESENT STRUCTURE, REMOVE	LSUM	1	\$	230,000.00	\$	230,000.00
203-02000	EXCAVATION, COMMON	CYS	350	\$	98.00	\$	34,300.00
203-02070	BORROW	CYS	575	\$	53.00	\$	30,475.00
205-12108	STORM WATER MANAGEMENT BUDGET	DOL	12000	\$	1.00	\$	12,000.00
205-12616	STORMWATER MANAGEMENT IMPLEMENTATION	LSUM	1	\$	10,000.00	\$	10,000.00
205-12618	SWQCP PREPARATION	LSUM	1	\$	20,000.00	\$	20,000.00
207-09935	SUBGRADE TREATMENT, TYPE IC	SYS	1715	\$	48.00	\$	82,320.00
214-12239	GEOTEXTILE FOR RIPRAP TYPE 2B	CYS	188	\$	10.00	\$	1,880.00
302-06464	SUBBASE FOR PCCP	CYS	47	\$	173.30	\$	8,145.10
306-08043	MILLING, TRANSITION	SYS	400	\$	11.00	\$	4,400.00
401-07322	QC/QA-HMA, 3, 64, SURFACE, 9.5 MM	TON	175	\$	241.50	\$	42,262.50
404 07000	QC/QA-HMA, 3, 64, INTERMEDIATE, 19.0	TON	000	Φ.	474.50	Φ.	07 700 00
401-07392		TON	220	\$	171.50	\$	37,730.00
	QC/QA-HMA, 3, 64, BASE, 19.0 MM	TON	715	\$	154.00	\$	110,110.00
	JOINT ADHESIVE, SURFACE	LFT	1350	\$	1.50	\$	2,025.00
	JOINT ADHESIVE, INTERMEDIATE	LFT	1050	\$	1.60	\$	1,680.00
_	LIQUID ASPHALT SEALANT	LFT	1350	\$	1.00	\$	1,350.00
406-05521	ASPHALT FOR TACK COAT	SYS	2400	\$	0.60	\$	1,440.00
601-01700	GUARDRAIL, TERMINAL SYSTEM, W- BEAM, CURVED, 1	EACH	1	\$	4,462.00	\$	4,462.00
601-02241	GUARDRAIL, REMOVE	LFT	500	\$	8.40	\$	4,200.00
601-02281	GUARDRAIL, MGS W-BEAM, 6 FT 3 IN SPA.	LFT	365	\$	30.00	\$	10,950.00
601-12289	GUARDRAIL, MGS, HEIGHT TRANSITION	EACH	2	\$	1,380.00	\$	2,760.00
601-12292	GUARDRAIL, MGS TRANSITION WITHOUT CURB	EACH	4	\$	4,200.00	\$	16,800.00
601-94689	GUARDRAIL, END TREATMENT, OS	EACH	2	\$	3,910.00	\$	7,820.00
609-06259	REINFORCED CONCRETE BRIDGE APPROACH, 12 IN.	SYS	195	\$	253.00	\$	49,335.00
616-05688	RIPRAP, CLASS 1	TON	150	\$	129.00	\$	19,350.00
616-12248	GEOTEXTILE FOR RIPRAP TYPE 2A	SYS	150	\$	14.50	\$	2,175.00
621-06553	SEED MIXTURE, R	LBS	35	\$	7.00	\$	245.00
621-06574	SODDING	SYS	40	\$	86.50	\$	3,460.00

Page_____of _____

 Job:
 Monroe County Bridge No. 913
 DES:
 AE
 DATE:
 11/19/2023

 Item:
 Cost Estimate- Replacement
 CK:
 AVW
 DATE:
 11/27/2023

3 SPAN CONTINUOUS PRESTRESSED CONCRETE BULB-T BEAM BRIDGE

Item Num.	Pay Item	UNIT	QUANTITY	U	NIT PRICE	AMOUNT
628-09403	FIELD OFFICE, C	MONTH	18	\$	2,933.00	\$ 52,794.00
701-09557	TEST PILE, DYNAMIC, PRODUCTION	LFT	90	\$	80.50	\$ 7,245.00
701-09559	TEST PILE, DYNAMIC, RESTRIKE	EACH	2	\$	4,485.00	\$ 8,970.00
701-09683	PILE SHOE, HP 12 X 74	EACH	30	\$	195.50	\$ 5,865.00
701-95780	PILE, STEEL H HP 12 X 74	LFT	500	\$	155.50	\$ 77,750.00
702-51005	CONCRETE, A, SUBSTRUCTURE	CYS	142	\$	1,495.00	\$ 212,290.00
702-51015	CONCRETE, B, FOOTINGS	CYS	70	\$	632.50	\$ 44,275.00
702-92857	CONCRETE, C, SUBSTRUCTURE	CYS	40	\$	1,725.00	\$ 69,000.00
703-06028	REINFORCING BARS	LBS	27488	\$	2.00	\$ 54,976.00
703-06029	REINFORCING BARS, EPOXY COATED	LBS	118640	\$	2.00	\$ 237,280.00
704-51002	CONCRETE, C, SUPERSTRUCTURE	CYS	300	\$	1,610.00	\$ 483,000.00
706-06351	CONCRETE BRIDGE RAILING TRANSITION, TPF-1	EACH	4	\$	7,475.00	\$ 29,900.00
706-09962	RAILING, CONCRETE PF-1	LFT	420	\$	165.60	\$ 69,552.00
706-11404	RAILING, STEEL PF-1	LFT	438	\$	100.60	\$ 44,062.80
707-09865	STRUCTURAL MEMBER, CONCRETE BULB-T BEAM, 36 IN. X 49 IN.	LFT	852	\$	768.20	\$ 654,506.40
709-51821	SURFACE SEAL	LSUM	1	\$	2,496.00	\$ 2,496.00
801-04308	ROAD CLOSURE SIGN ASSEMBLY	EACH	4	\$	359.00	\$ 1,436.00
801-06625	DETOUR ROUTE MARKER ASSEMBLY	EACH	30	\$	165.00	\$ 4,950.00
801-06640	CONSTRUCTION SIGN, A	EACH	30	\$	276.00	\$ 8,280.00
801-06775	MAINTAINING TRAFFIC	LSUM	1	\$	15,000.00	\$ 15,000.00
801-07119	BARRICADE, III-B	LFT	72	\$	20.00	\$ 1,440.00
808-75052	LINE, PREFORMED PLASTIC, SOLID, WHITE, 6 IN.	LFT	654	\$	9.20	\$ 6,016.80
808-75057	LINE, PREFORMED PLASTIC, SOLID, YELLOW, 6 IN.	LFT	1230	\$	7.00	\$ 8,610.00
808-75996	SNOWPLOWABLE RAISED PAVEMENT MARKER, REMOVE	EACH	7	\$	59.00	\$ 413.00
808-75998	SNOWPLOWABLE RAISED PAVEMENT MARKER	EACH	16	\$	196.00	\$ 3,136.00

Total = \$ 3,191,068.60

2023 Cost Estimate \$ 3,191,000.00

2029 Cost Estimate \$ 3,810,000.00

APPENDIX E Load Rating Summary and SI&A Inspection Report

MONROE COUNTY BRIDGE NO. 00913 LOAD RATING SUMMARY

 Des:
 KB
 Date:
 6/10/2020

 Ck:
 AVW
 Date:
 6/15/2020

Bridge Identification

	30 100111110011011			
8.	NBI Number:530013	30 27.	Year Built:	1946
2.	District:05 - SEYMOL	R 106.	Reconstructed:	1986
26.	Func. Class.:07 - RURAL - MAJOR COLLECTO	R 104:	Highway System of Inventory Route:	0
Brig	dge Geometrics	43.	Main Str. Type:	310 - STEEL TRUSS
52.	Deck Width (o-o):32	t. 44.	Str. Type-Approach:	000 - NONE
51.	Bridge Rdwy. Width:28	t. 107.	Deck Structure Type:	2 - CONCRETE PRECAST
48.	Max. Span:125	t. 108A	Wearing Surface:	3 - LATEX CONCRETE
49.	Structure Length:126.6	ft. 34.	Skew:	0 deg.
Cor	<u>ndition</u>			
58.	Deck:5 - FAI	R 60.	Substructure:	6 - SATISFACTORY
59.	Superstructure:5 - FAI	R 62.	Culvert:	N - NOT APPLICABLE

Load Rating Input and Assumptions

L.R. Program: AASHTOWare BrR Program Version: 6.8.3

Load Rating Method: LFR

Railing/Curb: Misc. Alum. with No curbs, assume 40 plf SIP Forms: N/A

Deck/Slab Depth: 6" pretensioned & post tensioned deck panels Wearing Surface Depth: 1.75" Mod. Portland Cement Concrete Overlay

Spans: 125'-0 3/8" CL Brg to CL Brg Span; 126'-6 3/4" structure length; Concrete deck f'ci =4 ksi & f'c =5 ksi;

Deck/Slab Material: 7/16" diam. 270 K pretensioned strands Ult. load= 31 K; 1/2" diam. 270 K coated Post Tensioned Strand Ult. Load=41.3 K

Beam: Original Stringers: west ext. W16x36 & int. W16x40; 2018 Stringers: east ext. Bays 1 & 2 = W18x35 & Bays 3 to 8 = W18x40

Beam/Girder Spacing/Overhangs: Original Floor Beams W36x170 & W36x160 Spaced at 15'-7 1/2"

Beam Material: Original Steel Fy= 33 ksi; 2018 Repair Stringers Fy= 50 ksi

Strands/Rebar: Stringer spa. Int. 6 spa. at 3'-9" = 22.5' Ext. spa.=3'-10" & overhang = 11"; Assume 1/4" Epoxy Mortar Fillet on Stringers Misc.: 33'-7 1/2" CL to CL Truss; Assume 15% additional dead load for connections/members not in model; 7/8" diameter Rivets per plans

Load Rating Notes

The 1946 original design plans, 1969, 1985, and 1995 rehabilitation plans are on file at the Monroe Highway Department. The original plans indicate a H-20 design loading in accordance with the 1941 AASHTO specifications and checked for H20-S16(44). In 1969 the deck was replaced with a 6.25" prestensioned deck that was post-tensioned together. In 1985 the deck was milled 1/4" and overlaid with 1.75" modified Portland cement concrete and the structural steel was cleaned and painted. In 1995 the joints and the ends of the deck were reconstructed. In 2018 the east exterior stringers were replaced with either a Grade 50 A588 W18x35 or W18x40.

The deck was noted as having some signs of minor distress. There is some leaking between panels. Transverse cracks in middle of deck and at edges of precast deck panels. South joint is failed. Delaminations in deck at northwest corner. Underside of 3rd full panel in bay 5 has multiple delaminations and large spall with 3 strands exposed. Some panels are missing beam connection clips. The east deck coping is spalled with exposed strands.

The superstructure was noted as having some signs of distress. Areas of heavy pitting and minor section loss on inside of flanges, top of web, and rivet heads of lower chords. Lateral bracing connections with moderate to heavy section loss. Areas of surface rust and minor expansion rust on stringers and floor beams.

The substructure was noted as having some signs of distress. There is spalling with exposed steel in mudwalls at each bridge corner with 3 to 6 inches of section loss. The expansion bearings are severely rotated to the south and may have seized. The northeast bridge seat is spalled.

All stringers will assume to have 5% total section loss. All floor beams will assume 5% total section loss for 5 feet at each end unless the fracture critical inspection report indicates differently. Assume stringers are not composite with the deck. The exterior stringer live load (LL) distribution factor (DF) per 2002 AASHTO Specifications 3.23.2.3.1.5 is probably for future bridge widenings; however this bridge will never be widened since it is a truss. Therefore, use the lever rule to determine the appropriate LL DF for the exterior stringers. The "allow plastic analysis" box in the control options was checked for the grade 50 stringers only.



MONROE COUNTY BRIDGE NO. 00913 LOAD RATING SUMMARY

KΒ Date: 6/10/2020 Des: AVW Ck: Date: 6/15/2020

Safe Load Capacity

(Ton)

72

75

Load Capacity

(Ton)

72.364

75.035

Design Loads Legal Loads

of Axles

Vehicle	Inventory Rating Factor	Load Capacity (Ton)
HL-93	NA	NA
Fatigue	NA	NA
H-20	1.051	21.020
HS-20	1.046	37.656
HS-25	0.837	37.665

EV2 Sing	gle Axle (Ton) =	42.2

EV2

EV3

Vehicle

EV3 Tandem Axle (Ton) = 54.1

10 20	0.001	01.000	# of Axles	Vehicle	Rating Factor	(Ton)	(Ton)
NRL Ve	hicle not used for	Load Capacity >>	varies	NRL	1.341	NA	NA
		2	H-20	1.755	35.100	35	
			2	Alternate Military	1.510	36.240	36
			3	HS-20	1.748	62.928	62
			3	AASHTO Type 3	2.086	52.150	52
			4	SU4	1.715	46.305	46
			5	AASHTO Type 3S2	2.107	75.852	75
			5	SU5	1.600	49.600	49
	nly when Span =: ure is Continuous		6	AASHTO Type 3-3	2.525	101.000	101
ine Type Vehicle Otherwise Input NA >>>>		6	Lane-Type	NA	NA	NA	
			6	SU6	1.456	50.596	50
inal Loa	d Rating Res	ults	7/8	SU7	1.396	54.095	54
III.	w reading read					·	

Rating Factor

2.517

1.745

For LRFR Only when Span => 200 ft. or Superstructure is Continuous, Input a RF for Lane Type Vehicle Otherwise Input NA >>>>

Final Load Rating Results

The stringers were assumed to not have lateral support of the top flange since deck is attached by clips and some clips are missing. The floor beams were given lateral supports at the stringer locations.

The axial compression of the end post diagonal controls the truss load rating. The stringers are controlled by the flexure near midspan of the 1st interior stringer.

The bridge's H-20 inventory load rating is controlled by the flexure near midspan of the interior floor beam 8.

The load capacity was determined using Load Factor Rating (LFR) Analysis according to the Manual of Bridge Evaluation 6B.4.1. Based on the assumptions made using plans, and existing conditions, we recommend a load limit of:


L.R. Program: AASHTOWare BrR	Prog	ram Version: 6.8.3	3	L.R. Method: LFR	
Rating Version: Deterioration	Deterioration:	Yes Click Box	Contract No.:	Proj. No.:	Des. No:
66B. Inventory (H):21 TON	S 66.	Inventory:	37 TONS	64. Operating:	62 TONS
65. Inventory LR Method:	1-Load Fad	ctor Rating (LFR)	63. Operating LR Method	od:1-Loa	ad Factor Rating (LFR)
41. Open,Posted,Closed:		A Open	31. Design Load:		5-HS 20
66C. Tons Posted:		TONS	70. Bridge Posting:	5-Equal to	or Above Legal Loads

66D. Date Posted/Closed: Toll Road: No / not within 15 mi Extra Heavy Duty Hwy.: No- Do Not Check Box This load rating is based upon the routine inspection conducted on 3/11/2020

6/15/2020

Date

I hereby certify that this report was prepared by me or under my direct personal supervision and that I am a duly Registered Professional Engineer under the laws of the State of Indiana.





MONROE COUNTY BRIDGE NO. 00913 - BUSINESS 37 NORTH OVER BEANBLOSSOM CREEK

APPROACH AND ELEVATION PHOTOS



APPROACH LOOKING NORTH



APPROACH LOOKING SOUTH




ELEVATION LOOKING WEST



TACK WELD SOUTHWEST L3

MONROE 913





MONROE COUNTY BRIDGE NO. 00913 - BUSINESS 37 NORTH OVER BEANBLOSSOM CREEK

ADDITIONAL PHOTOS



WEST L4 CONDITION



L4U3 NORTHWEST PAINT PEELING




L2U3 NORTHWEST PAINT PEELING



NORTH BRIDGE JOINT

ADDITIONAL PHOTOS AVAILABLE



* TYP. ALL BEAMS EXCEPT EAST EXT. BM.

CROSS SECTION



MONROE COUNTY BRIDGE NO. 00913 - BUSINESS 37 NORTH OVER BEANBLOSSOM CREEK

IDE	NTIFICATION			
2.	District:05 - SEYMOUR	3.	County:	053 - MONROE
4.	City:00000 - N/A	8.	NBI Number:	5300130
5.	Inventory Rte. On:141000370	9.	Location:	0.1 MILE SOUTH OF I-69
6.	Features Intersected:BEANBLOSSOM CREEK	16.	Latitude:	•
7.	Facility Carried:BUSINESS 37 NORTH	17.	Longitude:	86.54079 deg
STF	RUCTURE TYPE AND MATERIAL			
43.	Main Str. Type:310 - STEEL TRUSS	45.	Number of Spans-Main:	1
44.	Str. Type-Approach:000 - NONE	46.	Number of Spans-Appr.:	0000
108A	A. Wearing Surface:3 - LATEX CONCRETE	108E	. Membrane:	9 - OTHER
107.	Deck Structure Type:2 - CONCRETE PRECAST	1080	Protection:	9 - OTHER
AGI	E AND SERVICE			
	Year Built:	106.	Reconstructed:	1986
	Lanes On Structure:		Lanes Under Structure:	
	ADT:		ADT-Year:	
	Future ADT:		Future ADT-Year:	
	Average Truck Traffic:5 %		Detour Length:	
GE	OMETRIC DATA			
	Max. Span Length:125 ft.	10	Structure Length:	100.04
48. 50.	Sidewalk/Curb: LT:0 ft.; RT:0 ft.		Appr. Rdwy. Width:	
50. 51.	Bridge Rdwy. Width:	_	Deck Width (o-o):	
31. 47.	Total Hor, ClOver: 28 ft.		Skew:	
33.	Bridge Median:	_	Min. Vert. Clearance:	9
53.	Min. Vert. Clear. over Br. Rdwy:		Min. Underclearance:	
55. 56.	Min. Lateral Left:0 ft.			
	VIGATION DATA	, 552.		
38.	Navigation Control:	116.	Vertical Clearance - Lift Bridge:	
CL A	ASSIFICATION			
	<u> </u>	140	5 151 11	
	Highway System of Inventory Route:			
26.	Func. Class. of Inv. Route:06 - RURAL - MINOR ARTERIAL			
37.	Historical Significance:2 - ELIGIBLE FOR NAT. REG.	110.	Des. Nat. Network:	0
INS	PECTIONS			
90.	Inspection Date:4/28/2022	91.	Des. Inspection Frequency:	24 Mos.
92.	Crit. Feat. Inspection: AY24	B.	N	CN
93.	Crit. Feat. Insp. Date: A4/28/2022	B.		C
LOA	AD RATING AND POSTING			
31.	Design Load:5 - HS 20	41.	Open, Posted or Closed:A	- OPEN. NO RESTRICTIONS
63.	Operating LR Method:1 - LOAD FACTOR		Gross Tons or H Rating:	
65.	Inventory LR Method:1 - LOAD FACTOR		Inventory Rating:	
66C.		64.	Operating Rating:	
	Date Posted/Closed:	70.	Bridge Posting:5 - EQUAL T	
APF	PRAISAL			
67.	Structural:	36A	Bridge Railings:	0 - NOT ACCEPTARI F
68.	Geometry:		Bridge Railing Transitions:	
69.	Underclearance:N		Approach Guardrail:	
71.	Waterway Adequacy:9 - APPEARS ADEQUATE.		Guardrail End Treatments:	
		1		



	MONROE COUNTY BRIDGE NO. 00913 - BUSIN	ESS	37 NORTH OVER BEANBLOSS	OM CREEK
PR(OPOSED IMPROVEMENTS			
75.	Type of Work:35 - REHABILITATION 1 - CONTRACT		• •	
76.	Improvement Length:127 ft.			
97.	Year of Cost Estimate:2022	96.	Total Improvement Costs:	\$1600 x1,000
	osed Work:			
	IABILITATE STRUCTURE DUE TO CONDITION AND LOAD BY REF IBERS, RESET SOUTH ROCKER BEARINGS, CONSTRUCT NEW (ISS.			
Prop	osed Maintenance:		Maintenance Costs:	\$46 x1.000
UNT	IL REHABILITATED, INSTALL CURRENT STANDARD BRIDGE ANI NTS. PROVIDE REGULAR CLEANING OF TRUSS AND BEARINGS.) APF		
CO	NDITION			
58.0	1. Wearing Surface:5 - F	AIR		
	INCH CONCRETE OVERLAY - EAST COPING SPALLED AT FLOO ME PATCHED WITH BITUMINOUS.	R BE	AMS. AREAS DELAMINATED WITH SOM	E MINOR SPALLS AND
58.	Deck:	AIR		
	STRESSED CONCRETE PANELS - AREAS OF MINOR BRIDGE RA		MAGE. LEAKING BETWEEN PANELS. T	RANSVERSE CRACKS
UNE	IIDDLE OF DECK AND AT EDGES OF PRECAST DECK PANELS. F DERSIDE OF 3RD FULL PANEL IN BAY 5 HAS MULTIPLE DELAMIN IELS ARE MISSING BEAM CONNECTION CLIPS. EAST DECK COP	ATIO	NS AND LARGE SPALL WITH 3 STRAND	
59.	Superstructure:5 - F	AIR	59.01. Paint Rating:5 - F	AIR
PITT BRA STR	EL PONY TRUSS WITH STEEL FLOOR SYSTEM - EAST EXTERION ING AND MINOR SECTION LOSS ON INSIDE OF FLANGES, TOP COLOR CONNECTIONS WITH MODERATE TO HEAVY SECTION LOW INGERS AND FLOOR BEAMS. SEE FRACTURE CRITICAL REPORMERLY ROTATED TO THE SOUTH AND MAY HAVE SEIZED.	OF W SS. A	EB, AND RIVET HEADS OF LOWER CHO REAS OF SURFACE RUST AND MINOR	ORDS. LATERAL EXPANSION RUST ON
60.	Substructure:6 - SATISFACTO	DRY		
BRII	ICRETE ABUTMENTS ON TIMBER PILING - LEAKING ON ABUTME DGE CORNER WITH 3 TO 6 INCHES OF SECTION LOSS. NORTHE DSION AT SOUTHWEST AND NORTHEAST WINGS.			
61.	Channel:		N 6040 NO MA IOD DEFINIENDIES NOT	
SILI	FLOWLINE - NATURAL BANKS - TREES AT EAST COPING TRIMI	MEDI	N 2018. NO MAJOR DEFICIENCIES NOT	ED.
62.	Culvert:N - NOT APPLICA	BLE		
NOT	APPLICABLE.			
113.	<u> </u>	N. B	Y ASSESS., CALC. OR DESIGNED COUN	ITERMEASURES
NO I	MAJOR SCOUR VISIBLE.			

Roadway Alignment:8 - NO REDUCTION

BITUMINOUS APPROACHES - IN HORIZONTAL AND SAG CURVES, MERGING TRAFFIC TO NORTH - IMPACT DAMAGE TO SOUTHEAST BRIDGE RAIL TRANSITION AND DAMAGE TO NORTHEAST BRIDGE RAILING.

Sufficiency Rating:52.7 - FUNCTIONALLY OBSOLETE



MONROE COUNTY BRIDGE NO. 00913 - BUSINESS 37 NORTH OVER BEANBLOSSOM CREEK



OVERLAY SPALL NORTH END



OVERLAY SPALL MIDSPAN WEST COPING



SOUTH BRIDGE JOINT



DAMAGED EAST GUARDRAIL



OVER ROTATED EXPANSION BEARING



MODERATE SECTION LOSS IN WEB AT NELO



MONROE COUNTY BRIDGE NO. 00913 - BUSINESS 37 NORTH OVER BEANBLOSSOM CREEK



NORTHWEST ABUTMENT 2 SPALL IN MUDWALL



SPALL WITH EXPOSED REINFORCEMENT IN DECK



EXPANSION RUST AND SECTION LOSS AT NELO



SEL1 INTERIOR ANGLE SECTION LOSS



SEL1 EXTERIOR GUSSET PLATE SECTION LOSS



SEL2L1 INTERIOR GUSSET PLATE SECTION LOSS AT DIAGONAL END



MONROE COUNTY BRIDGE NO. 00913 - BUSINESS 37 NORTH OVER BEANBLOSSOM CREEK



SEL2L1 EXTERIOR GUSSET PLATE SECTION LOSS AT DIAGONAL END



EL4 WEB CONNECTION SEVERED FROM LOW CHORD



TYPICAL LOW CHORD SPLICE



NEL1 60% SECTION LOSS ON INTERNAL FLANGE OF VERTICAL



TYPICAL DETERIORATION OF EXTERNAL SWAY
BRACING



TYPICAL FLOOR BEAM DETERIORATION AT TOP FLANGE



MONROE COUNTY BRIDGE NO. 00913 - BUSINESS 37 NORTH OVER BEANBLOSSOM CREEK



TYPICAL FLOOR BEAM DETERIORATION AT BOTTOM FLANGE



TYPICAL HEAVY SECTION LOSS OF STAY PLATES AND LATTICE BARS ON END POST



APPENDIX F Fracture Critical Inspection Report



MONROE COUNTY

FRACTURE CRITICAL INSPECTION REPORT BRIDGE NO. 913 PHASE I 2022



PREPARED FOR:

PREPARED BY: BEAM, LONGEST & NEFF

MONROE COUNTY, INDIANA

MONROE COUNTY, INDIANA BRIDGE INVENTORY RATING AND SAFETY INSPECTION FRACTURE CRITICAL REPORT

MONROE COUNTY BOARD OF COMMISSIONERS

Julie Thomas

Lee Jones

Penny Githens

Catherine Smith - Auditor

Lisa Ridge - Highway Director

Prepared by:



Beam, Longest and Neff, L.L.C.

Consulting Engineers and Land Surveyors 8320 Craig Street Indianapolis, Indiana 46250 317.849.5832 317.841.4280 fax www.b-l-n.com

Certified

Alfred V. Wessling, P.E. Structural Engineer

Date _____




TABLE OF CONTENTS

<u>SECTIO</u>	<u>N</u>	<u>PAGE</u>
ABSTR/	ACT	i
PERSO	ii	
BRIDGE	NUMBER 913	
l.	INTRODUCTION	1
II.	FIELD INVESTIGATION	2
III.	SUMMARY OF INSPECTION RESULTS	3
IV.	NBIS CODING INFORMATION	3
V.	SUMMARY OF RECOMMENDATIONS	3
VI.	FIELD NOTES	3
PHOTO	GRAPHS	34

ABSTRACT

There are three fracture critical structures in Monroe County. Two of these structures are steel pony trusses (bridges 83 and 913) and the other is a steel thru truss (bridge 114). The steel pony trusses range in length from 72' to 127'. The steel thru truss is 100' in length. Plans were available for the original construction and subsequent repairs for Bridge No. 913. Rehabilitation details were also available for Bridge Nos. 83 and 114. In 2019 the Northeast bearing was repaired at Bridge No. 114.

The fracture critical bridge members inspected were non-redundant tension members. An up-close visual inspection was performed to locate possible problem areas in the fracture critical members. If any suspect surface discontinuities were found, a dye penetration test was performed.

STEEL PONY TRUSS BRIDGE NO. 913


All of the connections are in fair to good condition. All of the members are in satisfactory to good condition, with the exception of lower chord member L0L1 and vertical member northeast L1U1 which are in fair condition. Heavy debris had accumulated on the lower chord and at low chord connections.

The evaluation of the field inspection data indicated that the truss had varying amounts of surface rust and pitting. No cracks were found in any of the members or connections.

Aside from the deficiencies listed above, the lower chords and bridge seats of Bridge No. 913 should be cleaned regularly to remove debris. An in-depth fracture critical member inspection is required in two years for Bridge No. 913.

MONROE COUNTY BRIDGE INSPECTION PERSONNEL LISTING AND TEAM LEADER STATEMENT

RESPONSIBILITIES	Project Supervision Team Leader QC Inspection/Report	Project Manager Team Leader Routine Inspections Fracture Critical Insp. Load Ratings Report Development	Team Leader Routine Inspections	Team Leader Routine Inspections	Team Leader Routine Inspections	Krish Balasubramanian, E.I.T
QUALIFICATIONS	P.E. 19700067 Indiana BSAE Purdue University 1991 MSCE Purdue University 1993 Certified Inspection Team Leader, IN000162-2022-LRE 29 Years Bridge Inspection	P.E. 10809520 Indiana BSCE lowa State University 2002 MSCE lowa State University 2004 Certified Inspection Team Leader, IN000227-2022-ATL-F-LRE 17 Years Bridge Inspection	P.E. 11800329 Indiana BSCE Purdue University 2013 MSCE Purdue University 2014 Certified Inspection Team Leader, IN000456-2022-ATL-F-LRE 7 Years Bridge Inspection	BSARE Kansas State University 2015 MSCE Purdue Univeristy 2017 Certified Inspection Team Member, IN000697-2022-ATM 2 Years Bridge Inspection	BSCE PSG College of Technology India 2013 MSCE University of Alaska Fairbanks 2016 Certified Inspection Team Member, IN000696-2021-ATM 6 Years Bridge Inspection 6 Years Bridge Design	Ment Muen Ryan Whilehil Adam J. Clauss, P.E. Ryan T. Whelchel, E.I.T
NAME AND TITLE	Michael L. McCool Jr., P.E. Bridge Department Manager	Alfred V. Wessling, P.E. Senior Bridge Engineer	Adam J. Clauss, P.E. Bridge Engineer	Ryan T. Whelchel, E.I.T Bridge Engineer	Krish Balasubramanian, E.I.T Bridge Engineer	Alfred V. Wessling, P.E.
Load Rating						
Special Detail						Jr., P.E.
Under- water						McCool
Fracture Critical		×				2 7 (McCool Jr., P.E.
Biennial F		×	×	×	×	



I. INTRODUCTION

A. <u>Location and Description</u>

Bridge No. 913 is located 0.1 miles south of Interstate 69. The map location is at E-9. The bridge carries traffic on Business 37 over Bean Blossom Creek. The bridge is located at a latitude of N39°13'54.12" and a longitude of W86°32'26.85".

Bridge No. 913 is a single span steel pony truss. The structure is on an approximate zero degree skew. The structure length is 126.6 feet with a maximum span length of 125 feet. The structure has a clear roadway width of 28 feet. The average daily traffic was estimated to be 11,194 vehicles per day in 2014. The bridge has an H inventory rating of 21 tons and is not posted for load.

B. History

The estimated year of construction for Bridge No. 913 is 1946. The bridge was reconstructed in 1986 and repaired in 1995. An emergency repair of the east exterior stringers was completed in April of 2018.



II. FIELD INVESTIGATION

A. <u>Members to be Inspected</u>

The following truss tension members are considered to be non-redundant, fracture critical bridge members:

- 1. lower chords and lower chord connections
- 2. diagonals and diagonal connections in tension
- 3. verticals and vertical connections in tension
- 4. floor beam connections

The connection rating is based upon the condition of the connection and a \pm 1 foot section of the fracture critical member extending away from the connection.

B. Inspection Procedures

An up-close visual inspection was performed to locate possible problem areas in the fracture critical members.

If any suspect surface discontinuities were found, a dye penetration test would be performed. This test can help locate stringers (long, thin laminations), scams (shallow, thin voids), laminations (flat, subsurface discontinuities), and cracks in the base metal. It is also of use in checking for weld-related cracking and porous groove welds. This was not needed at this bridge.

C. Equipment Required for Inspection

Tools and equipment used to inspect each member or connection included a hard hat, safety glasses, chipping hammer, scraper, wire brush, feeler gauges, calipers, tape measure, flashlight, magnifying glass, swivel mirror, camera, and a punch.

A dye penetration kit was available for a more detailed inspection if needed.

D. Bridge Cleaning Requirements

The bearing areas contained heavy dirt and debris. The bearing areas were cleaned by the inspector utilizing a shovel, hand brush and scraper. Additionally, the lower chords were cleaned by the inspectors due to heavy debris build up. The inspectors used a hand brush and scraper to access the lower chords and connections.

E. <u>Traffic Maintenance Requirements</u>

All members were accessible without the use of a traffic closure. Bridge inspection signs and safety cones were utilized to warn oncoming traffic of the inspection.

F. Date and Conditions of Inspection

Date: 04/28/2022 Temperature: 64° F Conditions: Partly Sunny



G. Other Items

Original and rehabilitation plans were available for the bridge. The Steel truss members are stamped Illinois USA. Field notes and previous inspection reports were also available, in order to monitor the development of any deficiencies at the bridge.

III. SUMMARY OF INSPECTION RESULTS

A. Connections

All of the connections were in satisfactory to good condition with the exception of lower chord connection East and West L4, lower chord connection NEL0L1 and vertical connections SEL1U1 and Northeast L1U1 which are in fair condition. Debris has accumulated at the lower chord connections. No cracks were found

B. Members

All of the members are in satisfactory to good condition, with the exception of lower chord SWL0L1 and vertical member Northeast L1U1 which are in fair condition. Debris has accumulated on the lower chord members. No cracks were found.

IV. NBIS CODING INFORMATION

ITEM	CODE	DESCRIPTION
92A: Fracture Critical Details Inspection (Non-Redundant)	Y24	Fracture critical inspection every 24 months
93A: Fracture Critical Details Inspection Date	04/28/2022	Inspection date, April, 2022

V. SUMMARY OF RECOMMENDATIONS

Programmed Repairs: The truss's lower chord connections and members should be cleaned regularly to remove debris. Trees and vegetation should be cleared under and around the bridge. The bearings should be reset. The joints should be repaired. An in-depth fracture critical member inspection is required in two years.

Urgent Repairs: None

VI. FIELD NOTES

The following rating system was used to rate the fracture critical members and connections:

- 9 Excellent Condition
- 8 Very Good Condition No noteworthy deficiencies
- 7 Good Condition Some minor problems
- 6 Satisfactory Condition Minor structural deterioration
- 5 Fair Condition Minor section loss
- 4 Poor Condition Advanced section loss, deterioration
- 3 Serious Condition Local failures are possible
- 2 Critical Condition Advanced deterioration of primary elements
- 1 Imminent Failure Condition Major deterioration Structure should be closed
- 0 Failed Condition Out of service Bridge condition beyond corrective action



Connection at Southwest L0:

MEMBER	FATIGUE CAT.	RATING	REMARKS
Lower Chord (L0L1)	D	6	Surface rust and moderate pitting. Areas of heavy pitting with about 20% section loss on web. Heavy section loss in end 6 inches of web. Approximately 15% section loss of top exterior flange on inside face. Expansion rust at lateral bracing connection. Areas of paint peeling. Less than 10% total section loss. No cracks evident.
Diagonal (L0U1)	D	7	Light surface rust and minor pitting. Surface rust on inside faces. Bottom stay plate and lateral bracing have heavy expansion rust with section loss. Less than 5% total section loss. No cracks evident.
Bearing (expansion)	D	6	Light surface rust and minor pitting. Minor section loss and expansion rust between angles and gusset plates. Interior anchor nuts have moderate to heavy pitting. Bearing near limit of rotation. Less than 10% total section loss. No cracks evident.
Floor Beam	D	6	Light surface rust and minor pitting. Bottom flange coped. Minor expansion rust at bottom connection angle. Areas of moderate pitting and minor expansion rust on bottom flange. Moderate pitting on south face of floor beam web. Less than 5% total section loss. No cracks evident.



Connection at Southwest L1:

MEMBER	FATIGUE	RATING	REMARKS
	CAT.		
Lower Chord (L1L0) (continuous)	D	6	Light surface rust and minor pitting. Areas of heavy pitting with minor section loss on top surfaces. Plug weld is present on inside flange. Minor expansion rust between gusset plate and flanges with minor section loss. Expansion rust at lateral bracing connection. Less than 10% total section loss. No cracks evident.1/2" section loss of flange tip interior bottom flange.
Lower Chord (L1L2) (continuous)	D	6	Light surface rust and minor pitting. Areas of heavy pitting with minor section loss on top surfaces. Plug weld is present on inside flange. Minor expansion rust between gusset plate and flanges with minor section loss. Expansion rust at lateral bracing connection. Less than 10% total section loss. No cracks evident.
Vertical (L1U1)	D	6	Light surface rust and minor pitting. Minor expansion rust and section loss at floor beam connection on inside flange and at exterior lateral bracing. 20% section loss at inside flange at plate connection. Less than 10% total section loss. No cracks evident.
Floor Beam	D	6	Light surface rust and minor pitting. Minor expansion rust at web with about 10% section loss of top flange at gusset plate. Less than 5% total section loss. No cracks evident.



Connection at Southwest L2:

MEMBER	FATIGUE CAT.	RATING	REMARKS
Lower Chord (L2L1) (Splice)	D	6	Light surface rust and minor pitting. Areas of surface rust. Areas of heavy pitting on top surfaces and on rivets. 10% section loss of flange and interior gusset plate at connection. Minor out of plane distortion of interior gusset plate due to expansion rust. Expansion rust between splice plate and chord web. Expansion rust at lower lateral bracing connection. Less than 10% total section loss. No cracks evident.
Lower Chord (L2L3)	D	6	Light surface rust and minor pitting. Areas of surface rust. Areas of heavy pitting on top surfaces and on rivets. 10% section loss of flange and interior gusset plate at connection. Minor out of plane distortion of interior gusset plate due to expansion rust. Expansion rust at low lateral bracing connection. Less than 10% total section loss. No cracks evident.
Vertical (L2U2)	D	6	Light surface rust and minor pitting. Areas of heavy pitting and minor section loss on inside flange under railing connection, on web at lower chord splice and on vertical connection plates. Minor out of plane distortion from impact damage below rail on interior flange. Interior gusset plate has heavy section loss on top of north side. Less than 10% total section loss. No cracks evident.
Diagonal (L2U1)	D	6	Light surface rust and minor pitting. Areas of moderate pitting and minor expansion rust at inside gusset plate. Moderate to heavy pitting in gusset plate at end of member. Less than 5% total section loss. No cracks evident.
Diagonal (L2U3)	D	6	Light surface rust and minor pitting. Surface rust on bottom rivets. Areas of heavy pitting and minor expansion rust on interior faces of gusset plate at end of member. Tack welds on top flange edges. Less than 5% total section loss. No cracks evident. Heavy pitting in diagonal at end of connection plate on interior side.
Floor Beam	D	6	Light surface rust and minor pitting. Expansion rust at all floor beam connections. 10% section loss of top flange at gusset plate. Less than 5% total section loss. No cracks evident.



Connection at Southwest L3:

MEMBER	FATIGUE	RATING	REMARKS
	CAT.		
Lower Chord (L3L2) (continuous)	D	6	Light surface rust and minor pitting. Areas of moderate pitting and minor section loss on top surfaces and on rivets. Expansion rust on lateral bracing connection. Less than 10% total section loss. No cracks evident.
Lower Chord (L3L4) (continuous)	D	6	Light surface rust and minor pitting. Areas of moderate pitting and minor section loss on top surfaces and on rivets. Expansion rust on lateral bracing connection. Less than 10% total section loss. No cracks evident.
Vertical (L3U3)	D	6	Light surface rust and minor pitting. Areas of heavy pitting on inside flange and web below bridge rail. Moderate expansion rust at inside flange and lower chord connection. Less than 10% total section loss. No cracks evident. Tack weld on southwest and northwest edge between gusset and fill plate.
Floor Beam	D	6	Light surface rust and minor pitting. Minor expansion rust at all floor beam connections. 10% section loss of top flange at gusset plate. Less than 5% total section loss. No cracks evident.



Connection at West L4:

MEMBER	FATIGUE CAT.	RATING	REMARKS
Lower Chord (Southwest L4L3)	D	5	Light surface rust and minor pitting. Areas of heavy pitting and minor section loss on top surfaces and on rivets. Expansion rust and moderate pitting at gusset plate at lower lateral bracing connection. 25% section loss on top interior web angle. 10% section loss on gusset plates. Less than 15% total section loss. No cracks evident. Out of plane displacement exterior gusset plate due to expansion rust.
Lower Chord (Northwest L4L3) (Splice)	D	5	Light surface rust and minor pitting. Areas of heavy pitting and minor section loss on top surfaces and on rivets. Moderate to heavy section loss on rivets at splice. Expansion rust and moderate pitting at gusset plate at lower lateral bracing connection. 25% section loss on top interior web angle. 10% section loss on gusset plates. Less than 15% total section loss. No cracks evident.
Vertical (L4U4)	D	6	Light surface rust and minor pitting. Inside flange at vertical connection plate and interior North face of gusset plate with heavy expansion rust and moderate to heavy section loss. 10% section loss of interior flange. Less than 5% total section loss. No cracks evident.
Diagonal (Southwest L4U3)	D	6	Light surface rust and minor pitting. Areas of heavy pitting on inside flange at filler plate. Minor pitting in interior gusset plate at end of member. Less than 5% total section loss. No cracks evident.
Diagonal (Northwest L4U3)	D	6	Light surface rust and minor pitting. Areas of moderate pitting on inside flange at filler plate. Minor pitting in exterior gusset plate and moderate pitting in interior gusset plate at end of member. Less than 5% total section loss. No cracks evident.
Floor Beam	D	6	Light surface rust and minor pitting. Expansion rust at all floor beam connections. Areas of moderate pitting on bottom flange of web. 10% section loss of top flange at gusset plate. Less than 5% total section loss. No cracks evident.

Notes: Moderate expansion rust on south lower lateral bracing and north lower lateral bracing is severed.



Connection at Northwest L3:

MEMBER	FATIGUE CAT.	RATING	REMARKS
Lower Chord (L3L4) (continuous)	D	6	Light surface rust and minor pitting. Areas of heavy pitting and minor section loss on top surfaces and on rivets. Expansion rust at lower lateral bracing connection. Less than 10% total section loss. No cracks evident. Plug weld interior flange.
Lower Chord (L3L2) (continuous)	D	6	Light surface rust and minor pitting. Areas of heavy pitting and minor section loss on top surfaces and on rivets. Expansion rust at lower lateral bracing connection. Less than 10% total section loss. No cracks evident. Plug weld interior flange.
Vertical (L3U3)	D	6	Light surface rust and minor pitting. Areas of heavy pitting on inside flange and web below railing connection. Less than 5% total section loss. No cracks evident. Tack welds between gusset plate and fill plate (exterior) both north and south sides.
Floor Beam	D	7	Light surface rust and minor pitting. Expansion rust at top flange connection. 10% section loss of top flange at gusset plate. Less than 5% total section loss. No cracks evident.



Connection at Northwest L2:

MEMBER	FATIGUE CAT.	RATING	REMARKS
Lower Chord (L2L3)	D	6	Light surface rust and minor pitting. Areas of heavy pitting on top surfaces and on rivets. Expansion at lower lateral bracing connection. Minor section loss at gusset plate. Less than 10% total section loss. No cracks evident. Minor out of plane displacement interior/exterior gusset plate due to expansion rust.
Lower Chord (L2L1) (Splice)	D	6	Light surface rust and minor pitting. Areas of heavy pitting on top surfaces and on rivets. Expansion rust at splice plates and lower lateral bracing connection. Minor section loss at gusset plate. Less than 10% total section loss. No cracks evident.
Vertical (L2U2)	D	6	Light surface rust and minor pitting. Areas of heavy pitting on inside flange under railing connection and at vertical connection. Less than 10% section loss of interior flange. Approximately 15% section loss of rivets at connection angle with lower chord. Less than 5% total section loss. No cracks evident.
Diagonal (L2U1)	D	7	Light surface rust and minor pitting. Minor section loss on rivets. Minor expansion rust at filler plates. Moderate pitting in both gusset plates at end of member. 5% total section loss. No cracks evident.
Diagonal (L2U3)	D	6	Light surface rust and minor pitting. Minor pitting on inside flange at filler plate and on top of web. Less than 5% total section loss. No cracks evident. Minor expansion rust between gusset plate and diagonal member.
Floor Beam	D	6	Light surface rust and minor pitting. Minor expansion rust and section loss at all floor beam connections. 10% section loss of top and bottom flanges at gusset plate. Less than 5% total section loss. No cracks evident.



Connection at Northwest L1:

MEMBER	FATIGUE CAT.	RATING	REMARKS
Lower Chord (L1L2) (Continuous)	D	6	Light surface rust and minor pitting. Areas of heavy pitting on top surfaces and on rivets. Expansion rust at lower lateral brace connection. Less than 10% section loss at top flange edges at gusset plates. Plug weld on inside of flange. Less than 5% total section loss. No cracks evident.
Lower Chord (L1L0) (Continuous)	D	6	Light surface rust and minor pitting. Areas of heavy pitting on top surfaces and on rivets. Expansion rust at lower lateral brace connection. Less than 10% section loss at top flange edges at gusset plates. Plug weld on inside of flange. Less than 5% total section loss. No cracks evident.
Vertical (L1U1)	D	6	Light surface rust and minor pitting. Minor pitting at flanges at top of floor beam connection and top of external lateral bracing connection. Less than 5% total section loss. No cracks evident.
Floor Beam	D	6	Light surface rust and minor pitting. Minor expansion rust at all floor beam connections. 10% section loss of top flange at gusset plate. Less than 5% total section loss. No cracks evident.

Connection at Northwest L0:

MEMBER	FATIGUE CAT.	RATING	REMARKS
Lower Chord (L0L1)	D	6	Light surface rust and minor pitting. Areas of moderate pitting on top surfaces. Less than 5% total section loss. No cracks evident.
Diagonal (L0U1)	D	7	Light surface rust and minor pitting. Area of paint peeling and surface rust. Less than 5% total section loss. No cracks evident.
Bearing (fixed)	D	7	Light surface rust and minor pitting. Moderate pitting at interior base plate nuts. Tack welds at connection angle and gusset plate. Areas of surface rust. Less than 5% total section loss. No cracks evident.
Floor Beam	D	7	Light surface rust and minor pitting. Bottom flange coped. Minor expansion rust at top and bottom flanges and web. Less than 5% total section loss. No cracks evident.



Connection at Southwest U1:

MEMBER	FATIGUE CAT.	RATING	REMARKS
Vertical (L1U1)	D	7	Light surface rust and minor pitting. No section loss. No cracks evident.
Diagonal (L2U1)	D	7	Light surface rust and minor pitting. Minor expansion rust at interior gusset plate. Less than 5% total section loss. No cracks evident.

Connection at Southwest U2:

MEMBER	FATIGUE CAT.	RATING	REMARKS
Vertical (L2U2)	D	7	Light surface rust and minor pitting. No section loss. No cracks evident. Tack welds between fill plate and vertical, all sides.

Connection at Southwest U3:

MEMBER	FATIGUE CAT.	RATING	REMARKS
Vertical (L3U3)	D	7	Light surface rust and minor pitting. Minor surface rust at gusset plates. Areas of paint bubbling and peeling. No section loss. No cracks evident.
Diagonal (L4U3)	D	7	Light surface rust and minor pitting. Minor surface rust at gusset plates. Areas of paint bubbling and peeling. No section loss. No cracks evident.
Diagonal (L2U3)	D	7	Light surface rust and minor pitting. Minor surface rust at gusset plates. Areas of paint bubbling and peeling. No section loss. No cracks evident.

Connection at West U4:

MEMBER	FATIGUE CAT.	RATING	REMARKS
Vertical (L4U4)	D	7	Light surface rust and minor pitting. Tack welds at filler plate and flange edges. No section loss. No cracks evident.



Connection at Northwest U3:

MEMBER	FATIGUE CAT.	RATING	REMARKS
Vertical (L3U3)	D	7	Light surface rust and minor pitting. Minor surface rust at gusset plate. Areas of paint peeling. No section loss. No cracks evident.
Diagonal (L4U3)	D	7	Light surface rust and minor pitting. Minor surface rust at gusset plate. No section loss. No cracks evident. Areas of paint bubbling.
Diagonal (L2U3)	D	7	Light surface rust and minor pitting. Minor surface rust at gusset plate. Areas of paint peeling. No section loss. No cracks evident.

Connection at Northwest U2:

Commodicit de Nordinivose C2.			
MEMBER	FATIGUE CAT.	RATING	REMARKS
Vertical (L2U2)	D	7	Light surface rust and minor pitting. Tack welds at flange edges. Minor damage to northwest flange tip near connection. No section loss. No cracks evident.

Connection at Northwest U1:

MEMBER	FATIGUE CAT.	RATING	REMARKS
Vertical (L1U1)	D	7	Light surface rust and minor pitting. Minor section loss on rivets. No section loss. No cracks evident. Minor paint bubbling. Moderate pitting in gusset plate at end of member.
Diagonal (L2U1)	D	7	Light surface rust and minor pitting. Minor section loss on rivets. Areas of paint peeling. No section loss. No cracks evident. Moderate pitting in gusset plate at end of member.



West Truss Members:

MEMBER	FATIGUE CAT.	RATING	REMARKS
Lower Chord (Southwest L0L1)	В	5	Surface rust and moderate pitting. Areas of heavy pitting on top surfaces and moderate pitting at bottom of drain holes. One drain hole is 2 inch by 3.5 inch and has heavy pitting on underside. Less than 10% total section loss. No cracks evident.
Lower Chord (Southwest L1L2) (Spliced)	D	6	Light surface rust and minor pitting. Areas of heavy pitting on top surfaces and moderate pitting at bottom of drain holes. Minor expansion rust at web splice plate with minor section loss of rivets at splice. Less than 5% total section loss. No cracks evident.
Lower Chord (Southwest L2L3)	А	6	Light surface rust and minor pitting. Areas of heavy pitting on top surfaces and moderate pitting at bottom of drain holes. Less than 5% total section loss. No cracks evident.
Lower Chord (Southwest L3L4)	А	6	Light surface rust and minor pitting. Areas of heavy pitting on top surfaces and moderate pitting at bottom of drain holes. Less than 5% total section loss. No cracks evident.
Lower Chord (Northwest L3L4) (Spliced)	D	6	Light surface rust and minor pitting. Areas of heavy pitting on top surfaces and moderate pitting at bottom of drain holes. Heavy expansion rust and section loss of splice plate and rivets at splice in web only. Less than 5% total section loss. No cracks evident.
Lower Chord (Northwest L2L3)	А	6	Light surface rust and minor pitting. Areas of heavy pitting on top surfaces and moderate pitting at bottom of drain holes. Less than 5% total section loss. No cracks evident.
Lower Chord (Northwest L1L2) (Spliced)	D	6	Light surface rust and minor pitting. Areas of heavy pitting on top surfaces and moderate pitting at bottom of drain holes. Moderate expansion rust at splice plate and rivets at splice in web only. Less than 5% total section loss. No cracks evident.
Lower Chord (Northwest L0L1)	А	6	Light surface rust and minor pitting. Areas of heavy pitting and minor section loss on top surfaces and moderate pitting at bottom of drain holes. Less than 5% total section loss. No cracks evident.



West Truss Members (Continued):

west truss Members (Continued):				
MEMBER	FATIGUE	RATING	REMARKS	
	CAT.			
Vertical	В	7	Light surface rust and minor pitting. Less than	
(Southwest L1U1)			5% total section loss. No cracks evident. Paint	
			peeling.	
Vertical	В	6	Light surface rust and minor pitting. Areas of	
(Southwest L2U2)			surface rust and moderate pitting. Minor out of	
			plane distortion of interior flange under bridge	
			rail connection. Less than 5% total section loss.	
			No cracks evident. Paint peeling.	
Vertical	В	6	Light surface rust and minor pitting. Areas of	
(Southwest L3U3)			heavy pitting, minor expansion rust, and surface	
			rust. Less than 5% total section loss. No cracks	
			evident. Paint peeling.	
Vertical	В	7	Light surface rust and minor pitting. Areas of	
(West L4U4)			surface rust and moderate pitting. Less than 5%	
			total section loss. No cracks evident. Paint	
			peeling.	
Vertical	В	7	Light surface rust and minor pitting. Areas of	
(Northwest L3U3)			surface rust and moderate pitting. Less than 5%	
			total section loss. No cracks evident. Paint	
			peeling.	
Vertical	В	7	Light surface rust and minor pitting. Areas of	
(Northwest L2U2)			moderate pitting. Areas with paint bubbling and	
			peeling. Less than 5% total section loss. No	
			cracks evident.	
Vertical	В	7	Light surface rust and minor pitting. Less than	
(Northwest L1U1)			5% total section loss. No cracks evident. Paint	
			peeling.	



West Truss Members (Continued):

MEMBER	FATIGUE	RATING	REMARKS
Diagonal (Southwest L2U1)	B	6	Light surface rust and minor pitting. Areas of moderate pitting below railing on interior flange. Less than 5% total section loss. No cracks evident.
Diagonal (Southwest L2U3)	В	6	Light surface rust and minor pitting. Areas of surface rust and moderate pitting. Minor expansion rust with moderate pitting on underside surfaces. Less than 5% total section loss. No cracks evident. Significant paint peeling.
Diagonal (Southwest L4U3)	В	6	Light surface rust and minor pitting. Areas of surface rust and moderate pitting. Less than 5% total section loss. No cracks evident. Significant paint peeling.
Diagonal (Northwest L4U3)	В	6	Light surface rust and minor pitting. Areas of surface rust and moderate pitting. Less than 5% total section loss. No cracks evident. Significant paint peeling.
Diagonal (Northwest L2U3)	В	6	Light surface rust and minor pitting. Areas of surface rust and moderate pitting. Less than 5% total section loss. No cracks evident. Paint peeling.
Diagonal (Northwest L2U1)	В	6	Light surface rust and minor pitting. Areas of surface rust, minor expansion rust, and moderate pitting. Less than 5% total section loss. No cracks evident. Paint peeling.

Note: Heavy debris accumulation on lower chords with water ponding in lower chord webs. There are large areas of paint peeling on members.



Connection at Southeast L0:

		RATING	REMARKS
MEMBER	FATIGUE CAT.	RATING	REMARNS
Lower Chord (L0L1)	О	6	Surface rust and moderate pitting. Heavy pitting on top and bottom of web and insides of flanges with minor section loss. Moderate section loss at web drain hole. Expansion rust at web near connection ends of gusset plate. Expansion rust at lower lateral bracing connection. Less than 15% total section loss. No cracks evident.
Diagonal (L0U1)	D	6	Light surface rust and minor pitting. Heavy pitting on web on interior channel on inside face near bottom flange. Minor expansion rust at gusset plate and top flange of interior channel on inside face. Less than 5% section loss. No cracks evident.
Bearing (expansion)	D	5	Light surface rust and minor pitting. Rocker expanded nearly to maximum extent. Heavy pitting on interior nuts, washers and areas around the connection. Expansion rust at bearing plate below lower chord. Interior stay plate has section loss and moderate section loss of nuts. Less than 10% total section loss. No cracks evident.
Floor Beam	D	6	Light surface rust, minor pitting and expansion rust on top flange. Moderate expansion rust and section loss on top and bottom flanges, especially at bottom of web on the mudwall side. Less than 5% total section loss. No cracks evident.



Connection at Southeast L1:

MEMBER	FATIGUE CAT.	RATING	REMARKS
Lower Chord (L1L0) (continuous)	О	6	Surface rust and heavy pitting. Gusset plate and angle connection with expansion rust and section loss. Minor out of plane distortion at angle connection. Section loss of inside of flanges and top of web. Plug welds in interior flange. Expansion rust at lower lateral bracing connection. Less than 10% total section loss. No cracks evident.
Lower Chord (L1L2) (continuous)	О	6	Surface rust and heavy pitting. Gusset plate and angle connection with expansion rust and section loss. Minor out of plane distortion at angle connection. Section loss of inside of flanges and top of web. Plug welds in interior flange. Moderate expansion rust at lateral bracing connection. Less than 10% total section loss. No cracks evident.
Vertical (L1U1)	D	5	Surface rust and moderate pitting. Heavy pitting and 25% section loss on the interior angle of member at connection. Approximately 0.25 inch hole in web. Heavy expansion rust on lower lateral bracing. 10% section loss of gusset plate at exterior connection. Less than 15% total section loss. No cracks evident.
Floor Beam	D	6	Surface rust and moderate pitting. Flanges with moderate expansion rust and less than 10% section loss. Expansion rust and minor section loss at gusset plate and floor beam connection edges. Less than 5% total section loss. No cracks evident.



Connection at Southeast L2:

MEMBER	FATIGUE CAT.	RATING	REMARKS
Lower Chord (L2L1) (Splice)	D	5	Light surface rust and heavy pitting. Heavy pitting on top of web and inside top flanges with minor section loss. Expansion rust and section loss at splice plate connection. Section loss on rivets. Areas with approximately 30% section loss in gusset plate on inside faces at ends of L2U1diagonals. Less than 10% total section loss. No cracks evident.
Lower Chord (L2L3)	D	5	Light surface rust and heavy pitting. Heavy pitting on top of web and inside top flanges with minor section loss. Minor section loss on rivets. Less than 10% total section loss. No cracks evident.
Vertical (L2U2)	D	6	Light surface rust and minor pitting. Some areas of heavy pitting on web faces at end of members. Areas of heavy expansion rust on external sway bracing. Less than 5% total section loss. No cracks evident.
Diagonal (L2U1)	D	6	Light surface rust. Minor expansion rust and section loss at gusset plate connections. Less than 5% total section loss. No cracks evident.
Diagonal (L2U3)	D	6	Light surface rust. Minor expansion rust and section loss at gusset plate connection. Section loss on inside of gusset plates at end of member. Less than 5% total section loss. No cracks evident.
Floor Beam	D	6	Surface rust and minor pitting. Heavy expansion rust on both flanges and at angle connection and minor expansion rust at web connection. Less than 5% total section loss. No cracks evident.



Connection at Southeast L3:

MEMBER	FATIGUE CAT.	RATING	REMARKS
Lower Chord (L3L2) (Continuous)	D	6	Surface rust and moderate pitting. Moderate to heavy pitting on top of web and inside flange faces with minor section loss. Lower legs on connection plate with section loss and expansion rust at bottom flange. Section loss in gusset plates above top flange ends. Less than 10% total section loss. No cracks evident.
Lower Chord (L3L4) (Continuous)	D	6	Surface rust and moderate pitting. Moderate to heavy pitting on top of web and inside flange faces with minor section loss. Lower legs on connection plate with section loss and expansion rust at bottom flange. Section loss in gusset plates above top flange ends. Less than 10% total section loss. No cracks evident.
Vertical (L3U3)	D	6	Light surface rust and moderate pitting at interior flange on exterior face. Section loss at interior connection angle. Expansion rust at bottom of member. Areas of heavy expansion rust on external sway bracing. Less than 5% total section loss. No cracks evident.
Floor Beam	D	6	Surface rust and minor pitting. Areas of heavy expansion rust and minor section loss at angle connection and at top and bottom flanges of floor beam. Expansion rust at lower lateral bracing connection. Less than 5% total section loss. No cracks evident.



Connection at East L4:

MEMBER	FATIGUE	RATING	REMARKS
	CAT.		
Lower Chord (Southeast L4L3)	D	5	Light surface rust and moderate pitting. Minor out of plane distortion and section loss of gusset plate at interior connection. Areas of 50% section loss on inside of faces of gusset plate at end of SEL4U3 diagonal. Areas of heavy pitting and minor section loss on top of web and inside flange faces. Several rivets with 75% section loss at top flange. Less than 10% total section loss. No cracks evident.
Lower Chord (Northeast L4L3) (Splice)	D	5	Light surface rust and moderate pitting. Expansion rust and section loss at splice plate connection. Section loss at rivet heads in splice plate. Minor out of plane distortion and section loss of gusset plates. Areas of heavy pitting and minor section loss on top of web and inside flange faces. Several rivets with 75% section loss at top flange. Less than 10% total section loss. No cracks evident.
Vertical (L4U4)	D	5	Surface rust at gusset plate connection. Minor section loss and moderate pitting on interior angle connection. Minor section loss at bottom rivets. Areas of heavy expansion rust on external sway bracing. 100% section loss at web connection to lower chord. Less than 10% total section loss. No cracks evident.
Diagonal (Southeast L4U3)	D	6	Light surface rust and minor pitting. Minor section loss on inside flange at gusset plate. Section loss on inside of exterior gusset plate at end of member. Less than 5% total section loss. No cracks evident.
Diagonal (Northeast L4U3)	D	6	Light surface rust and minor pitting. Minor section loss on inside of exterior & interior gusset plate connections. Minor out of plane displacement of exterior gusset plate. Localized areas of heavy pitting and section loss at inside flange. Less than 5% total section loss. No cracks evident.
Floor Beam	D	6	Surface rust and minor pitting. Minor expansion rust and section loss at angle connection with web. Heavy expansion rust on top and bottom flanges. Minor section loss at plate connection. Lower lateral bracing has heavy section loss and expansion rust. Less than 5% total section loss. No cracks evident.



Connection at Northeast L3:

MEMBER	FATIGUE CAT.	RATING	REMARKS
Lower Chord (L3L4) (Continuous)	D	6	Light surface rust and moderate pitting. Minor section loss on some rivets. Areas of heavy pitting and minor section loss on top of web and inside flange faces. Expansion rust on top flanges at connection. Section loss of gusset plate at top of flanges. Less than 10% total section loss. No cracks evident.
Lower Chord (L3L2) (Continuous)	D	6	Light surface rust and moderate pitting. Minor section loss on some rivets. Areas of heavy pitting and minor section loss on top of web and inside flange faces. Expansion rust on top flanges at connection. Section loss of gusset plate at top of flanges. Less than 10% total section loss. No cracks evident.
Vertical (L3U3)	D	5	Light surface rust and moderate pitting. Areas of heavy pitting and 10% section loss on inside flange at angle connection. Areas of heavy expansion rust on external sway bracing. Minor section loss on interior flange at top of floor beam connection. Less than 10% total section loss. No cracks evident.
Floor Beam	D	6	Surface rust and moderate pitting. Areas of heavy expansion rust and section loss at top and bottom floor beam flanges. Minor expansion rust and minor section loss at web and angle connection. Lower lateral bracing has heavy section loss and expansion rust. Less than 5% total section loss. No cracks evident.



Connection at Northeast L2:

MEMBER	FATIGUE CAT.	RATING	REMARKS
Lower Chord (L2L3)	D	6	Light surface rust and heavy pitting. Areas of 15% section loss on inside faces of gusset plate at end of NEL2U3. Localized areas of heavy pitting and minor section loss on top of web and flanges. 40% maximum section loss on rivets. Expansion rust at bottom connection plate. Less than 10% total section loss. No cracks evident.
Lower Chord (L2L1) (Splice)	D	6	Light surface rust and heavy pitting. Expansion rust and minor section loss at splice plate connection. Localized areas of heavy pitting and minor section loss on top of web and flanges. 40% maximum section loss on rivets. Expansion rust at bottom connection plate. Less than 10% total section loss. No cracks evident.
Vertical (L2U2)	D	6	Light surface rust and minor pitting. Areas of moderate pitting at gusset connection with minor section loss. Areas of heavy expansion rust on external sway bracing. Less than 10% total section loss. No cracks evident.
Diagonal (L2U1)	D	6	Light surface rust and minor pitting. Areas of moderate pitting at gusset plate. 15% section loss on interior gusset plate on inside face and 10% section loss on exterior gusset plate on inside face at end of diagonal. 10% section loss on flanges at end of gusset plate. Less than 5% total section loss. No cracks evident.
Diagonal (L2U3)	D	6	Light surface rust and minor pitting. Inside face of gusset plates have heavy pitting and 10% section loss. Minor section loss in connection plate. Less than 5% total section loss. No cracks evident.
Floor Beam	D	6	Surface rust and minor pitting. Areas of heavy expansion rust and section loss at top and bottom flanges. Heavy section loss on some rivets. Expansion rust and minor section loss at web and angle connection. Lower lateral bracing has heavy section loss and expansion rust. South lateral bracing is severed. Less than 5% total section loss. No cracks evident.

Note: Tack welds found on top and bottom of Diagonals L2U1 and L2U3 at ends of stay plate.



Connection at Northeast L1:

MEMBER	FATIGUE	RATING	REMARKS
	CAT.		
Lower Chord (L1L2) (Continuous)	D	6	Light surface rust and moderate pitting. Areas of heavy pitting and minor section loss on top of web and inside flange faces. Moderate pitting on inside face of gusset plates at top of flanges. Rivets have 50% section loss. Moderate expansion rust at bottom connection plate. Less than 10% total section loss. No cracks evident.
Lower Chord (L1L0) (Continuous)	D	6	Light surface rust and moderate pitting. Areas of heavy pitting and minor section loss on top of web and inside flange faces. Moderate pitting on inside face of gusset plates at top of flanges. Rivets have 50% section loss. Moderate expansion rust at bottom connection plate. Less than 10% total section loss. No cracks evident.
Vertical (L1U1)	D	5	Surface rust and heavy pitting. Interior flange at top of angle connection with 60% section loss and two 1 inch holes through flange. Outside flange with 10% section loss. Areas of heavy expansion rust on external sway bracing. Less than 15% total section loss. No cracks evident.
Floor Beam	D	6	Surface rust and minor pitting. Areas of minor expansion rust and minor section loss at angle connection and heavy expansion rust at top and bottom flanges. Less than 5% total section loss. No cracks evident.



Connection at Northeast L0:

MEMBER	FATIGUE CAT.	RATING	REMARKS
Lower Chord (L0L1)	D	5	Surface rust and heavy pitting. Heavy expansion rust and section loss at rivet connection and gusset plate connection. Heavy pitting on top of web and inside flange faces. Drain hole is approximately 5 inches wide by 11 inches due to web section loss. Heavy surface rust with section loss on lower lateral bracing gusset plate. Less than 20% total section loss. No cracks evident.
Diagonal (L0U1)	D	6	Light surface rust and minor pitting. Areas of 15% section loss in interior gusset plate at end of interior end post channel. Heavy section loss and expansion rust on stay plates and lattices on bottom side. Less than 5% total section loss. No cracks evident.
Bearing (fixed)	D	6	Light surface rust and moderate pitting. Heavy pitting and minor section loss at angle connection and gusset plate. Interior nut with serious section loss. Large spall on bridge seat at edge of bearing. Less than 5% total section loss. No cracks evident.
Floor Beam	D	6	Light surface rust and minor pitting at angle connection. Moderate section loss and expansion rust at top and bottom flange. Minor expansion rust at web connection angle. Less than 5% total section loss. No cracks evident.



Connection at Southeast U1:

MEMBER	FATIGUE CAT.	RATING	REMARKS
Vertical (L1U1)	D	7	Light surface rust at gusset connection. Expansion rust on rivets. Areas of paint peeling. Less than 5% total section loss. No cracks evident.
Diagonal (L2U1)	D	7	Light surface rust and minor pitting. Minor expansion rust at exterior flange. Areas of paint chipping. Less than 5% total section loss. No cracks evident.

Connection at Southeast U2:

MEMBER	FATIGUE CAT.	RATING	REMARKS
Vertical (L2U2)	D	7	Light surface rust at rivets and angle connection. Minor expansion rust at exterior flange. Less than 5% total section loss. No cracks evident.

Connection at Southeast U3:

MEMBER	FATIGUE CAT.	RATING	REMARKS
Vertical (L3U3)	D	7	Light surface rust and minor pitting. Less than 5% total section loss. No cracks evident.
Diagonal (L4U3)	D	7	Light surface rust and minor pitting. Less than 5% total section loss. No cracks evident.
Diagonal (L2U3)	D	7	Light surface rust and minor pitting. Less than 5% total section loss. No cracks evident.

Connection at East U4:

MEMBER	FATIGUE CAT.	RATING	REMARKS
Vertical (L4U4)	D	7	Light surface rust and minor pitting. Less than 5% total section loss. No cracks evident.

Connection at Northeast U3:

MEMBER	FATIGUE CAT.	RATING	REMARKS
Vertical (L3U3)	D	7	Light surface rust and minor pitting. Less than 5% total section loss. No cracks evident.
Diagonal (L4U3)	D	7	Light surface rust and minor pitting. Less than 5% total section loss. No cracks evident.
Diagonal (L2U3)	D	7	Light surface rust and minor pitting. Less than 5% total section loss. No cracks evident.



Connection at Northeast U2:

MEMBER	FATIGUE CAT.	RATING	REMARKS
Vertical (L2U2)	D	7	Light surface rust and minor pitting. Less than 5% total section loss. No cracks evident.

Connection at Northeast U1:

MEMBER	FATIGUE CAT.	RATING	REMARKS
Vertical (L1U1)	D	7	Light surface rust and minor pitting. Paint cracking. Less than 5% total section loss. No cracks evident.
Diagonal (L2U1)	D	7	Light surface rust and minor pitting. Paint cracking. Less than 5% total section loss. No cracks evident.

Note: Tack welds found on all upper Diagonal connections at the gusset plate.



East Truss Members:

MEMBER	FATIGUE CAT.	RATING	REMARKS
Lower Chord (Southeast L0L1)	A	6	Light surface rust and moderate pitting. Heavy pitting along inside of lower chord flanges. Section loss on lower chord web near drain holes. Less than 5% total section loss noted. No cracks evident.
Lower Chord (Southeast L1L2)	D	5	Light surface rust and moderate pitting. Localized areas of heavy pitting on outside top of member with minor out of plane distortion of interior flange. Spliced connection plate with moderate expansion rust and pitting of web plate and rivets. Less than 5% total section loss noted. No cracks evident.
Lower Chord (Southeast L2L3	А	6	Light surface rust and moderate pitting. Localized areas of heavy pitting on top of member web and inside of flanges. Less than 5% total section loss noted. No cracks evident.
Lower Chord (Southeast L3L4)	A	6	Light surface rust and moderate pitting. Localized areas of heavy pitting on top of member web and inside of flanges. Less than 5% section loss noted. No cracks evident.
Lower Chord (Northeast L3L4)	D	6	Light surface rust and moderate pitting. Localized areas of heavy pitting on top of member web and inside of flanges. Section loss on rivets at connection. Approximately 7 rivets with 75% section loss. Moderate pitting at top web splice connection plate. Less than 5% total section loss noted. No cracks evident.
Lower Chord (Northeast L2L3)	А	6	Light surface rust and moderate pitting on top of member web and inside of flanges. Localized areas of heavy pitting. Less than 5% total section loss noted. No cracks evident.
Lower Chord (Northeast L1L2)	D	6	Light surface rust and moderate pitting. Localized areas of heavy pitting on top of member web and inside of flanges. Heavy expansion rust and section loss of top web splice connection plate and rivets. Less than 5% total section loss noted. No cracks evident.
Lower Chord (Northeast L0L1)	А	6	Light surface rust and moderate pitting. Localized areas of heavy pitting on top of member web and inside of flanges. Advanced section loss around north drain hole. Less than 5% total section loss noted. No cracks evident.



East Truss Members (Continued):

	viembers (Co		DEMARKS
MEMBER	FATIGUE	RATING	REMARKS
Vertical (Southeast L1U1)	B	6	Light surface rust and minor pitting. Localized areas of moderate pitting of web near deck. Less than 5% total section loss noted. No cracks evident.
Vertical (Southeast L2U2)	В	6	Light surface rust and minor pitting. Localized areas of heavy pitting on web south face. Less than 5% total section loss noted. No cracks evident.
Vertical (Southeast L3U3)	В	6	Light surface rust and minor pitting. Localized areas of moderate pitting at interior flange and south web. Less than 5% total section loss noted. No cracks evident.
Vertical (East L4U4)	Ш	6	Light surface rust and minor pitting. Localized areas of heavy pitting on web south face & 1 on north face. Less than 5% total section loss noted. No cracks evident.
Vertical (Northeast L3U3)	В	7	Light surface rust and minor pitting. No section loss noted. No cracks evident.
Vertical (Northeast L2U2)	В	6	Light surface rust and minor pitting. Localized areas of heavy pitting on web south face with paint peeling. Moderate pitting on north face of web. Less than 5% total section loss noted. No cracks evident.
Vertical (Northeast L1U1)	В	5	Light surface rust and moderate pitting. Areas of heavy pitting on inside of south web with 20% section loss on web. An approximate nickel and 1/4" sized holes in web. Less than 10% total section loss noted. No cracks evident.



East Truss Members (Continued):

MEMBER	FATIGUE	RATING	REMARKS
Diagonal (Southeast L2U1)	САТ. В	7	Light surface rust and minor pitting. Localized areas of moderate pitting at inside of interior flange. Localized areas of surface rust and minor expansion rust on web underside. No section loss noted. No cracks evident.
Diagonal (Southeast L2U3)	В	7	Light surface rust and minor pitting. Areas of minor expansion rust on underside. No section loss noted. No cracks evident.
Diagonal (Southeast L4U3)	В	6	Light surface rust and minor pitting. Localized areas of heavy pitting and surface rust. Section loss on bolt nuts on underside of member. Less than 5% total section loss noted. No cracks evident.
Diagonal (Northeast L4U3)	В	7	Light surface rust and minor pitting. Areas of minor paint peeling on bottom of web. No section loss noted. No cracks evident.
Diagonal (Northeast L2U3)	В	6	Light surface rust and minor pitting. Localized areas of moderate pitting on bottom of web. Section loss on bolt nuts on underside of member. Less than 5% total section loss noted. No cracks evident.
Diagonal (Northeast L2U1)	В	6	Light surface rust and minor pitting. Localized areas of moderate to heavy pitting and expansion rust on underside of flanges and web. Less than 5% total section loss noted. No cracks evident.

Note: Debris accumulation on lower chords with water ponding in lower chord webs. There are large areas of paint peeling on members.



West Truss Gusset Plates:

CONNECTION	THICKNESS	LOCATION/METHOD OF MEASUREMENT
Southwest L0	1/2"	Measured Interior and Exterior Gusset Plate
		at plate edge using calipers.
Southwest L1	7/16"	Measured Exterior Connection Plate at plate
		edge using calipers.
Southwest L2	7/16"	Measured Interior and Exterior Gusset Plate
		at plate edge using calipers.
Southwest L3	7/16"	Measured Exterior Connection Plate at plate
		edge using calipers.
West L4	7/16"	Measured Interior and Exterior Gusset Plate
		at plate edge using calipers.
Northwest L3	7/16"	Measured Exterior Connection Plate at plate
		edge using calipers.
Northwest L2	7/16"	Measured Interior and Exterior Gusset Plate
		at plate edge using calipers.
Northwest L1	7/16"	Measured Exterior Connection Plate at plate
		edge using calipers.
Northwest L0	1/2"	Measured Interior and Exterior Gusset Plate
		at plate edge using calipers.
Southwest U1	7/16"	Measured Interior and Exterior Gusset Plate
		at plate edge using calipers.
Southwest U2	7/16"	Measured Interior and Exterior Gusset Plate
		at plate edge using calipers.
Southwest U3	7/16"	Measured Interior and Exterior Gusset Plate
		at plate edge using calipers.
West U4	7/16"	Measured Interior and Exterior Gusset Plate
		at plate edge using calipers.
Northwest U3	7/16"	Measured Interior and Exterior Gusset Plate
		at plate edge using calipers.
Northwest U2	7/16"	Measured Interior and Exterior Gusset Plate
		at plate edge using calipers.
Northwest U1	7/16"	Measured Interior and Exterior Gusset Plate
		at plate edge using calipers.



East Truss Gusset Plates:

CONNECTION	THICKNESS	LOCATION/METHOD OF MEASUREMENT
Southeast L0	1/2"	Measured Interior and Exterior Gusset Plate
		at plate edge using calipers.
Southeast L1	7/16"	Measured Exterior Connection Plate at plate
		edge using calipers.
Southeast L2	7/16"	Measured Interior and Exterior Gusset Plate
		at plate edge using calipers.
Southeast L3	7/16"	Measured Exterior Connection Plate at plate
		edge using calipers.
East L4	7/16"	Measured Interior and Exterior Gusset Plate
		at plate edge using calipers.
Northeast L3	7/16"	Measured Exterior Connection Plate at plate
		edge using calipers.
Northeast L2	7/16"	Measured Interior and Exterior Gusset Plate
		at plate edge using calipers.
Northeast L1	7/16"	Measured Exterior Connection Plate at plate
		edge using calipers.
Northeast L0	1/2"	Measured Interior and Exterior Gusset Plate
		at plate edge using calipers.
Southeast U1	7/16"	Measured Interior and Exterior Gusset Plate
		at plate edge using calipers.
Southeast U2	7/16"	Measured Interior and Exterior Gusset Plate
		at plate edge using calipers.
Southeast U3	7/16"	Measured Interior and Exterior Gusset Plate
		at plate edge using calipers.
East U4	7/16"	Measured Interior and Exterior Gusset Plate
		at plate edge using calipers.
Northeast U3	7/16"	Measured Interior and Exterior Gusset Plate
		at plate edge using calipers.
Northeast U2	7/16"	Measured Interior and Exterior Gusset Plate
		at plate edge using calipers.
Northeast U1	7/16"	Measured Interior and Exterior Gusset Plate
		at plate edge using calipers.



Truss Floor Beam Members

MEMBER	FATIGUE	RATING	REMARKS
South L0	D D	6	Light surface rust and minor pitting. Less than 5% total shear section loss and no moment section loss. No cracks evident.
South L1	D	6	Light surface rust and minor pitting. Less than 5% total shear section loss and no moment section loss. No cracks evident.
South L2	D	6	Light surface rust and minor pitting. Less than 5% total shear section loss and no moment section loss. No cracks evident.
South L3	D	6	Light surface rust and minor pitting. Less than 5% total shear section loss and no moment section loss. No cracks evident.
L4	D	6	Light surface rust and minor pitting. Less than 5% total shear section loss and no moment section loss. No cracks evident.
North L3	D	6	Light surface rust and minor pitting. Less than 5% total shear section loss and no moment section loss. No cracks evident.
North L2	D	6	Light surface rust and minor pitting. Less than 5% total shear section loss and no moment section loss. No cracks evident.
North L1	D	6	Light surface rust and minor pitting. Less than 5% total shear section loss and no moment section loss. No cracks evident.
North L0	D	6	Light surface rust and minor pitting. Less than 5% total shear section loss and no moment section loss. No cracks evident.



MONROE COUNTY BRIDGE NO. 00913 - BUSINESS 37 NORTH OVER BEANBLOSSOM CREEK

APPROACH AND ELEVATION PHOTOS



APPROACH LOOKING NORTH



APPROACH LOOKING SOUTH




ELEVATION LOOKING WEST



TACK WELD SOUTHWEST L3

MONROE 913





MONROE COUNTY BRIDGE NO. 00913 - BUSINESS 37 NORTH OVER BEANBLOSSOM CREEK

ADDITIONAL PHOTOS



WEST L4 CONDITION



L4U3 NORTHWEST PAINT PEELING




L2U3 NORTHWEST PAINT PEELING



NORTH BRIDGE JOINT

ADDITIONAL PHOTOS AVAILABLE



* TYP. ALL BEAMS EXCEPT EAST EXT. BM.

CROSS SECTION



MONROE COUNTY BRIDGE NO. 00913 - BUSINESS 37 NORTH OVER BEANBLOSSOM CREEK



OVERLAY SPALL NORTH END



OVERLAY SPALL MIDSPAN WEST COPING



SOUTH BRIDGE JOINT



DAMAGED EAST GUARDRAIL



OVER ROTATED EXPANSION BEARING



MODERATE SECTION LOSS IN WEB AT NELO



MONROE COUNTY BRIDGE NO. 00913 - BUSINESS 37 NORTH OVER BEANBLOSSOM CREEK



NORTHWEST ABUTMENT 2 SPALL IN MUDWALL



SPALL WITH EXPOSED REINFORCEMENT IN DECK



EXPANSION RUST AND SECTION LOSS AT NELO



SEL1 INTERIOR ANGLE SECTION LOSS



SEL1 EXTERIOR GUSSET PLATE SECTION LOSS



SEL2L1 INTERIOR GUSSET PLATE SECTION LOSS AT DIAGONAL END



MONROE COUNTY BRIDGE NO. 00913 - BUSINESS 37 NORTH OVER BEANBLOSSOM CREEK



SEL2L1 EXTERIOR GUSSET PLATE SECTION LOSS AT DIAGONAL END



EL4 WEB CONNECTION SEVERED FROM LOW CHORD



TYPICAL LOW CHORD SPLICE



NEL1 60% SECTION LOSS ON INTERNAL FLANGE OF VERTICAL



TYPICAL DETERIORATION OF EXTERNAL SWAY
BRACING



TYPICAL FLOOR BEAM DETERIORATION AT TOP FLANGE



MONROE COUNTY BRIDGE NO. 00913 - BUSINESS 37 NORTH OVER BEANBLOSSOM CREEK



TYPICAL FLOOR BEAM DETERIORATION AT BOTTOM FLANGE




TYPICAL HEAVY SECTION LOSS OF STAY PLATES AND LATTICE BARS ON END POST



APPENDIX G Original and Rehabilitation Plans

Original Plans



STATE OF INDIANA
STATE HIGHWAY COMMISSION

BRIDGE PLANS

FOR SPANS OVER 20 FEET ON

STATE ROAD NO. 37 SECTION J

F PROJECTS NO. 428 (5) (1946) NO. 428 (6) (1946)

BLOOMINGTON -MARTINSVILLE ROAD

DESCRIPTION OF F PROJECT Nº 428(5)(1946):-BEGINNING AT A POINT IN SECTION 21 ON PROPOSED S.R. 37 APPROX. 82'SOUTH OF THE NORTH LINE OF SECTION 21 AND EXTENDING IN NORTHWESTERLY AND NORTHEASTERLY DIRECTIONS A DISTANCE OF APPROX. 11,600'TO A POINT IN SECTION 4 APPROX. 362'NORTHEAST OF THE WEST LINE OF SECTION 4, ALL IN T9N.,-RIW., MONROE COUNTY.

GROSS LENGTH = 2.196 MI.

NET LENGTH = 0.146 MI — STRUCTURE 37-J-3630

STRUCTURE 37-J-3630

MAX.GRADE:- -0.400%

ROADWAY LENGTH BRIDGE LENGTH TOTAL LENGTH

0.071

0.071

0.075


DESCRIPTION OF F PROJECT Nº428(6)(1946).-BEGINNING AT A POINT ON PROPOSED S.R. 37 APPROX. 2282' NORTHWEST OF THE SOUTH LINE OF SECTION 8 AND EXTENDING IN A NORTHERLY DIRECTION A DISTANCE OF APPROX. 1400' TO A POINT ON PROPOSED S.R. 37 APPROX. 3682' NORTHWEST AND NORTHERLY DIRECTIONS OF THE SOUTH LINE OF SECTION 8., ALL IN SECTION 8-T9N., -R1W., NONROE COUNTY.

ROADWAY LENGTH = 0.24! MI.

BRIDGE LENGTH = 0.024 MI.

TOTAL LENGTH = 0.265 MI.

MAX. GRADE:- 0.200%



BRIDGES OVER 20 SPAN

FUR. ROAD PROI. NO. YEAR NO SHEETS

APPROVED AND ADOPTED 5-24-46
BY STATE HIGHWAY COMMISSION OF INDIANA

CHAIRMAN. STATE HIGHWAY COMMISSION OF INDIA

APPROVED 5-24-46

CHIEF ENGINEER, STATE HIGHWAY COMMISSION OF INDIA

CHIEF ENGINEER, STATE HIGHWAY COMMISSION OF INDIA


RECOMMENDED FOR APPROVAL





APPROVED


PUBLIC ROADS ADMINISTRATION FEDERAL WORKS AGENCY

STATE HIGHWAY COMMISSION STANDARD
BRIDGE SPECIFICATIONS DATED NOVEMBER 1959
TO BE USED WITH THESE PLANS









radisk sistem i **ka k**itoto erkettu water

INDEX

STATE OF INDIANA
STATE HIGHWAY COMMISSION

PLAN AND PROFILE OF PROPOSED STATE HIGHWAY F PROJECT NO.428(11) (1948)

BLOOMINGTON~MARTINSVILLE ROAD

BEGINNING AT A POINT APPROX. 3 FT. NORTH OF THE NORTH CORPORATION LINE OF THE CITY OF BLOOMINGTON AND EXTENDING IN A NORTHWESTERLY DIRECTION TO A POINT APPROX. 3682 FT. NORTH OF THE SOUTH LINE OF SEC.8-T9N-RIW ALL IN MONROE COUNTY

GROSS LENGTH:- 3.773 MI.
NET LENGTH:- 3.748 MI.

PLAN | LONG:- 1" = 50-100' | HORIZ:- 1" = 50'-100' | VERT:- 1" = 10'

MAX. GRADE 4,000%

SRIMAGE

SRI

APPROVED AND ADOPTED 5-19-48
By State Highway Commission of Indiana

31- 16.11 A

CHAIRMAN - STATE HIGHWAY COMMISSION OF INDI

CHIEF ENGINEER - STATE A GHARAY COMMISSION O

DISTRICT ENGINEER PUBLIC ROADS ADMINISTRATION

1-22-18

APPROVED

DIVISION ENGINEER
PUBLIC ROADS ADMINISTRATION
PEDERAL WORKS AGENCY

DATE_

NDAR D SPECIFICATIONS DATED 1946


RECOMMENDED FOR APPROVAL 8-17-45
5-18-48


W. H. Behrens

ENGINEER OF ROAD DESIGN. STATE HIGHWAY COMMISSION OF INDIANA

_

7





Rehablitation Plans - A

A STATE OF THE STA BRIDGE CONTRACT No. B-82.30 BRIDGES OVER 20' SPAN PURLIC ROAD STATE FISCAL SHEET TOTAL YEAR NO. SHEETS PROJECT NO. STATE OF INDIANA INDEX 1969 IND. 22 INDIANA STATE HIGHWAY COMMISSION PROJECT SPAH STATION CONTRACT NO. INDEX CONTINUED STANDARD DRAWINGS BEAN BLOSSOM REPAIRS TO STEEL TRUSS HPR 1(7) 37-53-3629A 125 205 + 60SHEET NO. SHEET DESIGNATION B-8230 CREEK STANDARD MISCELLANEOUS DETAILS
STANDARD MISCELLANEOUS DETAILS
CASTING DETAILS ROADWAY DRAINS
ROADWAY DRAIN OUTLET DETAILS R-10:1-69 BRIDGE PLANS SHEET DESIGNATION **SUBJECT** INDEX & TITLE SHEET MISCELLANEOUS APPROACH DETAILS


R.C. BRIDGE APPROACH TURNOUT DETAILS-12'-6" SHOULDERS


SLOPEWALL AND DRAINAGE DETAILS 2 S 1 (STR. 37-53-3629A) GENERAL PLAN BRIDGE STD. M5 3 S 2 4 S 3 SLAB LAYOUT PRESTRESSED CONCRETE TYPE I-BEAMS
PRESTRESSED BOX BEAMS
PRESTRESSED COMPOSITE BOX BEAMS WIDE
TOLERANCES FOR FABRICATION OF PRESTRESSED BEAMS
ELASTOMERIC BEARING PAD DETAILS SLAB DETAILS FOR SPANS OVER 20 FEET BRIDGE STD. PB6 BRIDGE STD. PB 5 S 4 SLAB DETAILS 6 8 5 DETAILS BRIDGE STD. PB10 BRIDGE STD. PB11 BRIDGE STD. R1-C BRIDGE STD. R1-E BRIDGE STD. R1-F BRIDGE STD. R2A 7 56 DETAILS ALUMINUM RAILING-TYPE 5
ALUMINUM RAILING DETAILS 8 57 ALUMINUM RAILING DETAILS 9 58 ALUMINUM RAILING DETAILS STEEL RAILING-TYPE C
BRIDGE LIGHTING DETAILS
ALUMINUM BRIDGE RAILING 10 5 9 TYPE A EXPANSION JOINT DETAILS BRIDGE STD. BR1
BRIDGE STD. BR2
BRIDGE STD.
BRIDGE STD. S1 STATE ROAD NO. 37 SECTION 9-26-69 R-8-1-69 9-26-69 R-8-1-65 11 ONE SHEET SUMMARY ALUMINUM BRIDGE RAILING DETAILS TYPICAL DETAILS FOR PLACING GRADE "B" SPECIAL BORROW
TYPICAL DETAILS FOR PLACING GRADE "B" SPECIAL BORROW
STANDARD TEMPORARY BRIDGE
STANDARD TEMPORARY BRIDGE
STANDARD PAVEMENT JOINTS BRIDGE STD. S2


BRIDGE STD. T SHEET A

BRIDGE STD. T SHEET B F.A. PROJECT NO. HPR 1(7) PE. & CONST. ROAD STD. SHEET A
ROAD STD. SHEET MA
ROAD STD. SHEET MB
ROAD STD. SHEET MC
ROAD STD. SHEET MC R-1|-3-69 6-27-69 R-4-1-89 MISCELLANEOUS STANDARDS
MISCELLANEOUS STANDARDS
MISCELLANEOUS STANDARDS BLOOMINGTON-MARTINSVILLE ROAD MISCELLANEOUS STANDARDS ROAD STD. SHEET MC1
ROAD STD. SHEET MD
ROAD STD. SHEET MD1
ROAD STD. SHEET ME
ROAD STD. SHEET ME1
ROAD STD. SHEET MG
ROAD STD. SHEET MG
ROAD STD. SHEET MH
ROAD STD. SHEET MI
ROAD STD. SHEET MJ
ROAD STD. SHEET K STRUCTURE 37-53-3629A IS LOCATED AT A POINT ON PRESENT S.R. 37 APPROX. 3345' NORTHWEST OF THE SOUTH LINE OF MISCELLANEOUS STANDARDS
MISCELLANEOUS STANDARDS
MISCELLANEOUS STANDARDS
MISCELLANEOUS STRUCTURE STANDARDS
MISCELLANEOUS STRUCTURE STANDARDS SECTION 8, T.9N.-R.1W., MONROE COUNTY. MISCELLANEOUS STANDARDS
MISCELLANEOUS STANDARDS ROAD STD. SHEET MN ROAD STD. SHEET MP ROAD STD. SHEET MP1 ROAD STD. SHEET MQ ROAD STD. SHEET MR ROAD STD. SHEET MR1 MISCELLANEOUS STANDARDS MISCELLANEOUS STANDARD MISCELLANEOUS STANDARDS
MISCELLANEOUS STANDARDS MISCELLANEOUS STANDARDS CENTER DITCH INLETS
MISCELLANEOUS STANDARDS CENTER DITCH INLETS
MISCELLANEOUS STANDARDS
GUARD RAIL
ALUMINUM GUARD RAIL DETAILS R-11-3-49 R-11-3-60 ROAD STD. SHEET MISCELLANEOUS STANDARDS STANDARD STRUCTURE CONNECTIONS FOR ROAD STD. ROAD STD ROAD STD ROAD STD ROAD STD T.9N. T.10N. ROAD STD. ROAD STD. SHEET GR1 STRUCTURE 37-53-3629A 1 Spun @ 125' Steel Truss (Repairs)-PRESENT STRUCTURE 37-J-3629 1 Span @ 125'., St. Truss Awarded 1946, B.C. 2716 TRAFFIC DATA A.D.T. (1970) 9.000 V.P.D. A.D.T. (1990 PROJECTED) 8,180 V.P.D. A.D.T. (19 PROJECTED) V.P.D. TRUCKS 17 % DESIGN SPEED 70 M.P.H. ACCESS CONTROL NONE Scale:-1"= 2000' DEPARTMENT OF COMMERCE BUREAU OF PUBLIC ROADS REVISIONS DATE SHEET NO. APPROVED: 12-2-69 8,11 INDIANA STATE HIGHWAY COMMISSION STANDARD SPECIFICATIONS DATED 1969 DIVISION ENGINEER DATE TO BE USED WITH THESE PLANS.

BRIDGE FILE: 37-53-3629 A








PUB. ROAD STATE FROJECT FISCAL SHEET TOTAL SHEETS

4 IND. HP2 1(7) 1070 4 22

GENERAL NOTES

- SLABS SHALL BE PLACED FROM THE NORTH END TO THE SOUTH END. SLAB SB-4 SHALL BE ANCHORED TO STRINGER S-5.

 SUCCEEDING SLABS SHALL BE PLACED AND PULLED TIGHT AGAINST PREVIOUSY PLACED SLAB AND CLAMPED LOOSELY TO STRINGER S-5. AFTER ALL SECTIONS ARE FLACED THEY SHALL BE POST TENSIONED AND ANCHORED TO THE REMAINING STRINGERS AND FLOOR BEAMS.
- PRESTRESSED SLABS, EPOXY MORTAR, CLIPS, POST TENSIONING STRANDS, ANCHORS, GROUT, MORTAR, UT. SERLENT, AND ALL OTHER MATERIALS, EQUIPMENT, AND LABOR NECESSARY TO BUILD AND PLACE THE SLABS SHALL BE INCLUDED IN THE COST OF CONCRETE STRUCTURAL MEMBERS."
- J. FABRICATOR SHALL PROVIDE SHOP DRAWINGS WHICH SHOW POST TENSION ANCHORAGE SYSTEM AND OTHER NECESSARY DETAILS.



PART SECTION X-X

SLAB DETAILS INDIANA STATE HIGHWAY COMMISSION

SCALE: NOT TO SCALE

JULY 25

1969

RECOMMENDED FOR APPROVAL:


ENGINEER OF BRIDGE DES

ENGINEER OF ERIOGE DESIGN

PROJECT: - HPR 1(7)

ROAD CONTRACT NO. PROJECT NO. FISCAL YEAR W. W. W. L. L. ENT DE WAY PLANS IND. 57-F-428(17) 1968 DESIGN DATA A.D.T. (1970) A.D.T. (1990) PROJECTED STATE OF INDIANA D.H.V. (1990) DIRECTIONAL DISTRIBUTION INDIANA STATE HIGHWAY COMMISSION CCESS CONTROL PARTIAL PLAN AND PROFILE OF PROPOSED Code Nº. 0936 STATE HIGHWAY


ST-F-428 (16) P.E. ST-F-PROJECT NO. 428 BEGINNING AT A POINT APPROXIMATELY 2584 FEET SOUTH OF SR NO.46 APPROXIMATELY ONE MILE EAST OF THE WEST LINE OF BLOOMINGTON TOWNSHIP AND RUNNING NORTHEASTERLY A DISTANCE OF 21,483 FEET TO A POINT ALONG THE WEST RIGHT-OF-WAY LINE OF SR.NO.37 APPROXIMATELY 618 FEET NORTH OF THE STRUCTURE OVER BEAN BLOSSOM CREEK OVERFLOW ALL IN MONROE COUNTY. END PROJ. ST-F-428(17) BEGIN PROJ. ST-F-428(20) GROSS LENGTH:- 4,069 .MI. STA. 708 + 00 SCALES:-R/W PLANS FOR THIS PROJECT PLAN | LONG:- 1"-50' | PROFILE | HORIZ:-1"-50' | VERT:- 1"-10' INCLUDES RIW FOR SEPARATE AND MAX. GRADE 5.00 % PAVING EXCEPTION COMBINED CONTRACT STRUCTURES STA.658 + 63.39 TO -STA.660 + 36.61 "L" PROJECT BRIDGE FILE LEGEND ST-F-428(18) 46-F-5766 A BARRICADE TYPE "A" 57-F-428() 37-J9-5963 STRUCTURE NO. I
TO BE BUILT IN COMBINATION B BARRICADE TYPE "B" *ST*-F-428() 37-J9-5964 C TYPICAL SIGN STANDARDS 37-J-5986 57-F-428(18) CONSTRUCTION IDENTIFICATION SIGN 37-J-3630 A ST-F-428(18) 37-J-3630 J END PROJFF-893(7) BEGIN PROJ. ST F-428(17) STA. 493 + 17 RECOMMENDED FOR APPROVAL ASSISTANT ENGINEER OF PLANS AND SPECIFICATIONS STRUCTURE NO. 3 SEPARATE CONTRACT RECOMMENDED FOR APPROV STRUCTURE PAVING EXCERTION STA. 669 + 81.85 "L" ENGINEER OF PLANS AND SPECIFICATIONS - INDIANA STATE HIGHWAY TO BE BUILT IN COMBINATION PLANS PREPARED BY CHIEF ENGINEER-INDIANA STATE HIGHWAY COMMISSION WITH ROAD CONTRACT NO EXCEPTION BEAM, LONGEST & NEFF, INC. STRUCTURE NO. 5 CONSULTING STRUCTURAL ENGINEERS TO BE BUILT IN COMBINATION WITH ROAD CONTRACT INDIANAPOLIS, INDIANA PAVING EXCEPTION BUREAU OF PUBLIC ROADS STA. 700 + 29.18 TO STA. 701 + 83.18 "L" DEPARTMENT OF COMMERCE SUBMITTED FOR APPROVAL DATE Novamber 6 1.968 INDIANA STATE HIGHWAY COMMISSION No. 4327 STANDARD SPECIFICATIONS DATED 1963 STATE OF TO BE USED WITH THESE PLANS. DIVISION ENGINEER ROAD FILE :-PROJECT NO. LINE SHEET TOTAL SHEETS MAY , 1967



IND. 37-F-428(17) 1968 45 Revised R on Bean Blossom Creek & Co Road 9-3-69 Victor L. Risch APPROVED BY DESIGN 11-12-69 R.L. DODDEK Subject to a Blanket
Easement for Transmission
Line in favor of Interstate
Public Service Co. PI.=8+64.21 "SBL." = OPOT. (450.66' LT.) STA. 685+85.80 "L" \(\Delta = 83^\circ \text{19' 26''}\) D = 15^\circ SECTION 5 TON -RIW SUBJECT TO A BLANKET EASEMENT FOR RIGHT OF WAY IN FAVOR OF INDIANA Subject to 4 Blanket Eosements in favor of The Morgan Co. R. E. M. C. MONROE COUNTY T = 339.87 L = 555.49 E = 129.30 R = 381.97 STATEWIDE RURAL ELECTRIC CORP. WIT WILL PI. I+82.II "S.B.L." = 0.PO.T. (97.28 LT.) STA. 69I+78.03 "L" Δ = 28° 32' D = 8° T = 182.11 L= 356.67' E= 22.74' R= 716.20' IRVING E. BOBERG IRVING E. BOBERG EQUATION POT: 695+65.55 "L" POT: 50+00.0 "S-7-L" End L.A.R/W +75"5-6-L" \$ A.C.L. 40' 145'LA. R/W & A.C.L. (250) End Fence? (Woods) 145'L.A.R/W & A.C.L. Begin Fence POT. 690+73.18 PB-25B - ∃30¹. N. 27° 46' 35"E. SE COR, SE 4, SE 4 SEC 5. P.L.A.R/W &AC:L. PI. 17+16.25"SBL." = OPO.T. (323.88' RT.) STA.,679+91.47"L" △ = 28° 37' 25" D = 8° PB-24A D = 8° L = 182.71' L = 357.80' E = 22.93' R = 716.20' PT. 13+69.16 "NBL" = O.P.O.T. 72' RT. 689+58.57 NE COR, EZ, NE 4 SEC 8-5EC. 4 TON - RIW IRVING E. BOBERG IRVING E. BOBERG 7 P. 12+11.62 "NBL." = 0.P.O.T.(75.21' RT.) STA 687+98.09"L" △= 19°04'59" D= 6° Subject to a Blanket Easement for Transmission Line in favor of Interstate Public Service Co. +00,"NBL" # (98,021) Subject to 2 Blanket Easements in favor of The Morgan Co. R. E. M. C. PB-25A T = 160.51' L = 318.65' E = 13.39' R = 954.93' STUART, PAUL (25A) Temp. R/W for Channel Excav. SUBJECT TO A BLANKET EASEMENT FOR RIGHT OF WAY IN FAVOR OF INDIANA RURAY ELECTRIC CORP. PARCEL 25 ON PROJECT ST.F. 42807) AND PARCEL / ON PROJECT 57-F-428(20) COVER THE SAME LAND, WITH ACQUISITION THEREOF ENTIRELY UNDER SMID PROJECT ST-F. 428 (17) SEC 9 T9N-RIW INTERCHANGE RIGHT OF WAY S.R. 37 WITH EXISTING S.R. 37 DETAILS

SCALE 1"= 100' W. T. Lill school * Ad. 432

November 6 1964



LEGEND

I" Prefored Epansion Joint With Load Tranfer 8" Reinfored Concrete Povement 3" Bituminous Shoulder 5" Bituminous Shoulder

INTERCHANGE S.R.37 WITH EXISTING S.R.37

DETAILS

Scale |"=30'



W. W. Balleton

Rehablitation Plans - B

INDEX STRUCTURE BEAN BLOSSOM CREEK ST-8953(A) 37X-53-3629 B STEEL PONY TRUSS SHEET DESIGNATION SUBJECT TITLE & INDEX SHEET GENERAL PLAN CONSTRUCTION PROCEDURE, GENERAL NOTES, MATERIAL NOTES, STANDARD DRAWING TABLE & DETAILS BRIDGE ESTIMATE OF QUANTITIES


TRAFFIC DATA		
A.D.T. (1983)	1541	V.P.D.
A.D.T. (19 PROJECTED)		V.P.D.
D.H.V. (19 PROJECTED)		V.P.D.
TRUCKS	D.H. V. 🔏 /	A.D.T. %
DESIGN SPEED	-	M.P.H.
ACCESS CONTROL		

NOTE: WHEREVER "INDIANA STATE HIGHWAY COMMISSION" APPEARS IN THE PLANS IT SHALL BE INTERPRETED AS "INDIANA DEPARTMENT OF HIGHWAYS".

INDIANA DEPARTMENT OF HIGHWAYS

TO BE USED WITH THESE PLANS.

STANDARD SPECIFICATIONS DATED 1985



REVISIONS SHEET NO.

INDIANA DEPARTMENT OF **HIGHWAYS**


BRIDGE PLANS

FOR SPANS OVER 20 FEET ON STATE ROAD NO. 37 PROJECT NO. ST-8953(A)

Structure No. 37X-53-3629 B Located on Old S.R. 37 over Beanblossom Creek in Section 8, Township 9 North, Range I West, Bloomington Township, Monroe County, Indiana.

ROADWAY LENGTH: LENGTH: GRADE :

DATE



REVISIONS

SHEET NO.

BRIDGES OVER 201 SPAN
FEDERAL STATE PROJECT NO. FISCAL SHEET TOTAL YEAR NO. SHEETS

INDEX CONTINUED STANDARD DRAWINGS								
SHEET NO.	SHEET DESIGNATION	SUBJECT	F.H.W.A.	ADOPTED A REVISION R				
	BRIDGE STD. BRI	ALUMINUM BRIDGE RAILING						
	BRIDGE STD. BR2	ALUMINUM BRIDGE RAILING DETAILS						
	BRIDGE STD. BR3	STEEL BRIDGE RAILING	. 	<u> </u>				
	BRIDGE STD. BR4 BRIDGE STD. BR5	STEEL BRIDGE RAILING DETAILS RAILING CONNECTION DETAILS		<u> </u>				
	BRIDGE STD. BR6	RAILING CONNECTION DETAILS						
	BRIDGE STD. Cl	MISCELLANEOUS DETAILS						
	BRIDGE STD. C2	MUSCELLANEOUS DETAILS						
	BRIDGE STD. C3	MISCELLANEOUS DETAILS						
	BRIDGE STD. C4	MISCELLANEOUS DETAILS						
	BRIDGE STD. D	CASTING DETAILS ROADWAY DRAINS						
	BRIDGE STD. Di BRIDGE STD.	ADJUSTING FRAME DETAILS FOR ROADWAY DRAINS						
	BRIDGE STD. PB	PRESTRESSED CONCRETE TYPE I-BEAMS						
	BRIDGE STD. PB	PRESTRESSED CONCRETE TYPE I-BEAMS						
	BRIDGE STD. PB6	PRESTRESSED BOX BEAMS						
	BRIDGE STD. PB	PRESTRESSED COMPOSITE BOX BEAMS WIDE						
	BRIDGE STD. PB	PRESTRESSED COMPOSITE BOX BEAMS WIDE						
	BRIDGE STD. PB10	TOLERANCES FOR FABRICATION OF PRESTRESSED BEAMS						
	BRIDGE STD. PB11	ELASTOMERIC BEARING PAD DETAILS						
	BRIDGE STD.	<u> </u>	 	<u> </u>				
	BRIDGE STD.	PRINCE LIGHTING PERALIC		<u> </u>				
	BRIDGE STD. R2A BRIDGE STD. R2B	BRIDGE LIGHTING DETAILS						
	BRIDGE STD. RZB	BRIDGE LIGHTING DETAILS MISCELLANEOUS DETAILS	 					
	BRIDGE STD. SHi	STEEL SHOE DETAILS						
	BRIDGE STD. T SHEET A	STANDARD TEMPORARY BRIDGE						
	BRIDGE STD. T SHEET B	STANDARD TEMPORARY BRIDGE						
	BRIDGE STD.							
	BRIDGE STD.							
	BRIDGE STD.							
	BRIDGE STD.			,				
	BRIDGE STD.							
	ROAD STD. SHEET A	STANDARD PAVEMENT JOINTS	- }					
	ROAD STD. SHEET B ROAD STD. SHEET	STANDARD PAVEMENT JOINTS MISCELLANEOUS STANDARDS	 					
	ROAD STD. SHEET	MISCELLANEOUS STANDARDS						
	ROAD STD. SHEET	MISCELLANEOUS STAMDARDS						
	RGAD STD. SHEET	MISCELLANEOUS STANDARDS						
	ROAD STD. SHEET	MISCELLANEOUS STANDARDS						
	ROAD STD. SHEET	MISCELLANEOUS STANDARDS						
	ROAD STD. SHEET	MISCELLANEOUS STANDARDS						
	ROAD STD. SHEET ROAD STD. SHEET	MISCELLANEOUS STANDARDS MISCELLANEOUS STANDARDS						
	ROAD STD. SHEET	MISCELLANEOUS STANDARDS MISCELLANEOUS STANDARDS		<u> </u>				
	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~			<u> </u>				
	ROAD STD. SHEET ROAD STD. SHEET	MISCELLANEOUS STANDARDS MISCELLANEOUS STANDARDS	 					
	ROAD STD. SHEET	MISCELLANEOUS STANDARDS						
	ROAD STD. SHEET	MISCELLANEOUS STANDARDS						
	ROAD STD. SHEET	MISCELLANEOUS STANDARDS		<u> </u>				
	ROAD STD. SHEET	MISCELLANEOUS STANDARDS		· · · · · · · · · · · · · · · · · · ·				
	ROAD STD. SHEET	MISCELLANEOUS STANDARDS						
	ROAD STD. SHEET	MISCELLANEOUS STANDARDS						
	ROAD STD. SHEET .	MISCELLANEOUS STANDARDS		<u> </u>				
5	ROAD STD. SHEET MT3	MISCELLANEOUS STANDARDS	8-30-82	A JUL. 198				
	ROAD STD. SHEET	MISCELLANEOUS STANDARDS						
	ROAD STD. SHEET	MISCELLANEOUS STANDARDS						
	POAD STD. SHEET GR	GUARD RAIL CLASS						
	ROAD STD. SHEET GR	GUARD RAIL CLASS						
	ROAD STD. SHEET GR	GUARD RAIL CLASS						
	ROAD STD. SHEET GR	GUARD RAIL CLASS						
	ROAD STD. SHEET GR5 ROAD STD. SHEET GR6	ALUMINUM GUARD RAIL DETAILS STEEL TUBE GUARD RAIL DETAILS						
	ROAD STD. SHEET GR7	GUARD RAIL PIER CONNECTION DETAILS						
	ROAD STD. SHEET GR8	STEEL BEAM GUARD RAIL		<u> </u>				
	ROAD STD. SHEET GR9	ALUMINUM BEAM GUARD RAIL	<u> </u>	 				
	ROAD STD. SHEET GR10	GUARD RAIL BURIED ENDS	T					
	ROAD STD. SHEET GRIOA	GUARD RAIL BREAKAWAY CABLE TERM.	1					
	ROAD STD.		I					
6	ROAD STD. SHEET CB2	TEMPORARY CONCRETE BARRIER	PENDING	R 6-1-80				
	TRAFFIC STD. SHEET 9	TRAFFIC SIGN DETAILS						
7	ROAD STD. SHEET 1 DETOURS	STANDARD DETOUR SIGNS	PENDING	R 2-1-8				
	ROAD STD. SHEET 1A DETOURS	STANDARD DETOUR SIGNS						
	ROAD STD. SHEET 1B DETOURS	STANDARD DETOUR SIGNS	ļ					
	ROAD STD. SHEET 2 DETOURS	STANDARD DETOUR SIGNS	 	0 0				
8	ROAD STD. SHEET 2A DETOURS	STANDARD DETOUR SIGNS	4-1-85					
9	ROAD STD. SHEET 3 DETOURS	STANDARD DETOUR SIGNS	4-10-84	K 2-1-8				
10	ROAD STD. SHEET 3A DETOURS		12-8-83-	PIA 2-8				
11	ROAD STD. SHEET 4 DETOURS ROAD STD. SHEET 5 DETOURS	STANDARD DETOUR SIGNS STANDARD DETOUR SIGNS	4.10.84					
		STANDARD DETOUR SIGNS	1-10 04	<u> </u>				

RECOMMENDED FOR APPROVAL


ASSISTANT ENGINEER OF BRIDGE DESIGN,

RECOMMENDED FOR APPROVAL

DIVISION ADMINISTRATOR

FEDERAL HIGHWAY ADMINISTRATION DEPARTMENT OF TRANSPORTATION


BRIDGE FILE: 37X-53-3629 B




Rehablitation Plans - C

	·INDEX						
SHEET	DESCRIPTION						
1	TITLE, INDEX AND SUMMARY						
2 .	DETAILS SHOWING REMOVALS						
3	DETAILS SHOWING RECONSTRUCTION						
4	DETAILS						
5-6	STANDARD DETAILS						
	*						

MONROE COUNTY BRIDGE PLANS





BUTLER, FAIRMAN & SEUFERT, INC.

ENGINEERS

9405 DELEGATES ROW
INDIANAPOLIS, INDIANA 46240-3805
317-573-4615

INDIANA DEPARTMENT OF TRANSPORTATION, STANDARD SPECIFICATIONS DATED 1993 TO BE USED WITH THESE PLANS

APPROVED


ATTEST

MONROE COUNTY AUDITOR

BOARD OF MONROE COUNTY COMMISSIONERS


PROJECT PER INFORMATION COLLECTED DURING CONSTRUCTION

SUBMITTED FOR APPROVAL Supher F. Weintraut




PROJECT NO LINE SHEET TOTAL FILE

1 6 2548.9801



•47



APPENDIX H Traffic and Accident Data

	Traffic Data		CK. AVW	DATE
	Pric Data:			
			base , (see Atlached v	next)
		= 9,175 Upd		
F	Issume growth	rate = 1.51 %	6 PerIDM	(407 4A) V
	nndivided	Rural Arterial V		
		2 2 9		
	for construction ye	en 2027	× 9175= 10,190	
	HADT SOZ	-8 = (1-0151)	* 9175= 10,190	VPOL
	For Design ye	or 2649		
	DADT ONLY	8 - (1 15) 249 - 2025	19175=13,75	1 NPd
)	13131 284	0= (1.013)	R 111 3 = 1.3., 13	V V V



List View All DIRs



Transportation Data Management System

Disclaimer: The data is provided pursuant to the Indiana Open Records Act. It represents accurate reproductions of the records on file with the Indiana Department of Transportation; however, ... more

Record	! ! ! ! ! !	1	▶ H	of '	Goto Red	cord	go		
Location ID	L01p566						MPO ID	p566	
Туре	SPOT				HPMS ID				
On NHS	No				On HPMS	No			
LRS ID	3530000054	9000001					LRS Loc Pt.	1.432	7
SF Group	R2_SWGA					•	Route Type	Coun	ty Road
AF Group	R2_SWGA					•	Route	Local	
GF Group	R2_SWGA					•	Active	Yes	
Class Dist Grp							Category		
Seas Clss Grp									
WIM Group									
QC Group	Default								
Fnct'l Class	Minor Arteria	l					Milepost		
Located On	_			snand F	Rd.				
Loc On Alias	SR 37 BUSII	NESS (IR	549)						
More Detail 🕨	I								
STATION DAT	A								
Directions: 2	-WAY								
AADT 🕡									
Year	AADT	DHV-3	0 K	%	D %	PA	A E	BC .	Src
2022	9,175 ³								Grown
2022	9,173								from 2021
2021	9,343 ³								Grown from 2020
									Grown
2020	8,402 ³								from 2019
2040	0.0-03								Grown
2019	9,073 ³								from 2018
2018	9,028								
Travel Demand Model									

VOL	VOLUME COUNT								
	Date	Int	Total						
	No Data								
	1								

AM PHV

AM PPV

Model

AADT

Model

Year

VOLUME TREND 🥨							
Year	Annual Growth						
2022	-2%						
2021	11%						
2020	-7%						
2019	0%						

PM PPV

NT PHV

NT PPV

PM PHV

SPEED						CLASSIFICATION				
	Date	Int	Pace	85th	Total		Date	Int	t	Total
No Data				No Data						
WEIGH-IN-MOTION				PER VEHICLE						
	l I		1 -		T		Date	ΔνΙρς	85th	Total

MD PHV

MD PPV

Facility	Annual Growth Rate
Rural or Urban Freeway	3.07 %
Divided Rural Non-Freeway	1.51 %
Divided Urban Non-Freeway	1.32 %
Undivided Rural Arterial	1.51 %
Rural Collector or Local Road	2.45 %
Undivided Urban Facility	1.32 %

ANNUAL TRAFFIC GROWTH RATE

Figure 407-4A

Master Record Number	Agency	Local Code	County	Township	City	COLLDTE
902674106	MONROE SD	M16A5832	MONROE	BLOOMINGTON	BLOOMINGTON	3/21/2016
901627056	MONROE SD	M11A1259	MONROE	BLOOMINGTON	BLOOMINGTON	5/3/2011
901618432	MONROE SD	M11A1065	MONROE	BLOOMINGTON	BLOOMINGTON	4/14/2011
901717544	MONROE SD	M11A3059	MONROE	BLOOMINGTON	BLOOMINGTON	10/22/2011
901696948	MONROE SD	M11A2783	MONROE	BLOOMINGTON	BLOOMINGTON	9/24/2011
902664286	ISP BLOOMINGTON 33	201600051364	MONROE	BLOOMINGTON	BLOOMINGTON	2/19/2016
902355509	MONROE SD	M14A9684	MONROE	BLOOMINGTON	BLOOMINGTON	12/17/2014

Master Record Number	Collision Time	Vehicles Involved	Trailers Involved	Number Injured	Number Dead	Number Deer
902674106	1657	2	0	0	0	0
901627056	1004	1	0	0	0	0
901618432	1604	2	0	0	0	0
901717544	1006	1	0	1	0	0
901696948	1840	1	0	0	0	0
902664286	0927	1	0	0	0	0
902355509	1045	1	0	0	0	0

Master Record Number	Roadway Name	Roadway Suffix	Roadway Id	Intersecting Road	Corporate Limits?	Property Type
902674106	BUSINESS 37 NORTH	RD	BUSINESS 37 NORTH RD	WHISNAND	N	OTHER
901627056	BUSINESS 37 NORTH	RD	BUSINESS 37 NORTH RD	WHISNAND	N	OTHER
901618432	BUSINESS 37 NORTH	RD	BUSINESS 37 NORTH RD	WHISNAND	N	OTHER
901717544	BUSINESS 37 NORTH	RD	BUSINESS 37 NORTH RD	WHISNAND	N	OTHER
901696948	BUSINESS 37 NORTH	RD	BUSINESS 37 NORTH RD	WHISNAND	N	OTHER
902664286	BUSINESS 37 NORTH	RD	BUSINESS 37 NORTH RD	WHISNAND	N	PRIVATE
902355509	BUSINESS 37 NORTH	RD	BUSINESS 37 NORTH RD	WHISNAND	N	OTHER

Master Record Number	Feet From	Direction	Latitude	Longitude	Roadway Class	Aggressive Driving?
902674106			39.22466017	-86.53976999	LOCAL/CITY ROAD	N
901627056	600	N	39.22466017	-86.53976999	UNKNOWN	N
901618432	50	N	39.22466017	-86.53976999	COUNTY ROAD	N
901717544	2000	N	39.22466017	-86.53976999	LOCAL/CITY ROAD	N
901696948	1500	S	39.22466017	-86.53976999	COUNTY ROAD	N
902664286	1500	N	39.22466017	-86.53976999	COUNTY ROAD	N
902355509	500	S	39.22466017	-86.53976999	UNKNOWN	N

Master Record Number	Hit and Run?	Locality	School Zone?	Rumble Strips?	Construction?	Light Condition
902674106	Υ	RURAL	N	N	N	DAYLIGHT
901627056	N	RURAL	N	N	N	DAYLIGHT
901618432	N	RURAL	N	N	N	DAYLIGHT
901717544	N	RURAL	N	N	N	DAYLIGHT
901696948	N	RURAL	N	N	N	DAYLIGHT
902664286	N	URBAN	N	N	N	DAYLIGHT
902355509	N	RURAL	N	N	N	DAYLIGHT


Master Record Number	Weather Conditions	Surface Condition	Type of Median	Roadway Junction Type	Road Character	Roadway Surface
902674106	CLEAR	DRY	NONE	T-INTERSECTION	STRAIGHT/LEVEL	ASPHALT
901627056	CLOUDY	WET	NONE	NO JUNCTION INVOLVED	CURVE/LEVEL	ASPHALT
901618432	CLEAR	DRY	NONE	NO JUNCTION INVOLVED	STRAIGHT/LEVEL	ASPHALT
901717544	CLEAR	DRY	NONE	NO JUNCTION INVOLVED	STRAIGHT/GRADE	ASPHALT
901696948	CLOUDY	WET	NONE	NO JUNCTION INVOLVED	STRAIGHT/LEVEL	ASPHALT
902664286	CLEAR	DRY	NONE	NO JUNCTION INVOLVED	STRAIGHT/LEVEL	ASPHALT
902355509	CLEAR	DRY	NONE	NO JUNCTION INVOLVED	STRAIGHT/LEVEL	ASPHALT

Master Record Number	Primary Factor	Damage Estimate	Manner of Collision	Time Notified	Time Arrived	Investigation Complete?
902674106	FOLLOWING TOO CLOSELY	\$5001 TO \$10000	REAR END	1702	1719	Υ
901627056	OVERCORRECTING/OVERSTEERING	\$5001 TO \$10000	RAN OFF ROAD	1004	1014	Υ
901618432	FAILURE TO YIELD RIGHT OF WAY	\$2501 TO \$5000	LEFT/RIGHT TURN	1604	1624	Υ
901717544	OVERCORRECTING/OVERSTEERING	\$5001 TO \$10000	RAN OFF ROAD	1006	1010	Υ
901696948	RAN OFF ROAD RIGHT	\$2501 TO \$5000	RAN OFF ROAD	1840	1850	Υ
902664286	RAN OFF ROAD RIGHT	\$2501 TO \$5000	RAN OFF ROAD	0941	0941	Υ
902355509	DRIVER ASLEEP OR FATIGUED	\$1001 TO \$2500	RAN OFF ROAD	1047	1052	Υ

Master Record Number	Photos Taken?	Officer Last Name	Officer Id	Unique Location Id	State Property Damage?	Traffic Control
902674106	Υ	GREENE	5392	BUSINESS37RDWHISNANDRD	No	NONE
901627056	N	MULLIS	5329	BUSINESS37NORTHHWYWHISNANDRD	No	NO PASSING ZONE
901618432	Υ	MULLIS	5327	BUSINESS37NORTHRDWHISNANDROW	No	NO PASSING ZONE
901717544	Υ	SCUDDER	5375	BUSINESS37NORTHRDWHISNANDRD	No	NONE
901696948	N	MULLIS	5327	BUSINESS37RDWHISNANDRD	No	NO PASSING ZONE
902664286	N	MILLER	6911	BUSINESSSR37HWYWHISNANDRD	No	NO PASSING ZONE
902355509	N	HALE	5377	BUSINEESS37NSTATERDWISNANDRD	No	NONE

ter Record Number	Narrative						
902674106	D1 stated that she was driving north on business 37 when she came to a stop at Whisnand Rd due to traffic slowing in front of her. V2 was traveling directly behind v1 when she collided with the rear of v1. V1 rolled forward a little and v2 collided with v1 again. V2 left the scene with heavy front end damage and possible facial injuries. D2 was described as a blonde female. D1 refused medical treatment on the scene. My body worn camera was activated during this investigation.						
901627056	D-1 stated he was going south on business 37 north and he wasn't paying attention and got off the right side of the road and then overcorrected and went off the left side of the road and hit the ditch and embankment and went over the driveway and landed in the water.						
901618432	Driver of vehicle # 1 was looking for the entrance to Castle Mulch, when she jerked the wheel of her vehicle and crossed the center line. After she crossed the center line she struck vehicle # 2 in the drivers side rear door. Driver of Vehicle # 2 could not avoid being struck.						
901717544	D1 was traveling northbound in the 5200 block of N. Business 37. D1 stated another motor vehicle entered her lane of travel. At that time D1 swerved to the right to avoid a collision. After swerving right, D1 went back left and over corrected. V1 then went off the east side of the roadway and overturned. Skid marks began on the roadway approximately 80 feet from where V1 left the roadway. W1 also stated that D1 over corrected and left the roadway. W1 stopped to help D1. D1 was transported to Bloomington Hospital Emergency Department where I later me her. D1's major complaint was of pain to the head. There were non-life threatening injuries.						
901696948	Driver # 1 looked down for a moment and ran off of the right side of the roadway striking a no passing sign.						
	V1 was traveling north on Business SR37 north of Whisnand Road. V1 traveled off the east, right, side of the roadway for an unknown reason. V1 struck several small trees with the passenger side of V1. V1 struck a street sign post with the front left corner of V1. V1 came to final rest along the east side of Business SR37.						
	D1 stated she was traveling north on Business SR37. D1 stated she swerved to avoid impact with a deer and traveled off the right side of the roadway.						
lane of roadwa not nee W2 state right sight sight.	W1 stated he was a passenger in the vehicle driven by W2. W1 stated they were traveling north on Business SR37 behind V1. W1 stated V1 was swerving left of center into the southbound lane of Business SR37 causing vehicles to swerve to avoid impact. W1 stated V1 traveled off the right side of the roadway for an unknown reason and came to rest along the side of the roadway. W1 stated he exited the vehicle to check on D1. W1 stated the driver was a white male and was the sole occupant of V1. W1 stated D1 appeared disoriented and indicated he did not need assistance.						
	W2 stated she was driving a vehicle behind V1 north on Business SR37. W2 stated V1 was swerving left of center into the southbound lane of Business SR37. W2 stated V1 traveled off the right side of the roadway for an unknown reason and came to final rest along the side of the roadway. W2 indicated she believed the driver was a white male but she did not make contact with him.						
	Both W1 and W2 stated they did not observe any deer in the roadway prior to V1 traveling off the right side of the roadway.						
	Evidence shows V1 traveled off the right, east, side of the road before striking several small trees and a street sign. Evidence shows damage to the passenger side and front left corner of V1.						
	A black Jeep SUV was stopped behind V1 upon my arrival. The Jeep had Indiana registration, RXC169. A white male subject was sitting in the driver's seat who identified himself with an Indiana ID card as DAVID LEE EADS, DOB 1-05-1988 and OLN 3138-81-5250. A white female was sitting in the front passenger seat who identified herself with an Indiana driver's license as BAHIA BUNGE. The Jeep was registered to Bunge. Bunge indicated she was the driver of V1. Eads stated he drove Bunge's Jeep after learning of the collision. Eads denied driving V1 as reported by W1 and W2. I inquired how Eads learned of the collision. Eads indicated Bunge called his cell phone after the collision. I asked for consent to look at both Eads' and Bunge's call history. Eads made an outgoing call to Bunge at approximately the same time of the collision. It is my belief that Eads was actually the driver of V1 based on information provided by both W1 and W2 as well as inconsistent information provided by Eads. V1 is registered to Stephanie P. Rodriguez the mother of Eads roommate, Charles Rodriguez.						
	Driver 1 ran off the roadway due to being drowsy and struck several trees						

APPENDIX I Alternative Plan View Exhibits





REHAB TRUSS & NEW BYPASS BRIDGE

CHECKED: _

CHECKED: _

CONTRACT

