United States Department of the Interior Submitted
National Park Service

# **National Register of Historic Places** Inventory—Nomination Form



I. Nar	ne		
istoric	Columbus Historic District		·
nd/or commo			en e
	ation		
E. LUC	Roughly bounded by the Pennsylvania R.R. t	acks. Chestnut. Th	ird. Washington
treet & numbe	er Franklin Sts.		t for publication
ity, town	Columbus <u>N/A</u> vicinity of	greccional district	9th
tate	Indiana code 018 county Bar	holomew	code 005
3. Cla	ssification	Property of the Control of the Contr	
Ategory  X district building(s structure site object	public X occupied X unoccupied X both X work in progress X Public Acquisition Accessible	commercial X educational X entertainment X government — industrial	_ museum _ park _ private residence _ religious _ scientific _ transportation _ other:
. Ow	ner of Property		
ame	Multiple Ownership		
			Section 1995
treet & numbe	<del></del>	<u> </u>	<u></u>
ity, town	N/A vicinity of	state	
5. Loc	ation of Legal Description		
ourthouse, re	gistry of deeds, etc. Bartholomew County Courthouse	Annex	
treet & numbe			
tiest a mambe			47001
	Columbus	state India	ana 47201
3. Rep	presentation in Existing Sur	veys	. '+
S. Rep	a Historic Sites and	veys	yes X no
Indian tle Struct	a Historic Sites and	been determined eligible?	
Indian Struct Summer	a Historic Sites and ures Inventory has this property , 1979	been determined eligible?	
Indian Struct Summer	a Historic Sites and cures Inventory has this property	been determined eligible?	

## 7. Description

Condition       deteriorated         _X good       ruins         fair       unexposed	Check one unaltered altered	Check one X original site moved date	N/A
---	-----------------------------	--------------------------------------	-----

#### Describe the present and original (if known) physical appearance

#### The Commercial Area

The historic commercial area of Columbus forms the southwest corner of the historic district. Commencing opposite the Courthouse block at the south, and extending five and one-half blocks north along Washington Street to Seventh, the street is lined with two-and-three-story buildings, most constructed in the 1880's but with contributing representatives from as early as 1850. The commercial area extends east and west one block on either side of Washington along 3rd, 4th and 5th Streets. By far the most common architectural style represented here is the Italianate (numbers 5-07, 6-02, and 8-11). There are also outstanding examples of Federal style (7-04), Second Empire (Courthouse, 1-01), Queen Anne (Irwin Block, 8-03), Carpenter-Builder (Unger Monuments, 6-11), Neo-Classic (First National Bank, 6-10 and Old Post Office, 10-05), and Art Deco (Crump Theater, 5-10 and Reo Theater, 8-02).

Almost all of the contributing structures are of brick, with metal or stone trim. Decorative cornice lines and window hoods predominate the design of the Italianate structures while the Queen Anne buildings are decorated with metal oriel windows or brick or metal towers. The Neo-Classical structures are all of limestone with carved ornament. The Art Deco theaters, both results of 20th century remodelings of earlier buildings, have glass or enameled metal facades in bold geometric patterns.

Many buildings in the commercial area are constructed with cast-iron and pressed metal buildir components manufactured in Golumbus. The local firm of B. Busch made shopfronts for several buildings (5-07, 8-11). Prior to 1872 the Columbus Machine and Millwright Company produced fronts marked "C.M.&M. Co., Columbus" (6-01). There are also several iron fronts "imported" from Evansville, Indiana, and manufactured by the George Mesker Foundry (9-11, 3-06).

New construction in the commercial area adds variety to the streetscape and reflects the contemporary-historical mix for which Columbus is famous. There are 648 structures in the district.

#### The Residential Area

The more than 40 square blocks of residences in the Columbus Historic District are dotted with fine examples of Italianate, Queen Anne, Stick Style, Prairie and 20th Century Revival styles, intermixed with great numbers of workmen's homes of the late 19th century, known locally as "cross plan cottages." Franklin Street and Lafayette Avenue offer some of the most beautiful streetscapes, presenting a grand picture of pre-World War I Columbus. Here, closely-spaced houses of one and two stories sit in a park-like setting, occasionally high-lighted by large, ecclesiastical or institutional buildings.

The set-back distance of houses from the sidewalk varies from block to block, but is fairly consistent for buildings within the same block. Set-backs are in part dictated by the long, narrow lots present in much of the area. As the lots are much deeper than wide, the houses tend to be situated rather close to the street, with only five to ten feet between sidewalk and house; this arrangement opens up a larger private space to the rear of the house. Buildings are spaced closely in some blocks, with as little as five feet between them (Sycamore and Lafayette Streets north of 6th; 3rd Street east of Sycamore), or more distantly, as on Franklin Street north of 11th. Generally, the close spacing resulted from construction at different periods of time, when lots were subdivided and new buildings erected next to old.

Roof patterns participate actively in the residential streetscapes. The majority of homes in the District have gabled roofs, either of simple configuration or involving cross-gables sprouting from the main gable at various angles and positions. The effect of a street lined with roof shapes of similar proportions, yet with different details, produces a rhythmic continuity, punctuated here and there by an older, box-like Italianate, or a flamboyant Queen Anne.

(Continued)

## 8. Significance

Period prehistoric 1400–1499 1500–1599 1600–1699 X 1800–1899 X 1900–	Areas of Significance—C archeology-prehistoric archeology-historic agriculture architecture art X commerce communications		science sculpture social/ humanitarian theater
Specific dates	1821-1942	Builder/Architect	

#### Statement of Significance (Milene-panaguaph)

The Columbus Historic District is historically significant to the people of Columbus as the original center of the community's development and the heart of the modern-day city. Althoug very few resources remain from the town's earliest periods, the district is rich in resources from the 1870's on up to the present. The presence of rivers at the west and south edges of the downtown has limited its growth in those directions. Nevertheless, Columbus is fortunate that the downtown has encroached little on the adjacent residential neighborhoods. In addition, the district offers a fine collection of architecturally significant, late 19th and early 20th century buildings that are among the finest in the state. Of particular note are the cross-plan cottages, which are in greater abundance here than in other communities.

Columbus owes its existence to a strategic location at the center of the county, and at the confluence of several waterways. Bartholomew County was created by the State Legislature in January, 1821. Soon after, the county seat was established near the center, where the Flat Rock and Driftwood Rivers met at the East Fork of the White River. First called Tiptona, the town was renamed Columbus within months of its founding in 1821.

The early community was centered at the southwest corner of the District. Because of the natural boundaries created by the rivers and the swampy areas to the west and south, the town proceeded to grow north and east from there (see Growth Map).

Other than its function as the county seat, the town served as an agricultural and water transportation center in the early years. Flatboats used the White River to carry grain, beeswax, pelts, wood, and some livestock to the Ohio and Mississippi Rivers. Sawmills, grist mills, and woolen mills made use of the abundant local resources, with the first in-town grist mill being opened in 1835 just north of the District.

Very little remains from the early agricultural days of Columbus. The Ulrich Bakery (7-04; p. 7, 1850), the Samuel Harris House (8-05, p. 7, 1853), and the Keller House (31-06; p. 19, 1860), are among the mere handful of buildings in the District that date from before the Civil War.

Columbus' location placed it in the path of the Madison and Indianapolis Railroad, which came through in July, 1844. Railroad lines tying the city to Cincinnati, Louisville, and Shelbyville, were completed by 1850. Railroad Square and the first train depot in Columbus were located on the present site of the First Christian Church. The second depot was located on the present Old City Hall site. The railroad tracks now bypass the downtown, although the angled rear wall of building 4-02 is a lasting reminder of where the line was located.

The railroads and the Civil War dramatically changed Columbus from an agricultural community to a more diversified one with an active industrial base. The growing city elected its first city government in 1864. The First National Bank was established in 1865, and Joseph I. Irwin established the Irwin Bank in 1871. Industries began to spring up in the post-war period. The Cerealine Manufacturing Company, which began making one of the world's first ready-to-eat breakfast cereals in the 1860s, was followed by other agriculture-related firms, including Reeves and Company farm implements (1875), and the American Starch Company (1880s), who could process 4,000 bushels of corn per day. The only early industrial-type building remaining in the district is the Gent Mill (17-04, p. 11, c. 1875), now altered.


# 9. Major Bibliographical References

Please see continuation sheet

10. Ge	ograp	hical	Data			en Trans				
Acreage of non Quadrangle na UMT Reference	me CO I Ullibus	ty Approxin	nately 18	32 acres			Quadrang	le sc	ale 1:24,00	0
A 1 6 5 9 Zone Eas	13 1 8 0 ting	4 <sub>1</sub> 3 4 <sub>1</sub> 0 Northing	61910	•	B 1 <sub>16</sub> Zone	5 9 3 Easting	7,4,0	4 <sub>1</sub> .	3 4 10 7 13 10 thing	ו
E 116 5 9	0, 0, 8 E, 0 0, 7, 1 E, 0 0, 9, 0 E, 0	4 <sub>1</sub> 3 3 <sub>1</sub> 9   4 <sub>1</sub> 3 3 <sub>1</sub> 9   4 <sub>1</sub> 3 3 <sub>1</sub> 9	31410		D 1 <sub>1</sub> 6 F 1 <sub>1</sub> 6 H		3 2 1 8 1 5 3 1 1 0 1 0		3 3 <sub>1</sub> 9 3 <sub>1</sub> 5 <sub>1</sub> ( 3 3 <sub>1</sub> 9 4 <sub>1</sub> 0 <sub>1</sub> (	
Verbal bound	ary descript	ion and just	ification	(Justifi	cation,	see S	ignifica	ince)		
•	Plea	ase see co	ntinuatio	on sheet						٠.
List all states	and counti	es for prope	rties over	lapping s	ate or c	ounty b	oundaries	See	continuati	on shee
state N//			code	count					code	
state			code	count	у				code	
	rm Pro	epared	By							
name/title	Cynthia	Durko Lync Jones, Di	h, Direc	tor onsultar	t					
organization	Preserve	to Enjoy,	Inc.		d	late	Janua	ry 1	1, 1980	,
street & number	r 524 Thir	d Street			t	elephone	812/3	72-2	407	
city or town	Columbus				s	tate	India	na	47201	
12. St	ate Hi	storic	Pres	erva	tion	Offi	cer C	er:	tificat	ion
The evaluated										
•	national	_X_ s		X_ local						
As the designa 665), I hereby n according to the	ominate this	property for ii	nciusion in 1	fue usmom	ii negisie	I dilu coi	servation A tify that it I	ct of thas be	1966 (Public La een evaluated	aw 89–
State Historic F	Preservation C	Officer signatu	ıre	Na	Le	der				
title Indiana	State Hist	oric Prese	ervation	officer			date	10-1	9-82	rove bustonije sa
270 223 (16 23 1975)	e (all) 12 continue in the con	a propinij (b	nauvan		i Reciale	1	e e la companya di santa di sa			
Attest	re Nationa F	caster	VALUE OF	A Place			date		Tracin	

United States Department of the Interior Heritage Conservation and Recreation Service

# National Register of Historic Places Inventory—Nomination Form



Continuation sheet

Item number

7

Page One

Vegetation and tree cover provide pleasing visual effects as well as positive physical benefits throughout the residential area. Most streets in the area have generous tree cover, and many streets are almost park-like. Landscaping is common, with shrubbery and well-kept lawns predominating in the older area. Fences, too, whether locally made cast iron types from the late 19th Century, or the wooden picket type, add definition to property boundaries, especially on corner lots.

The Cross Plan Cottage

Of particular note in the residential area is the large number of "cross plan"cottages These are small, working-man's homes which exhibit many of the characteristics in detailing evident in larger Queen Anne, Stick Styleor Eastlake dwellings. The basic plan situates one room projecting toward the street, behind which are two rooms side by side, forming a cruciform plan. A side porch usually fills one of the spaces on the side of the front room. The houses are nearly all one story high, of frame construction, with intersecting gable roofs. Earliest examples of this type seem to be rather plain, with flat facades containing two windows (62-06, 26-28). In the 1880's, cut-away corners (corners cut at 45 degree angles) are popular, with fancy jig-sawn work at corners and on porch. Surface decoration, in the form of wavy siding or fish-scale shingles, is also common (59-01, 64-02). Later examples of the type are wider, with a shallower roof pitch and often have a one and one-half story section at the rear. Tacked-on bay windows are found on facades of houses built in the 1890's (15-02). Eastlake style porches of the 1880's and early 1890's are common, while later editions of cross plan houses have classical-form porches.

The cross plan cottage probably originated in an architectural pattern book. A publication called "Radford's Ideal Homes" contained house plans of this type from the 1880's well into the 20th Century in numerous editions. This book is known to have been used by local builders. Nearly 160 examples of this type of structure are found throughout the district. with concentrations on north Franklin, Sycamore and Chestnut Streets.

<u>Listings of Individual Structures within the District</u>

There follows a complete list of all buildings within the Columbus Historic District, numbered to correspond with the district sketch map, and containing descriptions and ratings for each. Outstanding buildings are marked "O", contributing buildings are marked "C" and non-contributing buildings (by reason of design or alterations) are marked "NC". Each structure is illustrated in the contact sheets included with this form; the photos are numbered with the same numbering system as appears in the list of descriptions.

CONTINUATION SHEET

#### ITEM NUMBER 7

PAGE THREE

## WASHINGTON STREET, WEST SIDE

- € 4-04. Commercial Building (532-534 washington St.), c. 1930, 1 story brick, battlement, vertical piers, stone banding; unaltered.
- C 4-05. Overstreet Building (538 washington St.), c. 1930, Chicago Commercial, 2 story brick, grouped windows, vertical piers, battlement, stone belt coursing.
- C 4-06. Commercial Building (542-548 washington St.), 1897, Victorian Romanesque; 2 story block, belt coursing, corbeling, battlement, oriel windows, oriel tower on corner, 1st floor altered. U. S. Post Office 1897-1910.

PAGE FOUR

## WASHINGTON STREET, EAST SIDE

- C 5-02. Commercial Building (201-205 washington St.), c. 1890, 2 story brick, cast iron pilasters, first floor cornice and window hood.
- NC 5-03. Commercial Building (207 washington St.), late 19th c., 2 story brick, extensive alterations; non-contributing.
- C 5-04. Eagles Building (211-219 washington St.), 1927, Moderne, 2 story brick; two toned brick, paired windows, parapet.
- C 5-05. Commercial Building (223 Washington St.), c. 1880, Italianate, 2 story brick, cast iron 1st floor cornice, window hood, columns, pilasters. B. Busch iron.
- NC 5-06. Commercial Building (225 washington St.), c. 1880, remodeled 1978; 2 story brick, cast iron columns, extensive alterations; non-contributing.
- O 5-07. Crump's Block (227-233 washington St.), 1872, Italianate, 2 story brick, cast iron facade, window hoods, cornice, pilasters, finial each end of cornice; pediment removed, 10 bay facade. B.Busch iron.
- C 5-08. Schwartzkopf Building (235-237 washington St.), 1885, Italianate, 2 story brick, pressed metal bracketed cornice; 7 bay facade, pediment removed.
- O 6-02. Irwin's Bank Building (301 washington St.), 1881, Italianate, 2 story brick, cast iron columns, recessed entry, pressed metal first floor cornice, window hood, heavy cornice with paired brackets; stone belt coursing and quions, finial each end of cornice, broken pediment with "Irwin's Bank/1881, "B. Busch iron; 5 bay facade; 1970's rennovation, entries altered, excellent condition.
- O 6-03. Masonic Temple (305 washington St.), 1931, Neo-Classic; 4 story ashlar stone, 3 bay facade, fluted pilasters, dentiled cornice, pressed metal pilasters on 1st floor; unaltered, excellent condition. St. John's Lodge No. 20 occupied a building on this site 1853-1979.
- 6-04. Rosenbush Building (309 Washington St.), 1912, Chicago Commercial, 2 story brick, stone belt coursing, decorative brick cornice, geometric designs, grouped windows, 1st floor altered, excellent condition. Rosenbush family was in the clothing business in this block from c. 1880 to c. 1930.
- NC 6-05. Commercial Building (315 washington St.), c. 1875, remodeled 1937, 3 story brick, large metal discs at roofline, extensively altered, non-contributing.
- NC 6-06. Commercial Building (321 Washington St.), 1976, 2 story brick, arched arcade, non-contributing.
- C 6-07. Carter Building (325 washington St.), 1907, 3 story brick, stone window sills and lintels, parapet; 1st floor facade altered.

CONTINUATION SHEET

## ITEM NUMBER 7

## WASHINGTON STREET, EAST SIDE

- 6-08. Commercial Building (327 washington St.), 19th c., 2 story glazed brick, 1st floor altered.
- O 6-09. Zaharako's (329 Washington St.), 1900, 2 story brick, heavy cornice with dentils, egg and dart design. Dutstanding interior with onyx counters, stained glass, paneled and carved wood. Documented by HABS. Zaharako Bros. have had a candy store and restaurant here since 1900.
- 6-10. First National Bank Building (331-333 washington St.), Neo-Classic, 1925; 3 story ashlar stone, fluted capitalized pilasters, heavy dentiled cornice, ballustrade, marble water table. Unaltered, excellent condition.
- C 7-06. Crump-Lucas Building (401-411 washington St.), c. 1910, Chicago Commercial, 2 story brick, 8 bay facade, oriel windows, parapet, pressed metal belt coursing and cornice; altered 1st floor.
- C 7-07. C. M. Keller Building (417 washington St.), 1913, Chicago Commercial, 3 story brick; metal cornice with paired brackets, parapet, vertical piers, grouped windows. Unaltered, excellent condition.
- C 7-08. Commercial Building (421-425 washington St), c. 1910, 2 story brick, oriel windows, corbeling, tapestry brick, decorative brick work; altered 1st floor.
- C 7-09. Commercial Building (427 washington St.), c. 1890, 2 story brick, pressed metal window hoods and 1st floor cornice, top cornice removed, 1st floor altered.
- NC 7-10. Commercial Building (431 washington St.), c. 1890, 2 story brick, metal panel facade, extensive alterations, non-contributing.
  - 7-11. Law Building (433 washington St.), c. 1900, Chicago Commercial, 3 story stone, mansard roof, bracketed cornice, grouped windows, recessed entry, lion head ornaments; unaltered.
- NC 7-12. Citizen's Savings and Loan Building (435 Washington St.), 1973, 2 story brick; non-contributing.
- NC 8-07. Home Federal Building (501 washington St.), 1960, 2 story brick, metal panels and screens; non-contributing.
  - 8-08. Commercial Building (511-515 washington St.), c. 1880, Italianate, 2 story brick, pressed metal bracketed cornice, pressed metal window hoods, beltcoursing, 1st floor alterations, 7 bay facade.
- C 8-09. Commercial Building (517-519 washington St.), c. 1880, Italianate, 7 bay facade, pressed metal bracketed cornice, pressed metal window hoods, 1st floor alterations.
- C 8-10. Commercial Building (521-523 washington St.), c. 1880, Italianate, 7 bay facade, pressed metal bracketed cornice, pressed metal window hood. 1st floor alterations. B. Busch iron, Colubus.

PAGE SIX

## WASHINGTON STREET, EAST SIDE

- 8-11. Mercantile Block (525-531 washington St.), c. 1880, Italianate; 2 story brick, 14-bay facade; pressed metal bracketed cornice, window hoods, and decorative lion heads; oriel windows; first floor altered; metal work stamped "B. Busch, Columbus, Ind."
- 9-07. Oddfellows Building (601-605 Washington St.), 1893, Queen Anne;
  3 story brick with tower; pressed metal window hoods (pediment-like);
  windows decoratively arranged in pairs and singly; fancy brickwork in
  gable, corbeling on tower; tower roof altered, first floor altered.
- 9-08. Commercial Building (607-609 Washington St.), 1891; 2 story brick, extensive alterations, non-contributing.
- 9-09. Commercial Building (611-615 Washington St.), c.1895; 2 story brick, corbeled cornice, stone window lintels and stils; first floor altered.
- 9-10. Commercial Building (617-619 Washington St.), c.1890; remodeled 1978; 3 story brick, 3 bay facade; large circular arched windows and bays; tall paired windows with metal hoods in central bay. Excellent condition.
- 9-11. Commercial Building (621-627 Washington St.), c.1890, Italianate; 2 story brick, 8 bay facade; wide pressed metal entablature, heavy bracketed cornice, pressed metal window hoods and first floor cornice; sone 1st floor alterations; George Mesker iron, Evansville.
- 9-12. Bassett Building (629 Washington St.), c.1910, Chicago Commercial;
  3 story brick, corbeled cornice, shallow piers with geometric pseudocapitals in stone; asymmetrical facade with 6-bay arcade (pointed arches)
  flanked by one bay on right and two bays on left; parapet peaks, forming
  pediment over arcade; stone banding; first floor cornice with large stone
  consoles; first floor altered with metal panels.
- Q 9-13. Charlotte Building (637-645 washington St.), c. 1925, Chicago Commercial; 2 story brick, 4 bay facade; grouped windows separated by brick piers; piers break above cornice line; brick corbeling under cornice; first floor retains dentiled cornice in brick; building turns corner, with 4 bays on Washington, 6 bays on 7th street. First floor alterations.
- 10-05. Old Post Office (703 washington St.), 1910, Neo-Classic, James Knox Taylor, architect. 2 story ashlar limestone; 5 bay facade, hip roof, dentiled cornice, balustrade. Tall first floor windows with small second floor windows above, separated by shallow piers. End bays project slightly, each contains tall entry door, with garlands over doors and large stone consoles. Raised basement. Excellent condition, now used as Community Educational Services Center.

PAGE SEVEN

- O 7-04. Ulrich Bakery (404 Franklin St.), c. 1850, Federal, 2 story brick, gable roof, end chimneys, 6 bay facade, stone sills and lintels, iron balcony, 6/6 lights in windows, large double door entrance. From 1856 to c. 1910, this building was a bakery owned and operated by Fred Ulrich, who had a government contract to bake bread for the Union Army during the Civil war. Attched to 7-03, Ulrich Block.
- O 8-05. Samuel Harris House (522 Franklin St.), 1853, Federal, 2 story brick, gable roof, box gutters, 3 bay facade, stone sills and lintels, 2/2 lights in windows, stone foundation, transomed doors. Now used as lawyers' offices. 8-05 and 8-06 were restored in 1970. Between the two houses, a garden was created. The quarter block is known as Franklin Square. Both Houses and garden are in excellent condition.
- O 8-06. william O. Hogue House (538 Franklin St.), 1870, Italianate, 2 story brick, low pitched hip roof, 3 bay facade, wide wood entablature with paired brackets, stone sills and lintels, transomed door with sidelights, stone foundation and water table; sash altered. Now used as interior design studio.
- C 9-01. A. B. Church House (604 Franklin St.), c. 1860, 2 story brick, 5 bay facade, columned porch with exposed rafters, gable/hip roof, fishscale shingles in gables. Built in the Federal style, roof and porch altered c. 1890. Now used as offices.
- NC 9-02. Commercial Building (606 Franklin St.), 1975, 1 story concrete block with brick facade. Non-contributing.
- NC 9-03. Commercial Building (618 Franklin St.), 20th c., 2 story concrete block with brick facade. Non-contributing.
- 9-04. Leist-Busse Apts. (622 Franklin St.), c. 1920, 2 story frame, low pitched hip roof, grouped windows, recessed central entrance.
- 9-05. House (624 Franklin St.), c. 1900, 2 story frame, jerkin head roof, lunette, portico with capitalized columns, clapboard siding.
- C 9-06. National Guard Armory (646 Franklin St.), 1925, 2 story brick, vertical piers, grouped windows, projecting central pavillion with compound elliptical arched entry and grouped circular arched windows. Unaltered, excellent condition. Now Indiana Vocational Technical College.
- NC 10-01. Indiana Bell Telephone Co. (420 7th St.), 1975, 2 story, reflective glass clad, space frame like trellisses front and side, Caudill, Rowlett and Scott, architects. Progressive Architecture (Magazine) citation winner, 1976.

PAGE EIGHT

- C 10-02. Franklin Building (724 Franklin St.), c. 1870, Italianate,2 story brick, hip roof, wide entablature, brackets removed, tall hooded windows except windows on facade altered, portico with capitalized columns, balcony, enclosed side porch, iron fence. Originally home of Nelson R. Keyes, distinguished Columbus attorney and judge.
- C 10-03. Aaron Hughes House (728 Franklin St.), 1883, Italianate, 2 story brick, hip roof, 3 bay facade, segmental arched windows with 2/2 lights, bay window, B. Busch iron fence, sun room addition on front. 60 year home of Hughes family, clinic of Dr. Dorothy Teal for 35 years, now Planned Parenthood.
- C 10-04. House (748 Franklin St.), 1938, Jacobethan Revival, 1½ story stone, slate roof, tudor arched entry, gable roof dormer windows, multigabled, circular arched porch, chimney pots, unaltered, excellent condition.
- O 11-02. Perry-Dunlap House (806 Franklin St.), late 19th c., 2 story brick, hip/gable roof, stone lintels and sills, box gutters, Eastlake porch, fishscale shingles in gables, bay window with fretwork at corners, excellent condition.
- O 11-03. House (814 Franklin St.), c. 1885, Queen Anne, 2 story frame, panelized, fishcale, waved and clapboard siding, multi-gabled, cut away corners with fretwork, lunette, decorative vergeboards.
- O 11-04. House (820 Franklin St.), c. 1885, Queen Anne, 2 story frame, multigabled, fishscale, waved and clapboard siding, panelized, tie beam and kingpost, corner brackets, sunburst, bay window, porch with capitalized columns and heavy cornice. Unaltered.
- C 11-05. Banker-Rost House (828 Franklin St.), late 19th c., remodeled c. 1920, Prairie, 2 story stucco, low pitch hip roof, wide eaves, stylized arched entry porch, sunroom addition on front.
- C 12-02. House (906 Franklin St.), c. 1930, Jacobethan Revival, 2 story stone, multi-gabled, bay window, arched entry, half-timbering, chimney pots, unaltered, excellent condition.
- C 12-03. House (914 Franklin St.), late 19th c., Free Classic, 2 story frame, multi-gabled, porch with capitalized columns and heavy cornice, fishscale, clapboard siding, corner brackets.
- C 12-04. House (920 Franklin St.), late 19th c., 2 story frame, cutaway corners, fretwork at corners, gable roof, asphalt siding.
- C 12-05. House (926 Franklin St.), c. 1885, Cross Plan Cottage, front bay window with concave roof, brick piered porch, asbestos siding.
- C 12-86. House (938 Franklin St.), late 19th c., 2 story frame, low pitch hip roof, clapboard siding, square bracketed oriel window, brick piered porch.

PAGE NINE

- C 13-02. House (1004 Franklin St.), c. 1890, Cross Plan Cottage, clapboard siding, brick piered porch.
- C 13-03. Baker S. Ruddick House (1006 Franklin St.), c. 1895, 2 story frame, gable roof, fishscale shingle, waved and clapboard siding, twin stained glass windows in gable, transomed doors, Eastlake detailing.
- C 13-04. House (1010 Franklin St.), c. 1895, identical to 13-03 except porch posts replaced and aluminum sided.
- C 13-05. House (1014 Franklin St.), c. 1920, 1 story frame, gable roof, large brick chimney and brick entry with jerkin head roof added, aluminum siding.
- C 13-06. House (1018 Franklin St.), c. 1895, virtually identical to 13-03, decorative vergeboard, brick piered porch.
- C 13-07. House (1022 Franklin St.), 20th c., 2 story frame, gable roof, clapboard siding, cornice returns, bracketed eaves, brick piered porch.
- C 13-08. Clay-Harrod House (1032 Franklin St.), c. 1910, Arts and Crafts, 2½ story brick, multi-gabled roof, half timbering, diagonal bracketed eaves, sun room. Unaltered, excellent condition.
- C 13-09. House (1040 Franklin St.), c. 1875, Second Empire, 2 story frame, mansard roof, tower with pyramidal roof, gable roof dormer windows, pediment-like window heads on 1st story windows, wide entablature, heavy bracketed cornice, polychromatic patterned shingles, asbestos siding.
- C 14-D1. C. C. McCullough House (1104 Franklin St.), c. 1900, Georgian Revival,  $2\frac{1}{2}$  story frame, hip roof, dormer windows, clapboard siding, bay window, ionic columned porch, projecting entry, transomed door with side lights.
- C 14-02. House (1114 Franklin St.), late 19th c., Cross Plan Cottage, cut away corners, multi-gabled, bay window on front, clapboard siding, brick piered porch.
- C 14-03. House (1120 Franklin St.), c. 1890, Cross Plan Cottage, brick piered porch, aluminum siding.
- C 14-04. James Coleman House (1130 Franklin St.), 1877, Italianate, 2 story frame, low pitch hip roof, box gutters, wide entablature, dentals, enclosed porch. Present owners are in process of restoring.
- C 15-D1. House (1204 Franklin St.), c. 1910, Bungalow,  $1\frac{1}{2}$  story frame, bracketed eaves, enclosed brick piered porch, dormer window, clapboard siding.

PAGE TEN

- C 15-02. House (1218 Franklin St.), late 19th c.,  $1\frac{1}{2}$  story frame, mult-gabled roof, fishscale shingles in gable, clapboard siding, front bay window, 20th c. porch.
- C 15-03. House (1224 Franklin St.), 20th c., Bungalow, 1½ story frame, gable roof, diagonal bracketed eaves, dormer windows, pediment like window heads, clapboard siding.
- C 15-04. House (1230 Franklin St.), late 19th c., Cross Plan Cottage, clapboard siding, enclosed porch.
- C 15-05. House (1234 Franklin St.), late 19th c., 1 story frame, gable roof, transomed door, decorative vergeboard, 20th c. gable roof porch, clapboard siding.
- C 15-06. House (1302 Franklin St.), late 19th c., 2 story frame, clapboard siding, large concrete block veranda with tapered posts.
- C 15-07. House (1304 Franklin St.), c. 1900, Colonial Revival, 2½ story frame, corner square bay window, side bowed bay window, gable roof, raking cornice with dentals, clapboard siding, columned veranda, entry door has side lights.
- C 15-08. House (1310 Franklin St.), late 19th c., Cross Plan Cottage, cut away corners, fretwork at corners, decorative vergeboard, clapboard siding, concrete piered porch.
- C 15-09. House (1316 Franklin St.), c. 1885, Cross Plan Cottage, cut away corners, fretwork at corners, transomed doors, Eastlake porch, clapboard siding, unaltered, excellent condition.
- C 15-10. House (1324 Franklin St.), late 19th c., Cross Plan Cottage, cut away corners, fretwork at corners, clapboard siding,
- C 15-11. House (1328 Franklin St.), late 19th c.,  $1\frac{1}{2}$  story frame, dormer windows added, asbestos siding.
- 15-12. House(1332 Franklin St.), late 19th c., Cross Plan Cottage, cut away corners, fretwork at corners, decorative vergeboard, transomed doors, clapboard siding. Unaltered but deteriorating condition.
- C 15-13. House (1338 Franklin St.), late 19th c., Cross Plan Cottage, cut away corners, aluminum siding.
- C 15-14. House (1404 Franklin St.), late 19th c., Cross Plan Cottage, corner square bay window, cut away corners, porch posts replaced, asbestos siding.

PAGE ELEVEN

- O 17-03. A. T. Griffith Building (305 Franklin St.), 1912, Chicago Commercial, 2 story brick, stone window lintels and sills, large square windows with prism glass, 3 by 8 bays, flat roof, doors replaced, excellent condition. Originally automobile dealership, now industrial training center.
- O 17-04. Gent Mill (315 Franklin St.), c. 1875, 3 story brick, 3 by 3 bays, large circular blind arcade, segmental arch windows, parapet walls, 1st floor additions on front and rear. Originally flour mill of J. R. Gent, now vacant.
- C 17-05. Garage (321 Franklin St.), c. 1910, 1 story brick, cast iron piers, parapet wall, corbeling, garage door opening, unaltered.
- C 17-D6. Robert D. Harden Building (331 Franklin St.), 1926, 1 story brick, tapastry brick, corbel table, verticle piers, unaltered, excellent condition.
- O 20-11. House (603 Franklin St.), c. 1890, Queen Anne,  $2\frac{1}{2}$  story frame, gable, hip roof, pedimented gable, bowed corner, bay window, fishscale, diagonal, waved and clapboard siding, stained galss, paneling, veranda with concrete posts. Excellent condition.
- 20-12. House (609 Franklin St.), c. 1890, 2 story frame, jerkin head roof,
- O 21-10. First United Presbyterian Church (703 Franklin St.), Victorian Gothic, 1871-1885, rectangular plan, brick, gable roof, tower with tall spire, pointed-arch windows, buttresses, round windows, stained glass, twin pointed arch doors on front, slate roof. Unaltered, excellent condition. Keller and Brockman, builders. Levi Levering, architect.
- NC 21-11. Presbyterian Church School (703 Franklin St.), 1948, 2 story brick, flat roof. Non-contributing.
- C 22-08. House (803 Franklin St.), c. 1915, Bungalow, 1½ story brick and stucco, gable roof, wide bracketed eaves, half timbering in gables, unaltered, excellent condition.
- C 22-09. House (813 Franklin St.), late 19th c., 2 story frame, gable roof, slate roof, stucco and half timbering in gables, brick piered porch, stained glass, aluminum siding.
- C 22-10. House (819 Franklin St.), c. 1910,  $2\frac{1}{2}$  story frame, clapboard siding, hip roof, dormer windows, leaded glass, wide eaves, brick piered porch. Unaltered, excellent condition.
- C 22-11. House (821 Franklin St.), late 19th c., remodeled c. 1920, 2 story brick and stucco, gable roof, wide bracketed eaves.

PAGE TWELVE

- C 22-12. House (825 Franklin St.), c. 1920,  $2\frac{1}{2}$  story brick and stucco, wide bracketed eaves, hip roof, dormer windows, entrance with side lights, sun room on front.
- C 23-07. House (903 Franklin St.), c. 1880, 2 story frame, hip roof, clapboard siding, bay window, brick piered porch, entry door with elliptical fan light and side lights.
- C 23-08. House (911 Franklin St.), late 19th c., 2 story frame, hip roof, clapboard siding, wide bracketed eaves, brick piered porch.
- O 23-09. Joseph F. Gent House (925 Franklin St.), 1873, Italianate, 2 story brick, pressed metal bracketed cornice, pressed metal window hoods, hip roof, fixed stained glass panel in each window, brick piered porch with heavy bracketed cornice, large rectangular plan with front and side bay windows, round windows, excellent condition.
- C 23-10. House (929 Franklin St.), c. 1900, Colonial Revival, 2½ story frame, hip roof, clapboard siding, wide eaves, extended rafters, side bowed-bay window, dormer windows, columned porch with wide cornice, dentals.
- O 24-06. House (1001 franklin St.), late 19th c., 2 story frame, low pitch hip roof, lights in entablature, dentals, clapboard siding, garlanded window hoods, french doors with leaded glass, garlanded, columned porch. Unaltered.
- O 24-07. House (1019 Franklin Street), late 19th c., Queen Anne, 2 story frame, gable roof, cut-away corners, fishscale, diagonal and clapboard siding, fretwork at corners, circle framed window, 20th c. porch. Excellent condition.
- O 24-08. House (1023 Franklin St.), c. 1910, Prairie, 2 story brick, hip roof, wide bracketed eaves, belt coursing, decorative brickwork, door with stained glass side lights, brick piered porch, balcony. Excellent, unaltered condition. Campbell + Osterhage architects Vincennes IN.
- C 24-09. House (1025 Franklin St.), late 19th c., 2 story frame, gable roof, decorative vergeboard, brick piered porch, asphalt siding.
- C 24-10. House (1027 Franklin St.), c. 1900, Dutch Colonial Revival, 2 story frame, gable roof dormer window, fishscale shingle and aluminum siding, partially enclosed porch. Originally same as 24-11.
- C 24-11. House (1033 franklin St.), c. 1900, Dutch Lolonial Revival, 2 story frame, gable roof dormer window, fishscale shingle and clapboard siding, porch with square posts and railing, lattice porch base.
- C 24-12. House (505 11th 5t.), late 19th c., 2 story frame, low pitch hip roof, clapboard siding, cornice-like window heads, wide entablature with dentals, enclosed front porch, side entrance with transom and side lights.

PAGE THIRTEEN

- 25-05. James Glanton House (1103 Franklin St.), c. 1875, 2 story frame, gable/hip roof, box gutters, side bay window, 20th c. enclosed porch on front, asbestos siding. Glanton was a local furniture maker.
- C 25-86. House(113 Franklin St.), c. 1885, Italianate, 2 story frame, hip roof, bracketed cornice, cornice-like window heads, transomed doors, side bay window, ionic columned porch.
- d 25-07. House (1119 Franklin St.), late 19th c., 2 story frame, jerkin head roof, clapboard siding, side bay window, columned porch.
- C 25-08. House (1129 Franklin St.), late 19th c., 2 story frame, hip roof, side bay window, asphalt siding, brick piered porch.
- C 26-15. Jarastus Dunlap House (1203 Franklin St.), 1884, 2 story frame, multi-gable roof, side bay window, oval window, enclosed porch, asbestos siding; Dunlap started in the building industry in 1877 with James Perkinson and the firm of Dunlap and Coats was one of the largest building/building supply companies of the late 19th c. in Columbus.
- C 26-16. House (1211 Franklin St.), c. 1910, 2 story frame, hip roof, dormer window, side bay window, ionic columned porch, leaded glass, clapboard siding.
- C 26-17. House (1219 Franklin St.), late 19th c., Cross Plan Cottage, front bay window, decorative vergeboard, clapboard siding, 20th c. porch.
- d 26-18. House (1227 Franklin St.). late 19th c., Cross Plan Cottage, side hay window, decorative vergeboards, transomed doors, aluminum siding, 20th c. porch.
- C 26-19. House (1233 Franklin St.), c. 1885, Cross Plan Cottage, enclosed porch, asbestos siding.
- C 26-20. House (1301 Franklin St.), c. 1880, 2 story frame, multi-gable roof, transomed doors, veranda with turned posts, asbestos siding.
- C 26-21. House (1309 Franklin St.), c. 1875, 2 story frame, gable roof, clap-board siding, cornice-like window heads, tall 1st story windows, 20th c. porch, excellent condition.
- C 26-22. House (1315 Franklin St.), c. 1880, Cross Plan Cottage, front bay window, porch replaced, aluminum siding.
- C 26-23. House (1321 Franklin St.), c. 1875, 2 story brick, gable roof, segmental arch windows and doors, corbeled window heads, bracketed eaves, 20th c. veranda.
- C 26-24. House (1329 Franklin St.), c. 1880, Cross Plan Cottage, cut-away corners with fretwork at corners, transomed doors, porch posts replaced, asphalt siding.

CONTINUATION SHEET

ITEM NUMBER 7

PAGE FOURTEEN

- C 26-25. House (1331 Franklin St.), c. 1880, Cross Plan Cottage, decorative vergeboard, porch with turned posts, clapboard siding, transomed doors, front windows altered.
- C 26-26. House (1335 Franklin St.), c. 1880, Cross Plan Cottage, aluminum siding, porch enclosed, non-contributing.
- C 26-27. House (1339 Franklin St.), c. 1890, Cross Plan Cottage, multigabled, fishscale and clapboard siding, pedimented porch with turned posts.
- C 26-28. House (1403 Franklin St.), c. 1880, Cross Plan Cottage, transomed doors, clapboard siding, porch replaced.
- C 26-29. House (1411 Franklin St.), c. 1880, Cross Plan Cottage, decorative vergeboard, transomed doors, 20th c. porch with square posts.
- C 26-30. House (1413 Franklin St.), c. 1880, Cross Plan Cottage, cornicelike window heads, clapboard siding, porch with concrete posts.

PAGE FIFTEEN

- O 20-02. House (604 Lafayette Ave.), c. 1865, Italianate, 2 story brick, wooden cornice with paired brackets, gable roof, rear extension with crossing gable roof, brick piered porch.
- C 20-03. House (608 Lafayette Ave.), c. 1890, Cross Plan Cottage, cut-away corners, diamond pattern shingles and clapboard siding, brick piered porch.
- C 20-04. Frank Ueberroth House (612 Lafayette Ave.), c. 1865, 1½ story wood frame, steep gable roof, board and batten siding, arched windows and doors, Eastlake porch, dormer window added on side c. 1975.
- C 20-05. John Mahoney House (616 Lafayette Ave.), late 19th c., 2 story frame, steep gable roof, clapboard siding.
- Q 20-06. House (624 Lafayette Ave.), late 19th c., Free Classic, 2 story frame, hip/gable roof, fishscale shingles, clapboard siding, lunette, bay window, pedimented, columned porch, decorative chimney, corner brackets.
- C 20-07. Uberroth-Seward House (628 Lafayette Ave.), c. 1865, remodeled c. 1920, 1 story brick, gable roof, pedimented gable, eliptical arched portico, entry with french doors and eliptical arched fanlight, segmental arched windows.
- C 20-08. Brown-Seward House (632 Lafayette Ave.), 1903,  $1\frac{1}{2}$  story frame, gable roof, clapboard siding, leaded glass windows.
- C 20-09. House (638 Lafayette Ave.), c. 1890, Cross Plan Cottage, cut away corners, tall windows, cornice-like window heads, tin roof, Eastlake porch, fishscale shingle and aluminum siding.
- C 20-10. House (644 Lafayette Ave.), c. 1890,  $2\frac{1}{2}$  story frame, multi gabled, bay window, decorative chimneys, brick piered porch, aluminum siding.
- O 21-02. John S. Grump House (704 Lafayette Ave.), 1872, Italianate, 2 story brick, low pitch hip roof, wide entablature, heavy cornice with paired brackets, stone water table, stone window lintels and sills, flat roof porch with concrete columns and ballustrade, cast iron fence.
- C 21-03. House (712 Lafayette Ave.), c. 1910, Colonial Revival, 2½ story frame, hip roof, gable roof dormer window, entrance with sidelights, leaded glass, columned porch with railing, aluminum siding.
- O 21-04. House (718 Lafayette Ave.), mid 19th c., 1 story, low pitch gable roof, 3 bay facade, clapboard siding tall double hung windows, 2/2; wood sills and heads, wide wood water table, eliptical arched portico with wide cornice and fretwork, end chimney.

PAGE SIXTEEN

- C 21-05. House (722 Lafayette Ave.), Cross Plan Cottage, brick piered porch, aluminum siding.
- O 21-06. House (724 Lafayette Ave.),c,1880, Cross Plan Cottage, clapboard siding, decorative vergeboard, columned, garlanded veranda, pedimented gable with sunburst, fan brackets, pediment-like window heads, transomed doors, excellent, unaltered condition.
- C 21-07. House (726 Lafayette Ave.), c.1880, Cross Plan Cottage, identical to 21-06 except porch post bases have been cut off and replaced with brick bases.
- C 21-08. House (738 Lafayette Ave.), c. 1900, Georgian Revival, 2½ story frame, hip roof, clapboard siding, hip roof dormer window, twin oriels, leaded and stained glass, entry with sidelights, pedimented, columned porch with railing. Excellent, unaltered condition.
- O 21-09. House (748 Lafayette Ave.), c. 1890, Queen Anne,  $2\frac{1}{2}$  story brick, multi gable roof, square oriel with fishscale shingles, diagonal shingles, sunbursts, bracketed, columned gable roof porch, stone window sills and lintels, transomed doors, large corner brackets, side bay windows. Excellent, unaltered condition.
- C 22-07. House (818 Lafayette Ave.), c. 1910, Bungalow,  $1\frac{1}{2}$  story frame gable roof, diagonal bracketed eaves, latticed windows, brick piered porch, shed roof dormer windows, aluminum siding.
- $\mathcal{C}$  23-02. House (904 Lafayette Ave.), 20th c., Arts and Crafts,  $1\frac{1}{2}$  story frame, jerkin head roof, multi-gabled, large side chimney, aluminum siding.
- O 23-03. Patram House (914 Lafayette Ave.), c. 1870, 1½ story steep gable roof, clapboard siding, pediment like window heads, windows partially closed up.
- C 23-04. House (918 Lafayette Ave.), c. 1910, 1½ story frame, hip/gable roof, palladian window, columned porch, oriel windows, partially enclosed porch.
- C 23-05. House (926 Lafayette Ave.), c. 1880, Cross Plan Cottage, cut away corners, fretwork and pendants at corners, decorative vergeboard brick piered porch.
- C 23-06. House (934 Lafayette Ave.), late 19th c., Cross Plan Cottage, multigable roof, sunroom addition on front.
- C 24-05. House (1026 Lafayette Ave.), late 19th c., Cross Plan Cottage, partially enclosed porch.

PAGE SEVENTEEN

- C 25-02. House (1114 Lafayette Ave.), late 19th c., Cross Plan Cottage, panelized, fishscale, diagonal shingles, waved siding, cut-away corners with fretwork and pendants at corners, tie beams, king posts, multi gabled. Unaltered but deteriorating condition.
- C 25-03. House (1118 Lafayette Ave.), late 19th c., Free Classic, 1½ story frame, gable roof, pedimented curved ionic columned porch, bowed bay window, transomed door with side lights, palladian like window, dormer window, bay window, shingles in gable, clapboard siding. Excellent, unaltered condition.
- C 25-04. House (1128 Lafayette Ave.), late 19th c., Queen Anne, 2 story frame, multi gabled, cut away corners, surburst, decorative chimneys, asbestos siding.
- C 26-01. House (1204 Lafayette Ave.), late 19th c., Cross Plan Cottage, porch altered, asbestos siding.
- C 26-02. O'Brien-Anderson House (1212 Lafayette Ave.), Italianate, 1883, 2 story brick, pressed metal cornice with paired brackets, 2 story corner bay window, segmental arched windows and doors, concrete columned veranda. Girlhood home of Margaret Anderson, editor of the "Little Review," published in Chicago, 1914-1929.
- C 26-03. House (1220 Lafayette Ave.), c. 1885, Cross Plan Cottage, diamond, fishscale shingles and vertical board siding, clapboard siding, sunbursts, cut away corners.
- C 26-04. House (1226 Lafayette Ave.), c. 1885, Cross Plan Cottage, brick piered porch, aluminum siding.
- C 26-05. House (1234 Lafayette Ave.), c. 1885, Cross Plan Cottage, enclosed porch.
- C 26-06. House (1250 Lafayette Ave.), c. 1910, 2 story frame, hip roof, dormer window, brick piered porch, wide eaves, clapboard siding.
- C 26-07. House (1304 Lafayette Ave.), c. 1885, 2 story frame, hip roof, brick piered porch, asbestos siding.
- C 26-08. House (1308 Lafayette Ave.), c. 1885, Cross Plan Cottage, brick piered porch, aluminum siding.
- C 26-09. House (1314 Lafayette Ave.), late 19th c., Italianate, 2 story frame, hip roof, enclosed porch, aluminum siding.
- C 26-10. House (1322 Lafayette Ave.), c. 1885, Cross Plan Cottage, window and door alterations, aluminum siding.
- C 26-11. House (1326 Lafayette Ave.), c. 1885, Cross Plan cottage, brick piered porch.

CONTINUATION SHEET

ITEM NUMBER 7

PAGE EIGHTEEN

- C 26-12. House (1334 Lafayette Ave.), c. 1885, Shotgun Cottage, shed roof porch with turned posts, aluminum siding.
- C 26-13. House (1336 Lafayette Ave.), 20th c., Bungalow, 1½ story frame, gable roof, diagonal bracketed wide eaves, dormer windows, aluminum siding.
- O 26-14. Henry Strassner House (1404 Lafayette Ave.), c. 1880, 2 story, steep gable roof, 3 bay facade, fishscale shingle and clapboard siding. 2nd story facade has decorative pressed metal piers, modillians, rosettes, pedimented gable. Gabled veranda with spindles in gables and turned posts, extended rafters. Unaltered. Strassner was a local tinsmith specializing in metal cornices.

PAGE NINETEEN

- C 28-06. House (423 and 425 Lafayette Ave.), c. 1920, 2 story frame, multi gabled roof, clapboard siding, twin oriels, half timbering, bracketed eaves, brick porch, stained glass.
- NC 28-07. House (427 Lafayette Ave.), c. 1915, 2 story frame, gambrel roof, aluminum siding, extensively altered. Non-contributing.
  - C 30-04. House (609 Lafayette Ave.), late 19th c., Cross Plan Cottage, cut away corners, rear additions, aluminum siding.
  - C 30-05. House (611 Lafayette Ave.), 1916, Colonial Revival, 2 story frame, cornice returns, pilasters, columned porch, portice, clapboard siding, entry with elliptical fanlight and sidelights. Unaltered, excellent condition.
- O 30-06. House (619 Lafayette Ave.), c. 1910, Prairie, 2 story stucco, low pitch hip roof, grouped casement windows, wide eaves, sun room, excellent, unaltered condition.
- C 30-07. House (621 Lafayette Ave.), c. 1900, 1½ story frame, multi gabled roof, clapboard siding, concrete block porch and foundation.
- 20-08. House (623 Lafayette Ave.), c. 1900, 2½ story frame, hip roof, clapboard siding, dormer window, enclosed veranda.
- 30-09. Stansifer House (637 Lafayette Ave.), c. 1865, 2 story brick, gable roof, stone window lintels and sills; 20th c. addition on front, apartment building.
- C 30-10. Brown House (645 Lafayette Ave.), c. 1930, Arts and Crafts, 2 story brick, hip roof, wide eaves with consoles, dormer window, portico, sunroom.
- O 31-06. Adam Keller House (703 Lafayette Ave.)c. 1860, Italianate, 2 story brick, hip roof, cornice with paired brackets, paneled entablature, stone window lintels and sills, veranda with heavy cornice and paired columns, tall windows, transomed door. Unaltered, excellent condition. House is still in Keller family.
- C 31-07. House (713 Lafayette Ave.), 20th c., 2½ story frame, pedimented gable, wide eaves, heavy brick porch, stained glass, aluminum siding, Colonial Revival.
- d 31-08. House (719 Lafayette Ave.), 20th c., Colonial Revival, 2 story frame, wide eaves, heavy brick porch, dormer window, stained glass.
- O 31-09. House (723 Lafayette Ave.), c. 1890, Queen Anne, 2½ story frame, fishscale shingle, waved, clapboard siding, panelized, columned porch, transomed entry door with sidelights. Unaltered, excellent condition.
- C 31-10. Smith Jones House (725 and 727 Lafayette Ave.), c. 1860, remodeled c. 1930, Arts and Crafts, 2 story stucco, gable roof, gable roof dormer windows, half timbering. Smith Jones was the first mayor of Columbus. House is now a duplex.

- O 31-11. Fred Volland House (737 Lafayette Ave.), c. 1870, Italianate, 2 story brick, gable roof, 3 bay facade, box gutters, stone window lintels and sills, bracketed hood over transomed double doors, side bay window. Excellent, restored interior.
- C 32-03. House (819 Lafayette Ave.), c. 1910, Bungalow, 1½ story frame, bracketed eaves, dormer window, brick piered porch, clapboard siding.
- O 33-10. F. M. Stevens House (903 Lafayette Ave.), late 19th c., Queen Anne, 2 story frame, multi gabled roof, cut away corners,, turned porch posts, sunburst in porch gable, fishscale shingle, diagonal and asbestos siding, double doors with stained glass.
- C 33-11. Charles Kerr House (915 Lafayette Ave.), c. 1875, Italianate, 2 story frame, hip roof, pediment-like window heads, clapboard siding, box gutters, corner pilasters, transomed door, iron fence.
- C 33-12. House (919 Lafayette Ave.), late 19th c., 1 story frame, transomed doors, cornice returns, turned porch posts, brackets, clapboard siding, rear additions.
- NC 33-13. Commercial Building (921 Lafayette Ave.), 20th c., 1 story concrete block. Non-contributing.
- NC 33-14. Commercial Building (925 Lafayette Ave.), 20th c., 1 story frame, asphalt siding.
- C 33-15. Commercial Building (933 Lafayette Ave.), 19th c., 2 story brick, segmental arch windows, flat roof, altered first floor.
- NC 34-03. Commercial Building (1001 Lafayette Ave.), 19th c., 1 story brick, facade altered. Non-contributing.
- C 34-04. House (1007 Lafayette Ave.), late 19th c., Cross Plan Cottage, vertical wood siding, side bay window.
- C 34-05. House (1011 Lafayette Ave.), late 19th c., Cross Plan Cottage, front bay window, 20th c. porch.
- C 34-06. House (1019 Lafayette Ave.), 20th c., 2 story frame, wide eaves, dormer window, asbestos siding.
- C 34-07. House (1023 Lafayette Ave.), late 19th c., Cross Plan Cottage, enclosed porch, windows altered, asbestos siding.
- C 34-08. House (1029 Lafayette Ave.), late 19th c., Cross Plan Cottage, cut away corners, clapboard siding, brick piered porch.
- C 34-09. House (1033 Lafayette Ave.), late 19th c., 1½ story frame, , gambrel roof, cut-away corners, fishscale shingle and clapboard siding, 20th c. porch.

PAGE TWENTY TWO

- C 37-06. House (1303 Lafayette Ave.), c. 1885, Cross Plan Cottage, rear additions, 20th c. porch, aluminum siding.
- C 37-07. House (1305 Lafayette Ave.), late 19th c., Cross Plan Cottage, cut away corners, turned porch posts, tie beam and kingpost, asphalt siding.
- NC 37-08. House (1309 Lafayette Ave.), late 19th c., Cross Plan Cottage, enclosed porch, altered windows, asbestos siding. Non-contributing.
- C 37-09. House (1317 Lafayette Ave.), late 19th c., Cross Plan Cottage, multi-gabled, cut away corners, aluminum siding, twin side porches.
- C 37-10. House (1325 Lafayette Ave.), late 19th c., Cross Plan Cottage, cut away corners, asbestos siding.
- C 37-11. House (1335 Lafayette Ave.), c. 1900, 1½ story frame, multigabled, decorative vergeboards, lunette, aluminum siding, brick piered porch.
- C 38-06. House (1403 Lafayette Ave.), c. 1885, 2 story frame, steep gable roof, hooded windows, 20th c. side porch, asbestos siding.
- C 38-07. House (1405 Lafayette Ave.), late 19th c., Cross Plan Cottage, porch removed, doors altered, aluminum siding.
- C 38-08. House (1409 Lafayette Ave.), late 19th c., Cross Plan Cottage, cut away corners with fretwork at corners, fishscale shingle, diagonal and clapboard siding, porch replaced.
- C 38-09. House (1419 Lafayette Ave.), late 19th c., Cross Plan Cottage, decorative vergeboards, turned porch posts.

PAGE TWENTY ONE

- C 34-10. House (1039 Lafayette Ave.), late 19th c., 2 story frame, hip roof, bay window with spindles and fretwork at corners, Eastlake porch and balcony, waved and clapboard siding, panelized.
- C 35-06. House (1105 Lafayette Ave.), c. 1870, 2 story frame, low pitch hip roof, clapboard siding, tall windows, square pillared porch, lattice like porch screen. Unaltered.
- C 35-07. House (1109 Lafayette Ave.), c. 1920, Bungalow,  $1\frac{1}{2}$  story frame, gable roof, bracketed eaves, clapboard siding, dormer window, sunroom, aluminum siding.
- C 35-08. House (1111 Lafayette Ave.), late 19th c., Cross Plan Cottage, multi gable roof, columned porch, clapboard siding.
- C 35-09. House (1117 Lafayette Ave.), late 19th c., Cross Plan Cottage, transomed doors, Eastlake porch.
- C 35-10. House (1121 Lafayette Ave.), c. 1915, Bungalow,  $1\frac{1}{2}$  story frame and stucco, gable roof, shed roof dormer window, brick piered porch, wide, bracketed eaves.
- C 35-11. House (1129 Lafayette Ave.), late 19th c., Cross Plan Cottage, cut away corners, side bay window, decorative vergeboards, clapboard siding, brick piered porch.
- C 36-05. House (1203 Lafayette Ave.), c. 1880, Cross Plan Cottage, asbestos siding.
- C 36-06. House (1209 Lafayette Ave.), late 19th c., Cross Plan Cottage, decorative vergeboard, multi-gabled, clapboard siding, concrete columned porch.
- C 36-07. House (1213 Lafayette Ave.), late 19th c., Cross Plan Cottage, corner brackets, clapboard siding.
- C 36-08. House (1217 Lafayette Ave.), late 19th c., Cross Plan Cottage, multi-gabled, columned porch with railing, transomed doors, aluminum siding.
- C 36-09. House (1221 Lafayette Ave.), late 19th c., Cross Plan Cottage, corner brackets, Eastlake porch, clapboard siding.
- C 36-10. House (1225 Lafayette Ave.), late 19th c., Shotgun Cottage, transomed doors, clapboard siding, porch removed.
- d 36-11. House (1227 Lafayette Ave.), c. 1885, Cross Plan Cottage, multi-gabled roof, columned porch with pediment and wide entablature, clapboard siding.

PAGE TWENTY THREE

#### PEARL STREET, WEST SIDE

- NC 28-05. House (418 Pearl St.), 20th c., 2 story frame, hip roof, extensive alterations. Non-contributing.
- NC 28-12. Apartment Building (428 Pearl St.), c. 1960, 1 story brick. Non-contributing.
- NC 31-04. Olympia Dairy (718 Pearl St.), c. 1940, 1 story glazed brick and glass. Non-contributing.
- O 31-05. washington Shool (722 Pearl St.), 1887, 2 story brick, hip roof, segmental arch windows, pressed metal bracketed cornice, entrance hood and pilasters, brick and stone belt coursing, stone steps and foundation, Tower over entry removed. Deteriorating condition. First high school in Columbus, now vacant. Charles F. Sparrell, architect.
- C 33-06. House (914 Pearl St.), late 19th c., Cross Plan Cottage, cut away corners.
- NC 33-07. House (922 Pearl St.), c. 1890, 2 story frame, gable roof, shingle and clapboard siding, panelized, windows altered.
- NC 33-08. House (924-926 Pearl St.), late 19th c., two Shotgun Cottages joined together, aluminum sided, non-contributing.
- O 33-09. House (633 10th St.), Italianate, c. 1875, 2 story frame, Hip roof, pediment-like window heads, wide entablature, Castlake porch.
- C 34-01. Banfill-Hays-Thomas House (1022 Pearl St.), 2 story brick, hip roof, heavy bracketed cornice, belvedere, front additions, segmental and circular arched windows. James w. Perkinson, builder. Now Hathaway-Myers Funeral Chapel. c. 1870, Italianate.
- C 34-02. House (1038 Pearl St.), c. 1920, 2 story frame, hip roof, dormer window, enclosed porch, aluminum siding.
- C 35-03. House (116 Pearl St.), 1880, 2 story frame, hip roof, cut away corners, panelized.
- C 35-04. House (1122 Pearl St.), c. 1895, 2 story frame, hip roof, dormer window, slate roof, extended eaves, exposed rafters.
- C 35-5. House (1130 Pearl St.), c. 1885, 2 story frame, hip roof, extended eaves, cornice-like window heads, enclosed porch.
- NC 36-01. House (1202 Pearl St.), Cross Plan Cottage, 20th c. porch, aluminum siding. Non-contributing.
  - O 36-02. House (1212 Pearl St.), c. 1890, free Classic,  $2\frac{1}{2}$  story frame, gable roof, pedimented gables, shed roof dormer window, turret, classical porch and balcony, fishscale shingle and clapboard siding.

PAGE TWENTY FOUR

## PEARL STREET, WEST SIDE

- C 36-03. House (1228 Pearl St.), c. 1890, Cross Plan Cottage, cut away corners.
- C 36-04. House (1230 Pearl St.), late 19th c., Cross Plan Cottage, cutaway corners, decorative vergeboard, fishcale shingles, diagonal, waved and asbestos siding, multi-gabled.
- Q 37-01. House (1304 Pearl St.), c. 1890, Cross Plan Cottage, porch with conical roof, cornice-like window heads, clapboard siding.
- C 37-02. House (1314 Pearl St.), c. 1900, 2 story frame, multi-gabled, vergeboard, tie beam and kingpost, exposed rafters, cornice like window heads, clapboard siding.
- C 37-03. House (1320 Pearl St.), c. 1880, 2 story frame, gable roof, clapboard siding, transomed doors, concrete block porch pillars.
- C 37-04. House (1324 Pearl St.),c. 1885, Cross Plan Cottage, exposed rafters, clapboard siding, enclosed porch, door altered.
- C 37-05. House (1328 Pearl St.), c. 1885, Cross Plan Cottage, aluminum siding.
- d 38-02. House (1402 Pearl St.), c. 1885, Cross Plan Cottage, aluminum siding.
- C 38-03. House (1408 Pearl St.), c. 1885, Cross Plan Cottage, asbestos siding.
- C 38-04. House (1414 Pearl St.), c. 1885, Cross Plan Cottage, aluminum siding.
- C 38-05. House (1418 Pearl St.), late 19th c., Shotgun Cottage, aluminum siding.

PAGE TWENTY FIVE

## PEARL STREET, EAST SIDE

- O 40-10. House (319 Pearl St.), late 19th c., 1 story frame, multi-gabled, fishscale shingles, diagonal siding, decorative vergeboards, unaltered.
- d 41\_11. House (405 Pearl St.), c. 1895, Queen Anne, 2 story frame, gable roof, cut-away corners, Eastlake porch, aluminum siding.
- d 41-12. House (413 Pearl St.), 20th c., Bungalow, 1½ story frame, hip roof, dormer window, extended eaves, exposed rafters, sun room, bracketed door hood, asbestos siding.
- d 41-13. House (417 Pearl St.), 20th c., Bungalow, 1½ story frame, gable roof, dormer window, extended eaves, diagonal brackets under eaves, clapboard siding.
- NC 41\_14. House (423 Pearl St.), late 19th c., 1 story frame, gable roof cornice-like window and door heads, exposed decorative rafters, potico, aluminum siding. Non-contributing.
  - C 41-15. House (429 Pearl St.), 20th c., Spanish Colonial Revival, 1 story, hip/gable roof, tile roof, stucco, large semi-circular arched window, wrought iron railings, unaltered.
- C 44-13. House (711 Pearl St.), 20th c., Dutch Colonial Revival,  $1\frac{1}{2}$  story frame, gambrel roof, wood shingle siding, aluminum siding.
- C 44-14. House (715 Pearl St.), 20th c., Colonial Revival,  $2\frac{1}{2}$  story frame, hip roof, dormer window, slate roof, classical porch, unaltered.
- O 44-15. House (719 Pearl St.), c. 1880, Italianate; 2½ story brick, hip roof, bay window, windows in frieze.
- C 44-16. House (725 Pearl St.), c. 1890,  $2\frac{1}{2}$  story frame, gable roof, cut away corners, classical porch, asbestos siding.
- C 44-17. House (733 Pearl St.), c. 1880, Italianate, 2 story brick, segmental arch windows with brick hoods, hip roof.
- O 45-07. House (803 Pearl St.), c. 1890, Free Classic, 1½ story frame, multigabled roof, fishscale shingle and clapboard siding, palladian windows, oval window, columned veranda, unaltered.
- C 45-08. House (811 Pearl St.), c. 1890, Queen Anne, 2½ story frame, multigabled roof, large corner brackets, many projections, exposed rafters, 20th c. porch, aluminum siding.
- C 45-09. House (821 Pearl St.), c. 1890, Queen Anne, 2½ story frame, hip/gable roof, shingle and clapboard siding, cut away corners, oriel, exposed rafters, panelized, balcony.
- C 45-10. House (825 Pearl St.), 19th c., 1½ story frame, steep gable roof, 4 bay facade, clapboard siding, dormer windows.

PAGE TWENTY SIX

## PEARL STREET, EAST SIDE

- C 46-08. House (903 Pearl St.), c. 1900, Jacobethan Revival, 1 story brick, jerkin head roof, textured brick, tapered porch columns, tapered chimney, arched attic vent, entrance with side lights.
- C 46-09. House (909 Pearl St.), late 19th c., 1 story frame, low pitch gable roof, cornice-like window heads, asbestos siding.
- 6 46-10. House (915 Pearl St.), c. 1880, 1 story brick, segmental arched windows with brick hoods, gable roof.
- C 46-11. House (921 Pearl St.), c. 1925, Colonial Revival/Prairie, 2 story brick, hip roof, columned portico, grouped casement windows, extended eaves, sunroom, entrance with side lights, excellent, unaltered condition.
- C 46-12. House (931 Pearl St.), late 19th c., Cross Plan Cottage, fishscale shingle and clapboard siding, cut away corners, panelized.
- NC 47-06. House (1003 Pearl St.), late 19th c., Cross Plan Cottage, extensive alterations, non-contributing.
  - d 47-07. House (1013 Pearl St.), late 19th c., Queen Anne, 23 story frame, multi-gabled, fishscale shingles, diagonal, waved and clapboard siding, panelized.
  - O 47-08. House (1021 Pearl St.), late 19th c., Cross Plan Cottage, pediment like window heads, Eastlake porch; excellent, unaltered condition.
  - d 47-09. House (1027 Pearl St.), late 19th c., Queen Anne, 2½ story frame, multi-gabled roof, cut away corners, square oriel, classical porch, asbestos siding.
  - d 47-10. House (1031 Pearl St.), c. 1925, Arts and Crafts, 2 story brick, jerkin head, tiled roof, segmental arched grouped windows, extended eaves, portico, sunroom, excellent, unaltered condition.
  - C 48-07. House (1103 Pearl St.), 20th c., Arts and Craffs, 23 story frame, low pitch hip roof, dormer window, extended eaves, tall grouped windows, diagonal brackets under eaves, porch with tapered column, exposed rafters, square bay window.
  - C 48-08, House (1111 Pearl St.), c. 1885, Queen Anne,  $2\frac{1}{2}$  story frame, hip/ gable roof, lunette, cut away corners, shingles, paneling.
  - 6 48-09. House (1121 Pearl St.), c. 1885, 2 story frame, hip roof, exposed rafters, clapboard siding.
  - d 48-10. House (1127 Pearl St.), c. 1925, 2 story frame, hip roof, slate roof, clapboard siding, duplex.

PAGE TWENTY SEVEN

## PEARL STREET, EAST SIDE

- C 49-07. House (1203 Pearl St.), late 19th c., 1 story frame, cornice-like window heads, asbestos siding.
- C 49-08, House (1211 Pearl St.), late 19th c., 1½ story frame, cornice-like window heads, aluminum siding.
- C 49-09. House (1217 Pearl St.), late 19th c., Cross Plan Cottage, pediment like window heads, side bay window, Eastlake porch.
- C 49-10. House (1229 Pearl St.), late 19th c., Queen Anne, 2½ story frame, multi-gabled, corner brackets, aluminum siding.
- C 50-08. House (1303 Pearl St.), late 19th c., 2 story frame, gable roof, cornice-like window heads, concrete porch.
- C 50-09. House (1311 Pearl St.), 20th c.,  $1\frac{1}{2}$  story frame, gable roof, dormer windows, concrete porch.
- C 50-10. House (1317 Pearl St.), 20th c., Bungalow, 1 story frame, gable roof, bracketed eaves, small windows flanking exterior chimney, clapboard siding.
- C 50-11. House (1321 Pearl St.), late 19th c., Shotgun Cottage, častlake porch, asbestos siding.
- C 50-12. House (1331 Pearl St.), late 19th c., Cross Plan Cottage, cornice like window heads, asbestos siding.
- C 51-01. House (1403 Pearl St.), late 19th c., Cross Plan Cottage, cut away corners,
- C 51-92. House (1409 Pearl St.), late 19th c.,  $1\frac{1}{2}$  story frame, gable roof, dormer windows, concrete porch, clapboard siding.
- C 51-03. House (1413 Pearl St.), late 19th c., 1\frac{1}{2} story frame, gable roof, clapboard siding, concrete porch.
- NC 51-04. House (1417 Pearl St.), late 19th c., Cross Plan Cottage, aluminum siding, extensive alterations, non-contributing.

PAGE TWENTY EIGHT

#### SYCAMORE STREET, WEST SIDE

- C 40-08. House (316 Sycamore St.), c. 1920,  $1\frac{1}{2}$  story, hip roof, hip roof dormer window, enclosed porch.
- NC 40-09. House (324 Sycamore St.), c. 1900, 12 story frame, jerkin head roof, enclosed porch, additions. Non-contributing.
  - C 41-04. House (404 Sycamore St.), late 19th c., 1 story frame, gable roof, cornice returns.
- NC 41-05. House (416 Sycamore St.), c. 1890, alterations, non-contributing.
- C 43-02. Wilson Building, Central Junior High School (620 Sycamore St.), 1922, Chicago Style, 3 story brick, flat roof, stone belt coursing, battlement, diamond pattern brickwork, grouped windows, vertical piers, stone arched entrances.
- C 44-06. Bruning Grocery (720 Sycamore St.), c. 1875, 1 story brick, gable roof, stepped gable facade. Now A B C Teachers' Supply Shop.
- C 44-07. House (724 Sycamore St.), c. 1895, Shotgun Cottage, Eastlake porch.
- NC 44-08. House (728 Sycamore St.),c. 1895, Shotgun Cottage, side bay window with fretwork at corners, 20th c. porch, asbestos siding. Non-contributing.
  - C 44-09. N. T. Carr House (734 Sycamore St.), c. 1875, Italianate, 2 story frame, hip roof, wide entablature, projecting cornice, 20th c. brick porch, asbestos siding.
  - C 44-10. House (738 Sycamore St.), c. 1890, 1 story frame, gable roof, concrete block foundation.
- NC 44-11. House(746 Sycamore St.), c. 1880, remodeled 1976, extensive alterations, non-contributing.
- C 45-05. House (818 Sycamore St.), late 19th c., 2 story frame, hip roof, dormer window, pedimented gable, bay window, wide eaves, concrete block foundation.
- 6 45-06. House (824 Sycamore St.), 20th c., Colonial Revival, 2½ story, gambrel roof, paneling, sunbursts, fishscale shingles and clapboard siding, ionic columned porch, palladian window.
- C 46-03. House (906 Sycamore St.), 19th c., Greek Revival, 1 story frame, gable roof, cornice returns, portico removed, asbestos siding.
- d 46-04. House (914 Sycamore St.), c. 1890, 2 story frame, diagonal, clapboard siding, cutaway corners, brackets,
- NC 46-05. House (920 Sycamore St. ), 20th c., non-contributing.
- NC 46-06. House (924 Sycamore St.), 19th c., extensive alterations, non-contributing.

PAGE TWENTY NINE

## SYCAMORE STREET, WEST SIDE

- C 46-07. House (932 Sycamore St.), c. 1920, Jacobethan Revival, 1 story brick and stucco, gable roof, half timbering, excellent, unaltered condition.
- 47-01. House (1004 Sycamore St.), c. 1885, Queen Anne,  $2\frac{1}{2}$  story frame, multi gabled, Eastlake porch and balcony, aluminum siding.
- C 47-02. House (1014 Sycamore St.), c. 1885,  $2\frac{1}{2}$  story frame, multi gabled.
- O 47-03. House (1022 Sycamore St.), c. 1885, Wueen Anne,  $2\frac{1}{2}$  story frame, multi gabled, panelized, fishscale shingle, waved and clapboard siding, sunbursts, tall thin chimneys, classical porch.
- C 47-04. House (1026 Sycamore St.), c. 1890, Cross Plan Cottage, cut away corners, fishscale shingle and waved siding.
- C 47-05. House(1038 Sycamore St.), c. 1880, Cross Plan Cottage, cornice-like window heads, gable roof, additions, asbestos siding.
- C 48-01. House (1104 Sycamore St.), 1882, Cross Plan Cottage, columned veranda, aluminum siding.
- NC 48-02. House (1110 Sycamore St.), c. 1885, Cross Plan Cottage, multi gabled, windows altered, aluminum siding, 20th c. porch. Non-contributing.
- C 48-03. House (1114 Sycamore St.), c. 1880, Shotgun Cottage.
- d 48-04. House (1120 Sycamore St.), late 19th c., Cross Plan Cottage, vergeboard, Eastlake porch, asbestos siding.
- NC 48-05. House (1128 Sycamore St.), c. 1900,  $1\frac{1}{2}$  story frame, aluminum siding, extensive alterations, non-contributing.
- C 48-06. House (1132 Sycamore St.), c. 1885, Cross Plan Cottage, multigabled, side bay window, columned porch.
- NC 49-01. House (1204 Sycamore St.), c. 1880, Cross Plan Cottage, bay window, enclosed porch, asbestos siding. Non-contributing.
- 49-02. House (1210 Sycamore St.), c. 1880, Shotgun Cottage, cornice-like window and door heads, asbestos siding.
- 49-03. House (1212 Sycamore St.), c. 1880, Shotgun Cottage, asbestos siding.
- 49-04. House (1214 Sycamore St.), c. 1880, Shotgun Cottage, asbestos siding.
- d 49-05. House (1220 Sycamore St.), c. 1880, Cross Plan Cottage, Eastlake porch, asbestos siding.
- NC. 49-06. House (1226 Sycamore St.), 20th c., Bungalow,  $1\frac{1}{2}$  story frame, gable roof, dormer window, asbestos siding, non-contributing.

PAGE THIRTY

## SYCAMORE STREET, WEST SIDE

- C 49-12. House (1236 Sycamore St.), 1878, Cross Plan Cottage, brick piered porch, asbestos siding.
- C 50-01. House (1302 Sycamore St.), c. 1890, 2 story frame, cut away corners, fishscale, diagonal shingles, paneling, gable roof.
- 6 50-02. House (1310 Sycamore St.), c. 1890, Cross Plan Cottage, multi gabled, enclosed porch.
- C 50-03. House (1312 Sycamore St.), c. 1880, 2 story frame, gable roof, asbestos siding.
- C 50-04. House (1322 Sycamore St.), c. 1885, Cross Plan Cottage, cut away corners, turned porch posts, asbestos siding.
- C 50-05. House (1328 Sycamore St.), c. 1880, Cross Plan Cottage, turned porch posts, asbestos siding.
- C 50-06. House (1330 Sycamore St.), c. 1880, Shotgun Cottage, pediment-like window and door heads, steep roof, asbestos siding.

PAGE THIRTY ONE

## SYCAMORE STREET, EAST SIDE

- C 52-09. House (319 Sycamore St.), c. 1905, 1 story stucco, gable roof.
- C 55-10. House (603 Sycamore St.), c. 1890, Cross Plan Cottage, multi gabled roof, cut away corners.
- NC 55-11. House (607 Sycamore St.), c. 1880, 1 story frame, extensive alterations, non-contributing.
- 55-12. House (611 Sycamore St.), c. 1880, Shotgun Cottage, Eastlake front and side porches, aluminum siding.
- C 55-13. House (615 Sycamore St.) late 19th c., Queen Anne, 2 story frame, gable roof, fishscale shingles in gable, kingpost, clapboard siding, Eastlake porch, hooded windows, unaltered.
- C 55-14. House (619 Sycamore St.), Cross Plan Cottage, enclosed porch, 20th c. veranda.
- 55-15. House (627 Sycamore St.), c. 1890, 2 story frame, multi gabled, brackets, kingpost, columned veranda.
- NC 55-16. House (633 Sycamore St.), late 19th c., Shotgun Cottage, aluminum siding. Non-contributing.
- No. 55-17. House (639 Sycamore St.), late 19th c., Cross Plan Cottage, brick piered porch, asbestos siding. Non-contributing.
- C 55-18. House (643 Sycamore St.), 20th c.,  $2\frac{1}{2}$  story frame, gable roof with flared eaves. window awnings, large flared porch posts.
- C 56-08. T. J. Council House (705 Sycamore St.), c. 1870, Italianate, 2 story brick, hip roof, stone window sills and lintels, 3 bay facade, 20th c. porch, rear additions.
- C 56-09. L. C. Griffith House (715 Sycamore St.), c. 1865, 2 story frame, steep gable roof, pediment-like window and door heads, dormer windows, bay window added, porch with square, fluted pillars.
- 56-10. St. Bartholomew Roman Catholic Church (731 Sycamore St.), 1891, Victorian Gothic, rectangular plan, gable roof, square tower, polychromatic brick, limestone and terra cotta trim, buttresses, qothic arched paired windlws, tracery, round windows.
- NC 56-11. St. Bartholomew School (745 Sycamore St.), c. 1945, 2 story brick, gable roof. Non-contributing.
- O 57-06. Griffith-Marr House (805 Sycamore St.), c. 1865, Italianate, 2 story brick, stone sills and lintels, extended cornice, box gutters, gable roof, entry with elliptical arched fanlight and sidelights.

PAGE THIRTY TWO

## SYCAMORE STREET, EAST SIDE

- C 57-07. Grove House (811 Sycamore St.), c. 1875, Italianate, 2 story frame, low pitch hip roof, box gutters, asbestos siding.
- C 57-08. Heicher-Richter House (817 Sycamore St.), late 19th c., 1 story frame, garlanded, columned porch, gable roof.
- C 57-09. House (827 Sycamore St.), c. 1880, 1 story frame, 20thc. porch, asbestos siding.
- C 57-10. Brown Grocery (829 Sycamore St.), c. 1905, 2 story brick, segmental arched windows, additions. Now a clothing store.
- C 58-09. House (905 Sycamore St.), c. 1910, 12 story frame, gable roof, dormer window, brick porch, aluminum siding.
- C 58-10. House (909 Sycamore St.), late 19th c., Cross Plan Cottage.
- C 58-11. House (913 Sycamore St.), late 19th c., Cross Plan Cottage, Eastlake porch.
- C 58-12. House (919 Sycamore St.), c. 1890, Queen Anne, 2 story frame, multi-gabled roof, octagonal turret with tent roof, side bay window, 20th c. brick porch.
- C 58-13. House (923 Sycamore St.), mid 19th c., Greek Revival, 1 story frame, 4 bay facade, gable roof, cornice returns, clapboard siding, 20th c. porch.
- C 58-14. House (933 Sycamore St.), c. 1880,  $1\frac{1}{2}$  story frame, jerkin head roof, palladian like attic window.
- C 59-07. House (1001 Sycamore St.), c. 1895 2 story frame, gable roof, columned veranda.
- . C 59-08. House (1007 Sycamore St.), late 19th c., Cross Plan Cottage, additions, aluminum siding.
- C 59-09. House (1013 Sycamore St.), late 19th c., Cross Plan Cottage, asbestos siding.
- 59-10. House (1021 Sycamore St.), c. 1890, 2 story, multi-gabled, cut away corners, aluminum siding.
- C 59-11. House (1025 Sycamore St.), late 19th c., Cross Plan Cottage, cut away corners, waved and clapboard siding, paired windows, pedimentlike window heads, brick piered porch.
- C 59-12. House (1033 Sycamore St.), late 19th c., Cross Plan Cottage, cut away corners, 20th c. columned side porch, transomed doors.
- C 59-13. House (1035 Sycamore St.), late 19th c., Cross Plan Cottage, Eastlake porch, transomed doors, aluminum siding.

PAGE THIRTY THREE

## SYCAMORE STREET, EAST SIDE

- 6 59-14. G. H. Vonfang Grocery (1039 Sycamore St.), 1884, 1 story frame, gable roof, false facade, shed roof porch on front, display windows, clapboard siding. Unaltered. Now clothing store.
- 60-02. House (1103 Sycamore St.), c. 1880, Italianate, 2 story frame, low pitch hip roof, clapboard siding, cornice-like window heads, box gutters, 20th c. brick porch.
- 60-03. House (1109 Sycamore St.), c. 1920, Bungalow, 1½ story frame, low pitch gable roof, diagonal brackets under eaves, wide eaves, brick piered porch, clapboard siding. excellent, unaltered condition.
- 60-04. House (1111 Sycamore St.), c. 1920, Bungalow, identical to 60-03.
- C 60-05. House (1117 Sycamore St.), c. 1930, 2 story frame, low pitch gable roof, extented rafters, wide eaves, clapboard siding, brick piered porch.
- C 60-06. House (1121 Sycamore St.), c. 1910, identical to 60-05.
- C 60-07. House (1129 Sycamore St.), late 19th c., Cross Plan Cottage, cut away corners, fishscale shingles, fretwork at corners, brick piered porch.
- NC 61-01. Jefferson School (1209 Sycamore St.), 1952, 1 story brick, flat roof. Non-contributing.
- C 62-01. House (1303 Sycamore St.), late 19th c., Shotgun Cottage, clapboard siding.
- 62-02. House (1309 Sycamore St.), late 19th c., Shotgun Cottage, clapboard siding.
- C 62-03. House (1315 Sycamore St.), 20th c.,  $1\frac{1}{2}$  story, gable roof, aluminum siding.
- 62-04. House (1321 Sycamore St.), c. 1900, 1½ story frame, multi gabled roof, hip roof dormer window, columned porch, cornice returns, asbestos siding.
- 62-05. House (1323 Sycamore St.), c. 1900, 1½ story frame, multi gabled roof, fishscale shingles and clapboard siding, cornice returns, columned porch, unaltered, excellent condition.
- 62-06. House (1327 Sycamore St.), c. 1880, Cross Plan Cottage, decorative vergeboard, cornice-like window and door heads, clapboard siding, columned porch.
- 62-07. House (1331 Sycamore St.), c. 1880, identical to 62-06 except asbestos siding.

PAGE THIRTY FOUR

## CHESTNUT STREET, WEST SIDE

- C 55-03. House (606 Chestnut St.), late 19th c., 1½ story frame, jerkin head roof, portice with raking cornice and returns, paired columns, clapboard siding.
- C 55-04. House (612 Chestnut St.), c. 1890, Cross Plan Cottage, cut away corners, side porch with turned posts.
- Q 55-05. Edgar Redman House (614 Chestnut St.), 1867, Greek Revival, 1 story frame, gable roof, tall double hung windows, clapboard siding, 5 bay facade, cornice returns, new recessed entry with sidelights, wide wood water table.
- O 55-06. House (624 Chestnut St.), 19th c., Shotgun cottage, clapboard siding, decorative vergeboard, Eastlake porch. Unaltered, excellent condition.
- NC 55-07. House (628 Chestnut St.), 19th c., Cross Plan Cottage, low pitch gable roof, enclosed porch, asbestos siding. Non-contributing.
- NC 55-08. House (630 Chestnut St.), 19th c., Cross Plan Cottage, 20thc. porch, aluminum siding. Non-contributing.
- C 55-09. House (632 Chestnut St.), c. 1875, 2 story frame, gable roof, 6 bay facade, clapboard siding and asbestos siding on facade.
- O 56-02. Commercial Building (702 Chestnut St.), c. 1875, Italianate, 1 story brick, 3 bay semi-circular arched arcade. Originally w. B. Sisk Grocery, now real estate office.
- C 56-03. Frank McNeal House (706 Chestnut St.), c. 1885, Cross Plan Cottage, cut away corners, fishscale, diagonal shingles add clapboard siding, enclosed brick porch.
- C 56-04. House (714 Chestnut St.), 20th c.,  $2\frac{1}{2}$  story frame, low pitch gable roof, diagonal bracketed eaves, square bay window, aluminum siding.
- C 56-05. House (724 Chestnut St.), c. 1880, Italianate, 2 story brick, hip roof, tall segmental arch windows, 3 bay facade, transomed doors, brick piered porch.
- 56-06. House (732 Chestnut St.), c. 1890, 1 story brick, cross plan, segmental arched windows and doors, ionic columned porch.
- O 56-07. Donner-Zaharako House (742 Chestnut St.), c. 1870, Italianate, 2 story brick, gable roof, crossing gabled extension, 3 bay facade, transomed door, stone window sills and litels, raking cornice, Eastlake portico. James Perkinson, builder.
- C 57-02. House (804 Chestnut St.), 20th c., Colonial Revival, 1½ story frame, gambrel roof, pent roof, slate fishscale shingles, lunettes, bay window, clapboard siding, enclosed brick piered porch.