

Company		Mine
<b>Alliance Coal</b>		<b>Gibson County Coal South</b>
Inspection Date:	Thursday, April 10, 2025	
Areas Inspected:	Unit #1, MC-8892, CR-8230	
Findings / Law(s) Violated:	The Unit looked good	
Corrective Actions Taken:	None	
Recommendation(s):	None	
Inspection Date:	Wednesday, April 16, 2025	
Areas Inspected:	2A Belt and primary, 2nd NW Main Belt and primary, CR-8650. MCI-8499, CR-8640	
Findings / Law(s) Violated:	75.220(a)(1)	
Corrective Actions Taken:	The affected area was dangerous off and the mine operator is correcting the issue.	
Recommendation(s):	2A belt XC- 7 to 8 Haulage side rib needs pruned down. XC-53 2nd NW Main could use added support between the belt and intake mandoor. 2nd NW Main Primary XC-62 the perimeter of the intake stopping needs replastered.	
Inspection Date:	Wednesday, April 24, 2024	
Areas Inspected:	2nd NW Submain belt and primary, SCSR cache XC-41	
Findings / Law(s) Violated:	None	
Corrective Actions Taken:	None	
Recommendation(s):	None	
Inspection Date:	Monday, April 28, 2025	
Areas Inspected:	1st SE Submain Belt and primary, 1st SE-2 Submain belt and primary, CR-8652	
Findings / Law(s) Violated:	None	
Corrective Actions Taken:	None	
Recommendation(s):	None	
Inspection Date:	Wednesday, May 7, 2025	
Areas Inspected:	Unit 3, MCI 8861, CR8206A, 3A9 Panel Belt and primary, 3B29 Panel belt and primary	
Findings / Law(s) Violated:	None	
Corrective Actions Taken:	None	
Recommendation(s):	Need to stay on top of cleaning at the face and outby the feeder.	
Inspection Date:	Wednesday, May 14, 2025	
Areas Inspected:	1st SW Main belt and Primary, 1st SW Main 2 Belt Primary, SCSR cache XC-80	
Findings / Law(s) Violated:	None	
Corrective Actions Taken:	None	
Recommendation(s):	1st SW Main 2 Belt needs spot shoveled under bottom rollers. 1st SW main primary will need rock dusted soon.	

cont...

Alliance Coal		Gibson County Coal South	
Inspection Date:	Wednesday, May 21, 2025		
Areas Inspected:	2A Secondary, CR8663, MCI8499, NW 48" 2 Secondary, CR8650, XC-99 SCSR Cache, NW 48" secondary		
Findings / Law(s) Violated:	75.1100-3, 75.809, 75.809		
Corrective Actions Taken:	The fire extinguisher was inspected and the tag properly marked. Labels were placed on the power cables.		
Recommendation(s):	Labels on power cables need to be accessible and legible.		
Inspection Date:	Thursday, May 29, 2025		
Areas Inspected:	1st NW2 Belt and Primary, XC-80 SCSR Cache, A-A Seals, A-B Seals		
Findings / Law(s) Violated:	The mine looked good.		
Corrective Actions Taken:	None		
Recommendation(s):	None		
Inspection Date:	Tuesday, June 10, 2025		
Areas Inspected:	Unit #4, MCI8850, CR8228		
Findings / Law(s) Violated:	75.1907(a)		
Corrective Actions Taken:	The equipment was immediately removed, the production was shut down for a safety meeting with the entire crew.		
Recommendation(s):	Have a mine-wide safety talk on the use of non-permissible equipment use.		
Inspection Date:	Wednesday, June 18, 2025		
Areas Inspected:	North Main Belt and Primary, 1st NW Main Belt and Primary		
Findings / Law(s) Violated:	Everything looked good!		
Corrective Actions Taken:	None		
Recommendation(s):	1st NorthWest belt XC-25 and 46 need added roof support between haulage and belt.		
Inspection Date:	Monday, June 23, 2025		
Areas Inspected:	A-C Seals, A-D Seals		
Findings / Law(s) Violated:	None		
Corrective Actions Taken:	None		
Recommendation(s):	Water P traps need installed vertically to perform their intended function properly.		
Inspection Date:			
Areas Inspected:			
Findings / Law(s) Violated:			
Corrective Actions Taken:			
Recommendation(s):			

Company		Mine
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		

Inspection Date:			
Areas Inspected:			
Findings / Law(s) Violated:			
Corrective Actions Taken:			
Recommendation(s):			
Inspection Date:			
Areas Inspected:			
Findings / Law(s) Violated:			
Corrective Actions Taken:			
Recommendation(s):			
Inspection Date:			
Areas Inspected:			
Findings / Law(s) Violated:			
Corrective Actions Taken:			
Recommendation(s):			
Inspection Date:			
Areas Inspected:			
Findings / Law(s) Violated:			
Corrective Actions Taken:			
Recommendation(s):			
Inspection Date:			
Areas Inspected:			
Findings / Law(s) Violated:			
Corrective Actions Taken:			
Recommendation(s):			
Inspection Date:			
Areas Inspected:			
Findings / Law(s) Violated:			
Corrective Actions Taken:			
Recommendation(s):			
Inspection Date:			
Areas Inspected:			
Findings / Law(s) Violated:			
Corrective Actions Taken:			
Recommendation(s):			

Company		Mine
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		

cont...

Inspection Date:			
Areas Inspected:			
Findings / Law(s) Violated:			
Corrective Actions Taken:			
Recommendation(s):			
Inspection Date:			
Areas Inspected:			
Findings / Law(s) Violated:			
Corrective Actions Taken:			
Recommendation(s):			
Inspection Date:			
Areas Inspected:			
Findings / Law(s) Violated:			
Corrective Actions Taken:			
Recommendation(s):			
Inspection Date:			
Areas Inspected:			
Findings / Law(s) Violated:			
Corrective Actions Taken:			
Recommendation(s):			
Inspection Date:			
Areas Inspected:			
Findings / Law(s) Violated:			
Corrective Actions Taken:			
Recommendation(s):			
Inspection Date:			
Areas Inspected:			
Findings / Law(s) Violated:			
Corrective Actions Taken:			
Recommendation(s):			
Inspection Date:			
Areas Inspected:			
Findings / Law(s) Violated:			
Corrective Actions Taken:			
Recommendation(s):			

Company

Mine

Peabody Midwest Mining		Francisco Mine
Inspection Date:	Tuesday, April 8, 2025	
Areas Inspected:	Unit #3, UT5002, UT5003	
Findings / Law(s) Violated:	75.220(a)(1)	
Corrective Actions Taken:	Bolts were installed to correct the issue.	
Recommendation(s):	Places need to be cleaned and dusted in a timely manner after being bolted.	
Inspection Date:	Monday, April 14, 2025	
Areas Inspected:	Unit #3, Return airshaft area	
Findings / Law(s) Violated:	75.1100-2	
Corrective Actions Taken:	The operator is addressing the issue.	
Recommendation(s):	None	
Inspection Date:	Tuesday, April 22, 2025	
Areas Inspected:	1st NW Main Belt and Primary, 2nd NW Main Belt and Primary, 2 NE Submain belt and Primary	
Findings / Law(s) Violated:	75.1731(a), 75.400	
Corrective Actions Taken:	The operator is addressing the issues.	
Recommendation(s):	1st NW Main belt needs cleaned and rock dusted. 2nd NW Belt needs cleaned and rock dusted. The belt may need more water to help with float dust.	
Inspection Date:	Tuesday, April 29, 2025	
Areas Inspected:	9 Main West belt and primary	
Findings / Law(s) Violated:	None	
Corrective Actions Taken:	None	
Recommendation(s):	9 West belt needs rock dusted, may consider adding water to the belt for dust suppression. Properly align belts after replacing rollers.	
Inspection Date:	Monday, May 5, 2025	
Areas Inspected:	Unit #1, UT5004, UT5001	
Findings / Law(s) Violated:	None	
Corrective Actions Taken:	None	
Recommendation(s):	The production unit looked good well dusted and ventilated.	
Inspection Date:	Tuesday, May 13, 2025	
Areas Inspected:	8 Main West Belt and Secondary, BT5010, BT5021, BT5042, BT5037	
Findings / Law(s) Violated:	75.110-3	
Corrective Actions Taken:	The fire extinguisher was replaced.	
Recommendation(s):	8 West Belt needs floor dusted from XC-92 - tail. Float dust is accumulating on the mine floor and waterline. Make sure the belt is properly guarded if you are going tp park underneath it.	

Inspection Date:	Monday, May 19, 2025
Areas Inspected:	7 Main West Belt and secondary, DVB-5110, BT-5019
Findings / Law(s) Violated:	75.1731(a), 75.1731(b)
Corrective Actions Taken:	The operator is addressing the issues.
Recommendation(s):	7 Main West belt need rock dusted from XC-51 to the tail. The belt needs aligned badly. XCX-41 - 42 needs roof support.

Inspection Date:	Tuesday, May 27, 2025
Areas Inspected:	6 West Belt and secondary, Air shaft belt and secondary, BT5012, BT5029, DVB5112, DVB5103
Findings / Law(s) Violated:	75.1731(b), 75.370(a)(1) Section 3-1(a) of approved ventilation plan.
Corrective Actions Taken:	The mine operator is addressing the issues. The belt spray valve was turned on.
Recommendation(s):	6W belt from the drive to XC-16 needs rock dusted. XC-10-16 needs spot cleaned and the belt needs properly adjusted to avoid rubbing.

Inspection Date:	Thursday, June 12, 2025
Areas Inspected:	3 West Belt and Secondary, 4 West Belt and Secondary, DVB5006, DVB-5109, T5028
Findings / Law(s) Violated:	75.202(a), 75.202(a), 75.1731(b), 75.1731(b)
Corrective Actions Taken:	The mine operator is addressing the B.O. rollers and the belt was trained to prevent rubbing.
Recommendation(s):	Kettle Bottoms in the mine roof could use floor to roof support above walkways in the 3W Belt at XC-20 to 29, XC-29 to 30, and the 4W XC-5 to 6. 3 West belt needs cleaned and rock dusted. 4 West belt needs rock dusted.

Inspection Date:	Tuesday, June 17, 2025
Areas Inspected:	Unit #3, PB5002, PB5003
Findings / Law(s) Violated:	Everything looked good.
Corrective Actions Taken:	None
Recommendation(s):	Stay on top of cleaning, rock dusting, belt training, and roller replacement.

Inspection Date:	Tuesday, June 24, 2025
Areas Inspected:	5 West Belt and secondary, PC5007, BT5018
Findings / Law(s) Violated:	75.1100(2)(b)
Corrective Actions Taken:	The road hose was removed.
Recommendation(s):	3 West belt needs added roof support XC-8 to 9 intake side. Transfer points needs rock dusted from the drive to at lease 3 cross cuts outby. Rebolts are to be limited to no more than 6 inches of spacers and Kerr-Thos not more than 12 inches of spacers... per the roof control plan.

Inspection Date:	Monday, June 30, 2025
Areas Inspected:	2 East SubMain Seals, 4 West Submain Seals, 5 West SubMain Seals
Findings / Law(s) Violated:	None
Corrective Actions Taken:	None
Recommendation(s):	None



Peabody Midwest Mining		Francisco Mine
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		

cont...

Inspection Date:			
Areas Inspected:			
Findings / Law(s) Violated:			
Corrective Actions Taken:			
Recommendation(s):			
Inspection Date:			
Areas Inspected:			
Findings / Law(s) Violated:			
Corrective Actions Taken:			
Recommendation(s):			
Inspection Date:			
Areas Inspected:			
Findings / Law(s) Violated:			
Corrective Actions Taken:			
Recommendation(s):			
Inspection Date:			
Areas Inspected:			
Findings / Law(s) Violated:			
Corrective Actions Taken:			
Recommendation(s):			
Inspection Date:			
Areas Inspected:			
Findings / Law(s) Violated:			
Corrective Actions Taken:			
Recommendation(s):			
Inspection Date:			
Areas Inspected:			
Findings / Law(s) Violated:			
Corrective Actions Taken:			
Recommendation(s):			

Company		Mine
<b>Sunrise Coal</b>		<b>Oaktown Fuels #1 Mine</b>
Inspection Date:	Tuesday, April 1, 2025	
Areas Inspected:	Unit #2, UT13, S2E Primary and belt.	
Findings / Law(s) Violated:	None	
Corrective Actions Taken:	None	
Recommendation(s):	S2E belt needs spot shoveled. Keep an eye on entry widths.	
Inspection Date:	Wednesday, April 9, 2025	
Areas Inspected:	SD4 Belt and secondary, SD4 1st Right Belt and Secondary, LBT14, LBT19, VCB-T.18,	
Findings / Law(s) Violated:	None	
Corrective Actions Taken:	None	
Recommendation(s):	Sd4 Belt looks great but needs dusted, Make sure there is plenty of lagging in Ziggy rails so that the mine roof is properly supported.	
Inspection Date:	Tuesday, April 15, 2025	
Areas Inspected:	SC-4 belt and secondary, XC-22 refuge chamber, KBT-38, KUT-11, DVB-2, KUT-10	
Findings / Law(s) Violated:	75.220(a)(1)	
Corrective Actions Taken:	The mine operator is installing floor to roof support	
Recommendation(s):	SC-4 belt head to XC-18 needs spot shoveled, XC-8 next to walkway needs added support. SC-4 travelway XC-8 needs lagging added between Ziggy bars and roof for sufficient support.	
Inspection Date:	Monday, April 21, 2025	
Areas Inspected:	S3-C Belt and secondary, S3-C 1st Right Belt Secondary, p3-9 Belt and Secondary, KBT33, BT5, T14VC, T50	
Findings / Law(s) Violated:	75.400	
Corrective Actions Taken:	The operator is addressing the issues.	
Recommendation(s):	S3-C Belt drive to XC-25 needs cleaned and dusted, XC-32-33 and XC-37-39 Hog panels that are damaged and hanging in the walkway need removed. XC-46 needs raised to prevent friction. P3-9 belt needs spot-cleaned.	
Inspection Date:	Thursday, May 1, 2025	
Areas Inspected:	M1 Belt and secondary, M2 Belt and secondary, BT23, MC1, BT24, BT1, DVB3, LBT6, MC5	
Findings / Law(s) Violated:	None	
Corrective Actions Taken:	None	
Recommendation(s):	M1 belt needs dusted from Head to XC-10. M2 belt needs dusted from Head to XC-5. Remove pumps that aren't in use, or they need to be inspected/permitted as if they were in use.	

cont...

Sunrise Coal		Oaktown Fuels #1 Mine
Inspection Date:	Tuesday, May 6, 2025	
Areas Inspected:	Unit #4, LUT-04, M-2 Belt XC-12	
Findings / Law(s) Violated:	75.370(a)(1), 75.11002(a),75.512	
Corrective Actions Taken:	The pump was removed from the mine. Adjustemnts were made in the ventilation controls and the required amount of air was supplied.	
Recommendation(s):	Need to work on temporarily ventilation controls efficiency.	
Inspection Date:	Friday, May 16, 2025	
Areas Inspected:	Unit #2	
Findings / Law(s) Violated:	None	
Corrective Actions Taken:	None	
Recommendation(s):	The unit was well maintained.	
Inspection Date:	Friday, May 16, 2025	
Areas Inspected:	Unit #2	
Findings / Law(s) Violated:	None	
Corrective Actions Taken:	None	
Recommendation(s):	Looked good!	
Inspection Date:	Wednesday, May 28, 2025	
Areas Inspected:	M17 Fall Area and belt XC-18 to 19, 3S-B Belt, 3S-B Secondary, Bt12, LDVB3, T27, DBB-1, Lbt7	
Findings / Law(s) Violated:	None	
Corrective Actions Taken:	None	
Recommendation(s):	3S-B Belt needs added roof support at; XC-7, XC-15, XC-24. It needs rock dusted from belt head to XC25	
Inspection Date:	Monday, June 9, 2025	
Areas Inspected:	Unit #1, BT-28	
Findings / Law(s) Violated:	75.370(a)(1)	
Corrective Actions Taken:	The bolter wasshut down, and the proper ventilation controls were installed.	
Recommendation(s):	Make sure to use sounding devices when required. Keep an eye out for loose top.	
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		

Company

Mine

Sunrise Coal		Oaktown Fuels #2 Mine	
Inspection Date:		Wednesday, April 23, 2025	
Areas Inspected:		M8 Primary and secondary, LUT05, LMC13, T7, C/T1	
Findings / Law(s) Violated:		None	
Corrective Actions Taken:		None	
Recommendation(s):		None	
Inspection Date:		Wednesday, April 30, 2025	
Areas Inspected:		M7 Primary and Secondary, T49, LPDB02	
Findings / Law(s) Violated:		None	
Corrective Actions Taken:		None	
Recommendation(s):		None	
Inspection Date:		Thursday, May 1, 2025	
Areas Inspected:		M4 XC-38 Roff fall area	
Findings / Law(s) Violated:		A rehabilitation plan is being submitted for approval	
Corrective Actions Taken:		None	
Recommendation(s):		Additional roof support needs added to the primary escapeway.	
Inspection Date:		Thursday, May 8, 2025	
Areas Inspected:		M6 Primary and Secondary, DVB-13, LBT-15, T-35	
Findings / Law(s) Violated:		None	
Corrective Actions Taken:		None	
Recommendation(s):		M-6 XC-B Intake stopping needs replastered. Need to relabel 110v cables at powert boxes. They are becoming illegible.	
Inspection Date:		Thursday, May 15, 2025	
Areas Inspected:		M4 Primary and secondary, LMC05 and 06, BT4	
Findings / Law(s) Violated:		None	
Corrective Actions Taken:		None	
Recommendation(s):		M4 Intake XC 45-47 needs added roof support or barricaded. XC 50-51 could use added roof support.	
Inspection Date:		Friday, May 30, 2025	
Areas Inspected:		M8-A Seals, M7-A Seals, S1-A Seals	
Findings / Law(s) Violated:		None	
Corrective Actions Taken:		None	
Recommendation(s):		M8 Return stopping XC14 to 15 mandoor latch needs replaced on haulage side of doghouse. M-7 Haulage XC-9 Ziggy bar needs reset on the outby end of intersection.	

cont...

Sunrise Coal		Oaktown Fuels #1 Mine
Inspection Date:	Tuesday, May 20, 2025	
Areas Inspected:	M4 Belt and secondary, M5 Belt and secondary, BT21, KDBB7, BT13	
Findings / Law(s) Violated:	75.202(a), 75.333(b)(1)	
Corrective Actions Taken:	Areas were flagged off and being addressed by the operator.	
Recommendation(s):	M4 Belt- Timbers holding up rib fencing could use replaced in several areas. Kettle bottoms could use floor to roof support at XC-117 on the haulage side of the belt and intake side of the bel at XC-137 and 138.	
Inspection Date:	Thursday, June 19, 2025	
Areas Inspected:	M7 Belt and secondary, BT12, LBT13, DVB5, T22, T26, M7 Airlocks	
Findings / Law(s) Violated:	75.333(d)(3)	
Corrective Actions Taken:	Both sets of doors were closed.	
Recommendation(s):	M17 Belt XC-46 to 47 damaged hog panels need removed in walkways on both sides of the belt. XC-10 B.O. Bottom roller needs changed soon.	
Inspection Date:	Wednesday, June 25, 2025	
Areas Inspected:	M1 Primary and secondary, M2 Primary and secondary, M3 Primary and secondary, M1 Seals, LMC6, LBT8	
Findings / Law(s) Violated:	None	
Corrective Actions Taken:	None	
Recommendation(s):	None	
Inspection Date:	Thursday, June 26, 2025	
Areas Inspected:	M7 Secondary, M16 Belt and Secondary, T-3, BT-18	
Findings / Law(s) Violated:	75.333(d)(3)	
Corrective Actions Taken:	The air locks door were closed.	
Recommendation(s):	M16 belt needs spot shoveled and rock dusted from the belt drive to XC-5. XC-79 Needs cleaned between the haulage and belt to access the mandor to the escapeway. Need to have a compnay-wide meeting about the importance and proper use of airlock doors.	
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		

Company		Mine
<b>Sunrise Coal</b>		<b>Oaktown Fuels #2 Mine</b>
Inspection Date:	Thursday, May 22, 2025	
Areas Inspected:	M9 Constrction area, M9 Secondary, M9 Seals, LCT-2, KBT-35	
Findings / Law(s) Violated:	None	
Corrective Actions Taken:	None	
Recommendation(s):	None	
Inspection Date:	Wednesday, June 11, 2025	
Areas Inspected:	M10 Seals, 2nd South SubMain Seals, 3rd Main South Seals	
Findings / Law(s) Violated:	75.333(d)(3)	
Corrective Actions Taken:	Both sets of airlock doors were closed. The operator was involved in the meeting about this issue.	
Recommendation(s):	Added roof support is needed outby the 3rd Main South Seals just outby the air pump.	
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		

Recommendation(s):	
--------------------	--

cont...

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	



Recommendation(s):	
--------------------	--

Company		Mine
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		
Corrective Actions Taken:		
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s) Violated:		

Corrective Actions Taken:	
Recommendation(s):	

cont...

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Corrective Actions Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	

Corrective Actions Taken:	
Recommendation(s):	