Company	Min	
Gibson County	Coal Gibson Min	
Inspection Date:	Tuesday, August 1, 2017	
Areas Inspected:	Surface Areas of Underground - surface facilities, shop area, surface belts, substation, fan	
Findings / Law(s) Violated:	No violations noted	
Corrective Actions Taken:	None	
Recommendation(s):	None noted	
Inspection Date:	Tuesday, August 1, 2017	
Areas Inspected:	Surface Facilities Areas - plant, belts, tunnels	
Findings / Law(s) Violated:	No violations noted	
Corrective Actions Taken:	None	
Recommendation(s):	None noted	
Inspection Date:	Monday, August 7, 2017	
Areas Inspected:	Surface Areas of Underground (Portal 2) - warehouse, shop, , hoist, fuel storage, substation, fan house, surface pumps, water tank	
Findings / Law(s)	No violations noted.	
Violated:	No violations noted.	
Corrective Actions Taken:	None	
Recommendation(s):	None noted	
Inspection Date:	Thursday, September 14, 2017	
Areas Inspected:	Underground Areas (N Portal) - books and records, unit 4, primaries, secondaries, bottom, sumps	
Findings / Law(s) Violated:	No violations noted.	
Corrective Actions Taken:	None	
Recommendation(s):	None noted	
Company	Min	
Gibson County	Coal Gibson South Min	
Inspection Date:	Thursday, August 10, 2017	
Areas Inspected:	Surface Areas of Underground - offices, shop, warehouse, supply yard, fuel storage and drop area, substations 1 & 2, hoist, rock dust drop, fueling stations, pumps, water tank, plant shop	
Findings / Law(s) Violated:	47.41(a)	
Corrective Actions Taken:	Hazards have been addressed by management and corrected	
Recommendation(s):	None noted	
Inspection Date:	Tuesday, August 22, 2017	
Areas Inspected:	Underground Areas - belts, primaries	
Findings / Law(s) Violated:	75.1731(a); 75.400	

Corrective Actions Taken:	Hazards have been addressed by management and corrected	
Recommendation(s):	None noted	

Company Mine

Peabody Midw	est Mining	Francisco Mine	
Inspection Date:	Wednesday, August 2, 2017		
Areas Inspected:	Surface Facilities Areas - plant and facilities, shop, belts, traffic flow, tunnels		
Findings / Law(s) Violated:	77.104; 77.205(b)		
Corrective Actions Taken:	Hazards have been addressed by manag	gement and corrected	
Recommendation(s):	Add skirting around the shaker to preve	nt spillage of fines in Tunnel 1	
Inspection Date:	Tuesday, August 8, 2017		
Areas Inspected:	Underground Areas - belts, unit 3, prima	ries	
Findings / Law(s) Violated:	75.1731(a); 75.1731(a)		
Corrective Actions Taken:	Hazards have been addressed by manag	ement and corrected	
Recommendation(s):	Have a safety talk with all crews on aud and bells can be heard over equipment	ible warnings when traversing through curtains. Make sure horns motors.	
Inspection Date:	Tuesday, September 19, 2017		
Areas Inspected:	Surface of Underground Areas - books a	Surface of Underground Areas - books and records, offices, bath house, warehouse, shop, supply yard	
Findings / Law(s) Violated:	No violations noted.		
Corrective Actions Taken:	None		
Recommendation(s):	None noted		
Inspection Date:	Thursday, September 21, 2017		
Areas Inspected:	Underground Areas - belts, unit 3, primaries		
Findings / Law(s) Violated:	No violations noted.		
Corrective Actions Taken:	None		
Recommendation(s):	Watch closely that belts are maintained, especially rollers and tracking. Change rollers when needed. Manage belt alignment issues.		
Inspection Date:	Thursday, September 21, 2017		
Areas Inspected:	Surface Areas of Underground - pit areas		
Findings / Law(s) Violated:	47.41(a)		
Corrective Actions Taken:	Hazards have been addressed by management and corrected		
Recommendation(s):	None noted		

Company Mine

ERC Mining Indiana Group		GoldStar Mine
Inspection Date:	Tuesday, July 18, 2017	

Areas Inspected: Underground Areas - secondaries, belts, returns, unit		
Findings / Law(s)		
Violated:	No violations noted.	
Corrective Actions	None	
Taken:		
Recommendation(s):	Continue pumping water from the faces and seal areas.	
Inspection Date:	Tuesday, July 18, 2017	
Areas Inspected:	Surface Areas of Underground - pit, highwall, roadways, openings, pumps, belts, shop, substation	
Findings / Law(s) Violated:	No violations noted.	
Corrective Actions Taken:	None	
Recommendation(s):	None noted	
Inspection Date:	Tuesday, July 18, 2017	
Areas Inspected:	Surface Facilities Areas - plant, facilities	
Findings / Law(s) Violated:	No violations noted.	
Corrective Actions Taken:	None	
Recommendation(s):	None noted	
Inspection Date:	Thursday, August 24, 2017	
Areas Inspected:	Underground Areas - primaries, secondaries, seals, unit	
Findings / Law(s) Violated:	No violations noted.	
Corrective Actions Taken:	None	
Recommendation(s):	Control water and muddy conditions regularly.	
Inspection Date:	Thursday, August 24, 2017	
Areas Inspected:	Surface Areas of Underground - books and records, pit, highwall, roadways, openings, pumps, belts, shop, substation	
Findings / Law(s) Violated:	No violations noted.	
Corrective Actions Taken:	None	
Recommendation(s):	None noted	
Inspection Date:	Tuesday, September 12, 2017	
Areas Inspected:	Underground Areas - secondaries, seals, primaries, unit	
Findings / Law(s) Violated:	No violations noted.	
Corrective Actions Taken:	None	
Recommendation(s):	None noted	
Inspection Date:	Tuesday, September 26, 2017	
Areas Inspected:	Surface Facilities Areas - plant, facilities	
	_	

Findings / Law(s) Violated:	No violations noted.
Corrective Actions Taken:	None
Recommendation(s):	None noted

Company		N	
Sunrise Coal		Carlisle Mi	
Inspection Date:	Friday, July 21, 2017	Carriste iviii	
Areas Inspected:		- mine fanc substation elevator	
•	Surface Areas of Undergorund (Portal 2) - mine fans, substation, elevator		
Findings / Law(s) Violated:	No violations noted.		
Corrective Actions	None		
Taken:			
Recommendation(s)): None noted		
nspection Date:	Tuesday, September 5, 2017		
Areas Inspected:	Surface Areas of Undergorund (Portal 1) shop, offices, bath house, warehouse, pa	- main mine fans, substation, north mine fans, underground die	
Findings / Law(s) Violated:	No violations noted.	its yard, books and records	
Corrective Actions Taken:	None		
Recommendation(s)): None noted		
nspection Date:	Tuesday, September 5, 2017		
reas Inspected:	Underground Areas (Portal 1) - prep plant, plant shop, surface diesel shop		
Findings / Law(s) Violated:	No violations noted.		
Corrective Actions Taken:	None		
Recommendation(s)): None noted	None noted	
nspection Date:	Wednesday, September 6, 2017		
reas Inspected:	Surface Facilities Areas (Portal 1) - prima	aries, returns, records and books	
Findings / Law(s) Violated:	No violations noted.		
Corrective Actions Taken:	None		
Recommendation(s)): None noted	None noted	
nspection Date:	Tuesday, September 26, 2017		
reas Inspected:	Surface Areas of Undergorund (Portal 2)	- mine fans, substation, elevator	
Findings / Law(s) Violated:	No violations noted.		
Corrective Actions Taken:	None		
Recommendation(s)	None noted		
Company		N	
Sunrise Coal		Oaktown Fuels #1 Min	

Inspection Date:	Thursday, July 20, 2017		
Areas Inspected:	Underground Areas - belts, secondaries, unit 3		
Findings / Law(s) Violated:	No violations noted.		
Corrective Actions Taken:	None		
Recommendation(s):	None noted		
Inspection Date:	Friday, August 4, 2017		
Areas Inspected:	Surface Areas of Underground - warehouse, shop, fuel storage area, stacker belt, fan, hoist, substation		
Findings / Law(s) Violated:	No violations noted.		
Corrective Actions Taken:	None		
Recommendation(s):	Review HazCom Program; Conduct more frequent examinations of firefighting equipment.		
Inspection Date:	Friday, August 4, 2017		
Areas Inspected:	Surface Facilities Areas - raw coal tunnel, plant, facilities, belts,		
Findings / Law(s) Violated:	77.1104		
Corrective Actions Taken:	Hazards have been addressed by management and corrected		
Recommendation(s):	Review HazCom Program; Conduct more frequent examinations of firefighting equipment.		
Inspection Date:	Tuesday, August 15, 2017		
Areas Inspected:	Surface Areas of Underground (Portal 2) - Construction Area - hoist construction, power layout, building		
Findings / Law(s) Violated:	construction activities, fueling stations No violations noted.		
Corrective Actions Taken:	None		
Recommendation(s):	None noted		
Inspection Date:	Wednesday, August 16, 2017		
Areas Inspected:	Surface Areas of Underground (Portal 2) - Construction Area - observed hoist safety checks, power layout, building construction activities, fueling stations		
Findings / Law(s) Violated:	No violations noted.		
Corrective Actions Taken:	None		
Recommendation(s):	None noted		
Inspection Date:	: Monday, August 28, 2017		
Areas Inspected:	Underground Areas(Portal 2) - belts, primaries, secondaries		
Findings / Law(s) Violated:	47.41(a); 75.1100-3(a); 75.380(d)(7)(vi)		
Corrective Actions Taken:	Hazards have been addressed by management and corrected		
Recommendation(s):	None noted		
Inspection Date:	Thursday, September 7, 2017		
Areas Inspected:	Surface Areas of Underground (Portal 2) - Construction Area - hoist, power layout, building construction		
ousopeoteur	activities, fueling stations, books and records		

Findings / Law(s) Violated:	No violations noted.	
Corrective Actions Taken:	None	
Recommendation(s):	None noted	
Inspection Date:	Wednesday, September 27, 2017	
Areas Inspected:	Underground Areas (Portal 1) - secondaries, unit 4, belts	
Findings / Law(s) Violated:	75.320(a); 75.222	
Corrective Actions Taken:	Hazards have been addressed by management and corrected	
Recommendation(s):	None noted	
Company		Mine
Sunrise Coal		Oaktown Fuels #2 Mine

Company		Min
Sunrise Coal	Oaktown Fuels #2 M	line
Inspection Date:	Monday, July 24, 2017	
Areas Inspected:	Underground Areas - secondaries, belts, unit 2	
Findings / Law(s) Violated:	No violations noted.	
Corrective Actions Taken:	None	
Recommendation(s):	Remove or dispose of partially filled oil cans.	
Inspection Date:	Friday, August 4, 2017	
Areas Inspected:	Surface Areas of Underground - warehouse, shop, fuel storage area, stacker belt, fan, hoist, substation	
Findings / Law(s) Violated:	47.41(a); 77.1103(a)	
Corrective Actions Taken:	Hazards have been addressed by management and corrected	
Recommendation(s):	Review HazCom Program; Conduct more frequent examinations of firefighting equipment.	
Inspection Date:	Friday, August 4, 2017	
Areas Inspected:	Surface Facilities Areas - raw coal tunnel, plant, facilities, belts	
Findings / Law(s) Violated:	No violtions noted.	
Corrective Actions Taken:	None	
Recommendation(s):	Review HazCom Program; Conduct more frequent examinations of firefighting equipment.	
Inspection Date:	Friday, August 25, 2017	
Areas Inspected:	Surface Facilities Areas - belts, rail stacker, stackers, stacker tunnels, rail scale house, traffic flow	
Findings / Law(s) Violated:	No violtions noted.	
Corrective Actions Taken:	None	
Recommendation(s):	None noted	
Inspection Date:	Tuesday, September 26, 2017	
Areas Inspected:	Underground Areas - secondaries, primaries, belts, unit 4, staging area	

Findings / Law(s) Violated:	75.1104; 47.41(a)
Corrective Actions Taken:	Hazards have been addressed by management and corrected
Recommendation(s):	None noted

Company		Mir
Triad Mining		Freelandville West Min
Inspection Date:	Friday, July 21, 2017	
Areas Inspected:	Surface Areas of Underground - substati	ion, water tank, pit, highwall, roadways, openings, surface pumps,
	bore holes, MCCs, shop area, parts yard, office	
Findings / Law(s) Violated:	No violations noted.	
Corrective Actions Taken:	None	
Recommendation(s):	None noted	
Inspection Date:	Wednesday, August 9, 2017	
A		ion, water tank, pit, highwall, roadways, openings, surface pumps,
Areas Inspected:	bore holes, MCCs, shop area, parts yard,	
Findings / Law(s)	No violations noted.	
Violated:	No violations noted.	
Corrective Actions	None	
Taken:	None	
Recommendation(s):	: None noted	
Inspection Date:	Tuesday, September 5, 2017	
Areas Inspected:	Surface Areas of Underground - substation, water tank, pit, highwall, roadways, openings, surface pumps, bore holes, MCCs, shop area, parts yard, office	
Findings / Law(s)		
Violated:	No violations noted.	
Corrective Actions	None	
Taken:	None	
Recommendation(s):	None noted	
nspection Date:	Wednesday, September 27, 2017	
	Surface Areas of Underground - substati	ion, water tank, pit, highwall, roadways, openings, surface pumps,
Areas Inspected:	bore holes, MCCs, shop area, parts yard,	office
Findings / Law(s) Violated:	No violations noted.	
Corrective Actions Taken:	None	
Recommendation(s):	None noted	
Company		М
Triad Mining		Log Creek Mir
Inspection Date:	Wednesday, July 26, 2017	
•	Surface Areas of Underground - substati	ion, water tank, pit, highwall, roadways, openings, surface pumps,
Areas Inspected:	MCCs, shop area, parts yard, office	
Findings / Law(s)	No violations noted.	

None

Recommendation(s): None noted

Violated: Corrective Actions

Taken:

Inspection Date:	Monday, July 31, 2017
	Surface Areas of Underground - substation, water tank, pit, highwall, roadways, openings, surface pumps,
Areas Inspected:	MCCs, shop area, parts yard, office
Findings / Law(s)	No violations noted.
Violated:	The violations noted.
Corrective Actions	None
Taken:	
Recommendation(s):	None noted
Inspection Date:	Wednesday, August 9, 2017
Areas Inspected:	Surface Areas of Underground - substation, water tank, pit, highwall, roadways, openings, surface pumps,
	MCCs, shop area, parts yard, office
Findings / Law(s) Violated:	No violations noted.
Corrective Actions Taken:	None
Recommendation(s):	None noted
Inspection Date:	Wednesday, August 9, 2017
Areas Inspected:	Underground Areas - all entries and crosscuts upto entry 4
Findings / Law(s) Violated:	No violations noted.
Corrective Actions Taken:	None
Recommendation(s):	None noted
Inspection Date:	Wednesday, August 23, 2017
Areas Inspected:	Surface Areas of Underground - substation, water tank, pit, highwall, roadways, openings, surface pumps,
	MCCs, shop area, parts yard, office
Findings / Law(s) Violated:	No violations noted.
Corrective Actions	
Taken:	None
Recommendation(s):	None noted
Inspection Date:	Wednesday, August 23, 2017
Areas Inspected:	Underground Areas - secondaries, unit, primaries
Findings / Law(s) Violated:	No violations noted.
Corrective Actions Taken:	None
Recommendation(s):	None noted
Inspection Date:	Wednesday, September 13, 2017
Areas Inspected:	Surface Areas of Underground - substation, water tank, pit, highwall, roadways, openings, surface pumps,
	MCCs, shop area, parts yard, office
Findings / Law(s) Violated:	No violations noted.
Corrective Actions Taken:	None
Recommendation(s):	None noted
Inspection Date:	Wednesday, September 13, 2017
·	
Areas Inspected:	Underground Areas - secondaries, unit, primaries

Findings / Law(s) Violated:	No violations noted.
Corrective Actions Taken:	None
Recommendation(s):	None noted