

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Registration	<b>Date:</b> 12/27/2013	<b>Time:</b> 11:34 AM
<b>Name of School Corporation:</b> SETON CATHOLIC SCHOOL	<b>Corp ID:</b> D842	
<b>Address of School Corporation:</b> 233 South 5th Street		
<b>City:</b> Richmond	<b>Zip:</b> 47374	<b>County Number:</b> 89
<b>VIN:</b> 1HVBABN91A937335	<b>License Number:</b> b362j	<b>Bus Number:</b> 4
<b>Make of Body:</b> AmTran	<b>Year:</b> 2001	<b>Make of Chassis:</b> IC Corporation
<b>Bus Type:</b> C	<b>Mileage:</b> Unknown	<b>Year:</b> 2001
<b>Inspection Status:</b> O	<b>Inspected By:</b> Jeremy Mason	<b>PE:</b> 8139

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
12-1-1	Clearance light is missing, cracked, faded, wrong color, or inoperative.
56-1-5	Step-well light is missing or inoperative
61-1-2	One (1) taillight or one (1) brake light does not function
42-1-2	Required lettering is missing or faded.
69-1-10	Emergency window instructions are illegible, missing, or not within 6 inches of the release handle
69-1-8	Required reflective tape is applied in the wrong location, missing, and wrong width or badly faded
19-1-1	Lettering is missing or improper.
19-1-7	If required, reflective tape is applied in the wrong location, missing, and wrong width or badly faded.
79-1-2	Outside exit not outlined with yellow or white 1" in width reflective tape(after chassis manufactured date of 05-02-94)

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
7-2-6	There is any defect which the inspector feels would adversely affect the ability of the vehicle to stop safely.
7-2-1	There is no brake certification, the certification is expired, or is not signed within the six-month requirement.

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more

than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.