

## REPORT OF SCHOOL BUS INSPECTION

|                                       |                              |                        |               |                         |                |
|---------------------------------------|------------------------------|------------------------|---------------|-------------------------|----------------|
| <b>Type of Inspection:</b>            | Post-Crash Inspection        | <b>Date:</b>           | 4/7/2015      | <b>Time:</b>            | 8:46 AM        |
| <b>Name of School Corporation:</b>    | VALPARAISO COMMUNITY SCHOOLS | <b>Corp ID:</b>        | 646560        |                         |                |
| <b>Address of School Corporation:</b> | 55 Evans St                  |                        |               |                         |                |
| <b>City:</b>                          | Valparaiso                   | <b>Zip:</b>            | 46383         | <b>County Number:</b>   | 64             |
| <b>VIN:</b>                           | 4DRBWAAN4AA192148            | <b>License Number:</b> | 33109         | <b>Bus Number:</b>      | 58             |
| <b>Make of Body:</b>                  | IC Corporation               | <b>Year:</b>           | 2010          | <b>Make of Chassis:</b> | IC Corporation |
| <b>Year:</b>                          |                              |                        |               | <b>Year:</b>            | 2010           |
| <b>Bus Type:</b>                      | D                            | <b>Mileage:</b>        | 66001         |                         |                |
| <b>Inspection Status:</b>             | O                            | <b>Inspected By:</b>   | Nathan Sherer | <b>PE:</b>              | 7029           |

### Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u>   |
|------------------------|--|
| 57-1-2                 | Step-well area is weakened   |
| 11-1-2                 | The front or rear bumper is not properly attached, missing, torn, loose, or altered. |
| 70-1-2                 | There are intersecting cracks in the windshield area covered by the wipers           |

### Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u>  |
|------------------------|---|
| 24-2-1                 | There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)). |
| 41-2-1                 | Interior is excessively dirty. (Excessive trash or dirt that would jeopardize the safety of students)   |
| 63-2-3                 | Any tire is flat  |
| 70-2-1                 | Any glass or glazing is broken through or missing   |
| 51-2-1                 | The service door does not open or close properly  |
| 7-2-8                  | There is any defect which the inspector feels would adversely affect the ability of the vehicle to stop safely  |

### Bus Type Description

**Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.**