## REPORT OF SCHOOL BUS INSPECTION

Type of 8:06 Post-Crash Inspection 3/13/2017 **Time:** Date: Inspection: AM Name of School Corporation: CROWN POINT COMM. SCHOOL CORP. Corp ID: 454660 **Address of School Corporation:** 1151 E Summit County City: Crown Point Zip: 46307 45 Number: License VIN: 4UZABRDT2HCHW9518 15398 **Bus Number:** 21 Number: Make of Thomas Built Buses, Make of Body: Year: 2016 Freightliner Year: 2017 Inc. Chassis: **Bus Type:** С Mileage: 14099 Inspected Nathan Sherer PE: 7029 **Inspection Status:** O By:

## **Violations - Rejected**

Inspection Code	<u>Description</u>
29-1-2	Floor covering is missing, cut, loose, buckled, bulging, or not secure
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails

## **Violations - Out of Service**

<u>Inspection</u> <u>Code</u>	<u>Description</u>
7-2-8	There is any defect which the inspector feels would adversely affect the ability of the vehicle to stop safely
53-2-5	"U" bolts are loose, broken, or missing

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.