

REPORT OF SCHOOL BUS INSPECTION

| | | | | | | | |
|--------------------------------|--------------------------------|---------------|-----------------|------------------|----------------|-------|------|
| Type of Inspection: | Annual | Date: | 4/7/2017 | Time: | 8:31 AM | | |
| Name of School Corporation: | RICHLAND-BEAN BLOSSOM C.S.CORP | | | Corp ID: | 535705 | | |
| Address of School Corporation: | 600 S Edgewood Dr | | | | | | |
| City: | Ellettsville | Zip: | 47429 | County Number: | 53 | | |
| VIN: | 4DRBRAAN74B967239 | | License Number: | 19776 | Bus Number: | 35 | |
| Make of Body: | IC Corporation | Year: | 2003 | Make of Chassis: | IC Corporation | Year: | 2004 |
| Bus Type: | C | | | Mileage: | 92887 | | |
| Inspection Status: | R | Inspected By: | Mark Raper | PE: | 6473 | | |

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|---|
| 35-1-1 | A heater motor is not operating properly |
| 23-1-3 | Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted). |
| 23-1-6 | Tailpipe does not extend to, or extends more than 1" beyond the perimeter of the bus body |

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.