REPORT OF SCHOOL BUS INSPECTION

Type of 5:18 Post-Crash Inspection 9/14/2018 **Time**: Date: Inspection: PM Name of School Corporation: LINTON-STOCKTON SCH CORP Corp ID: 282950 **Address of School Corporation:** 801 Northeast First St County City: Linton Zip: 47441 28 Number: License VIN: 1GB3G3BGXF1268601 35776 **Bus Number:** SP3 Number: Thomas Built Buses, Make of Year: 2015 Chevrolet Year: Make of Body: 2015 Inc. Chassis: **Bus Type:** Mileage: 6022 Inspected Inspection Status: O PE: Mark Raper 6473 By:

Violations - Rejected

<u>Inspection</u>	Description
<u>Code</u>	<u>Description</u>

The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails

Violations - Out of Service

Inspection Code	<u>Description</u>
70-2-1	Any glass or glazing is broken through or missing
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
25-2-1	Mountings are broken or bent badly enough to inhibit proper adjustment

Bus Type Description