

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Post-Crash Inspection	<b>Date:</b>	10/22/2019	<b>Time:</b>	4:18 PM
<b>Name of School Corporation:</b>	NORTH VERMILLION COMM SCH CORP	<b>Corp ID:</b>	838010		
<b>Address of School Corporation:</b>	5551 N Falcon Dr				
<b>City:</b>	Cayuga	<b>Zip:</b>	47928	<b>County Number:</b>	83
<b>VIN:</b>	1GB3G3BG2B1175629	<b>License Number:</b>	47357	<b>Bus Number:</b>	18
<b>Make of Body:</b>	Thomas Built Buses, Inc.	<b>Year:</b>	2011	<b>Make of Chassis:</b>	Chevrolet
<b>Bus Type:</b>		<b>Mileage:</b>	132933		
<b>Inspection Status:</b>	O	<b>Inspected By:</b>	Byron Goodman	<b>PE:</b>	7008

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
34-1-1	Any headlight is inoperative
64-1-4	Any front turn signal does not function properly
64-1-2	A lens is cracked, missing or wrong color

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-2	Any body surface protrudes beyond the normal limits of the body structure
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)(Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district).
34-2-1	Both lamps are inoperative on low beam
34-2-2	Both lamps are inoperative on high beam

### Bus Type Description