

REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|--------------------------------|-------------------------------|-----------------|----------------|------------------|--------------|
| Type of Inspection: | Semi-Annual | Date: | 1/13/2021 | Time: | 9:07 AM |
| Name of School Corporation: | JOHN GLENN SCHOOL CORPORATION | Corp ID: | 717150 | | |
| Address of School Corporation: | 101 John Glen Dr | | | | |
| City: | Walkerton | Zip: | 46574 | County Number: | 71 |
| VIN: | 4UZ6CJAA7XCA36161 | License Number: | 72446 | Bus Number: | 34 |
| Make of Body: | Blue Bird Corporation | Year: | 1999 | Make of Chassis: | Freightliner |
| Bus Type: | | Mileage: | 130697 | Year: | 1999 |
| Inspection Status: | O | Inspected By: | Travis Harrold | PE: | 8022 |

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--|
| 24-1-1 | The bus body has rust or rusted through areas which may weaken the body |
| 46-1-1 | Any seat is loose from the floor or seat rail |
| 70-1-8 | Any required reflective tape is applied in the wrong location, missing, and wrong width or badly faded |
| 57-1-2 | Step-well area is weakened |

Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|---|
| 24-2-1 | There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)). |
| 57-2-1 | Any part of the step-well or support structure is rusted through |

Bus Type Description