

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Post-Crash Inspection	<b>Date:</b>	9/28/2021	<b>Time:</b>	9:17 AM
<b>Name of School Corporation:</b>	NORTH JUDSON-SAN PIERRE SCH CO	<b>Corp ID:</b>	757515		
<b>Address of School Corporation:</b>	801 Campbell Dr				
<b>City:</b>	North Judson	<b>Zip:</b>	46366	<b>County Number:</b>	75
<b>VIN:</b>	4DRBUC8P7FB143715	<b>License Number:</b>	8235	<b>Bus Number:</b>	23
<b>Make of Body:</b>	IC Corporation	<b>Year:</b>	2014	<b>Make of Chassis:</b>	IC Corporation
<b>Bus Type:</b>	C	<b>Mileage:</b>	58500	<b>Year:</b>	2015
<b>Inspection Status:</b>	O	<b>Inspected By:</b>	Nathan Sherer	<b>PE:</b>	7029

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.
62-1-2	One (1) taillight or one (1) brake light does not function

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
20-2-2	Door glass is missing
64-2-1	Any rear turn signal does not function properly
8-2-1	There is no brake certification, or the certification has expired or is not signed

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**