

# REPORT OF SCHOOL BUS INSPECTION

|                                |                          |               |                |                  |              |
|--------------------------------|--------------------------|---------------|----------------|------------------|--------------|
| Type of Inspection:            | Registration             | Date:         | 1/26/2022      | Time:            | 10:07 AM     |
| Name of School Corporation:    |                          |               |                | Corp ID:         | 747385       |
| Address of School Corporation: |                          |               |                |                  |              |
| City:                          | Lincoln City             | Zip:          | 47552          | County Number:   | 74           |
| VIN:                           | 4UZABRDU9BCAR7862        |               |                | License Number:  | NBNS18       |
| Make of Body:                  | Thomas Built Buses, Inc. | Year:         | 2009           | Make of Chassis: | Freightliner |
| Bus Type:                      | C                        |               |                | Year:            | 2009         |
| Inspection Status:             | R                        | Inspected By: | Philip Lubbers | PE:              | 7703         |

## Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u>                                                                                        |
|------------------------|-----------------------------------------------------------------------------------------------------------|
| 57-1-1                 | Step covering is loose, buckled, or made of a material other than rubber (i.e. rugs, carpets, mats, etc.) |
| 57-1-2                 | Step-well area is weakened                                                                                |
| 24-1-6                 | There are unauthorized attachments to the exterior of the bus                                             |
| 49-1-4                 | Any reflector is missing, cracked, faded, or the wrong color.                                             |
| 64-1-4                 | Any front turn signal does not function properly                                                          |
| 50-1-1                 | The seat belt cutter is not located within the driver's view and reach                                    |
| 50-1-2                 | The seat belt cutter is not secured using a positive fastening method.                                    |

## Violations - Out of Service

### Inspection Code Description

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.