REPORT OF SCHOOL BUS INSPECTION

Type of Post-Crash Inspection Date: 1/18/2024 Time: 12:38 PM

Name of School Corporation: SOUTHWEST PARKE COMM SCH CORP Corp ID: 616260

Address of School Corporation: RR 1

City: Montezuma Zip: 47862 County Number: 61
VIN: 4DRBUC8N2GB129205 License Number: B988K Bus Number: 11

Make of Body: Year: 2015 Make of Chassis: IC Corporation Year: 2016

Bus Type: C Mileage: 56930

Inspection Status: O Inspected By: Byron Goodman PE: 7008

Violations - Rejected

Inspection Code	<u>Description</u>
52-1-4	Any shock absorber is broken or missing
11-1-1	The front bumper does not extend to the edge of the fenders
64-1-4	Any front turn signal does not function properly
7-1-3	Air leak at proper connection
34-1-1	Any headlight is inoperative
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails

Violations - Out of Service

Inspection Code	<u>Description</u>
55-2-7	There are any cracks in any steering component
63-2-3	Any tire is flat
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.