

REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---------------------------------------|-----------------------|------------------------|-------------|-------------------------|-----------------------|
| Type of Inspection: | Semi-Annual | Date: | 10/29/2024 | Time: | 9:38 AM |
| Name of School Corporation: | INDIANA ACADEMY | Corp ID: | 29B190 | | |
| Address of School Corporation: | 24815 SR 19 | | | | |
| City: | Cicero | Zip: | 46034 | County Number: | 29 |
| VIN: | 1BABKCXA94F219815 | License Number: | B874N | Bus Number: | 2 |
| Make of Body: | Blue Bird Corporation | Year: | 2003 | Make of Chassis: | Blue Bird Corporation |
| Bus Type: | C | Mileage: | 134736 | Year: | 2004 |
| Inspection Status: | O | Inspected By: | Joel Flores | PE: | 7415 |

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--|
| 49-1-1 | The reflective material is placed anywhere other than on the front and rear, or both, of the bus between the warning lamps; each side beltline, seat line, or floor line or all three (3); outlining each required emergency exit; or across the rear of the bus directly above the rear bumper. |
| 43-1-8 | Any required lettering is missing or faded. |

Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|---|
| 7-2-1 | There is no brake certification form the certification is expired or is not signed within the six-month requirement |
| 50-2-1 | There is no seat belt cutter in the vehicle |
| 18-2-3 | Center/carrier bearing: any broken or loose center/carrier bearing bracket, bolts or mounting hardware, any center bearing bracket crack equaling fifty (50) percent or more of the original width, more than one half (1/2) inch vertical movement of the shaft in the center bearing carrier (rubber) |

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.