

## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection Date: 9/19/2025 Time: 10:24 AM  
Name of School Corporation: PERU COMMUNITY SCHOOLS Corp ID: 525635  
Address of School Corporation: 35 W 3rd St  
City: Peru Zip: 46970 County Number: 52  
VIN: 4UZABRFC7RCUD2446 License Number: 25966 Bus Number: 7  
Make of Body: Freightliner Year: 2022 Make of Chassis: Freightliner Year: 2024  
Bus Type: C Mileage: 61587  
Inspection Status: O Inspected By: Randy McPike PE: 7018

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
68-1-1	Washers do not function properly in any manner
11-1-1	The front bumper does not extend to the edge of the fenders
3-1-7	Battery compartment door is not securely fastened.
67-1-2	Rims are bent or loose
64-1-4	Any front turn signal does not function properly
28-1-4	The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1"x5yd, 1 blunt scissor, 6 3x3" gauze pads (sterile), 4 2"x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction.

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
63-2-3	Any tire is flat
7-2-3	The required low air-pressure warning device fails to operate properly
55-2-3	Any steering component jams or inhibits safe movement
55-2-4	Tie rod end movement is greater than 1/8 inch (rotational movement is acceptable)
34-2-1	Both lamps are inoperative on low beam
64-2-1	Any rear turn signal does not function properly
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
53-2-4	Shackles are worn, loose, broken, cracked or missing
59-2-4	Stop arm does not function properly

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.