

## REPORT OF SCHOOL BUS INSPECTION

|                                                                   |                                    |                                        |
|-------------------------------------------------------------------|------------------------------------|----------------------------------------|
| <b>Type of Inspection:</b> Spot Checks                            | <b>Date:</b> 9/16/2026             | <b>Time:</b> 10:03 AM                  |
| <b>Name of School Corporation:</b> MERRILLVILLE COMM. SCHOOL CORP | <b>Corp ID:</b> 454600             |                                        |
| <b>Address of School Corporation:</b> 6601 Delaware St            |                                    |                                        |
| <b>City:</b> Merrillville                                         | <b>Zip:</b> 46410                  | <b>County Number:</b> 45               |
| <b>VIN:</b> 4DRBUC8N5HB758426                                     | <b>License Number:</b> 12560       | <b>Bus Number:</b> 84                  |
| <b>Make of Body:</b> IC Corporation                               | <b>Year:</b> 2016                  | <b>Make of Chassis:</b> IC Corporation |
| <b>Year:</b> 2017                                                 |                                    |                                        |
| <b>Bus Type:</b> C                                                | <b>Mileage:</b> 69081              |                                        |
| <b>Inspection Status:</b> O                                       | <b>Inspected By:</b> Nathan Sherer | <b>PE:</b> 7029                        |

### Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u>                                                                                           |
|------------------------|--------------------------------------------------------------------------------------------------------------|
| 50-1-1                 | The seat belt cutter is not located within the driver's view and reach                                       |
| 50-1-3                 | The seat belt cutter is contained in a compartment.                                                          |
| 50-1-2                 | The seat belt cutter is not secured using a positive fastening method.                                       |
| 41-1-5                 | There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.)                       |
| 70-1-10                | If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle |

### Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u>                                                                                                  |
|------------------------|---------------------------------------------------------------------------------------------------------------------|
| 7-2-1                  | There is no brake certification form the certification is expired or is not signed within the six-month requirement |

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**