# REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---|---|---|---|---|---|
| **Type of Inspection:** | Annual | **Date:** | 3/13/2012 | **Time:** | 8:55 AM |
| **Name of School Corporation:** | SOUTH MADISON COMM. SCHOOLS | | | **Corp ID:** | 485255 |
| **Address of School Corporation:** | 203 S Heritage Way | | | | |
| **City:** | Pendleton | **Zip:** | 46064 | **County Number:** | 48 |
| **VIN:** | 4UZABRDT38CZ55176 | **License Number:** | 13645 | **Bus Number:** | 7 |
| **Make of Body:** | Thomas Built Buses, Inc. **Year:** 2008 | **Make of Chassis:** | Freightliner | **Year:** | 2007 |
| **Bus Type:** | C | **Mileage:** | Unknown | | |
| **Inspection Status:** | O | **Inspected By:** | Dave Whitinger | **PE:** | 6480 |

**Violations - Rejected**

| Inspection Code | Description |
|---|---|
| 120-1-1 | A bus must have interior lights that are automatically or manually activated, sufficiently illuminate the lift area, and are activated from the door area |
| 76-1-1 | There are any loose, broken, or missing mountings |

**Violations - Out of Service**

| Inspection Code | Description |
|---|---|
| 108-2-1 | Power lift does not operate in the proper manner |

**Bus Type Description**

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**