REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	4/12/2012	**Time:**	10:44 AM
Name of School Corporation:	HAMILTON SOUTHEASTERN SCHOOLS			**Corp ID:**	293005
Address of School Corporation:	13485 Cumberland Rd				
City:	Fishers	**Zip:**	46038	**County Number:**	29
VIN:	1HVBJAAR81A938018	**License Number:**	17918	**Bus Number:**	125
Make of Body:	AmTran **Year:** 2001	**Make of Chassis:**	AmTran	**Year:**	2001
Bus Type:	D	**Mileage:**	Unknown		
Inspection Status:	O	**Inspected By:**	John Pang	**PE:**	6196

Violations - Rejected

Inspection Code	Description
41-1-2	The first aid kit is not properly filled in accordance with the '24 Unit Kit'.
34-1-1	There is significant engine oil or fluid leak from the engine.
34-1-4	There is a significant fluid leak from the transmission.

Violations - Out of Service

Inspection Code	Description
14-2-2	Any push-rod travel measures 1/4 inch or more beyond the readjustment limit, or if any two (2) brakes measure less than 1/4 inch beyond the readjustment limit.
14-2-6	There is any defect which the inspector feels would adversely affect the ability of the vehicle to stop safely.

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.