# REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---|---|---|---|---|---|
| **Type of Inspection:** | Annual | **Date:** | 5/7/2012 | **Time:** | 10:45 AM |
| **Name of School Corporation:** | NEW PALESTINE COMMUNITY SCHOOLS | | | **Corp ID:** | 303115 |
| **Address of School Corporation:** | PO Box 508 | | | | |
| **City:** | New Palistine | **Zip:** | 46163 | **County Number:** | 30 |
| **VIN:** | 1BABLCPH6FF313129 | **License Number:** | MOSB31901 | **Bus Number:** | 31 |
| **Make of Body:** | Blue Bird Corporation **Year:** 2015 | **Make of Chassis:** | Blue Bird Corporation | **Year:** | 2015 |
| **Bus Type:** | B | **Mileage:** | Unknown | | |
| **Inspection Status:** | O | **Inspected By:** | Amy Gaul | **PE:** | 5934 |

**Violations - Rejected**

| Inspection Code | Description |
|---|---|

**Violations - Out of Service**

| Inspection Code | Description |
|---|---|
| 36-2-1 | Exhaust leak occurs in the exhaust system prior to the muffler outlet. |

**Bus Type Description**

**Type B School Bus - A conversion or body constructed and installed upon a van or front-section vehicle chassis or stripped chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. Part of the engine is beneath and/or behind the windshield and beside the driver's seat. The entrance door is behind the front wheels.**