# REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---|---|---|---|---|---|
| **Type of Inspection:** | Annual | **Date:** | 2/6/2013 | **Time:** | 10:25 AM |
| **Name of School Corporation:** | M.S.D. LAWRENCE TOWNSHIP | | | **Corp ID:** | 495330 |
| **Address of School Corporation:** | 5850 Thunderbird Rd | | | | |
| **City:** | Indianapolis | **Zip:** | 46236 | **County Number:** | 49 |
| **VIN:** | 1HVBJAAR11A938717 | **License Number:** | 18190 | **Bus Number:** | 99 |
| **Make of Body:** | AmTran **Year:** 2001 | **Make of Chassis:** | AmTran | **Year:** | 2001 |
| **Bus Type:** | D | **Mileage:** | Unknown | | |
| **Inspection Status:** | O | **Inspected By:** | Amy Gaul | **PE:** | 5934 |

**Violations - Rejected**

| Inspection Code | Description |
|---|---|
| 43-1-1 | Marker light or lens is missing, cracked, faded, wrong color, or inoperative. |
| 67-1-3 | Reservoir is empty. |
| 7-1-1 | Any push-rod travel measures less than 1/4 inch beyond the readjustment limit. |
| 45-1-5 | Upholstery or padding is ripped, torn, or improperly repaired. |

**Violations - Out of Service**

| Inspection Code | Description |
|---|---|
| 69-2-4 | Audible warning device, when required, is not working properly. Buzzers are required after 5-2-94 |

**Bus Type Description**

**Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.**