# REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---|---|---|---|---|---|
| **Type of Inspection:** | Annual | | **Date:** | 5/3/2013 | **Time:** | 10:16 AM |
| **Name of School Corporation:** | SOUTH KNOX SCHOOL CORPORATION | | | | **Corp ID:** | 424325 |
| **Address of School Corporation:** | 6116 E SR 61 | | | | | |
| **City:** | Vincennes | **Zip:** | 47591 | | **County Number:** | 42 |
| **VIN:** | 4DRBBAAP03B581654 | | **License Number:** | B321D | **Bus Number:** | 14 |
| **Make of Body:** | Blue Bird Corporation | **Year:** 2003 | **Make of Chassis:** | IC Corporation | **Year:** | 2003 |
| **Bus Type:** | C | | **Mileage:** | Unknown | | |
| **Inspection Status:** | R | **Inspected By:** | Chuck Tharp | | **PE:** | 5618 |

**Violations - Rejected**

| Inspection Code | Description |
|---|---|
| 19-1-7 | If required, reflective tape is applied in the wrong location, missing, and wrong width or badly faded. |
| 3-1-3 | Battery is loose in its mounting. |
| 27-1-2 | The first aid kit is not properly filled. |

**Violations - Out of Service**

| Inspection Code | Description |
|---|---|

**Bus Type Description**

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**