# REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---|---|---|---|---|---|
| **Type of Inspection:** | Re-Inspection | **Date:** | 7/8/2015 | **Time:** | 8:46 AM |
| **Name of School Corporation:** | EASTERN HANCOCK CSC | | | **Corp ID:** | 303145 |
| **Address of School Corporation:** | 10370 E 250 N | | | | |
| **City:** | Charlottesville **Zip:** | 46117 | | **County Number:** | 30 |
| **VIN:** | 1GB3G2BG3E1102977 | **License Number:** | 7148 | **Bus Number:** | AV1 |
| **Make of Body:** | Starcraft **Year:** 2014 | **Make of Chassis:** | Starcraft | **Year:** | 2014 |
| **Bus Type:** | A2 | **Mileage:** | 12677 | | |
| **Inspection Status:** | O **Inspected By:** | Edwin Davis | | **PE:** | 3981 |

**Violations - Rejected**

| Inspection Code | Description |
|---|---|
| 28-1-2 | The first aid or bodily fluid (optional) kit is not securely mounted, inside, in a location accessible to the driver in plain view, or if in a bulkhead or storage compartment, is not secured, or the cover of the bulkhead/storage compartment is not clearly labeled "Emergency Equipment." |

**Violations - Out of Service**

| Inspection Code | Description |
|---|---|
| 26-2-1 | The fire extinguisher is missing |

**Bus Type Description**

**Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:**

1. **Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
2. **Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**