REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	**Date:**	9/23/2015	**Time:**	10:37 AM
Name of School Corporation:	SOUTH MADISON COMM. SCHOOLS			**Corp ID:**	485255
Address of School Corporation:	203 S Heritage Way				
City:	Pendleton	**Zip:**	46064	**County Number:**	48
VIN:	4DRBUSKN68B633325	**License Number:**	31294	**Bus Number:**	26
Make of Body:	IC Corporation **Year:** 2008	**Make of Chassis:**	IC Corporation	**Year:**	2007
Bus Type:	C	**Mileage:**	134628		
Inspection Status:	O	**Inspected By:**	Jeremy Mason	**PE:**	8139

Violations - Rejected

Inspection Code	Description
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.
61-1-4	There is an air leak from any hose, line, tank, bag, or other component of an air suspension system

Violations - Out of Service

Inspection Code	Description
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
14-2-1	Any crossmember is cracked or broken

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.