REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	8/24/2018	**Time:**	9:07 AM
Name of School Corporation:	TRINITY LUTHERAN HIGH SCHOOL			**Corp ID:**	36B452
Address of School Corporation:	7120 N CR 875 E				
City:	Seymour	**Zip:**	47274	**County Number:**	36
VIN:	1GB3G2BG5D1166114	**License Number:**	B955h	**Bus Number:**	1
Make of Body:	Starcraft **Year:** 2013	**Make of Chassis:**	Chevrolet	**Year:**	2013
Bus Type:		**Mileage:**	52380		
Inspection Status:	O	**Inspected By:**	Travis Coryea	**PE:**	5892

Violations - Rejected

Inspection Code	Description
23-1-5	Any hanger, clamp or bracket is missing, loose or broken
70-1-7	Any emergency window is too difficult to open
25-1-5	See Notes: Any defect inspector deems a violation not listed
20-1-10	See Notes: Any defect inspector deems a violation not listed
50-1-1	The seat belt cutter is not located within the driver’s reach

Violations - Out of Service

Inspection Code	Description
8-2-1	There is no brake certification, or the certification has expired or is not signed

Bus Type Description