REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	7/13/2020	**Time:**	10:00 AM
Name of School Corporation:	TRI-COUNTY SCHOOL CORPORATION			**Corp ID:**	918535
Address of School Corporation:					
City:		**Zip:**		**County Number:**	91
VIN:	4DRBUSKN7CB591059	**License Number:**	B971F	**Bus Number:**	4
Make of Body:	IC Corporation **Year:** 2011	**Make of Chassis:**	IC Corporation	**Year:**	2012
Bus Type:		**Mileage:**	102867		
Inspection Status:	O	**Inspected By:**	Nate King	**PE:**	7421

Violations - Rejected

Inspection Code	Description
52-1-2	Any shock absorber is leaking fluid
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired

Violations - Out of Service

Inspection Code	Description
59-2-6	LED type lights have 50% or more pixels inoperable in one light. (NOTE: one letter in the word “STOP” equals one light.)

Bus Type Description