# REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---|---|---|---|---|---|
| **Type of Inspection:** | Semi-Annual | **Date:** | 11/4/2020 | **Time:** | 9:01 AM |
| **Name of School Corporation:** | EVANSVILLE-VANDERBURGH SCH COR | | | **Corp ID:** | 827995 |
| **Address of School Corporation:** | 951 Walnut St | | | | |
| **City:** | Evansville | **Zip:** | 47713 | **County Number:** | 82 |
| **VIN:** | 4UZAAXBV52CJ49343 | **License Number:** | B208K | **Bus Number:** | H67B |
| **Make of Body:** | Freightliner **Year:** 2001 | **Make of Chassis:** | Freightliner | **Year:** | 2002 |
| **Bus Type:** | C | **Mileage:** | 154442 | | |
| **Inspection Status:** | O | **Inspected By:** | Bradley MIller | **PE:** | 7809 |

**Violations - Rejected**

| Inspection Code | Description |
|---|---|
| 46-1-2 | Any seat back or bottom is loose |
| 3-1-3 | Any battery is loose in its mounting. |
| 44-1-1 | Any marker light or lens is missing, cracked, faded, wrong color, or inoperative |

**Violations - Out of Service**

| Inspection Code | Description |
|---|---|
| 70-2-4 | Audible warning device, when required, is not working properly. Buzzers are required after 5-2-94 |

**Bus Type Description**

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**