REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection			**Date:**	2/11/2021	**Time:**	2:45 PM
Name of School Corporation:		NORTH PUTNAM COMMUNITY SCHOOLS				**Corp ID:**	676715
Address of School Corporation:		Box 169					
City:	Bainbridge	**Zip:**	46105			**County Number:**	67
VIN:	1GB3GSBG8K1174334			**License Number:**	24043	**Bus Number:**	421
Make of Body:	Thomas Built Buses, Inc.	**Year:**	2019	**Make of Chassis:**	Thomas Built Buses, Inc.	**Year:**	2021
Bus Type:				**Mileage:**	9545		
Inspection Status:	O	**Inspected By:**	Byron Goodman			**PE:**	7008

Violations - Rejected

Inspection Code	Description
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.
34-1-1	Any headlight is inoperative
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
64-1-4	Any front turn signal does not function properly
64-1-1	Turn signals are not properly mounted
33-1-1	The grill has any exposed edges that may cause injury

Violations - Out of Service

Inspection Code	Description
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description