REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection			**Date:**	3/15/2021	**Time:**	4:48 PM
Name of School Corporation:		HAMILTON SOUTHEASTERN SCHOOLS				**Corp ID:**	293005
Address of School Corporation:		13485 Cumberland Rd					
City:	Fishers	**Zip:**	46038			**County Number:**	29
VIN:	1T7YR4E2191114173			**License Number:**	31677	**Bus Number:**	9
Make of Body:	Thomas Built Buses, Inc.	**Year:**	2008	**Make of Chassis:**	Thomas Built Buses, Inc.	**Year:**	2009
Bus Type:	D			**Mileage:**	95958		
Inspection Status:	O	**Inspected By:**	Jeff Kastenschmidt			**PE:**	5805

Violations - Rejected

Inspection Code	Description
80-1-8	See Notes: Any defect inspector deems a violation not listed
11-1-7	See Notes: Any defect inspector deems a violation not listed
34-1-1	Any headlight is inoperative

Violations - Out of Service

Inspection Code	Description
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.