# REPORT OF SCHOOL BUS INSPECTION

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Type of Inspection:** | Registration | | | **Date:** | 5/14/2021 | **Time:** | 1:28 PM |
| **Name of School Corporation:** | | GROW EARLY LEARNING | | | | **Corp ID:** | |
| **Address of School Corporation:** | | 506-B Pender Street East | | | | | |
| **City:** | Wilson | **Zip:** | 27893 | | | **County Number:** | 79 |
| **VIN:** | 4UZAAWAL94CM20224 | | | **License Number:** | ECMHSP0224 | **Bus Number:** | 23 |
| **Make of Body:** | Thomas Built Buses, Inc. | **Year:** | 2003 | **Make of Chassis:** | Freightliner | **Year:** | 2004 |
| **Bus Type:** | C | | | **Mileage:** | 155490 | | |
| **Inspection Status:** | O | **Inspected By:** | Jeremy Mason | | | **PE:** | 8139 |

**Violations - Rejected**

| Inspection Code | Description |
|---|---|
| 49-1-4 | Any reflector is missing, cracked, faded, or the wrong color. |
| 43-1-8 | Any required lettering is missing or faded. |

**Violations - Out of Service**

| Inspection Code | Description |
|---|---|
| 65-2-3 | There is not 2 amber and 2 red seven inch rear warning lamps horizontally mounted at least 60” apart above the top of the side windows. (Amber lights must be mounted in between the red) |

**Bus Type Description**

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**