REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	**Date:**	1/4/2022	**Time:**	9:19 AM
Name of School Corporation:	FRANKTON-LAPEL COMM. SCHLS.			**Corp ID:**	485245
Address of School Corporation:	7916 W 300 N				
City:	Anderson	**Zip:**	46011	**County Number:**	48
VIN:	4DRBUC8PXMB407782	**License Number:**	23637	**Bus Number:**	55
Make of Body:	IC Corporation **Year:** 2019	**Make of Chassis:**	IC Corporation	**Year:**	2021
Bus Type:	C	**Mileage:**	24084		
Inspection Status:	O	**Inspected By:**	Jeremy Mason	**PE:**	8139

Violations - Rejected

Inspection Code	Description
90-1-3	The trash container is not secured to prevent movement and does not allow for easy removal and replacement
34-1-1	Any headlight is inoperative
11-1-1	The front bumper does not extend to the edge of the fenders
64-1-4	Any front turn signal does not function properly
41-1-5	There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.)
59-1-15	See Notes: Any defect inspector deems a violation not listed

Violations - Out of Service

Inspection Code	Description
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
25-2-2	Reflective glass is cracked, broken, or missing
25-2-1	Mountings are broken or bent badly enough to inhibit proper adjustment

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.