# REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---|---|---|---|---|---|
| **Type of Inspection:** | Annual | **Date:** | 4/27/2022 | **Time:** | 10:16 AM |
| **Name of School Corporation:** | HEARTLAND HALL CHILD DEVELOPMENT CHENTER | | | **Corp ID:** | |
| **Address of School Corporation:** | 11540 N Meridian Street | | | | |
| **City:** | Carmel | **Zip:** | 46032 | **County Number:** | 29 |
| **VIN:** | 1FDES6PM0KKA24698 | **License Number:** | B116R | **Bus Number:** | 2 |
| **Make of Body:** | Starcraft **Year:** 2018 | **Make of Chassis:** | Starcraft | **Year:** | 2018 |
| **Bus Type:** | A1 | **Mileage:** | 9072 | | |
| **Inspection Status:** | O | **Inspected By:** | Nick Cox | **PE:** | 8795 |

**Violations - Rejected**

| Inspection Code | Description |
|---|---|
| 57-1-5 | Step-well light is missing or inoperative |
| 12-1-6 | The re-set switch is not of a push button type, requires a key, or has an override (bypass) capability. |
| 24-1-2 | The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails |
| 41-1-5 | There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.) |

**Violations - Out of Service**

| Inspection Code | Description |
|---|---|
| 8-2-1 | There is no brake certification, or the certification has expired or is not signed |

**Bus Type Description**

**Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:**

1. **Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
2. **Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**