# REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---|---|---|---|---|---|
| **Type of Inspection:** | Semi-Annual | **Date:** | 8/1/2022 | **Time:** | 9:32 AM |
| **Name of School Corporation:** | CROTHERSVILLE COMM. SCHOOLS | | | **Corp ID:** | 363710 |
| **Address of School Corporation:** | 201 S Preston St | | | | |
| **City:** | Crothersville | **Zip:** | 47229 | **County Number:** | 36 |
| **VIN:** | 4UZABRDU28CZ46669 | **License Number:** | 31637 | **Bus Number:** | 2 |
| **Make of Body:** | Thomas Built Buses, Inc. **Year:** 2007 | **Make of Chassis:** | Freightliner | **Year:** | 2007 |
| **Bus Type:** | C | **Mileage:** | 140205 | | |
| **Inspection Status:** | O | **Inspected By:** | Seth Davidson | **PE:** | 8101 |

**Violations - Rejected**

| Inspection Code | Description |
|---|---|
| 44-1-1 | Any marker light or lens is missing, cracked, faded, wrong color, or inoperative |
| 59-1-4 | LED type lights have 25% to 49% pixels inoperable in any one light. (NOTE: one letter in the word “STOP” equals one light |

**Violations - Out of Service**

| Inspection Code | Description |
|---|---|
| 20-2-1 | Is no audible signal when the emergency door is open and ignition switch is on |

**Bus Type Description**

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**