REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	**Date:**	9/21/2022	**Time:**	12:30 PM
Name of School Corporation:	SOUTHWEST DUBOIS SCH. CORP.			**Corp ID:**	192110
Address of School Corporation:	105 W Sunset Dr				
City:	Huntingburg	**Zip:**	47542	**County Number:**	19
VIN:	4DRBUAAN5AB220748	**License Number:**	B790B	**Bus Number:**	11
Make of Body:	IC Corporation **Year:** 2009	**Make of Chassis:**	IC Corporation	**Year:**	2010
Bus Type:	C	**Mileage:**	Unknown		
Inspection Status:	O	**Inspected By:**	Philip Lubbers	**PE:**	7703

Violations - Rejected

Inspection Code	Description
62-1-1	Any lens is cracked, missing, faded or of the wrong color
62-1-2	One (1) taillight or one (1) brake light does not function
64-1-2	A lens is cracked, missing or wrong color
65-1-1	Any lens is cracked, broken or discolored
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
23-1-10	The exhaust system is not properly installed
23-1-12	See Notes: Any defect inspector deems a violation not listed
20-1-2	Excessive effort is needed to open the emergency door
20-1-4	Rubber seals are missing or loose
30-1-3	See Notes: Any defect inspector deems a violation not listed
41-1-1	There are objects blocking aisles or exits
41-1-2	Any interior protrusions have sharp edges or corners
41-1-4	There is debris in the bus. (needs cleaned/includes dirt)
46-1-1	Any seat is loose from the floor or seat rail
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired
70-1-12	See Notes: Any defect inspector deems a violation not listed

Violations - Out of Service

Inspection Code	Description
62-2-1	Two (2) or more taillights or brake lights do not function (LED lights are considered non-functional if 50% or more pixels are inoperable in one light.)
64-2-1	Any rear turn signal does not function properly
65-2-1	Warning lights fail to operate correctly
11-2-2	A bumper does not meet manufactures specifications
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

24-2-2	Any body surface protrudes beyond the normal limits of the body structure
70-2-1	Any glass or glazing is broken through or missing

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.