# REPORT OF SCHOOL BUS INSPECTION

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Type of Inspection:** | Semi-Annual | | | **Date:** | 10/12/2022 | **Time:** | 9:39 AM |
| **Name of School Corporation:** | | SOUTHWEST DUBOIS SCH. CORP. | | | | **Corp ID:** | 192110 |
| **Address of School Corporation:** | | 105 W Sunset Dr | | | | | |
| **City:** | Huntingburg | **Zip:** | 47542 | | | **County Number:** | 19 |
| **VIN:** | 1T7YT4A2471286721 | | | **License Number:** | B878N | **Bus Number:** | 10 |
| **Make of Body:** | Thomas Built Buses, Inc. | **Year:** | 2006 | **Make of Chassis:** | Thomas Built Buses, Inc. | **Year:** | 2007 |
| **Bus Type:** | C | | | **Mileage:** | 180624 | | |
| **Inspection Status:** | O | **Inspected By:** | Philip Lubbers | | | **PE:** | 7703 |

**Violations - Rejected**

| Inspection Code | Description |
|---|---|

**Violations - Out of Service**

| Inspection Code | Description |
|---|---|
| 70-2-4 | Audible warning device, when required, is not working properly. Buzzers are required after 5-2-94 |
| 59-2-6 | LED type lights have 50% or more pixels inoperable in one light. (NOTE: one letter in the word “STOP” equals one light.) |

**Bus Type Description**

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**