REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual			**Date:**	4/12/2023	**Time:**	10:40 AM
Name of School Corporation:		HAMILTON SOUTHEASTERN SCHOOLS				**Corp ID:**	293005
Address of School Corporation:		13485 Cumberland Rd					
City:	Fishers	**Zip:**	46038			**County Number:**	29
VIN:	1T7YR4E25F1277808			**License Number:**	7520	**Bus Number:**	149
Make of Body:	Thomas Built Buses, Inc.	**Year:**	2013	**Make of Chassis:**	Thomas Built Buses, Inc.	**Year:**	2015
Bus Type:	D			**Mileage:**	74879		
Inspection Status:	O	**Inspected By:**	Joel Flores			**PE:**	7415

Violations - Rejected

Inspection Code	Description
70-1-10	If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle
70-1-9	If the words “EMERGENCY EXIT” does not appear on the top or bottom of the window or directly above each emergency exit window on the inside of the bus

Violations - Out of Service

Inspection Code	Description
59-2-3	Stop arm does not fully extend to a right angle to the bus

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.