REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual		**Date:** 10/30/2023	**Time:**	10:36 AM
Name of School Corporation:	RANDOLPH SOUTHERN SCHOOL CORP.			**Corp ID:**	686805
Address of School Corporation:	One Rebel Dr				
City:	Lynn	**Zip:**	47355	**County Number:**	68
VIN:	4UZABRDK38CZ10889		**License Number:** 31494	**Bus Number:**	8
Make of Body:	Thomas Built Buses, Inc.	**Year:** 2007	**Make of Chassis:** Freightliner	**Year:**	2008
Bus Type:	C		**Mileage:** 116630		
Inspection Status:	O	**Inspected By:**	Steve Spallinger	**PE:**	6921

Violations - Rejected

Inspection Code	Description
70-1-2	There are intersecting cracks in the windshield area covered by the wipers
76-1-2	The back – up warning alarm is not 97 DBA (+/- 4 DBA

Violations - Out of Service

Inspection Code	Description
32-2-1	There is fuel leaking from any point on in the fuel system

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.