REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Re-Inspection		**Date:** 11/1/2023	**Time:**	10:17 AM
Name of School Corporation:	UNION SCHOOL CORPORATION			**Corp ID:**	686795
Address of School Corporation:	8707 W US 36				
City:	Modoc	**Zip:**	47358	**County Number:**	68
VIN:	4uzabrdu6dcbr8554		**License Number:** 2737	**Bus Number:**	21
Make of Body:	Thomas Built Buses, Inc. **Year:** 2011		**Make of Chassis:** Freightliner	**Year:**	2012
Bus Type:	C		**Mileage:** 238457		
Inspection Status:	O	**Inspected By:**	Steve Spallinger	**PE:**	6921

Violations - Rejected

Inspection Code	Description
95-1-6	Does not have a circuit breaker of fuse connecting the lift motor to the power source
97-1-1	Not equipped with two lights mounted over the special service entrance door that are operable from the door area and illuminate the special service entrance door area
50-1-2	The seat belt cutter is not secured using a positive fastening method.
41-1-5	There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.)
62-1-2	One (1) taillight or one (1) brake light does not function
35-1-1	A heater motor is not operating properly

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.