REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual			**Date:**	4/3/2024	**Time:**	10:00 AM
Name of School Corporation:		HAMILTON SOUTHEASTERN SCHOOLS				**Corp ID:**	293005
Address of School Corporation:		13485 Cumberland Rd					
City:	Fishers	**Zip:**	46038			**County Number:**	29
VIN:	1T7YR4E21C1145057			**License Number:**	1606	**Bus Number:**	113
Make of Body:	Thomas Built Buses, Inc.	**Year:**	2010	**Make of Chassis:**	Thomas Built Buses, Inc.	**Year:**	2012
Bus Type:	D			**Mileage:**	103264		
Inspection Status:	R	**Inspected By:**	Joel Flores			**PE:**	7415

Violations - Rejected

Inspection Code	Description
28-1-4	The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1”x5yd, 1 blunt scissor, 6 3x3” gauze pads (sterile), 4 2”x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction.
28-1-1	The first aid or bodily fluid (optional) kit is not in a dustproof, detachable container, has sharp protrusions, or requires tools to open.

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.