# REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---|---|---|---|---|---|
| **Type of Inspection:** | Annual | | **Date:** | 4/17/2024 | **Time:** | 9:30 AM |
| **Name of School Corporation:** | EDINBURGH COMM. SCHOOL CORP. | | | | **Corp ID:** | 414215 |
| **Address of School Corporation:** | 202 S Keeley St | | | | | |
| **City:** | Edinburg | **Zip:** | 46124 | | **County Number:** | 41 |
| **VIN:** | 1GB3G2BG4B1160642 | | **License Number:** | 9225 | **Bus Number:** | 21 |
| **Make of Body:** | Chevrolet | **Year:** 2011 | **Make of Chassis:** | Chevrolet | **Year:** | 2011 |
| **Bus Type:** | | | **Mileage:** | 48864 | | |
| **Inspection Status:** | R | **Inspected By:** | Nick Cox | | **PE:** | 8795 |

**Violations - Rejected**

| Inspection Code | Description |
|---|---|
| 45-1-1 | Switch does not simultaneously disable interior noise-producing accessories such as radios or speakers, NOT including 2 way radios, defroster fans, passenger heater fans, powered roof ventilators, or any other noise- producing device. EXEMPTION Type A buses - OEM accessories not including two-way, AM/FM, Satellite, or similiar. |

**Violations - Out of Service**

| Inspection Code | Description |
|---|---|

**Bus Type Description**