REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual			**Date:**	10/28/2024	**Time:**	10:35 AM
Name of School Corporation:		HAMILTON SOUTHEASTERN SCHOOLS				**Corp ID:**	293005
Address of School Corporation:		13485 Cumberland Rd					
City:	Fishers	**Zip:**	46038			**County Number:**	29
VIN:	1T7YR4E21A1126621			**License Number:**	33028	**Bus Number:**	97
Make of Body:	Thomas Built Buses, Inc.	**Year:**	2010	**Make of Chassis:**	Thomas Built Buses, Inc.	**Year:**	2010
Bus Type:	D			**Mileage:**	108551		
Inspection Status:	R	**Inspected By:**	Jeff Stone			**PE:**	8184

Violations - Rejected

Inspection Code	Description
34-1-2	The headlight dimmer switch fails to operate properly
16-1-1	There are any leaks from the differential, pinion seal, hubs or wheel seals

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.