REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual			**Date:**	5/27/2025	**Time:**	10:50 AM
Name of School Corporation:		HAMILTON SOUTHEASTERN SCHOOLS				**Corp ID:**	293005
Address of School Corporation:		13485 Cumberland Rd					
City:	Fishers	**Zip:**	46038			**County Number:**	29
VIN:	1T7Y54D24K1139216			**License Number:**	22345	**Bus Number:**	182
Make of Body:	Thomas Built Buses, Inc.	**Year:**	2017	**Make of Chassis:**	Thomas Built Buses, Inc.	**Year:**	2019
Bus Type:	D			**Mileage:**	49554		
Inspection Status:	R	**Inspected By:**	Joel Flores			**PE:**	7415

Violations - Rejected

Inspection Code	Description
20-1-2	Excessive effort is needed to open the emergency door
20-1-7	If bus manufactured after 5-2-1994, one (1) inch reflective tape is not applied to the door outline, is missing, or badly faded (two (2) is persmissible on bumper below door if insufficient space on body
70-1-7	Any emergency window is too difficult to open

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.