REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual			**Date:**	6/16/2025	**Time:**	10:29 AM
Name of School Corporation:		RANDOLPH SOUTHERN SCHOOL CORP.				**Corp ID:**	686805
Address of School Corporation:		One Rebel Dr					
City:	Lynn	**Zip:**	47355			**County Number:**	68
VIN:	4UZABRFD0MCMR1327			**License Number:**	24541	**Bus Number:**	4
Make of Body:	Thomas Built Buses, Inc.	**Year:**	2020	**Make of Chassis:**	Thomas Built Buses, Inc.	**Year:**	2021
Bus Type:	C			**Mileage:**	71857		
Inspection Status:	R	**Inspected By:**	Steve Spallinger			**PE:**	6921

Violations - Rejected

Inspection Code	Description
82-1-2	See Notes: Any defect inspector deems a violation not listed
64-1-4	Any front turn signal does not function properly
50-1-2	The seat belt cutter is not secured using a positive fastening method.

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.