REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Registration			**Date:**	6/18/2025	**Time:**	1:04 PM
Name of School Corporation:		SOUTH PUTNAM COMMUNITY SCHOOLS				**Corp ID:**	676705
Address of School Corporation:		3999 S US 231					
City:	Greencastle	**Zip:**	46135			**County Number:**	67
VIN:	1T7Y74D29T1241199			**License Number:**	NEW1199Y	**Bus Number:**	SP1
Make of Body:	Thomas Built Buses, Inc.	**Year:**	2024	**Make of Chassis:**	Thomas Built Buses, Inc.	**Year:**	2025
Bus Type:				**Mileage:**	846		
Inspection Status:	O	**Inspected By:**	Byron Goodman			**PE:**	7008

Violations - Rejected

Inspection Code	Description
44-1-1	Any marker light or lens is missing, cracked, faded, wrong color, or inoperative
74-1-1	The anti-vandalism device fails to operate

Violations - Out of Service

Inspection Code	Description
62-2-1	Two (2) or more taillights or brake lights do not function (LED lights are considered non-functional if 50% or more pixels are inoperable in one light.)
64-2-1	Any rear turn signal does not function properly

Bus Type Description