

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection	Date: 5/8/2026	Time: 9:06 AM
Name of School Corporation: WAWASEE COMMUNITY SCHLS		Corp ID: 434345
Address of School Corporation: 1 Warrior Path Bldg 2		
City: Syracuse	Zip: 46567	County Number: 43
VIN: 1BAKJCSA2MF372062	License Number: 23873	Bus Number: 29
Make of Body: Blue Bird Corporation	Year: 2019	Make of Chassis: Blue Bird Corporation
Year: 2021		
Bus Type: C	Mileage: 93477	
Inspection Status: O	Inspected By: Travis Harrold	PE: 8022

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
64-1-4	Any front turn signal does not function properly
82-1-2	The mirrors do not meet the outside mirror standard as set forth in 575 IAC 1-2-49
53-1-3	Any spring hanger bushings or torque leaf bushings are worn, loose, broken or missing
67-1-2	Rims are bent or loose
61-1-4	There is an air leak from any hose, line, tank, bag, or other component of an air suspension system
52-1-4	Any shock absorber is broken or missing
3-1-7	Battery compartment door is not securely fastened.
21-1-1	Any belt is badly chaffed, cracked, broken or missing
70-1-9	If the words "EMERGENCY EXIT" does not appear on the top or bottom of the window or directly above each emergency exit window on the inside of the bus
70-1-8	Any required reflective tape is applied in the wrong location, missing, and wrong width or badly faded
70-1-5	There are any decals or stickers, except those required by law, in the windshield or in the windows to the immediate right or left of the driver
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
90-1-3	The trash container is not secured to prevent movement and does not allow for easy removal and replacement
41-1-9	See Notes: Any defect inspector deems a violation not listed
41-1-5	There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.)
41-1-7	Non safety related signs/decorations posted.
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.
59-1-15	See Notes: Any defect inspector deems a violation not listed
55-1-2	There is movement at any spring loaded drag link or the rod end (using hand pressure)
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired
7-1-2	ABS warning light is illuminated
34-1-1	Any headlight is inoperative

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
36-2-1	The latch mechanism is missing
70-2-4	Audible warning device, when required, is not working properly. Buzzers are required after 5-2-94
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
63-2-3	Any tire is flat
7-2-1	There is no brake certification form the certification is expired or is not signed within the six-month requirement
65-2-1	Warning lights fail to operate correctly
25-2-1	Mountings are broken or bent badly enough to inhibit proper adjustment

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.