REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	**Date:**	11/2/2026	**Time:**	11:16 AM
Name of School Corporation:	PLYMOUTH COMMUNITY SCHOOL CORP			**Corp ID:**	505485
Address of School Corporation:	701 E Berkley St				
City:	Plymouth	**Zip:**	46563	**County Number:**	50
VIN:	4DRBUC8N9MB495724	**License Number:**	24114	**Bus Number:**	30
Make of Body:	IC Corporation **Year:** 2020	**Make of Chassis:**	IC Corporation	**Year:**	2021
Bus Type:	C	**Mileage:**	68478		
Inspection Status:	O	**Inspected By:**	Travis Harrold	**PE:**	8022

Violations - Rejected

Inspection Code	Description
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
3-1-7	Battery compartment door is not securely fastened.
7-1-5	See Notes: Any defect inspector deems a violation not listed

Violations - Out of Service

Inspection Code	Description
18-2-3	Center/carrier bearing: any broken or loose center/carrier bearing bracket, bolts or mounting hardware, any center bearing bracket crack equaling fifty (50) percent or more of the original width, more than one half (1/2) inch vertical movement of the shaft in the center bearing carrier (rubber)
18-2-1	Yokes: any visible crack in a yoke end, any yoke mounting hardware loose, horizontal or vertical movement of slip joint yoke great than half (1/2) inch, any loose, broken or missing end fitting fastener
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.