

## REPORT OF SCHOOL BUS INSPECTION

|                                |                                |                 |           |                  |                          |       |      |
|--------------------------------|--------------------------------|-----------------|-----------|------------------|--------------------------|-------|------|
| Type of Inspection:            | Annual                         | Date:           | 4/27/2015 | Time:            | 11:16 AM                 |       |      |
| Name of School Corporation:    | SOUTHEAST FOUNTAIN SCHOOL CORP |                 |           | Corp ID:         | 232455                   |       |      |
| Address of School Corporation: | 744 E US 136                   |                 |           |                  |                          |       |      |
| City:                          | Veedersburg                    | Zip:            | 47987     | County Number:   | 23                       |       |      |
| VIN:                           | 4UZABRDUX8CZ11040              | License Number: | 7752      | Bus Number:      | 10                       |       |      |
| Make of Body:                  | Thomas Built Buses, Inc.       | Year:           | 2008      | Make of Chassis: | Thomas Built Buses, Inc. | Year: | 2008 |
| Bus Type:                      | C                              | Mileage:        | 39600     |                  |                          |       |      |
| Inspection Status:             | O                              | Inspected By:   | Nate King | PE:              | 7421                     |       |      |

### Violations - Rejected

#### Inspection Code Description

### Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u>                                                                                                                                                                                                                                                                                      |
|------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 18-2-3                 | Center/carrier bearing: any broken or loose center/carrier bearing bracket, bolts or mounting hardware, any center bearing bracket crack equaling fifty (50) percent or more of the original width, more than one half (1/2) inch vertical movement of the shaft in the center bearing carrier (rubber) |

#### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.