Company		Mine
Alliance Coal		Gibson County Coal South
Inspection Date: Thursday, October 5, 2023		
Areas Inspected:	1 Northwest (cut through)and (parallel)	Primary and right return, 1 Southwest Parallel Primary
Findings / Law(s)	Nana	
Violated:	None	
Corrective Actions	Corrective Actions	
Taken:		
Recommendation(s): Make better repairs to ventilation holes in stoppings, sclae down loose material from roof a		in stoppings, sclae down loose material from roof and ribs.
Inspection Date:	Wednesday, October 11, 2023	
Areas Inspected:	1st SouthWest Main Primary, 1st South	Nest Main Right Return
Findings / Law(s)	75.333(b)(1)	

Violated:	75.333(b)(1)	
Corrective Actions	The mine operator made the reparis immediately.	
Taken:	The nime operator made the repairs inimediately.	
Recommendation(s):	Scale loose coal from ribs in walkways. Ventillation holes for chargers need placed in the upper portion of stoppings.	

Inspection Date:	Tuesday, October 17, 2023
Areas Inspected:	1 SouthWest belt and travelway, 2 NW Submain belt and travelway, Chargers 2039,8677,8207,8681
Findings / Law(s) Violated:	75.371 ventilation plan (u)(A), 75.340(a)(1)(i), 75.701
Corrective Actions Taken:	Vent holes were placed in the stoppings, ground clamp was attached.
Recommendation(s)	Removed loose rock and coal from roof and ribs.

Inspection Date: Tuesday, October 24, 2023		Tuesday, October 24, 2023	
Areas Inspected: Production Unit #1		Production Unit #1	
Z	Findings / Law(s) Violated:	The production unit looked great!	
	Corrective Actions Taken:	None	
		Make sure that faces are properly rock dusted immediately after bloting. Make sure that ventilation holes for battery chargers are as close to the mine roof as possible. Hydrogen gas is lighter than air.	

Inspection Date:	Tuesday, October 31, 2023
Areas Inspected:	1st Southwest Main Left intake and left return, 1st Norhtwest Left Intake
Findings / Law(s) Violated:	None
Corrective Actions Taken:	Looked good
Recommendation(s):	None

Ins	pection Date:	Wednesday, November 8, 2023	
Are	as Inspected:	1 SW Parallel Left Return, 1st NW Parallel Left Return, SW Main Return, West Main Return	
	Findings / Law(s)	75 400 75 402	
	Violated:	75.400, 75.402	
	Corrective Actions	Violations were addressed with the mine operator	
	Taken:		
	Recommendation(s):	Scale loose rock from mine roof, Keep an eye on rib conditions, rock dust loose material.	

Alliance Coal		Gibson County Coal South
Inspection Date:	Wednesday, November 15, 2023	,
Areas Inspected: 1 Northeast Main Belt and Primary, 1 Northeast Main 2 Belt and Primary		
Findings / Law(s)		
Violated:	75.400	
Corrective Actions		
Taken:	Operator is addressing the issue	
Recommendation(s):	Ensure that mandoors are accessible from the secondary to the primary. The 1 NE main neutral needs rock dusted.	
Inspection Date:	Tuesday, November 28, 2023	
Areas Inspected:	Unit #3, MCI 8861, UT8233	
Findings / Law(s)	01111 #3, 10101 8801, 018233	
Violated:	The unit and power centers looked very	good
Corrective Actions Taken:	None	
Recommendation(s):	Stay on top of hand-dusting and cleanin	g.
Inspection Date:	Tuesday, December 5, 2023	
Areas Inspected:	1 Northeast Panel Mian retun, H seals	
Findings / Law(s)		
Violated:	None	
Corrective Actions		
Taken:	None	
Recommendation(s):	: Mandoors must be accessible. Wlakways to mandoors must be clear and safe.	
Inspection Date:	Wednesday, December 20, 2023	
Areas Inspected:	!st Southeast primary and return, 1st No	ortheast main, 1 Seals
Findings / Law(s)	75 402 75 222(-)(4)	
Violated:	75.403, 75.333(c)(1)	
Corrective Actions Taken:	Addressed with mangement	
Recommendation(s):	Maintain walkways to mandoors, keep a	air courses rock dusted, remove losse hog panels from mine roof.
Inspection Date:		
Areas Inspected:		
Findings / Law(s)	ł	
Violated:		
Corrective Actions	<u> </u>	
Taken:		
	<u> </u>	
Recommendation(s):		
Inspection Date:		
Areas Inspected:		
Findings / Law(s)	<u> </u>	
Violated:		
Corrective Actions	<u> </u>	
Taken:	ł	
Recommendation(s):		

Mine Inspection Reports

Company	Mine
In an action Date:	
Inspection Date:	
Areas Inspected: Findings / Law(s)	
Violated:	
Corrective Actions	
Taken:	
Recommendation(s):	
· · · · ·	
Inspection Date:	
Areas Inspected:	
Findings / Law(s)	
Violated:	
Corrective Actions	
Taken:	
Recommendation(s):	
Inspection Date:	
Areas Inspected:	
Findings / Law(s)	
Violated:	
Corrective Actions	
Taken:	
Recommendation(s):	
Inspection Date:	
Areas Inspected:	
Findings / Law(s)	
Violated: Corrective Actions	
Taken:	
Recommendation(s):	
Recommendation(s).	
Inspection Date:	
Areas Inspected:	
Findings / Law(s)	
Violated:	
Corrective Actions	
Taken:	
Recommendation(s):	
Inspection Date:	
Areas Inspected:	
Findings / Law(s)	
Violated: Corrective Actions	
Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s)	
Violated:	
Corrective Actions	
Taken:	
Recommendation(s):	
Inspection Date:	
Areas Inspected:	
Findings / Law(s)	
Violated:	
Corrective Actions	
Taken:	
Recommendation(s):	
Inspection Date:	
Areas Inspected:	
Findings / Law(s)	
Violated: Corrective Actions	
Taken:	
Recommendation(s):	
Inspection Date:	
Areas Inspected:	
Findings / Law(s)	
Violated: Corrective Actions	
Taken:	
Recommendation(s):	
Inspection Data	
Inspection Date: Areas Inspected:	
Findings / Law(s)	<u> </u>
Violated:	
Corrective Actions	
Taken:	
Recommendation(s):	
Inspection Date:	
Inspection Date: Areas Inspected:	
Findings / Law(s)	
Violated:	
Corrective Actions	
Taken:	
Recommendation(s):	

Mine Inspection Reports

Company	Mine
la continue Datas	
Inspection Date:	
Areas Inspected:	
Findings / Law(s)	
Violated: Corrective Actions	
Taken:	
Recommendation(s):	
Inspection Date:	
Areas Inspected:	
Findings / Law(s)	
Violated:	
Corrective Actions	
Taken:	
Recommendation(s):	
Inspection Date:	
Areas Inspected:	
Findings / Law(s)	
Violated: Corrective Actions	
Taken:	
Recommendation(s):	
Recommendation(3).	
Inspection Date:	
Areas Inspected:	
Findings / Law(s)	
Violated:	
Corrective Actions	
Taken:	
Recommendation(s):	
Inspection Date:	
Areas Inspected:	
Findings / Law(s)	
Violated:	
Corrective Actions	
Taken:	
Decemmendation(c)	
Recommendation(s):	
Inspection Date:	
Areas Inspected:	
Findings / Law(s)	
Violated:	
Corrective Actions	
Taken:	
Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s)	
Violated:	
Corrective Actions	
Taken:	
Recommendation(s):	
lassestica Data	
Inspection Date:	
Areas Inspected: Findings / Law(s)	
Violated:	
Corrective Actions Taken:	
Recommendation(s):	
Increation Date:	
Inspection Date: Areas Inspected:	
Findings / Law(s)	
Violated:	
Corrective Actions	
Taken:	
Recommendation(s):	
Inspection Date:	
Areas Inspected:	
Findings / Law(s)	
Violated:	
Corrective Actions	
Taken:	
Recommendation(s):	
Inspection Date:	
Areas Inspected: Findings / Law(s)	
Violated: Corrective Actions	
Taken:	
Recommendation(s):	
Inspection Date:	
Areas Inspected:	
Findings / Law(s)	
Violated:	
Corrective Actions	
Taken:	
Recommendation(s):	

Company Mine			
Peabody Midwe	st Mining	Francisco Mine	
Inspection Date:			
Areas Inspected:			
Findings / Law(s)			
Violated:			
Corrective Actions			
Taken:			
Recommendation(s):			
Inspection Date:			
Areas Inspected:			
Findings / Law(s)			
Violated:			
Corrective Actions			
Taken:			
Recommendation(s):			
Inspection Date:			
Areas Inspected:			
Findings / Law(s)			
Violated:			
Corrective Actions Taken:			
Recommendation(s):			
Inspection Date:			
Areas Inspected:			
Findings / Law(s)			
Violated:			
Corrective Actions			
Taken:			
Recommendation(s):			
Inspection Date:			
Areas Inspected:			
Findings / Law(s) Violated:			
Corrective Actions			
Taken:			
Recommendation(s):			
Inspection Date:			
Areas Inspected:			
Findings / Law(s)			
Violated:			
Corrective Actions			
Taken:			
Recommendation(s):			

Peabody Midwest Mining		Francisco Mine
Inspection Date: Tuesday, October 3, 2023		
Areas Inspected:	Main West 8 belt and travelway	
Findings / Law(s)	None, ther belt line looked great!!	
Violated:	None, ther beit line looked great!!	
Corrective Actions		
Taken:		
Recommendation(s):		

Insp	pection Date:	Friday, October 13, 2023
Areas Inspected:		Main West 7 Primary, Main West 7 Right Intake XC-38 to the end
	Findings / Law(s)	News
	Violated:	None
	Corrective Actions	
	Taken:	
	Recommendation(s):	Remove loose rock and damaged hog panels from the mine roof.

Incr	ection Date:	Thursday, October 19, 2023
-		
Areas Inspected:		Unit #3
	Findings / Law(s)	None
	Violated:	
	Corrective Actions	
	Taken:	
	Recommendation(s):	Rock dust and clean each area after bolting.

Thursday, October 19, 2023
Unit #3
None
The mine looked good!

nspection Date:	Thursday, October 26, 2023
Areas Inspected:	Main return shaft, Air ahaft mains neutral
Findings / Law(s)	75.380(d)(4)(iii), 75.360(b)(9)
Corrective Actions	The operator will have a safety meeting outlining the details of a proper preshift examination.
Recommendation(s):	Keep walkways clear for accessability to mandoors.

Inspection Date:		Thursday, November 2, 2023
Areas Inspected:		9 West Belt and travelway, 10 West Belt and travelway
	Findings / Law(s) Violated:	75.1731(a), 75.400, 75.1403-5(g)
	Corrective Actions Taken:	The affected belts were shut down and repairs made.
	Recommendation(s):	clean and rock dust 10 West belt, Make sure hazards are reported and repaired. Pump water from the 10 West belt line walkways.

Mine Inspection Reports

4th Quarter 2023

Company Mine Peabody Midwest Mining Francisco Mine		
		Francisco Mine
Inspection Date:	Monday, November 13, 2023	
Areas Inspected:	9 West Belt and travelway	
Findings / Law(s) Violated:	75.380(d)(4)(iii), 75.1731(b), 75.220 per	roof control plan Section 8-4
Corrective Actions Taken:	Bad top was dangered out. Belt structure an	d feeder location on the belt were addressed with management.
Recommendation(s):	10 West belt needs aligned to prevent s Do not block mandoors to escapeways.	oillage, 9 West belt needs cleaned and dusted from xc-50 to tail,

Inspection Date:	Thursday, November 30, 2023
Areas Inspected:	Unit #3
Findings / Law(s) Violated:	75.380(d)(4)(ii), 75.402, 75.208
Corrective Actions Taken:	Main West 10 belt was cleaned and dusted, Main West 9 belt support was added, a mandoor was added at th feeder. The rock dusting was addressed with management.
Recommendation(s):	None

Inspection Date:	Thursday, December 7, 2023
Areas Inspected:	8 Main West Primary, 8 Main West Return
Findings / Law(s)	Looked good!
Violated:	Looked good:
Corrective Actions	None
Taken:	none
Recommendation(s):	Return needs rock dusted, water pump needs moved to XC-123

Inspection Date:	Thursday, December 21, 2023
Areas Inspected:	1 South Mains Panel
Findings / Law(s) Violated:	Looked good!
Corrective Actions Taken:	None
Recommendation(s):	None

Inspection Date:	
Areas Inspected:	
Findings / Law(s) Violated:	
Violated:	
Corrective Action	
Taken:	
Recommendation	(s):

Inspection Date:		
Areas Inspected:		
	Findings / Law(s) Violated:	
	Violated:	
	Corrective Actions	
	Taken:	
	Recommendation(s):	

Inspection Date:	
Areas Inspected:	
Findings / Law(s)	
Violated:	
Corrective Actions	
Taken:	
Recommendation(s):	
Inspection Date:	
Areas Inspected:	
Findings / Law(s)	
Violated:	
Corrective Actions	
Taken:	
Recommendation(s):	
Inspection Date:	
Areas Inspected:	
Findings / Law(s)	
Violated: Corrective Actions	
Taken:	
Recommendation(s):	
Inspection Date:	
Areas Inspected:	
Findings / Law(s)	
Violated: Corrective Actions	
Taken:	
Recommendation(s):	
Inspection Data	
Inspection Date: Areas Inspected:	
Findings / Law(s)	<u> </u>
Violated:	
Corrective Actions	
Taken:	
Recommendation(s):	
Inspection Date:	
Inspection Date: Areas Inspected:	
Findings / Law(s)	
Violated:	
Corrective Actions	
Taken:	
Recommendation(s):	

Sunrise Coal		Oaktown Fuels #1 Mine
nspection Date:	Monday, October 2, 2023	
Areas Inspected:	1 North Belt and travelway, 1 North A Be	elt travelway, 5A-4 Belt and travelway
Findings / Law(s) Violated:	75.631(a)(i)	
Corrective Actions Taken:	The area where work was being performed v	was examined by a qualifed person.
Recommendation(s):	Identify power cables at power connecti	on points.

Inspection Date:	Tuesday, October 10, 2023
Areas Inspected:	1 North A Primary and right return, SA-4 Primary and Right Return
Findings / Law(s)	75.1000-3
Violated:	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
Corrective Actions	The fire extinguisher was properly inspected and tagged.
Taken:	
Recommendation(s):	Scale down loose roof and rib, keep mandoors clear of water.

Inspection Date:		Monday, October 16, 2023
Areas Inspected:		1 North A left return, 1 North A Seals, 1 North 1 Left Seals, SA-4 Left return
	Findings / Law(s)	None
	Violated:	
	Corrective Actions	
	Taken:	
	Recommendation(s):	Keep water removed from accessways from seals, roof falls ne to be dangered out to prevent access.

Inspection Date:		Monday, October 23, 2023
Are	as Inspected:	Production Unit #4
	Findings / Law(s)	75.362(d)(3), 75.325(a)(1) MMU Ventilation Plan A8II
	Violated:	
	Corrective Actions	The roof bolter was supplied with a spooter for gas checks. The curtains were aiduted in the face.
	Taken:	The foor bolter was supplied with a spooler for gas checks. The curtains were ajudted in the face.
	Recommendation(s):	Retrain production employees on 20 minute gas checks.
		······································

Inspection Date:	Wednesday, November 1, 2023
Areas Inspected:	SB-4 belt and travelway, SC-4 Belt and travelway
Findings / Law(s) Violated:	75.380(d)(4)(iii), 75.380(d)(4)(iii)
Corrective Actions Taken:	Areas were dangered out and are being addressed by the operator.
Recommendation(s).	Belt lines need spot shoveled and rock dusted. Belt structure needs replaced or repaired as soon as possible. Mandoors leading to escapeways need to be accessible at all times.

Inspection Date:		Thursday, November 9, 2023
Area	as Inspected:	SD4 Drive, SB4 Primary and Right return, SC4 Primary and Right return
	Findings / Law(s)	75.1403-5(g), 75.1100-3
	Violated:	73.1403-3(g), 73.1100-3
	Corrective Actions	Issues were addressed with management.
	Taken:	issues were addressed with management.
	Recommendation(s):	Keep cross cuts with mandoors accessible. Remove damaged hog paneals and loose rock from the mine roof.

Sunrise Coal	Oaktown Fuels #1 Mine
Inspection Date:	Tuesday, November 14, 2023
Areas Inspected:	SD4 Belt and travelway
Findings / Law(s)	The mine looked good!
Violated:	
Corrective Actions	
Taken:	
Recommendation(s):	Replace bad belt structure as soon as possible. Scale loose roc and hog panels from mine roof.

Inspection Date:		Wednesday, November 29, 2023
Are	as Inspected:	Production Unit #3
	Findings / Law(s)	75.342(a)(4)
	Violated:	/3.342(d)(4)
	Corrective Actions	The machine was taken out of service for repairs.
	Taken:	
	Recommendation(s):	Need to work on the travelways to the unit. Keep temporary ventilations controls as tight as possible.

Inspection Date:		Wednesday, December 6, 2023
Are	as Inspected:	M4 Belt, M4 Travelway
	Findings / Law(s)	None. The mine looked good!
	Violated:	
	Corrective Actions	
	Taken:	
	Recommendation(s)	Make sure that mandoors are accessibile. Continue rock dusting and spot cleaning along the M4 belt, Remove loose rock and broken hog panels where needed.

Inspection Date:		Wednesday, December 27, 2023
Are	as Inspected:	SD4 Primary, SD4 Return, SD4 Belt, Rescuer cache
	Findings / Law(s)	75.1403(5)(g), 75.202(a)
	Violated:	/3.1405(5)(8), /3.202(8)
	Corrective Actions	Addressed with management.
	Taken:	Addressed with management.
	Recommendation(s):	Contiue dusting SD-4 Primary from XC50 inby. Spot dust intake entries other than the primary.

-		
Inspection Date:		
Areas Inspected:		
	Findings / Law(s)	
	Violated:	
	Corrective Actions	
	Taken:	
	Recommendation(s):	

Inspection Date:		
Areas Inspected:		
	Findings / Law(s)	
	Violated:	
	Corrective Actions	
	Taken:	
	Recommendation(s):	

Mine Inspection Reports

Company		Mine
Sunrise Coal		Oaktown Fuels #2 Mine
Inspection Date:	Wednesday, October 4, 2023	
Areas Inspected:	M8 Belt and travelway, M9 Belt and trav	/elway
Findings / Law(s)	None, the mine looked good!	
Violated:	None, the mine looked good!	
Corrective Actions		
Taken:		
Recommendation(s):	Safely scale roof and ribs where needed sources and disconnecting devices.	. Replace belt rollers that are in bad order. Label cables at power

Inspection Date:		Thursday, October 12, 2023
Areas	s Inspected:	M8 Primary and return, M9 Primary and Return, M81A Seals, M9 Seals, M8 Belt
F	Findings / Law(s)	75.202(a)
١	Violated:	· 5.652(6)
C	Corrective Actions	Addressed with management.
1	Taken:	Autosseu with multigement.
F	Recommendation(s):	Need to remove loose hog panels from the roof in travelways and walkways.

Inspection Date:		Wednesday, October 18, 2023
Are	as Inspected:	M10 Belt and travelway, M11 Belt and travelway to XC-69
	Findings / Law(s)	75.380(d)(4)(iii)
	Violated:	75.380(¤)(4)(III)
	Corrective Actions	The area was dangered out to prevent access.
	Taken:	The area was uangeled out to prevent access.
	Recommendation(s):	Remove loose rock from roof and ribs, keep walkways clear of trippin hazards, prevent access to unsupported roof areas.

Inspection Date:	Wednesday, October 25, 2023
Areas Inspected:	M10 Primary and Right Return, M11 Primary and Right return to crosscut 69
Findings / Law(s)	75.333(b)(1), 75.333(c)(4)
Violated: Corrective Actions	Issues were addressed with management.
Taken:	
Recommendation(s):	Concentrate on mandoor accessibilty, Dust auxillary intake entries as well.

Inspection Date:	
Areas Inspected:	
Findings / Law(s)	
Violated:	
Corrective Actions	
Taken:	
Recommendation(s):	

Inspection Date:		Monday, October 30, 2023
A	eas Inspected:	Unit #1
1	Findings / Law(s) Violated:	None
	Corrective Actions Taken:	None
	Recommendation(s):	None

cont...

Sunrise Coal		Oaktown Fuels #2 Mine
Inspection Date:	Monday, November 6, 2023	
Areas Inspected:	M10 Right Seals	
Findings / Law(s) Violated:	75.333(h)	
Corrective Actions Taken:	The ventillation was adjusted.	
Recommendation(s):	Make sure mandoors remain shut when	not in use. Carefully monitor seals when out-gassing.

Inspection Date:	Thursday, November 16, 2023
Areas Inspected:	M10 1st Right seals, M10 Left Return
Findings / Law(s)	75.333(b)(2), 75.403
Violated:	
Corrective Actions	Addressed issue with the mine operator.
Taken:	
Recommendation(s):	Make reapirs to permanent ventilation controls.

Inspection Date:	Monday, November 27, 2023
Areas Inspected:	Unit #1, M10 Left Return XC-10, M10 Left Return XC-12
Findings / Law(s)	75.333(b)(2), 75.333(c)
Violated:	75.555(b)(2), 75.555(c)
Corrective Actions	Addressed with management again.
Taken:	Autresseu with management agam.
Recommendation(s):	Steel and Wooden crossbars need floor to roof support at all times.

Inspection Date:	Monday, December 4, 2023
Areas Inspected:	M12 1st Left Panel
Findings / Law(s) Violated:	75.364(a)
Corrective Actions Taken:	Proper examinations were discussed with the mine operator.
Recommendation(s):	

Inspection Date:		
Areas Inspected:		
Findings / Law	(s)	
Violated:		
Corrective Act	ions	
Taken:		
Recommendat	tion(s):	

Inspection Date:		
Areas Inspected:		
Findings / L	aw(s)	
Violated:		
Corrective A	Actions	
Taken:		
Recommen	dation(s):	

Mine Inspection Reports

Company	Mine
la continue Datas	
Inspection Date:	
Areas Inspected:	
Findings / Law(s)	
Violated: Corrective Actions	
Taken:	
Recommendation(s):	
Inspection Date:	
Areas Inspected:	
Findings / Law(s)	
Violated:	
Corrective Actions	
Taken:	
Recommendation(s):	
Inspection Date:	
Areas Inspected:	
Findings / Law(s)	
Violated: Corrective Actions	
Taken:	
Recommendation(s):	
Recommendation(3).	
Inspection Date:	
Areas Inspected:	
Findings / Law(s)	
Violated:	
Corrective Actions	
Taken:	
Recommendation(s):	
Inspection Date:	
Areas Inspected:	
Findings / Law(s)	
Violated:	
Corrective Actions	
Taken:	
Decemmendation(c)	
Recommendation(s):	
Inspection Date:	
Areas Inspected:	
Findings / Law(s)	
Violated:	
Corrective Actions	
Taken:	
Recommendation(s):	

Inspection Date:					
Areas Inspected:					
Findings / Law(s)					
Violated:					
Corrective Actions					
Taken:					
Recommendation(s):					
Inspection Date:					
Areas Inspected:					
Findings / Law(s)					
Violated:					
Corrective Actions Taken:					
Recommendation(s):					
Inspection Date:					
Areas Inspected:					
Findings / Law(s)					
Violated:					
Corrective Actions					
Taken:					
Recommendation(s):					
lassesting Data:					
Inspection Date:					
Areas Inspected: Findings / Law(s)					
Violated:					
Corrective Actions					
Taken:					
Recommendation(s):					
Inspection Date:					
Areas Inspected:					
Findings / Law(s)					
Violated:					
Corrective Actions					
Taken:					
Recommendation(s):					
Inspection Date:					
Areas Inspected:					
Findings / Law(s)					
Violated:					
Corrective Actions					
Taken:					
Recommendation(s):					

Mine Inspection Reports

Company	Mine
la continue Datas	
Inspection Date:	
Areas Inspected:	
Findings / Law(s)	
Violated: Corrective Actions	
Taken:	
Recommendation(s):	
Inspection Date:	
Areas Inspected:	
Findings / Law(s)	
Violated:	
Corrective Actions	
Taken:	
Recommendation(s):	
Inspection Date:	
Areas Inspected:	
Findings / Law(s)	
Violated: Corrective Actions	
Taken:	
Recommendation(s):	
Recommendation(3).	
Inspection Date:	
Areas Inspected:	
Findings / Law(s)	
Violated:	
Corrective Actions	
Taken:	
Recommendation(s):	
Inspection Date:	
Areas Inspected:	
Findings / Law(s)	
Violated:	
Corrective Actions	
Taken:	
Decemmendation(c)	
Recommendation(s):	
Inspection Date:	
Areas Inspected:	
Findings / Law(s)	
Violated:	
Corrective Actions	
Taken:	
Recommendation(s):	

Inspection Date:				
Areas Inspected:				
Findings / Law(s)				
Violated:				
Corrective Actions				
Taken:				
Recommendation(s):				
Inspection Date:				
Areas Inspected:				
Findings / Law(s)				
Violated:				
Corrective Actions Taken:				
Recommendation(s):				
Lucas the Data				
Inspection Date:				
Areas Inspected: Findings / Law(s)				
Violated: Corrective Actions				
Taken:				
Recommendation(s):				
Inspection Date:				
Areas Inspected:				
Findings / Law(s)				
Violated:				
Corrective Actions				
Taken:				
Taken.				
Recommendation(s):				
Inspection Data:				
Inspection Date: Areas Inspected:				
Findings / Law(s)	+			
Violated:				
Corrective Actions				
Taken:				
Recommendation(s):				
	l			
Inspection Date:				
Areas Inspected:				
Findings / Law(s)				
Violated:				
Corrective Actions				
Taken:				
Recommendation(s):				