


Source: Google Map Pro

2019 Aerial Photograph

Bridge Project
Blackiton Mill Road over Silver Creek
New Albany and Jeffersonville Townships,
Floyd and Clark Counties, Indiana
Des. No. 1700788
Metric Project # 18-0145

Note: All locations are approximate





Drawn by: ILJ

Checked by: SC

Approved by: JRP

Date: January, 2021





25. View from north bank of Silver Creek, looking northwest. (Taken 5/14/2020)



27. View of south bank of Silver Creek from Floyd County Bridge No. 51, looking southeast. (Taken 5/14/2020)



26. View of south bank of Silver Creek from Floyd County Bridge No. 51, looking southeast. (Taken 5/14/2020)



28. View of Silver Creek from Floyd County Bridge No. 51, looking east (upstream). (Taken 5/14/2020)





29. View of north bank of Silver Creek from Floyd County Bridge No. 51, looking northeast. (Taken 5/14/2020)



31. View of north bank of Silver Creek from Floyd County Bridge No. 51, looking northwest. (Taken 5/14/2020)



30. View of north bank of Silver Creek from Floyd County Bridge No. 51, looking northeast. (Taken 5/14/2020)



32. View of north bank of Silver Creek from Floyd County Bridge No. 51, looking west. (Taken 5/14/2020)





33. View of Silver Creek from Floyd County Bridge No. 51, looking southwest. (Taken 5/14/2020)



35. View of Silver Creek from CV 3 at western PSL, looking northeast. (Taken 5/14/2020)



34. View of south bank of Silver Creek from Floyd County Bridge No. 51 and CV 3, looking southwest. (Taken 5/14/2020)



36. View of Silver Creek from CV 3 at western PSL, looking northwest. (Taken 5/14/2020)





37. View of Silver Creek from CV 3 at western PSL, looking southwest (downstream). (Taken 5/14/2020)



39. View of CV 3, looking southeast. (Taken 5/14/2020)



38. View of south bank of Silver Creek from CV 3 at western PSL, looking southwest. (Taken 5/14/2020)



40. View of dam in Silver Creek from southern bank of Silver Creek, looking north. (Taken 5/14/2020)





41. View of oxbow feature of Silver Creek at the south bank of Silver Creek, looking northwest. (Taken 5/14/2020)



43. View of northern bank of Silver Creek from western PSL, looking northeast. (Taken 5/14/2020)



42. View of oxbow feature of Silver Creek at the south bank of Silver Creek, looking northeast. (Taken 5/14/2020)



44. View of Silver Creek and CV 3 from northern bank of Silver Creek at western PSL, looking southwest. (Taken 5/14/2020)





45. View of Silver Creek from northern bank of Silver Creek at western PSL, looking southwest (downstream). (Taken 5/14/2020)



47. View of northern bank of Silver Creek from western PSL, looking west. (Taken 5/14/2020)



46. View of northern bank of Silver Creek from western PSL, looking northeast. (Taken 5/14/2020)



48. View of freshwater mussel shells in Silver Creek. (Taken 5/14/2020)





49. View of remains of catfish species in Silver Creek. (Taken 5/14/2020)



51. View of UNT 1 to Silver Creek, looking south (downstream). (Taken 5/14/2020)



50. View of UNT 1 to Silver Creek and CV 4 at the northern PSL, looking north (upstream). (Taken 5/14/2020)



52. View of UNT 1 to Silver Creek and CV 5, looking northwest (upstream). (Taken 5/14/2020)





53. View of UNT 1 to Silver Creek, looking northwest (upstream). (Taken 5/14/2020)



55. View of UNT 1 to Silver Creek from its confluence with Silver Creek, looking northeast (upstream). (Taken 5/14/2020)



54. View of UNT 1 to Silver Creek, looking southeast (downstream). (Taken 5/14/2020)



56. View of the confluence of UNT 1 to Silver Creek with Silver Creek, looking south. (Taken 5/14/2020)





61. View of UNT 2 to Silver Creek, looking northwest (upstream). (Taken 5/14/2020)



63. View of UNT 2 to Silver Creek, looking northwest (upstream). (Taken 5/14/2020)



62. View of UNT 2 to Silver Creek, looking southeast (downstream). (Taken 5/14/2020)



64. View of the confluence of UNT 2 to Silver Creek with Silver Creek, looking southwest. (Taken 5/14/2020)





65. View of CV 7 inlet and Blackiston Mill Rd ROW, looking southeast. (Taken 5/14/2020)



67. View of CV 7 outlet and Blackiston Mill Rd ROW, looking northwest. (Taken 5/14/2020)



66. View of Blackiston Mill Rd ROW from CV 7 inlet, looking northwest. (Taken 5/14/2020)



68. View of NHD flowline (unobserved) from CV 7 outlet, looking southwest. (Taken 5/14/2020)





69. View of upland area north of Silver Creek and west of Blackiston Mill Rd, looking southwest. (Taken 5/14/2020)



71. View of Blackiston Mill Rd ROW from northwestern PSL, looking northeast. (Taken 5/14/2020)



70. View of Blackiston Mill Rd ROW from northwestern PSL, looking northeast. (Taken 5/14/2020)



72. View of Blackiston Mill Rd ROW from intersection of Blackiston Mill Rd and Blackiston Blvd, looking southwest. (Taken





73. View of Blackiston Blvd ROW from intersection of Blackiston Mill Rd and Blackiston Blvd, looking northeast. (Taken 5/14/2020)



75. View of Blackiston Blvd ROW from the intersection of Blackiston Mill Rd and Blackiston Blvd, looking northeast. (Taken $5/14/2020)\,$



74. View of Blackiston Mill Rd and Blackiston Blvd intersection, looking southeast. (Taken 5/14/2020)



76. View of Blackiston Blvd ROW from northern PSL, looking southwest. (Taken 5/14/2020)





77. View of Blackiston Blvd ROW from northern PSL, looking southwest. (Taken 5/14/2020)



79. View of SD 2 and Blackiston Mill Rd ROW from intersection of Blackiston Mill Rd and Silverwood Ct, looking west. (Taken 5/14/2020)



78. View of Blackiston Mill Rd ROW, looking southeast. (Taken 5/14/2020)



80. View of Wetland A and Silverwood Ct from its intersection with Blackiston Mill Rd, looking northeast. (Taken 5/14/2020)





81. View of Blackiston Mill Rd ROW from intersection of Blackiston Mill Rd and Silverwood Ct, looking southeast. (Taken



83. View of upland area east of the intersection of Blackiston Mill Rd and Silverwood Ct, looking southeast. (Taken 5/14/2020)



82. View of Silverwood Ct from the northern PSL, looking southwest. (Taken 5/14/2020)



84. View of upland area east of the intersection of Blackiston Mill Rd and Silverwood Ct, looking northeast. (Taken 5/14/2020)





85. View of Wetland A and upland area east of the intersection of Blackiston Mill Rd and Silverwood Ct, looking northwest. (Taken



87. View of Blackiston Mill Rd ROW, looking northwest. (Taken 5/14/2020)



86. View of upland area east of the intersection of Blackiston Mill Rd and Silverwood Ct, looking southwest. (Taken 5/14/2020)



88. View of Blackiston Mill Rd ROW, looking southeast. (Taken 5/14/2020)





89. View of Blackiston Mill Rd ROW, looking northwest. (Taken 5/14/2020)



91. View of Blackiston Mill Rd ROW, looking northwest. (Taken 5/14/2020)



90. View of Blackiston Mill Rd ROW, looking southeast. (Taken 5/14/2020)



92. View of Blackiston Mill Rd ROW and upland area, looking northwest. (Taken 5/14/2020)





93. View of Blackiston Mill Rd ROW and upland area, looking northeast. (Taken 5/14/2020)



95. View of Blackiston Mill Rd ROW, looking southeast. (Taken 5/14/2020)



94. View of Blackiston Mill Rd ROW and upland area, looking east. (Taken 5/14/2020)



96. View of intersection of Walnut Grove and Blackiston Mill Rd, looking southwest. (Taken 5/14/2020)





97. View of Blackiston Mill Rd ROW from intersection of Walnut Grove and Blackiston Mill Rd, looking northwest. (Taken



99. View of SD 3 and Blackiston Mill Rd ROW, looking southeast. (Taken 5/14/2020)



98. View of Blackiston Mill Rd ROW from interstection of Walnut Grove and Blackiston Mill Rd, looking southeast. (Taken 5/14/2020)



100. View of CV 8 (comprised of two metal pipes and one HDPE pipe), looking southwest. (Taken 5/14/2020)





101. View of SD 4 and Blackiston Mill Rd ROW, looking southeast. (Taken 5/14/2020)



103. View of SD 5 and Blackiston Mill Rd ROW, looking northwest. (Taken 5/14/2020)



102. View of Blackiston Mill Rd ROW from SD 4, looking northwest. (Taken 5/14/2020)



104. View of Blackiston Mill Rd ROW from SD 5, looking southeast. (Taken 5/14/2020)





105. View of SD 6 and Blackiston Mill Rd ROW, looking southeast. (Taken 5/14/2020)



107. View of CV 9 and Blackiston Mill Rd ROW, looking northwest. (Taken $5/14/2020)\,$



106. View of Blackiston Mill Rd ROW, looking northwest. (Taken 5/14/2020)



108. View of intersection of Starlight Dr. and Blackiston Mill Rd from southwestern PSL, looking northeast. (Taken 5/14/2020)





109. View of Blackiston Mill Rd ROW from intersection of Starlight Dr and Blackiston Mill Rd intersection, looking northwest.



111. View of Blackiston Mill Rd ROW from southeastern PSL, looking northwest. (Taken 5/14/2020)



110. View of Blackiston Mill Rd ROW from intersection of Starlight Dr. and Blackiston Mill Rd intersection, looking southeast. (Taken 5/14/2020)



112. View of Blackiston Mill Rd ROW from southeastern PSL, looking northwest. (Taken 5/14/2020)





113. View of upland area south of Silver Creek from eastern PSL, looking northeast. (Taken 5/14/2020)



115. View of upland area south of Silver Creek from eastern PSL, looking southeast. (Taken 5/14/2020)



114. View of upland area south of Silver Creek from eastern PSL, looking southeast. (Taken 5/14/2020)



116. View of upland area south of Silver Creek from eastern PSL, looking southwest. (Taken 5/14/2020)





117. View of upland area south of Silver Creek from eastern PSL, looking west. (Taken 5/14/2020)



119. View of upland area south of Silver Creek from western PSL, looking northeast. (Taken 5/14/2020)



118. View of upland area south of Silver Creek from western PSL, looking north. (Taken 5/14/2020)



120. View of upland area south of Silver Creek from western PSL, looking southeast. (Taken 5/14/2020)

